

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "657c431e3fcadc67776c1647"
    },
    "firstName": "Pradeep Kumar ",
    "type": "CREDITOFFICER",
    "_id": "657c431e3fcadc67776c1649",
    "lastName": "Sahoo",
    "mobileNo": "",
    "workMobileNo": "9918900173",
    "email": "ubin0555851@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "657c431e3fcadc67776c1647",
  "name": "Airoli Branch",
  "branchCode": "555851",
  "mobileNo": "02227693402",
  "alternateMobileNo": "",
  "email": "ubin0555851@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Airoli Branch,\nBlacksmith Tower, Ground Floor, Plot No 14, Sector 6,
Airoli, Thane Navi Mumbai-400708"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
],
```

```
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
```

```
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.029096243640108",
  "longitude": "73.1028854163081"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kalamboli",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "F-10",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "4E/A",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```

```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```



```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": " 1 : 2 (Total 01 No.)",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 410 218",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering_with_POP_false_Celling",
  "label": "Cement Plastering with POP false Ceiling"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "City Industrial Development Corporation of Maharashtra"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Building No. F-9",
    "west": "Building No. F-13",
    "south": "kalamboli Market Road",
    "east": "D Mart Road"
  },
  "asPerDocumentAgreement": {
    "north": "Plot No. 3",
    "west": "30 Mtr. Wide Road",
    "south": "11 Mtr. Wide Road",
    "east": "8 Mtr. Wide Road"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
```

```
    "north": "Room No. 1",
    "east": "Open Space",
    "south": "Open Space",
    "west": "Open Space"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "The property is constructed by CIDCO, hence CIDCO
itself is an issuing authority.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_use",
    "label": "Commercial use"
  }
}
```

```
},
"propertyOccupiedByList": {
  "value": "Tenant_Occupied",
  "label": "Tenant Occupied"
},
"monthlyRent": "N.A.",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "Mrs. Vandana",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
},
```

```
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2012",
  "fullDate": "1/1/2012"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
```

```
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_commencement_certificate",
  "label": "As per commencement certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "48",
"ageOfBuilding": "12",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "Ground",
"noOfLifts": "",
```

```
    "noOfDwellingUnitsInBuilding": "2"
  },
  "finalPlinthArea": {
    "area": "1214.40",
    "areaType": "Built Up",
    "measurementType": "Sq. Ft.",
    "areaAsPer": "Carpet Area + 20%"
  },
  "routeMap": {
    "routeMapDetail": {
      "routeMapImg": "cases/66a37e9f8b202f344c316d6b/
routeMap_1722328185828_Image.png",
      "routeLat": "19.028542",
      "routeLng": "73.101663",
      "stationName": "K",
      "routeDistance": "3.9KM",
      "routeStation": {
        "value": "Railway_Station",
        "label": "Railway Station"
      }
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "j9fkab",
      "name": "j9fkab",
      "image": "cases/66a37e9f8b202f344c316d6b/
routeMap_1722327959841_Image.png"
    }
  ],
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": ""
    }
  }
}
```



```
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "1214.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
```

```
{
  "status": false,
  "_id": "66a8a57d24c0566f86156f5a",
  "name":
"externallmg_1722328444768_WhatsApp_Image_20240730_at_11047_PM_2.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444768_WhatsApp_Image_20240730_at_11047_PM_2.jpeg",
  "orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "66a8a55c2282636f80b2e80d",
    "name":
"externallmg_1722328412100_WhatsApp_Image_20240730_at_11053_PM_3.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412100_WhatsApp_Image_20240730_at_11053_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a8a55c2282636f80b2e808",
    "name":
"externallmg_1722328412032_WhatsApp_Image_20240730_at_11052_PM_2.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412032_WhatsApp_Image_20240730_at_11052_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a8a55c2282636f80b2e805",
    "name":
"externallmg_1722328412001_WhatsApp_Image_20240730_at_11051_PM_2.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412001_WhatsApp_Image_20240730_at_11051_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a8a56d24c0566f86156ef3",
    "name":
"externallmg_1722328429061_WhatsApp_Image_20240730_at_11053_PM.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429061_WhatsApp_Image_20240730_at_11053_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a8a56d24c0566f86156ef4",
    "name":
"externallmg_1722328429077_WhatsApp_Image_20240730_at_11054_PM_1.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429077_WhatsApp_Image_20240730_at_11054_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a8a55c2282636f80b2e809",
    "name":
"externallmg_1722328412049_WhatsApp_Image_20240730_at_11052_PM_3.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412049_WhatsApp_Image_20240730_at_11052_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a8a54f24c0566f86156e72",
    "name":
"externallmg_1722328398983_WhatsApp_Image_20240730_at_11049_PM_2.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328398983_WhatsApp_Image_20240730_at_11049_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a8a56d24c0566f86156efb",
    "name":
"externallmg_1722328429291_WhatsApp_Image_20240730_at_11046_PM.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429291_WhatsApp_Image_20240730_at_11046_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a8a57d24c0566f86156f5e",
    "name":
"externallmg_1722328444836_WhatsApp_Image_20240730_at_11048_PM_2.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444836_WhatsApp_Image_20240730_at_11048_PM_2.jpeg",
    "orientation": "portrait"
  }
}
```

```
    },
    {
      "status": false,
      "_id": "66a8a57d24c0566f86156f5d",
      "name":
"externallmg_1722328444822_WhatsApp_Image_20240730_at_11048_PM_1.jpeg",
      "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444822_WhatsApp_Image_20240730_at_11048_PM_1.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66a8a56d24c0566f86156ef9",
      "name":
"externallmg_1722328429224_WhatsApp_Image_20240730_at_11045_PM_2.jpeg",
      "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429224_WhatsApp_Image_20240730_at_11045_PM_2.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66a8a57d24c0566f86156f59",
      "name":
"externallmg_1722328444745_WhatsApp_Image_20240730_at_11047_PM_1.jpeg",
      "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444745_WhatsApp_Image_20240730_at_11047_PM_1.jpeg",
      "orientation": "landscape"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```



```
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1012.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66a37e9f8b202f344c316d6b",
"ownerName": "Shri. Subhash Sanchalal Jain & Mrs. Saroj S. Jain",
"ownerPhoneNo": "9820137663",
"fullAddress": "Residential Flat No. 1 : 2 (Total 01 No.), Ground Floor, Building No
F-10, Sector 4E/A, Village - Kalamboli, Taluka - Panvel, District - Raigad, Navi Mumbai,
PIN Code - 410 218, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
    "inputs": {
      "documentDate": "17/12/1999",
      "from": {
        "value": "The_Corporation",
```

```
    "label": "The Corporation"
  },
  "The_Corporation": "City and Industrial Development Corporation of Maharashtra",
  "to": {
    "value": "The_Apartment_Owner",
    "label": "The Apartment Owner"
  },
  "The_Apartment_Owner": "Dr. Subhash S. Jain & Mrs. Saroj S. Jain"
},
"isHardCopy": false,
"displayStatus": true,
"id": "933737",
"path": "cases/66a37e9f8b202f344c316d6b/
document_1721990683788_F_type_Document_Part_1_2.pdf",
"fileName": "document_1721990683788_F_type_Document_Part_1_2.pdf"
},
{
  "documentType": {
    "value": "60ae124daa6d152c1801b305",
    "label": "Tripartite Agreement"
  },
  "inputs": {
    "documentDate": "29/12/1999",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    }
  }
},
"isHardCopy": false,
"displayStatus": true,
"id": "988508",
"path": "cases/66a37e9f8b202f344c316d6b/
document_1721990776157_F_type_Document_Part_1.pdf",
"fileName": "document_1721990776157_F_type_Document_Part_1.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fc",
    "label": "Assessment Order"
  },
  "inputs": {
    "documentDate": "08/10/2012",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    }
  }
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1722326044616_119226.pdf",
    "path": "cases/66a37e9f8b202f344c316d6b/
document_1722326044616_119226.pdf",
    "id": "430350",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Tue Jul 30 2024 13:24:04 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "08/10/2012",
      "nameOfApprovingAuthority": {
        "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_Ltd.",
        "label": "City and Industrial Development Corp Of Maharashtra Ltd."
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "CIDCO / ATPO / 901"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1722326195802_143264.pdf",
    "path": "cases/66a37e9f8b202f344c316d6b/
document_1722326195802_143264.pdf",
    "id": "976231",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Tue Jul 30 2024 13:26:35 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae127aaa6d152c1801b3db",
      "label": "Society NOC Certificate"
    },
    "inputs": {
      "documentDate": "19/07/2012",
      "nameOfApprovingAuthority": {
        "value": "SOCIETY",
        "label": "SOCIETY"
      }
    }
  }
}
```

```
    }
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1722326370714_89858.pdf",
  "path": "cases/66a37e9f8b202f344c316d6b/document_1722326370714_89858.pdf",
  "id": "783226",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Tue Jul 30 2024 13:29:30 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "010198",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "965368",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jul 26 2024 16:16:55 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri. Subhash Sanchalal Jain & Mrs. Saroj S. Jain",
    "phone": "9820137663",
    "ownershipShare": "",
    "email": "",
    "id": "966687"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "526772",
    "name": "Living Room",
    "length": "11.00",
    "length1": "11",
  }
]
```

```
"length2": "00",
"width": "35.00",
"width1": "35",
"width2": "00",
"totalArea": "385.00",
"images": [],
"extraAreas": [],
"finalArea": "385.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "150.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "150.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "121.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "121.00"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "10",
"name": "Bedroom",
"length": "7.00",
"length1": "7",
"length2": "0",
"width": "10.00",
"width1": "10",
"width2": "0",
"totalArea": "70.00",
"images": [],
"finalArea": "70.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "13.00",
  "width1": "13",
  "width2": "00",
  "totalArea": "78.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "78.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "5.00",
```

```
"width1": "5",
"width2": "00",
"totalArea": "20.00",
"images": [],
"extraAreas": [],
"finalArea": "20.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "0",
  "width": "4.00",
  "width1": "4",
  "width2": "0",
  "totalArea": "20.00",
  "images": [],
  "finalArea": "20.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "21.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Terrace",
      "value": "Terrace"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "6.00",
    "length1": "6",
    "length2": "00",
    "width": "39.00",
    "width1": "39",
    "width2": "00",
    "totalArea": "234.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "234",
    "percentageBeforeTotal": "234.00",
    "percentage": "100"
  }
],
"externalReport": [],
```



```
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "209075",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "1012",
    "squareMeterArea": "94.02",
    "docFinalBuiltUp": "1214.4",
    "docFinalBuiltUpSquareMeter": "112.824",
    "docBultupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a54f24c0566f86156e71",
    "name":
"externallmg_1722328398956_WhatsApp_Image_20240730_at_11049_PM_1.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328398956_WhatsApp_Image_20240730_at_11049_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a54f24c0566f86156e72",
    "name":
"externallmg_1722328398983_WhatsApp_Image_20240730_at_11049_PM_2.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328398983_WhatsApp_Image_20240730_at_11049_PM_2.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a54f24c0566f86156e73",
    "name":
"externallmg_1722328399003_WhatsApp_Image_20240730_at_11049_PM.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328399003_WhatsApp_Image_20240730_at_11049_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a54f24c0566f86156e74",
    "name":
"externallmg_1722328399028_WhatsApp_Image_20240730_at_11050_PM_1.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328399028_WhatsApp_Image_20240730_at_11050_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a54f24c0566f86156e75",
    "name":
"externallmg_1722328399045_WhatsApp_Image_20240730_at_11050_PM_2.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328399045_WhatsApp_Image_20240730_at_11050_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a54f24c0566f86156e76",
    "name":
"externallmg_1722328399065_WhatsApp_Image_20240730_at_11050_PM_3.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328399065_WhatsApp_Image_20240730_at_11050_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a54f24c0566f86156e77",
    "name":
"externallmg_1722328399071_WhatsApp_Image_20240730_at_11050_PM.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328399071_WhatsApp_Image_20240730_at_11050_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a54f24c0566f86156e78",
    "name":
"externallmg_1722328399078_WhatsApp_Image_20240730_at_11051_PM_1.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328399078_WhatsApp_Image_20240730_at_11051_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a54f24c0566f86156e79",
    "name":
"externallmg_r_1722328398945_WhatsApp_Image_20240730_at_11036_PM.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_r_1722328398945_WhatsApp_Image_20240730_at_11036_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a55c2282636f80b2e805",
    "name":
"externallmg_1722328412001_WhatsApp_Image_20240730_at_11051_PM_2.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412001_WhatsApp_Image_20240730_at_11051_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a55c2282636f80b2e806",
    "name":
"externallmg_1722328412005_WhatsApp_Image_20240730_at_11051_PM.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412005_WhatsApp_Image_20240730_at_11051_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a55c2282636f80b2e807",
```

```
    "name":
"externallmg_1722328412020_WhatsApp_Image_20240730_at_11052_PM_1.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412020_WhatsApp_Image_20240730_at_11052_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a55c2282636f80b2e808",
  "name":
"externallmg_1722328412032_WhatsApp_Image_20240730_at_11052_PM_2.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412032_WhatsApp_Image_20240730_at_11052_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a55c2282636f80b2e809",
  "name":
"externallmg_1722328412049_WhatsApp_Image_20240730_at_11052_PM_3.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412049_WhatsApp_Image_20240730_at_11052_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a55c2282636f80b2e80a",
  "name":
"externallmg_1722328412060_WhatsApp_Image_20240730_at_11052_PM.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412060_WhatsApp_Image_20240730_at_11052_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a55c2282636f80b2e80b",
  "name":
"externallmg_1722328412080_WhatsApp_Image_20240730_at_11053_PM_1.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412080_WhatsApp_Image_20240730_at_11053_PM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a55c2282636f80b2e80c",
  "name":
"externallmg_1722328412091_WhatsApp_Image_20240730_at_11053_PM_2.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412091_WhatsApp_Image_20240730_at_11053_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a55c2282636f80b2e80d",
  "name":
"externallmg_1722328412100_WhatsApp_Image_20240730_at_11053_PM_3.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328412100_WhatsApp_Image_20240730_at_11053_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a56d24c0566f86156ef3",
  "name":
"externallmg_1722328429061_WhatsApp_Image_20240730_at_11053_PM.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429061_WhatsApp_Image_20240730_at_11053_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a56d24c0566f86156ef4",
  "name":
"externallmg_1722328429077_WhatsApp_Image_20240730_at_11054_PM_1.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429077_WhatsApp_Image_20240730_at_11054_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a56d24c0566f86156ef5",
  "name":
"externallmg_1722328429100_WhatsApp_Image_20240730_at_11054_PM.jpeg",
```

```
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429100_WhatsApp_Image_20240730_at_11054_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a56d24c0566f86156ef6",
    "name":
"externallmg_1722328429115_WhatsApp_Image_20240730_at_11039_PM.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429115_WhatsApp_Image_20240730_at_11039_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a56d24c0566f86156ef7",
    "name":
"externallmg_1722328429145_WhatsApp_Image_20240730_at_11044_PM.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429145_WhatsApp_Image_20240730_at_11044_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a56d24c0566f86156ef8",
    "name":
"externallmg_1722328429195_WhatsApp_Image_20240730_at_11045_PM_1.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429195_WhatsApp_Image_20240730_at_11045_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a56d24c0566f86156ef9",
    "name":
"externallmg_1722328429224_WhatsApp_Image_20240730_at_11045_PM_2.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429224_WhatsApp_Image_20240730_at_11045_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66a8a56d24c0566f86156efa",
  "name":
"externallmg_1722328429253_WhatsApp_Image_20240730_at_11045_PM.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429253_WhatsApp_Image_20240730_at_11045_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a56d24c0566f86156efb",
  "name":
"externallmg_1722328429291_WhatsApp_Image_20240730_at_11046_PM.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328429291_WhatsApp_Image_20240730_at_11046_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a57d24c0566f86156f59",
  "name":
"externallmg_1722328444745_WhatsApp_Image_20240730_at_11047_PM_1.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444745_WhatsApp_Image_20240730_at_11047_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a57d24c0566f86156f5a",
  "name":
"externallmg_1722328444768_WhatsApp_Image_20240730_at_11047_PM_2.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444768_WhatsApp_Image_20240730_at_11047_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a8a57d24c0566f86156f5b",
  "name":
"externallmg_1722328444785_WhatsApp_Image_20240730_at_11047_PM_3.jpeg",
  "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444785_WhatsApp_Image_20240730_at_11047_PM_3.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a57d24c0566f86156f5c",
    "name":
"externallmg_1722328444802_WhatsApp_Image_20240730_at_11047_PM.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444802_WhatsApp_Image_20240730_at_11047_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a57d24c0566f86156f5d",
    "name":
"externallmg_1722328444822_WhatsApp_Image_20240730_at_11048_PM_1.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444822_WhatsApp_Image_20240730_at_11048_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a57d24c0566f86156f5e",
    "name":
"externallmg_1722328444836_WhatsApp_Image_20240730_at_11048_PM_2.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444836_WhatsApp_Image_20240730_at_11048_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a8a57d24c0566f86156f5f",
    "name":
"externallmg_1722328444847_WhatsApp_Image_20240730_at_11048_PM.jpeg",
    "path": "cases/66a37e9f8b202f344c316d6b/
externallmg_1722328444847_WhatsApp_Image_20240730_at_11048_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
```



```
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-26T10:46:55.389Z",
"updatedAt": "2024-07-30T09:15:57.880Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Shri. Subhash Sanchalal Jain & Mrs. Saroj S. Jain",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820137663",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 2 Toilet + 2 Passage",
"carpetTotal": "885",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "234.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1230.90",
"finalCarpetArea": "1119.00",
"finalSalableArea": "1353.99",
"salablePercentage": "10",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "234.00",
"otherCompositionSaleableTotal": "0.00",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 885.00\nTerrace Area in Sq. Ft. = 234.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Deed of Apartment",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1012.00",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
```

```

    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	11'00"	35'00"	385.00
Bedroom	15'00"	10'00"	150.00
Bedroom	11'00"	11'00"	121.00
Bedroom	7'0"	10'0"	70.00
Kitchen	6'00"	13'00"	78.00
Toilet	4'00"	5'00"	20.00
Toilet	4'00"	5'00"	20.00
Passage	5'0"	4'0"	20.00
Passage	3'00"	7'00"	21.00
Other Composition :			
Terrace	6'00"	39'00"	234.00