

```
{
  "typeOfReport": {
    "value": "Land",
    "label": "Land"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "657c431e3fcadc67776c1647"
    },
    "firstName": "Pradeep Kumar ",
    "type": "CREDITOFFICER",
    "_id": "657c431e3fcadc67776c1649",
    "lastName": "Sahoo",
    "mobileNo": "",
    "workMobileNo": "9918900173",
    "email": "ubin0555851@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "657c431e3fcadc67776c1647",
  "name": "Airoli Branch",
  "branchCode": "555851",
  "mobileNo": "02227693402",
  "alternateMobileNo": "",
  "email": "ubin0555851@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Airoli Branch,\nBlacksmith Tower, Ground Floor, Plot No 14, Sector 6,
Airoli, Thane Navi Mumbai-400708"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.566653612343263",
  "longitude": "73.1073716042915"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Khupri",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Wada",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
}
```

```
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
```

```
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "259/21",
  "label": false
},
"municipalityWardNo": {
```



```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "259/21 & 259/20",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
```

```
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
```

```
"routeMapDetail": {
  "routeMapImg": "",
  "routeLat": "",
  "routeLng": "",
  "stationName": "",
  "routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
}
```

```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```



```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66a381688b202f344c3170ae",
"ownerName": "M/s. Parshwa Pipe",
"ownerPhoneNo": "9820137663",
"fullAddress": "Industrial Land No. 259/21, Ground Floor, Village - Khupri, Gut No.
259/21 & 259/20, Taluka - Wada, District - palghar, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
  },
  "inputs": {
    "documentDate": "12/07/2018",
    "from": {
      "value": "Developers",
      "label": "Developers"
    },
  },
  "Developers": "M/s. Laxmidevi Casting Company",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "M/s. Parshwa Pipe",
  "number": {
    "value": "No",
    "label": "No"
  }
}
```

```
    },
    "No": "913/2018"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1721991523645_Index_2_1.pdf",
  "path": "cases/66a381688b202f344c3170ae/
document_1721991523645_Index_2_1.pdf",
  "id": "583255",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Fri Jul 26 2024 16:28:48 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "010199",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "588077",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jul 26 2024 16:28:48 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Parshwa Pipe",
    "phone": "9820137663",
    "ownershipShare": "",
    "email": "",
    "id": "231184"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84d375301f243894d225",
    "name":
"externallmg_1722582226941_WhatsApp_Image_20240802_at_121552_1.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226941_WhatsApp_Image_20240802_at_121552_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84d375301f243894d226",
    "name":
"externallmg_1722582226944_WhatsApp_Image_20240802_at_121552.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226944_WhatsApp_Image_20240802_at_121552.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84d375301f243894d227",
    "name":
"externallmg_1722582226947_WhatsApp_Image_20240802_at_091127_1.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226947_WhatsApp_Image_20240802_at_091127_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84d375301f243894d228",
    "name":
"externallmg_1722582226950_WhatsApp_Image_20240802_at_091128.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226950_WhatsApp_Image_20240802_at_091128.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84d375301f243894d229",
    "name":
"externallmg_1722582226953_WhatsApp_Image_20240802_at_091129.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226953_WhatsApp_Image_20240802_at_091129.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84d375301f243894d22a",
    "name":
"externallmg_1722582226955_WhatsApp_Image_20240802_at_091130_1.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226955_WhatsApp_Image_20240802_at_091130_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84d375301f243894d22b",
    "name":
"externallmg_1722582226956_WhatsApp_Image_20240802_at_091130_2.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226956_WhatsApp_Image_20240802_at_091130_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84d375301f243894d22c",
    "name":
"externallmg_1722582226959_WhatsApp_Image_20240802_at_091130.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226959_WhatsApp_Image_20240802_at_091130.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84d375301f243894d22d",
    "name":
"externallmg_1722582226961_WhatsApp_Image_20240802_at_091131_1.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226961_WhatsApp_Image_20240802_at_091131_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84d375301f243894d22e",
```

```
    "name":
"externallmg_1722582226964_WhatsApp_Image_20240802_at_091131.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226964_WhatsApp_Image_20240802_at_091131.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84d375301f243894d22f",
  "name":
"externallmg_1722582226967_WhatsApp_Image_20240802_at_091132_1.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226967_WhatsApp_Image_20240802_at_091132_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84d375301f243894d230",
  "name":
"externallmg_1722582226981_WhatsApp_Image_20240802_at_091132.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226981_WhatsApp_Image_20240802_at_091132.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84d375301f243894d231",
  "name":
"externallmg_1722582226985_WhatsApp_Image_20240802_at_091133_1.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226985_WhatsApp_Image_20240802_at_091133_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84d375301f243894d232",
  "name":
"externallmg_1722582226990_WhatsApp_Image_20240802_at_091133.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226990_WhatsApp_Image_20240802_at_091133.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84d375301f243894d233",
  "name":
"externallmg_1722582226993_WhatsApp_Image_20240802_at_091134_1.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582226993_WhatsApp_Image_20240802_at_091134_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84f6eeb9d855e4ce64e6",
  "name":
"externallmg_1722582262168_WhatsApp_Image_20240802_at_091134_1.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262168_WhatsApp_Image_20240802_at_091134_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84f6eeb9d855e4ce64e7",
  "name":
"externallmg_1722582262170_WhatsApp_Image_20240802_at_091134_2.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262170_WhatsApp_Image_20240802_at_091134_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84f6eeb9d855e4ce64e8",
  "name":
"externallmg_1722582262173_WhatsApp_Image_20240802_at_091134.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262173_WhatsApp_Image_20240802_at_091134.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84f6eeb9d855e4ce64e9",
  "name":
"externallmg_1722582262177_WhatsApp_Image_20240802_at_091135_1.jpeg",
```

```
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262177_WhatsApp_Image_20240802_at_091135_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84f6eeb9d855e4ce64ea",
    "name":
"externallmg_1722582262179_WhatsApp_Image_20240802_at_091135.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262179_WhatsApp_Image_20240802_at_091135.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84f6eeb9d855e4ce64eb",
    "name":
"externallmg_1722582262181_WhatsApp_Image_20240802_at_091136_1.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262181_WhatsApp_Image_20240802_at_091136_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84f6eeb9d855e4ce64ec",
    "name":
"externallmg_1722582262184_WhatsApp_Image_20240802_at_091136.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262184_WhatsApp_Image_20240802_at_091136.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84f6eeb9d855e4ce64ed",
    "name":
"externallmg_1722582262186_WhatsApp_Image_20240802_at_091137_1.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262186_WhatsApp_Image_20240802_at_091137_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66ac84f6eeb9d855e4ce64ee",
  "name":
"externallmg_1722582262189_WhatsApp_Image_20240802_at_091137.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262189_WhatsApp_Image_20240802_at_091137.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84f6eeb9d855e4ce64ef",
  "name":
"externallmg_1722582262192_WhatsApp_Image_20240802_at_091138.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262192_WhatsApp_Image_20240802_at_091138.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84f6eeb9d855e4ce64f0",
  "name":
"externallmg_1722582262196_WhatsApp_Image_20240802_at_091139.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262196_WhatsApp_Image_20240802_at_091139.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84f6eeb9d855e4ce64f1",
  "name":
"externallmg_1722582262198_WhatsApp_Image_20240802_at_091143.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262198_WhatsApp_Image_20240802_at_091143.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac84f6eeb9d855e4ce64f2",
  "name":
"externallmg_1722582262211_WhatsApp_Image_20240802_at_091144_1.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262211_WhatsApp_Image_20240802_at_091144_1.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84f6eeb9d855e4ce64f3",
    "name":
"externallmg_1722582262215_WhatsApp_Image_20240802_at_091144.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262215_WhatsApp_Image_20240802_at_091144.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac84f6eeb9d855e4ce64f4",
    "name":
"externallmg_1722582262220_WhatsApp_Image_20240802_at_091145_1.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582262220_WhatsApp_Image_20240802_at_091145_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac850775301f243894d2ec",
    "name":
"externallmg_1722582279163_WhatsApp_Image_20240802_at_091145_1.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279163_WhatsApp_Image_20240802_at_091145_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac850775301f243894d2ed",
    "name":
"externallmg_1722582279166_WhatsApp_Image_20240802_at_091145.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279166_WhatsApp_Image_20240802_at_091145.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac850775301f243894d2ee",
```

```
    "name":
"externallmg_1722582279170_WhatsApp_Image_20240802_at_091146_1.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279170_WhatsApp_Image_20240802_at_091146_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac850775301f243894d2ef",
  "name":
"externallmg_1722582279173_WhatsApp_Image_20240802_at_091146.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279173_WhatsApp_Image_20240802_at_091146.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac850775301f243894d2f0",
  "name":
"externallmg_1722582279176_WhatsApp_Image_20240802_at_091147_1.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279176_WhatsApp_Image_20240802_at_091147_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac850775301f243894d2f1",
  "name":
"externallmg_1722582279180_WhatsApp_Image_20240802_at_091147.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279180_WhatsApp_Image_20240802_at_091147.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac850775301f243894d2f2",
  "name":
"externallmg_1722582279182_WhatsApp_Image_20240802_at_091148_1.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279182_WhatsApp_Image_20240802_at_091148_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac850775301f243894d2f3",
  "name":
"externallmg_1722582279185_WhatsApp_Image_20240802_at_091148.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279185_WhatsApp_Image_20240802_at_091148.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac850775301f243894d2f4",
  "name":
"externallmg_1722582279188_WhatsApp_Image_20240802_at_091149_1.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279188_WhatsApp_Image_20240802_at_091149_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac850775301f243894d2f5",
  "name":
"externallmg_1722582279191_WhatsApp_Image_20240802_at_091149_2.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279191_WhatsApp_Image_20240802_at_091149_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac850775301f243894d2f6",
  "name":
"externallmg_1722582279194_WhatsApp_Image_20240802_at_091149.jpeg",
  "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279194_WhatsApp_Image_20240802_at_091149.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac850775301f243894d2f7",
  "name":
"externallmg_1722582279197_WhatsApp_Image_20240802_at_091150_1.jpeg",
```

```
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279197_WhatsApp_Image_20240802_at_091150_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac850775301f243894d2f8",
    "name":
"externallmg_1722582279201_WhatsApp_Image_20240802_at_091150.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279201_WhatsApp_Image_20240802_at_091150.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac850775301f243894d2f9",
    "name":
"externallmg_1722582279205_WhatsApp_Image_20240802_at_091151.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279205_WhatsApp_Image_20240802_at_091151.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac850775301f243894d2fa",
    "name":
"externallmg_1722582279208_WhatsApp_Image_20240802_at_091126.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279208_WhatsApp_Image_20240802_at_091126.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac850775301f243894d2fb",
    "name":
"externallmg_1722582279211_WhatsApp_Image_20240802_at_091127.jpeg",
    "path": "cases/66a381688b202f344c3170ae/
externallmg_1722582279211_WhatsApp_Image_20240802_at_091127.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-26T10:58:48.805Z",
"updatedAt": "2024-08-02T07:04:39.379Z",
"__v": 0,
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "M/s. Parshwa Pipe",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820137663"
```

}

Name	Length	Width	Total
------	--------	-------	-------

Composition :

Other

Composition :