

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "firstName": "Nikita",
    "type": "CREDITOFFICER",
    "_id": "65d31e0addc2ef120ed2adb1",
    "lastName": "Jagtap",
    "mobileNo": "",
    "workMobileNo": "7304948055",
    "email": "8cord.21117@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2000000",
    "discussWithPerson": "Nikita",
    "expectedFees": 1000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
]
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.14570759030492",
  "longitude": "73.24586302042007"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.24586302042007,
    19.14570759030492
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "29/07/2024 08:44 am"
    },
    {
      "dateTime": "29/07/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kharvai",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambarnath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Usha Kiran Residancey",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```

```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```



```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "604",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66a4e99a7cad740610eb7757",
"ownerName": "Sunil Magan Shinde And Ratna SUnil Shinde",
"ownerPhoneNo": "9768989185",
"appAddress": "flat no. 604.6 th floor A wing Usha kiran Residency \nkhharvai Badlapur",
"remark": "SSL Ashwin kamble ",
"documents": [
```

```
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66a4e99a7cad740610eb7757/
document_1722083718095_1722083614712_Sunil_Shinde_Kharvai_1.pdf",
  "fileName":
"document_1722083718095_1722083614712_Sunil_Shinde_Kharvai_1.pdf",
  "id": "857513",
  "uploadedBy": "60b7189d2ffdf65bcd65882b",
  "createdAt": "Sat Jul 27 2024 18:05:38 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010218",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "951841",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jul 27 2024 18:05:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sunil Magan Shinde And Ratna SUnil Shinde",
    "phone": "9768989185",
    "ownershipShare": "",
    "email": "",
    "id": "744277"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "66a720ae00d67e06071b5df9",
    "name": "externallmg_1722228886021_1722228786047_image_0.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228886021_1722228786047_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a720ae00d67e06071b5dfa",
    "name": "externallmg_1722228895863_1722228786047_image_1.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228895863_1722228786047_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a720ae00d67e06071b5dfb",
    "name": "externallmg_1722228906548_1722228786047_image_2.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228906548_1722228786047_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a720ae00d67e06071b5dfc",
    "name": "externallmg_1722228908124_1722228786047_image_3.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228908124_1722228786047_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a720ae00d67e06071b5dfd",
    "name": "externallmg_1722228909485_1722228786047_image_4.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228909485_1722228786047_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "66a720bc00d67e06071b5e33",
    "name": "externallmg_1722228914830_1722228812147_image_0.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228914830_1722228812147_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e34",
    "name": "externallmg_1722228916113_1722228812147_image_1.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228916113_1722228812147_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e35",
    "name": "externallmg_1722228916318_1722228812147_image_2.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228916318_1722228812147_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e36",
    "name": "externallmg_1722228917088_1722228812147_image_3.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228917088_1722228812147_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e37",
    "name": "externallmg_1722228917244_1722228812147_image_4.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228917244_1722228812147_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e38",
```

```
    "name": "externallmg_1722228917408_1722228812147_image_5.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228917408_1722228812147_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e39",
    "name": "externallmg_1722228918599_1722228812147_image_6.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228918599_1722228812147_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e3a",
    "name": "externallmg_1722228919763_1722228812147_image_7.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228919763_1722228812147_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e3b",
    "name": "externallmg_1722228920573_1722228812147_image_8.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228920573_1722228812147_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e3c",
    "name": "externallmg_1722228921727_1722228812147_image_9.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228921727_1722228812147_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e3d",
    "name": "externallmg_1722228922568_1722228812147_image_10.jpeg",
```

```
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228922568_1722228812147_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e3e",
    "name": "externallmg_1722228923339_1722228812147_image_11.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228923339_1722228812147_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a720bc00d67e06071b5e3f",
    "name": "externallmg_1722228923858_1722228812147_image_12.jpeg",
    "path": "cases/66a4e99a7cad740610eb7757/
externallmg_1722228923858_1722228812147_image_12.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-27T12:35:38.634Z",
"updatedAt": "2024-07-29T04:55:24.653Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 604, 6th Floor, Usha Kiran Residancey, Village -
Kharvai, Taluka - Ambernath, State - Maharashtra, India",
"updatedBy": "64e5a649daae6a1c98101989",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Sunil Magan Shinde And Ratna SUnil Shinde",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": ""
```

"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9768989185"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			