

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b263d9191f7b344b008894"
    },
    "firstName": "Ravi Ratnaparikhi",
    "type": "CREDITOFFICER",
    "_id": "64c7602105efe8082a8c9b43",
    "lastName": "Ratnaparikhi",
    "mobileNo": "",
    "workMobileNo": "9970694920",
    "email": "ravi.ratnaparikhi@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b263d9191f7b344b008894",
  "name": "SME Fort Branch",
  "branchCode": "",
  "mobileNo": "022-22624308",
  "alternateMobileNo": "",
  "email": "sbi.60113@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Gresham House, Sir P. M. Road Branch, Fort, \nMumbai - 400 001, State
- Maharashtra, Country - India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af3d172ffdf65bcd6585cd",
  "role": "PICKUPPERSON",
  "firstName": "Sachin",
  "email": "sachin.joshi@vastukala.org",
  "lastName": "Joshi",
  "mobileNo": "9167204063",
  "shortName": "SJ",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
  "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": ""
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "18.96376534244921",
  "longitude": "72.82258794010532"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82258794010532,
    18.96376534244921
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "1/08/2024 12:54 pm"
    },
    {
      "dateTime": "1/08/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Girgaon",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "36",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ruby",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near C P Tank Circle And Shree Pimpleshwar Mahadev and hanuman
Mandir",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
```

```
"key": "street2",
"value": "Tatya Gharpure Marg Pimpalwadi",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Shreepari Jewels",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```



```
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "3603 & 3604 ",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Girgaon",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Italian Marble Flooring",
    "value": "ItalianMarbleFlooring"
  },
  "doors": {
    "label": "Teak Wood Door frame with Solid flush door",
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door"
  },
  "windows": {
```

```

    "label": "Powder coated Aluminum sliding windows",
    "value": "Powder_coated_Aluminum_sliding_windows"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed ",
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_"
  },
  "finishing": {
    "label": "Cement Plastering with POP Finished",
    "value": "Cement_Plastering_with_POP_Finished"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Shreepati jewels B wing",
    "west": "Level 40 building",
    "south": "Chawl",
    "east": "C and D wing"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Entrance 3603-04",
      "west": "Passage",
      "south": "Lift",
      "east": "Building outer view"
    },
    "asPerDocument": {

```

```
"north": "",
"west": "",
"south": "",
"east": ""
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"waterTank": {
  "label": "Municipal Water Supply",
  "value": "MunicipalWaterSupply"
},
"carParking": {
  "label": "Podium Parking",
  "value": "Podium_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2004",
  "fullDate": "1/1/2004"
},
"propertyTypeList": {
  "label": "Residential",
  "value": "Residential"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
}
```



```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```



```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
```

```
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66a899af24c0566f861568b7",
"ownerName": "Bhavik Arvindkumar Shah ",
```

```
"ownerPhoneNo": "9819870330",
"appAddress": "Flat no 3603 &3604, 36Floor,A-wing,Shreepati Tower,( Shreepati
Jewels Ruby) Girgaon Charni Road ",
"remark": "Contact Person Mr Paresh Bhai 981987330",
"documents": [
  {
    "documentType": {
      "label": "Old Valution Report ",
      "value": "60ae1296aa6d152c1801b455"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66a899af24c0566f861568b7/
document_1722325407102_347242.pdf",
    "fileName": "document_1722325407102_347242.pdf",
    "id": "249976",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue Jul 30 2024 13:13:42 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Old Valution Report ",
      "value": "60ae1296aa6d152c1801b455"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66a899af24c0566f861568b7/document_1722326893589_172232679
4784_Bhavik_ShahFkat_no_36033604_Old_Valuation_Report_SBI_SME_Fort.pdf",
    "fileName": "document_1722326893589_1722326794784_Bhavik_ShahFkat_no_36
033604_Old_Valuation_Report_SBI_SME_Fort.pdf",
    "id": "248560",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue Jul 30 2024 13:38:32 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66a899af24c0566f861568b7/document_1722326906535_172232680
3809_Bhavik_Shah_Flat_no_3603_3604_Agreement.pdf",
    "fileName": "document_1722326906535_1722326803809_Bhavik_Shah_Flat_no_3
603_3604_Agreement.pdf",
    "id": "564326",
```

```
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue Jul 30 2024 13:38:32 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010247",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "770345",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 30 2024 13:13:43 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Bhavik Arvindkumar Shah ",
    "phone": "9819870330",
    "ownershipShare": "",
    "email": "",
    "id": "895014"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "66b19ad14388d81213f236a5",
    "area": "1711",
    "providedByName": "Bhavik Arvindkumar Shah ",
    "providedByContactNo": "9819870330"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
  },
]
```

```
"id": "429794",
"name": "Living /_Dinning",
"length": "22.33",
"length1": "22",
"length2": "4",
"width": "22.17",
"width1": "22",
"width2": "2",
"totalArea": "495.06",
"images": [
  {
    "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916197217_image.jpeg",
    "orientation": "portrait"
  },
  {
    "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916197372_image.jpeg",
    "orientation": "portrait"
  },
  {
    "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916197446_image.jpeg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "495.06"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "17.67",
  "length1": "17",
  "length2": "8",
  "width": "9.83",
  "width1": "9",
  "width2": "10",
  "totalArea": "173.72",
  "images": [
    {
      "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916319432_image.jpeg",
```

```
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "173.72"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "41.96",
  "images": [],
  "extraAreas": [],
  "finalArea": "41.96"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "11.33",
  "length1": "11",
  "length2": "4",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "110.50",
  "images": [
    {
      "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916425862_image.jpeg",
      "orientation": "portrait"
    }
  ]
},
"extraAreas": [
```



```
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "_id": "66b1a0884388d81213f23a07",
  "name": "additional area",
  "extraAreaType": "Add",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "11.00"
}
],
"finalArea": "121.5"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "23.00",
  "length1": "23",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "69.00",
  "images": [
    {
      "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916488202_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "69.00"
},
{
  "measurementType": {
    "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "10.50",
  "width1": "10",
  "width2": "6",
  "totalArea": "130.37",
  "images": [
    {
      "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916530274_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "130.37"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
  "width": "4.25",
  "width1": "4",
  "width2": "3",
  "totalArea": "27.98",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "_id": "66b1a0884388d81213f23a08",
      "name": "additional area",
      "extraAreaType": "Add",
      "length": "2.42",
```

```
    "length1": "2",
    "length2": "5",
    "width": "1.25",
    "width1": "1",
    "width2": "3",
    "totalArea": "3.02"
  }
],
"finalArea": "31"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "11.83",
  "length1": "11",
  "length2": "10",
  "width": "10.50",
  "width1": "10",
  "width2": "6",
  "totalArea": "124.25",
  "images": [
    {
      "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916648271_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "124.25"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "6.42",
  "length1": "6",
  "length2": "5",
  "width": "3.58",
  "width1": "3",
```

```
"width2": "7",
"totalArea": "22.99",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "_id": "66b1a0884388d81213f23a09",
    "name": "extra area",
    "extraAreaType": "Add",
    "length": "3.17",
    "length1": "3",
    "length2": "2",
    "width": "1.25",
    "width1": "1",
    "width2": "3",
    "totalArea": "3.96"
  }
],
"finalArea": "26.95"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "9",
  "name": "Bedroom",
  "length": "16.33",
  "length1": "16",
  "length2": "4",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "164.69",
  "images": [
    {
      "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916767047_image.jpeg",
      "orientation": "portrait"
    }
  ]
},
"extraAreas": [],
"finalArea": "164.69"
```

```
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "10",
  "name": "Toilet",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "25.67",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "_id": "66b1a0884388d81213f23a0a",
      "name": "extra area",
      "extraAreaType": "Add",
      "length": "2.25",
      "length1": "2",
      "length2": "3",
      "width": "1.42",
      "width1": "1",
      "width2": "5",
      "totalArea": "3.19"
    },
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "_id": "66b1a0884388d81213f23a0b",
      "name": "extra area",
      "extraAreaType": "Add",
      "length": "2.42",
      "length1": "2",
      "length2": "5",
      "width": "1.58",
      "width1": "1",
```

```
    "width2": "7",
    "totalArea": "3.83"
  }
],
"finalArea": "32.690000000000005"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "11",
  "name": "Store Room",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "45.00",
  "images": [
    {
      "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916910529_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "45.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "12",
  "name": "Balcony Area",
  "length": "50.50",
  "length1": "50",
  "length2": "6",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "202.00",
  "images": [
    {
```

```
    "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916947264_image.jpeg",
    "orientation": "portrait"
  },
  {
    "path": "cases/66a899af24c0566f861568b7/
compositionImg_1722916947632_image.jpeg",
    "orientation": "landscape"
  }
],
"extraAreas": [],
"finalArea": "202.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "13",
  "name": "Balcony Area",
  "length": "9.58",
  "length1": "9",
  "length2": "7",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "33.54",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.54"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8d5",
    "name":
"externallmg_1722916359775_WhatsApp_Image_20240806_at_091622.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359775_WhatsApp_Image_20240806_at_091622.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8d6",
    "name":
"externallmg_1722916359780_WhatsApp_Image_20240806_at_091623_1.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359780_WhatsApp_Image_20240806_at_091623_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8d7",
    "name":
"externallmg_1722916359781_WhatsApp_Image_20240806_at_091623.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359781_WhatsApp_Image_20240806_at_091623.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8d8",
    "name":
"externallmg_1722916359783_WhatsApp_Image_20240806_at_091520.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359783_WhatsApp_Image_20240806_at_091520.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8d9",
    "name":
"externallmg_1722916359785_WhatsApp_Image_20240806_at_091521_1.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359785_WhatsApp_Image_20240806_at_091521_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8da",
```



```
    "name":
"externallmg_1722916359787_WhatsApp_Image_20240806_at_091521_2.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359787_WhatsApp_Image_20240806_at_091521_2.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8db",
    "name":
"externallmg_1722916359788_WhatsApp_Image_20240806_at_091521.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359788_WhatsApp_Image_20240806_at_091521.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8dc",
    "name":
"externallmg_1722916359789_WhatsApp_Image_20240806_at_091522_1.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359789_WhatsApp_Image_20240806_at_091522_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8dd",
    "name":
"externallmg_1722916359790_WhatsApp_Image_20240806_at_091522_2.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359790_WhatsApp_Image_20240806_at_091522_2.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8de",
    "name":
"externallmg_1722916359791_WhatsApp_Image_20240806_at_091522.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359791_WhatsApp_Image_20240806_at_091522.jpeg",
    "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e07da840b1214c1c8df",
  "name":
"externallmg_1722916359792_WhatsApp_Image_20240806_at_091523_1.jpeg",
  "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359792_WhatsApp_Image_20240806_at_091523_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e07da840b1214c1c8e0",
  "name":
"externallmg_1722916359793_WhatsApp_Image_20240806_at_091523.jpeg",
  "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359793_WhatsApp_Image_20240806_at_091523.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e07da840b1214c1c8e1",
  "name":
"externallmg_1722916359794_WhatsApp_Image_20240806_at_091524_1.jpeg",
  "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359794_WhatsApp_Image_20240806_at_091524_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e07da840b1214c1c8e2",
  "name":
"externallmg_1722916359795_WhatsApp_Image_20240806_at_091524_2.jpeg",
  "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359795_WhatsApp_Image_20240806_at_091524_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e07da840b1214c1c8e3",
  "name":
"externallmg_1722916359798_WhatsApp_Image_20240806_at_091524.jpeg",
```

```
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359798_WhatsApp_Image_20240806_at_091524.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8e4",
    "name":
"externallmg_1722916359798_WhatsApp_Image_20240806_at_091525_1.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359798_WhatsApp_Image_20240806_at_091525_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8e5",
    "name":
"externallmg_1722916359799_WhatsApp_Image_20240806_at_091525_2.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359799_WhatsApp_Image_20240806_at_091525_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8e6",
    "name":
"externallmg_1722916359800_WhatsApp_Image_20240806_at_091525.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359800_WhatsApp_Image_20240806_at_091525.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e07da840b1214c1c8e7",
    "name":
"externallmg_1722916359802_WhatsApp_Image_20240806_at_091526.jpeg",
    "path": "cases/66a899af24c0566f861568b7/
externallmg_1722916359802_WhatsApp_Image_20240806_at_091526.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66b1a0aada840b1214c1ca94",
  "name": "externalImg_1722917032682_image.jpeg",
  "path": "cases/66a899af24c0566f861568b7/
externalImg_1722917032682_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b1a0aada840b1214c1ca95",
  "name": "externalImg_1722917033042_image.jpeg",
  "path": "cases/66a899af24c0566f861568b7/
externalImg_1722917033042_image.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "ACCOUNTANT",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66aa28837a0b656fbbdd4129",
    "note": "Given approx. value",
    "taskId": "66a899af24c0566f861568c8",
    "createdAt": "2024-07-31T12:05:22.996Z"
  }
],
"createdAt": "2024-07-30T07:43:43.133Z",
"updatedAt": "2024-08-06T04:04:00.390Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "62550ed0aba01e0af98f2f75",
"assignmentType": {
```

```

"value": "Commercial",
"label": "Commercial"
},
"fullAddress": "Residential Flat No. 3603 & 3604 , 36th Floor, Wing - A, Ruby,
Shreepari Jewels, Near C P Tank Circle And Shree Pimpleshwar Mahadev and
hanuman Mandir, Taty Gharpure Marg Pimpalwadi, Village - Girgaon, Girgaon,
Mumbai, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Bhavik Arvindkumar Shah ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819870330",
"briefDescOfProperty": "4 Bedroom + Kitchen + Living /_Dinning + 4 Toilet + Passage
+ Store Room + 2 Balcony Area",
"carpetTotal": "1666.73",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			
Living /_Dinning	22'4"	22'2"	495.06
Bedroom	17'8"	9'10"	173.72
Toilet	9'6"	4'5"	41.96
Kitchen	11'4"	9'9"	110.50
Passage	23'00"	3'00"	69.00
Bedroom	12'5"	10'6"	130.37
Toilet	6'7"	4'3"	27.98
Bedroom	11'10"	10'6"	124.25
Toilet	6'5"	3'7"	22.99
Bedroom	16'4"	10'1"	164.69

Toilet	7'4"	3'6"	25.67
Store Room	9'00"	5'00"	45.00
Balcony Area	50'6"	4'00"	202.00
Balcony Area	9'7"	3'6"	33.54
Other Composition :			