

```
{
  "typeOfReport": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "masterTypeOfPurpose": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "toAssess": {
    "value": "Capital_Gain_2001",
    "label": "Capital Gain 2001"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "66a9cda42282636f80b33ef9",
```

```
"type": "PRIVATE_CLIENT",
"name": "Mr. Walter Pius Sebastain Pereira & Mrs. Gretta Walter Pereira",
"displayName": "Mr. Walter Pius Sebastain Pereira & Mrs. Gretta Walter Pereira",
"initial": "M"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "email": "jagdish.bhatt@vastukala.org",
    "lastName": "Bhatt",
    "mobileNo": "8425864014",
    "shortName": "JB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
    "role": "MAKER",
    "firstName": "Bhavika",
    "email": "bhavikachavan0102@gmail.com",
    "lastName": "chavan",
    "mobileNo": "8390804382",
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "rateVerifier": null,
  "maker": null,
  "checker": null,
```

```
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
],
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.139558767431392",
  "longitude": "72.86527815546313"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
    0,  
    0  
  ]  
},  
"siteVisit": {  
  "siteVisitStatus": false,  
  "schedule": [],  
  "visitedDate": []  
},  
"marketAnalysisAndRemark": {  
  "audioNotes": []  
},  
"externalReportDetails": {  
  "finalAreaType": "Built_Up",  
  "finalMeasurementType": "Sq. Ft.",  
  "underConstruction": false  
},  
"address": {  
  "state": {  
    "status": true,  
    "name": "State",  
    "key": "state",  
    "value": "Maharashtra",  
    "label": true  
  },  
  "country": {  
    "status": true,  
    "name": "Country",  
    "key": "country",  
    "value": "India",  
    "label": false  
  },  
  "village": {  
    "status": false,  
    "name": "Village",  
    "key": "village",  
    "value": "",  
    "label": true  
  },  
  "floorNo": {  
    "status": true,  
    "name": "Floor No",  
    "key": "floorNo",  
    "value": "2",  
    "label": false  
  },  
}
```

```
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "2",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Andheri",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
```

```
"value": "Takshila CHSL",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mahakali Caves",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
```

```
"status": false,
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "21 A",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
```

```
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
```



```
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
```

```
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
```

```
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66a9cda42282636f80b33efe",
"ownerName": "Mr. Walter Pius Sebastain Pereira & Mrs. Gretta Walter Pereira",
"ownerPhoneNo": "9820160560",
"fullAddress": "Residential Capital Gain No. 21 A, 2nd Floor, Building No 2, Takshila
CHSL, Mahakali Caves, Andheri",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1722404213930_Sale_Deed.pdf",
    "path": "cases/66a9cda42282636f80b33efe/
document_1722404213930_Sale_Deed.pdf",
    "id": "507896",
    "uploadedBy": "6006d4ce5080a310ac1fd2",
    "createdAt": "Wed Jul 31 2024 11:07:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1722404224384_Agreement_For_Sale.pdf",
    "path": "cases/66a9cda42282636f80b33efe/
document_1722404224384_Agreement_For_Sale.pdf",
```



```
"id": "466033",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Wed Jul 31 2024 11:07:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1722404234061_Deed_Of_declaration.pdf",
  "path": "cases/66a9cda42282636f80b33efe/
document_1722404234061_Deed_Of_declaration.pdf",
  "id": "326010",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Wed Jul 31 2024 11:07:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1722404244545_Document.pdf",
  "path": "cases/66a9cda42282636f80b33efe/
document_1722404244545_Document.pdf",
  "id": "924961",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Wed Jul 31 2024 11:07:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1722404253582_Form_Of_Application.pdf",
  "path": "cases/66a9cda42282636f80b33efe/
document_1722404253582_Form_Of_Application.pdf",
  "id": "969484",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Wed Jul 31 2024 11:07:40 GMT+0530 (India Standard Time)"
}
}
```

```
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "010265",
"createdBy": "6006d4ce5080a310ac1fd2",
"caseHistory": [
  {
    "id": "275683",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jul 31 2024 11:07:40 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Walter Pius Sebastain Pereira & Mrs. Gretta Walter Pereira",
    "phone": "9820160560",
    "ownershipShare": "",
    "email": "",
    "id": "488301"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9d05924c0566f8615eac6",
    "name": "externalImg_1722404949341_1722404846843_image_0.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/externalImg_1722404949341_1722404846843_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9d05924c0566f8615eac7",

```

```
    "name": "externallmg_1722404950750_1722404846843_image_1.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404950750_1722404846843_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9d05924c0566f8615eac8",
    "name": "externallmg_1722404951471_1722404846843_image_2.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404951471_1722404846843_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9d05924c0566f8615eac9",
    "name": "externallmg_1722404951774_1722404846843_image_3.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404951774_1722404846843_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9d05924c0566f8615eaca",
    "name": "externallmg_1722404952226_1722404846843_image_4.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404952226_1722404846843_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9d05924c0566f8615eacb",
    "name": "externallmg_1722404952938_1722404846843_image_5.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404952938_1722404846843_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a9d05a24c0566f8615eb09",
    "name": "externallmg_1722404946105_1722404818395_image_0.jpeg",
```

```
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404946105_1722404818395_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a9d05a24c0566f8615eb0a",
    "name": "externallmg_1722404946261_1722404818395_image_1.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404946261_1722404818395_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a9d05a24c0566f8615eb0b",
    "name": "externallmg_1722404946695_1722404818395_image_2.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404946695_1722404818395_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a9d05a24c0566f8615eb0c",
    "name": "externallmg_1722404947373_1722404818395_image_3.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404947373_1722404818395_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a9d05a24c0566f8615eb0d",
    "name": "externallmg_1722404947758_1722404818395_image_4.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404947758_1722404818395_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a9d05a24c0566f8615eb0e",
    "name": "externallmg_1722404948154_1722404818395_image_5.jpeg",
    "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404948154_1722404818395_image_5.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb0f",
  "name": "externallmg_1722404948749_1722404818395_image_6.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404948749_1722404818395_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb10",
  "name": "externallmg_1722404949245_1722404818395_image_7.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404949245_1722404818395_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb11",
  "name": "externallmg_1722404949255_1722404818395_image_8.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404949255_1722404818395_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb12",
  "name": "externallmg_1722404949466_1722404818395_image_9.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404949466_1722404818395_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb13",
  "name": "externallmg_1722404950202_1722404818395_image_10.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404950202_1722404818395_image_10.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb14",
  "name": "externallmg_1722404950620_1722404818395_image_11.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404950620_1722404818395_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb15",
  "name": "externallmg_1722404950940_1722404818395_image_12.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404950940_1722404818395_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb16",
  "name": "externallmg_1722404951129_1722404818395_image_13.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404951129_1722404818395_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb17",
  "name": "externallmg_1722404951393_1722404818395_image_14.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404951393_1722404818395_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb18",
  "name": "externallmg_1722404951618_1722404818395_image_15.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externallmg_1722404951618_1722404818395_image_15.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb19",
  "name": "externalImg_1722404952282_1722404818395_image_16.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externalImg_1722404952282_1722404818395_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb1a",
  "name": "externalImg_1722404953781_1722404818395_image_17.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externalImg_1722404953781_1722404818395_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb1b",
  "name": "externalImg_1722404953868_1722404818395_image_18.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externalImg_1722404953868_1722404818395_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a9d05a24c0566f8615eb1c",
  "name": "externalImg_1722404954293_1722404818395_image_19.jpeg",
  "path": "cases/66a9cda42282636f80b33efe/
externalImg_1722404954293_1722404818395_image_19.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-31T05:37:40.264Z",
"updatedAt": "2024-07-31T05:49:14.600Z",
"__v": 0,
"updatedBy": "62691c48afd7d55eddecfda3",
```

```
"addressForMap": "",
"caseReferredBy": "5ff3ead28cda966090eachbbe",
"contactPersonName": "Mr. Walter Pius Sebastain Pereira ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820160560"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			