

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "r. Mohanty",
    "type": "CREDITOFFICER",
    "_id": "646dc536b05e530fb6c47b3d",
    "lastName": " Sir",
    "mobileNo": "",
    "workMobileNo": "8411020137",
    "email": "rlf.nasik@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
```

```
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
```

```
    "designation": "",
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chauthari_Photo_2.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.984397102542697",
  "longitude": "73.76466465138276"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2/08/2024 01:40 pm"
    },
    {
      "dateTime": "2/08/2024 12:00 am"
    },
    {
      "dateTime": "2/08/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-01",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Nashik",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
```

```
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "11+12+13",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ramalya Sansruti Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Jagtap Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Nitin Car Towing Service ",
  "label": false
},
"wing": {
  "status": false,
```



```
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "763/2/2/2",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```

```
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "PowderCoatedAluminiumSliding",
    "label": "Powder Coated Aluminium Sliding"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
},
```

```
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Building",
    "west": "Shriram Co.Op.Hsg.Soc",
    "south": "Road",
    "east": "Road"
  },
  "asPerDocumentAgreement": {
    "north": "Survey No.763/2/2",
    "west": "Survey No.763/1/1/1/4",
    "south": "9.00 Meter Colony Road",
    "east": "6.00 Meter Colony Road"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space",
      "east": "Marginal Space",
      "south": "Lobby, Passage, Staircase",
      "west": "Marginal Space"
    },
    "asPerDocument": {
      "north": "Marginal Space",
      "east": "Marginal Space",
      "south": "Lobby, Passage, Staircase",
      "west": "Marginal Space"
    }
  },
}
```

```
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No.LND/BP/67/2021
Dated 14.06.2021 , Issued by Nashik Municipal Corporation ",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "7200.00",
  "depreciatedBuildingRate": "2000"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "37400",
  "landRate": "1400",
  "igrImage": "cases/66ac94bc200457247bd57fbf/igr_1722587891868_Image.png",
  "squareMeterGuideLineRate": "37400.00",
  "squareFeetGuideLineRate": "3475.00"
```

```
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "37400.00",
  "squareMeterGuideLineRate": "37400.00",
  "squareFeetGuideLineRate": "3475.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "n.a.",
  "assessmentNo": "Details Not Provided",
  "taxPaidHolderName": "Details Not Provided",
  "taxAmount": "Details Not Provided",
  "electricityServiceConnectionNo": "Details Not Provided",
  "meterCardHolderName": "Details Not Provided",
  "undividedAreaOfLandAsPerSaleDeed": "Details Not Available ",
  "floorSpaceIndex": "As Per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
```

```
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Yes",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2022",
"fullDate": "1/1/2022"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
}
```

```
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
```



```
"label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "58",
"ageOfBuilding": "2",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "5",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "1546.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66ac94bc200457247bd57fbf/
routeMap_1722589826343_Image.png",
    "routeLat": "19.984470",
    "routeLng": "73.764639",
    "stationName": "Nashik Road",
    "routeDistance": "11.4 KM",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
```

```
"finalatlng": false
},
"locationMapImg": [
  {
    "id": "hzue78",
    "name": "hzue78",
    "image": "cases/66ac94bc200457247bd57fbf/
routeMap_1722589715539_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "9280800.00",
```

```
"distressValuePercentage": "80",
"realizableValuePercentage": "95",
"bookValue": "0",
"finalValue": "9280800.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5375130.00",
  "selectedBuildUpValue": "1546.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66ac955c200457247bd580b2",
      "name":
"externallmg_1722586459532_WhatsApp_Image_20240731_at_54331_PM_2.jpeg",
      "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459532_WhatsApp_Image_20240731_at_54331_PM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "66ac955178e85a24399c68c8",
      "name":
"externallmg_1722586448050_WhatsApp_Image_20240731_at_53112_PM.jpeg",
      "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586448050_WhatsApp_Image_20240731_at_53112_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66ac955c200457247bd580af",
      "name":
"externallmg_1722586459267_WhatsApp_Image_20240731_at_54328_PM.jpeg",
      "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459267_WhatsApp_Image_20240731_at_54328_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66ac955c200457247bd580b0",
      "name":
"externallmg_1722586459353_WhatsApp_Image_20240731_at_54329_PM.jpeg",
      "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459353_WhatsApp_Image_20240731_at_54329_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [
    {
```

```
    "status": false,
    "_id": "66ac955c200457247bd580b1",
    "name":
"externallmg_1722586459445_WhatsApp_Image_20240731_at_54331_PM_1.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459445_WhatsApp_Image_20240731_at_54331_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "66ac955178e85a24399c68bf",
    "name": "Living Room",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447718_WhatsApp_Image_20240731_at_53109_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66ac955178e85a24399c68c0",
    "name": "Living Room",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447774_WhatsApp_Image_20240731_at_53109_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66ac955178e85a24399c68c1",
    "name": "Living Room",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447801_WhatsApp_Image_20240731_at_53110_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66ac955178e85a24399c68c2",
    "name": "Living Room",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447840_WhatsApp_Image_20240731_at_53110_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66ac955178e85a24399c68c4",
    "name": "Living Room",
```

```
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447907_WhatsApp_Image_20240731_at_53111_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66ac955178e85a24399c68c7",
    "name": "Living Room",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586448022_WhatsApp_Image_20240731_at_53112_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66ac955178e85a24399c68c9",
    "name": "Living Room",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586448101_WhatsApp_Image_20240731_at_53113_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66ac955178e85a24399c68ca",
    "name": "Living Room",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586448125_WhatsApp_Image_20240731_at_53113_PM_2.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7200.00",
    "max": "7907.00"
  },
  "builtUpRateRange": {
    "min": "6000.00",
    "max": "6590.00"
  },
  "saleableRateRange": {
    "min": "5000.00",
    "max": "5491.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```



```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1289.00",
"empanelmentNo": [
  "ZO :MZ:ADV:46:941\t"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66ac94bc200457247bd57fbf",
"ownerName": "Shri. Rajendra Ramdas Pingale & Shri. Sanjay Pundlik Gharte",
"ownerPhoneNo": "7721814607",
"fullAddress": "Residential Flat No. 403, 4th Floor, Ramalya Sansruti Apartment, Near
Nitin Car Towing Service , Plot No. 11+12+13, Jagtap Nagar, Village - Nashik, Taluka -
Nashik, District - Nashik, Nashik, 422003, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae12adaa6d152c1801b4bf",
      "label": "Notarized Agreement for Sale"
    },
    "inputs": {
      "documentDate": "29/07/2024",
      "amount": "5500000",
      "from": {
        "value": "Developers",
```

```
    "label": "Developers"
  },
  "Developers": "Shri. Rajendra Ramdas Pingale & Shri. Sanjay Pundlik Gharte",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Shri. Sujit Gulabrao Bhosale"
},
"isHardCopy": false,
"displayStatus": true,
"id": "537136",
"path": "cases/66ac94bc200457247bd57fbf/
document_1722586291155_DRAFT.pdf",
"fileName": "document_1722586291155_DRAFT.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "30/06/2022",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "NRV/30249/2022"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1722588633637_OC.pdf",
  "path": "cases/66ac94bc200457247bd57fbf/document_1722588633637_OC.pdf",
  "id": "229554",
  "uploadedBy": "636a1ad14d42487767af3f91",
  "createdAt": "Fri Aug 02 2024 14:20:33 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
}
```

```

"inputs": {
  "documentDate": "14/06/2021",
  "nameOfApprovingAuthority": {
    "value": "Nashik_Municipal_Corporation",
    "label": "Nashik Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "LND/BP/CD/67/2021"
},
"isHardCopy": false,
"displayStatus": true,
"id": "670769",
"path": "cases/66ac94bc200457247bd57fbf/document_1722588697467_CC.pdf",
"fileName": "document_1722588697467_CC.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "14/06/2021",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "LND/BP/CD/67/2021 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "839519",
  "path": "cases/66ac94bc200457247bd57fbf/
document_1722588756833_Building_Plan.pdf",
  "fileName": "document_1722588756833_Building_Plan.pdf"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
}

```

```
},
"caseNumber": "010315",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "222764",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Aug 02 2024 13:41:40 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri. Rajendra Ramdas Pingale & Shri. Sanjay Pundlik Gharte",
    "phone": "7721814607",
    "ownershipShare": "",
    "email": "",
    "id": "142768"
  }
],
"proposePurchasers": [
  {
    "name": "Shri. Sujit Gulabrao Bhosale",
    "phone": "7721814607",
    "email": "",
    "ownershipShare": ""
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "13",
    "name": "Kitchen",
    "length": "9.75",
    "length1": "9",
    "length2": "9",
    "width": "17.58",
    "width1": "17",
    "width2": "7",
    "totalArea": "171.44",
    "images": [],
    "finalArea": "171.44",
```

```
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "8.33",
  "width1": "8",
  "width2": "4",
  "totalArea": "38.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "38.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Living Room",
  "length": "12.00",
  "length1": "12",
  "length2": "0",
  "width": "21.50",
  "width1": "21",
  "width2": "6",
  "totalArea": "258.00",
  "images": [],
  "finalArea": "258.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Balcony",
  "length": "3.25",
```

```
"length1": "3",
"length2": "3",
"width": "9.67",
"width1": "9",
"width2": "8",
"totalArea": "31.42",
"images": [],
"extraAreas": [],
"finalArea": "31.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "5.08",
  "length1": "5",
  "length2": "1",
  "width": "8.08",
  "width1": "8",
  "width2": "1",
  "totalArea": "41.09",
  "images": [],
  "extraAreas": [],
  "finalArea": "41.09"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Bedroom",
  "length": "12.50",
  "length1": "12",
  "length2": "6",
  "width": "15.08",
  "width1": "15",
  "width2": "1",
  "totalArea": "188.54",
  "images": [],
  "finalArea": "188.54",
  "extraAreas": []
},
```



```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Balcony",
  "length": "10.50",
  "length1": "10",
  "length2": "6",
  "width": "11.50",
  "width1": "11",
  "width2": "6",
  "totalArea": "120.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "120.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "32.76",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.76"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bedroom",
  "length": "13.67",
  "length1": "13",
  "length2": "8",
```

```
"width": "11.25",
"width1": "11",
"width2": "3",
"totalArea": "153.75",
"images": [],
"extraAreas": [],
"finalArea": "153.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Balcony",
  "length": "3.50",
  "length1": "3",
  "length2": "6",
  "width": "11.42",
  "width1": "11",
  "width2": "5",
  "totalArea": "39.96",
  "images": [],
  "finalArea": "39.96",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Toilet",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "32.76",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.76"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "12.75",
  "width1": "12",
  "width2": "9",
  "totalArea": "140.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "140.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Balcony",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "11.00",
  "width1": "11",
  "width2": "0",
  "totalArea": "48.58",
  "images": [],
  "finalArea": "48.58",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae12adaa6d152c1801b4bf",
      "label": "Notarized Agreement for Sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
"selectAreaTypeDocument": "Carpet",
"squareMeterArea": "119.75",
"totalAreaDocument": "1289",
"docBuiltpPercentage": "20",
"docFinalBUILTUp": "1546.80",
"docFinalBUILTUpSquareMeter": "143.70",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "484285"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "763.89",
"squareMeterArea": "70.97",
"expectedRate": "7199.99",
"percentage": ""
},
"builtUpArea": {
"area": "916.67",
"squareMeterArea": "85.16",
"expectedRate": "5999.98",
"percentage": "20"
},
"saleableArea": {
"area": "1100.00",
"squareMeterArea": "102.19",
"expectedRate": "5000.00",
"percentage": "20"
},
"printlnReport": true,
"_id": "66ac9b48eeb9d855e4ce777d",
"property": "Flat",
"area": "1100",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Saleable",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "5500000",
"expectedRate": "5000",
```

```
"builtUpExpectedRate": "5999.98",
"image": "cases/66ac94bc200457247bd57fbf/
indicator_1722587724774_Image.png",
"squareMeter": "102.19",
"id": "750467"
},
{
  "carpetArea": {
    "area": "1252.08",
    "squareMeterArea": "116.32",
    "expectedRate": "7906.84",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1502.50",
    "squareMeterArea": "139.59",
    "expectedRate": "6589.02",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1803.00",
    "squareMeterArea": "167.50",
    "expectedRate": "5490.85",
    "percentage": "20"
  },
  "printInReport": true,
  "_id": "66ac9b48eeb9d855e4ce777e",
  "property": "Flat",
  "area": "1803",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Saleable",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "9900000",
  "expectedRate": "5490.848585690515",
  "builtUpExpectedRate": "6589.02",
  "image": "cases/66ac94bc200457247bd57fbf/
indicator_1722587818108_Image.png",
  "squareMeter": "167.50",
  "id": "454428"
}
],
"externallImages": [
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68be",
    "name":
"externallmg_1722586447695_WhatsApp_Image_20240731_at_53109_PM_1.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447695_WhatsApp_Image_20240731_at_53109_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68bf",
    "name":
"externallmg_1722586447718_WhatsApp_Image_20240731_at_53109_PM_2.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447718_WhatsApp_Image_20240731_at_53109_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68c0",
    "name":
"externallmg_1722586447774_WhatsApp_Image_20240731_at_53109_PM.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447774_WhatsApp_Image_20240731_at_53109_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68c1",
    "name":
"externallmg_1722586447801_WhatsApp_Image_20240731_at_53110_PM_1.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447801_WhatsApp_Image_20240731_at_53110_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68c2",
    "name":
"externallmg_1722586447840_WhatsApp_Image_20240731_at_53110_PM_2.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447840_WhatsApp_Image_20240731_at_53110_PM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68c3",
    "name":
"externallmg_1722586447866_WhatsApp_Image_20240731_at_53110_PM.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447866_WhatsApp_Image_20240731_at_53110_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68c4",
    "name":
"externallmg_1722586447907_WhatsApp_Image_20240731_at_53111_PM_1.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447907_WhatsApp_Image_20240731_at_53111_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68c5",
    "name":
"externallmg_1722586447960_WhatsApp_Image_20240731_at_53111_PM.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447960_WhatsApp_Image_20240731_at_53111_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68c6",
    "name":
"externallmg_1722586447985_WhatsApp_Image_20240731_at_53112_PM_1.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586447985_WhatsApp_Image_20240731_at_53112_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68c7",
```

```
    "name":  
    "externallmg_1722586448022_WhatsApp_Image_20240731_at_53112_PM_2.jpeg",  
    "path": "cases/66ac94bc200457247bd57fbf/  
externallmg_1722586448022_WhatsApp_Image_20240731_at_53112_PM_2.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "66ac955178e85a24399c68c8",  
    "name":  
    "externallmg_1722586448050_WhatsApp_Image_20240731_at_53112_PM.jpeg",  
    "path": "cases/66ac94bc200457247bd57fbf/  
externallmg_1722586448050_WhatsApp_Image_20240731_at_53112_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "66ac955178e85a24399c68c9",  
    "name":  
    "externallmg_1722586448101_WhatsApp_Image_20240731_at_53113_PM_1.jpeg",  
    "path": "cases/66ac94bc200457247bd57fbf/  
externallmg_1722586448101_WhatsApp_Image_20240731_at_53113_PM_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "66ac955178e85a24399c68ca",  
    "name":  
    "externallmg_1722586448125_WhatsApp_Image_20240731_at_53113_PM_2.jpeg",  
    "path": "cases/66ac94bc200457247bd57fbf/  
externallmg_1722586448125_WhatsApp_Image_20240731_at_53113_PM_2.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "66ac955178e85a24399c68cb",  
    "name":  
    "externallmg_1722586448152_WhatsApp_Image_20240731_at_53113_PM.jpeg",  
    "path": "cases/66ac94bc200457247bd57fbf/  
externallmg_1722586448152_WhatsApp_Image_20240731_at_53113_PM.jpeg",  
    "orientation": "portrait"  
  },  
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac955178e85a24399c68cc",
  "name":
"externallmg_1722586448176_WhatsApp_Image_20240731_at_53114_PM_1.jpeg",
  "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586448176_WhatsApp_Image_20240731_at_53114_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac955178e85a24399c68cd",
  "name":
"externallmg_1722586448191_WhatsApp_Image_20240731_at_53114_PM.jpeg",
  "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586448191_WhatsApp_Image_20240731_at_53114_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac955178e85a24399c68ce",
  "name":
"externallmg_1722586448252_WhatsApp_Image_20240731_at_53115_PM_1.jpeg",
  "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586448252_WhatsApp_Image_20240731_at_53115_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac955178e85a24399c68cf",
  "name":
"externallmg_1722586448292_WhatsApp_Image_20240731_at_53115_PM_2.jpeg",
  "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586448292_WhatsApp_Image_20240731_at_53115_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac955178e85a24399c68d0",
  "name":
"externallmg_1722586448306_WhatsApp_Image_20240731_at_53115_PM.jpeg",
```

```
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586448306_WhatsApp_Image_20240731_at_53115_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955178e85a24399c68d1",
    "name":
"externallmg_1722586448332_WhatsApp_Image_20240731_at_53116_PM_1.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586448332_WhatsApp_Image_20240731_at_53116_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955c200457247bd580ac",
    "name":
"externallmg_1722586459113_WhatsApp_Image_20240731_at_53116_PM_2.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459113_WhatsApp_Image_20240731_at_53116_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955c200457247bd580ad",
    "name":
"externallmg_1722586459136_WhatsApp_Image_20240731_at_53116_PM.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459136_WhatsApp_Image_20240731_at_53116_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955c200457247bd580ae",
    "name":
"externallmg_1722586459165_WhatsApp_Image_20240731_at_54328_PM_1.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459165_WhatsApp_Image_20240731_at_54328_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66ac955c200457247bd580af",
  "name":
"externallmg_1722586459267_WhatsApp_Image_20240731_at_54328_PM.jpeg",
  "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459267_WhatsApp_Image_20240731_at_54328_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac955c200457247bd580b0",
  "name":
"externallmg_1722586459353_WhatsApp_Image_20240731_at_54329_PM.jpeg",
  "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459353_WhatsApp_Image_20240731_at_54329_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac955c200457247bd580b1",
  "name":
"externallmg_1722586459445_WhatsApp_Image_20240731_at_54331_PM_1.jpeg",
  "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459445_WhatsApp_Image_20240731_at_54331_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac955c200457247bd580b2",
  "name":
"externallmg_1722586459532_WhatsApp_Image_20240731_at_54331_PM_2.jpeg",
  "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459532_WhatsApp_Image_20240731_at_54331_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ac955c200457247bd580b3",
  "name":
"externallmg_1722586459619_WhatsApp_Image_20240731_at_54331_PM_3.jpeg",
  "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459619_WhatsApp_Image_20240731_at_54331_PM_3.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955c200457247bd580b4",
    "name":
"externallmg_1722586459680_WhatsApp_Image_20240731_at_54331_PM.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459680_WhatsApp_Image_20240731_at_54331_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ac955c200457247bd580b5",
    "name":
"externallmg_1722586459770_WhatsApp_Image_20240731_at_54332_PM.jpeg",
    "path": "cases/66ac94bc200457247bd57fbf/
externallmg_1722586459770_WhatsApp_Image_20240731_at_54332_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Building Plan.pdf",
    "filename": "1722588005548_Building_Plan.pdf",
    "path": "cases/66ac94bc200457247bd57fbf/
processingDocuments/1722588005548_Building_Plan.pdf",
    "size": "449843",
    "createdAt": "Fri Aug 02 2024 14:10:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "636a1ad14d42487767af3f91"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1722588005598_CC.pdf",
    "path": "cases/66ac94bc200457247bd57fbf/
processingDocuments/1722588005598_CC.pdf",
    "size": "295297",
    "createdAt": "Fri Aug 02 2024 14:10:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "636a1ad14d42487767af3f91"
  },
  {
    "originalname": "Notarized Agreement.pdf",
    "filename": "1722588005622_Notarized_Agreement.pdf",
```

```
"path": "cases/66ac94bc200457247bd57fbf/
processingDocuments/1722588005622_Notarized_Agreement.pdf",
"size": "14444857",
"createdAt": "Fri Aug 02 2024 14:10:08 GMT+0530 (India Standard Time)",
"uploadedBy": "636a1ad14d42487767af3f91"
},
{
"originalname": "OC.pdf",
"filename": "1722588008647_OC.pdf",
"path": "cases/66ac94bc200457247bd57fbf/
processingDocuments/1722588008647_OC.pdf",
"size": "106840",
"createdAt": "Fri Aug 02 2024 14:10:08 GMT+0530 (India Standard Time)",
"uploadedBy": "636a1ad14d42487767af3f91"
},
{
"originalname": "Sujit Bhosale.xlsx",
"filename": "1722588008659_Sujit_Bhosale.xlsx",
"path": "cases/66ac94bc200457247bd57fbf/
processingDocuments/1722588008659_Sujit_Bhosale.xlsx",
"size": "593443",
"createdAt": "Fri Aug 02 2024 14:10:08 GMT+0530 (India Standard Time)",
"uploadedBy": "636a1ad14d42487767af3f91"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-02T08:11:40.053Z",
"updatedAt": "2024-08-03T07:48:37.255Z",
"__v": 0,
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Shri. Sujit Gulabrao Bhosale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Shri. Sujit Gulabrao Bhosale",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Applicant",
"siteVisitContactNo": "7721814607",
"buildingServicesRate": "2000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Notarized Agreement for Sale",
```

```
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1289.00",
"flatRate": "7200",
"landOtherRate": "5200",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "1298.1899999999998",
"extendOfSiteRemark": "",
"finalBuiltupArea": "1428.01",
"finalCarpetArea": "1298.19",
"finalSalableArea": "1570.81",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Fri Aug 02 2024 14:09:31 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-08-01",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Passage + 4 Balcony + 3 Toilet"
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Kitchen	9'9"	17'7"	171.44
Passage	4'8"	8'4"	38.89
Living Room	12'0"	21'6"	258.00
Balcony	3'3"	9'8"	31.42
Toilet	5'1"	8'1"	41.09
Bedroom	12'6"	15'1"	188.54
Balcony	10'6"	11'6"	120.75
Toilet	7'5"	4'5"	32.76
Bedroom	13'8"	11'3"	153.75
Balcony	3'6"	11'5"	39.96
Toilet	7'5"	4'5"	32.76
Bedroom	11'00"	12'9"	140.25
Balcony	4'5"	11'0"	48.58
Other Composition :			