

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65310e60619c14402da5c533"
    },
    "firstName": "Sachin ",
    "type": "CREDITOFFICER",
    "_id": "65310e60619c14402da5c537",
    "lastName": "Pingle",
    "mobileNo": "7249659315",
    "workMobileNo": "7249659315",
    "email": "nasikhhighway@unionbankofindia.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1180"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65310e60619c14402da5c533",
  "name": "Nashik Highway Branch",
  "branchCode": "576981 ",
  "mobileNo": "+91 2532303177",
  "alternateMobileNo": "",
  "email": "nasikhhighway@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No. 2,3,4 Sagar Plaza, S.no 250/7/2/1, plot No 1, Amrut Dham,
Panchawati, Nasik, 422003"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9f4adce84bf289ba9956e",
```

```
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": null,
"maker": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERIFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
```

```
    "mobileNo": "8007230780",
    "designation": "",
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.08449336255717",
  "longitude": "73.91462477977929"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Ozar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Ram",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shivaji Nagar, Ojhar, NH3 Highway",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Ozar Road",
```

```
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Shinde Lawns",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```

```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "01",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```



```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422207",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood",
    "label": "Proposed Teak wood"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  }
}
```

```
},
"fittings": {
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
  "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
},
"finishing": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
}
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Rural",
    "label": "Rural"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Plot No. 18",
    "west": "Plot No. 19 & 21 ",
    "south": "09 Mtr. Colony Road ",
    "east": "09 Mtr. Colony Road. "
  },
  "asPerDocumentAgreement": {
    "north": "Plot No. 18",
    "west": "Plot No. 19 & 21 ",
    "south": "09 Mtr. Colony Road ",
    "east": "09 Mtr. Colony Road. "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Building Side Margin",
```

```
"east": "Building Side Margin",
"south": "Flat No. 10, Lift, Duct",
"west": "Passage and Stair Case"
},
"asPerDocument": {
  "north": "Building Side Margin",
  "east": "Building Side Margin",
  "south": "Flat No. 10, Lift, Duct",
  "west": "Passage and Stair Case"
},
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "",
"approvePlanVerified": "",
"empanelledOfApprovePlan": "",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "25600",
  "landRate": "6600",
  "igrImage": "cases/66acbccc375301f243894fdb3/igr_1722600167219_Image.png",
  "squareMeterGuideLineRate": "25600.00",
  "squareFeetGuideLineRate": "2378.00"
```

```
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "25600.00",
  "squareMeterGuideLineRate": "25600.00",
  "squareFeetGuideLineRate": "2378.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "NA",
  "assessmentNo": "",
  "taxPaidHolderName": "",
  "taxAmount": "",
  "electricityServiceConnectionNo": "",
  "meterCardHolderName": "",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "As Ozar Coparation",
  "tenantName": "",
  "maintenanceOfFlat": ""
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "NA",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
```

```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"carParking": "Open Parking",
"constructionWorkStatus": {
"value": "InProgress",
"label": "Under Construction"
},
"asthetikLook": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"dateOfConstruction": {
"date": "",
"month": "1",
"year": "2024",
"fullDate": "1/1/2024"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "Proposed_R.C.C_Framed_Structure",
"label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"materialUsedList": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
```

```
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "stilt",
```

```
"label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "5",
"flatFloorNo": "1",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "370.70",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66acbcc375301f243894fdb3/
routeMap_1722600550790_Image.png",
    "routeLat": "20.084470",
    "routeLng": "73.914620",
    "stationName": "Nashik Road",
    "routeDistance": "17.7 KM",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
}
```

```
},
"locationMapImg": [
  {
    "id": "9qrct",
    "name": "9qrct",
    "image": "cases/66acb375301f243894fdb3/
routeMap_1722600937325_Image.png"
  }
],
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "1348000.00",
  "distressValuePercentage": "80",
```



```
"realizableValuePercentage": "95",
"bookValue": "0",
"finalValue": "1348000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "5",
    "percentage": "28.571428571428573",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "5",
    "percentage": "5.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "5",
    "percentage": "5.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "5",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "5",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "53.57",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "881525.00",
  "selectedBuildUpValue": "370.70",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
```

```
"frontPageImages": [
  {
    "status": false,
    "_id": "66acbd4a200457247bd59b03",
    "name":
"externallmg_1722596671115_WhatsApp_Image_20240730_at_54416_PM.jpeg",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596671115_WhatsApp_Image_20240730_at_54416_PM.jpeg",
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "66acbd4a200457247bd59b05",
    "name":
"externallmg_1722596672037_WhatsApp_Image_20240730_at_54417_PM.jpeg",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596672037_WhatsApp_Image_20240730_at_54417_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66acbd4a200457247bd59b03",
    "name":
"externallmg_1722596671115_WhatsApp_Image_20240730_at_54416_PM.jpeg",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596671115_WhatsApp_Image_20240730_at_54416_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66acbd4a200457247bd59b07",
    "name":
"externallmg_1722596680370_WhatsApp_Image_20240730_at_54418_PM.jpeg",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596680370_WhatsApp_Image_20240730_at_54418_PM.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
```

```
    "_id": "66acbd4a200457247bd59b04",
    "name": "Living Room",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596671517_WhatsApp_Image_20240730_at_54417_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66acbd4a200457247bd59b06",
    "name": "Living Room",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596678663_WhatsApp_Image_20240730_at_54418_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66acbd4a200457247bd59b07",
    "name": "Living Room",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596680370_WhatsApp_Image_20240730_at_54418_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66acbd4a200457247bd59b09",
    "name": "Living Room",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596680680_WhatsApp_Image_20240730_at_54419_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66acbd4a200457247bd59b0c",
    "name": "Living Room",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681334_WhatsApp_Image_20240730_at_54421_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66acbd4a200457247bd59b0b",
    "name": "Living Room",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681330_WhatsApp_Image_20240730_at_54420_PM.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "status": false,
  "_id": "66acbd4a200457247bd59b0d",
  "name": "Living Room",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681339_WhatsApp_Image_20240730_at_54421_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "66acbd4a200457247bd59b0f",
  "name": "Living Room",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681386_WhatsApp_Image_20240730_at_54422_PM.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "66acbd4a200457247bd59b10",
  "name": "Living Room",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681853_WhatsApp_Image_20240730_at_54423_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "66acbd4a200457247bd59b11",
  "name": "Living Room",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681875_WhatsApp_Image_20240730_at_54423_PM.jpeg",
  "orientation": "landscape"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "3843.00",
    "max": "6234.00"
  },
  "builtUpRateRange": {
    "min": "3494.00",
    "max": "5667.00"
  },
  "saleableRateRange": {
    "min": "2911.00",
    "max": "4723.00"
  }
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```



```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "337.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66acbcc375301f243894fdb3",
"ownerName": "Nitin Pawar Ozar ",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Flat No. 01, 1st Floor, Shree Ram, Near Shinde Lawns, Shivaji Nagar, Ojhar, NH3 Highway, Ozar Road, Village - Ozar, Nashik, 422207",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f8",
      "label": "Draft Agreement"
    }
  },
  "inputs": {
    "from": {
      "value": "Developers",
      "label": "Developers"
    }
  }
}
```

```
    },
    "Developers": " Kunal Devidas Jadhav",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Pawar"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "690203",
  "path": "cases/66acbcc375301f243894fdb3/document_1722596500491_1_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
  "fileName": "document_1722596500491_1_Building_Plan_Approval___NA_Order_f
or_plotted_development.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "10/02/2023",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "O.N.P./Nar/Work-174/2022-23"
},
  "isHardCopy": false,
  "displayStatus": false,
  "id": "914849",
  "path": "cases/66acbcc375301f243894fdb3/document_1722596518389_1_Commen
cement_Certificates___NA_Order_for_plotted_development.pdf",
  "fileName": "document_1722596518389_1_Commencement_Certificates___NA_Or
der_for_plotted_development.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "29/03/2023",
    "number": {
      "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "101"
},
"isHardCopy": false,
"displayStatus": false,
"id": "154175",
"path": "cases/66acbcc375301f243894fdb3/
document_1722596533075_P51600051163.pdf",
"fileName": "document_1722596533075_P51600051163.pdf"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "010323",
"createdBy": "63f9f4adce84bf289ba9956e",
"caseHistory": [
  {
    "id": "518553",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Aug 02 2024 16:32:27 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Nitin Pawar Ozar ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "250981"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "846870",
    "name": "Bedroom",
    "length": "13.00",
```

```
"length1": "13",
"length2": "00",
"width": "10.00",
"width1": "10",
"width2": "00",
"totalArea": "130.00",
"images": [],
"extraAreas": [],
"finalArea": "130.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "81.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "81.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "24.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.00"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "30.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Living Room",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "72.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "72.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "663.64",
      "squareMeterArea": "61.65",
```

```
    "expectedRate": "3842.44",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "730.00",
    "squareMeterArea": "67.82",
    "expectedRate": "3493.15",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "876.00",
    "squareMeterArea": "81.38",
    "expectedRate": "2910.96",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "66acc6b7200457247bd5a532",
  "property": "Flat",
  "area": "730",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "2550000",
  "expectedRate": "3842.44",
  "builtUpExpectedRate": "2550000",
  "image": "cases/66acb375301f243894fdb3/
indicator_1722598927116_Image.png",
  "squareMeter": "67.82",
  "id": "464625"
},
{
  "carpetArea": {
    "area": "1090.91",
    "squareMeterArea": "101.35",
    "expectedRate": "6233.33",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1200.00",
    "squareMeterArea": "111.48",
    "expectedRate": "5666.67",
    "percentage": "10"
  },
}
```

```
"saleableArea": {
  "area": "1440.00",
  "squareMeterArea": "133.78",
  "expectedRate": "4722.22",
  "percentage": "20"
},
"printlnReport": true,
"_id": "66acc6b7200457247bd5a533",
"property": "Flat",
"area": "1200",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Makaan.com",
"expectedPrice": "6800000",
"expectedRate": "6233.33",
"builtUpExpectedRate": "6800000",
"image": "cases/66acb375301f243894fdb3/
indicator_1722599095281_Image.png",
"squareMeter": "111.48",
"id": "554960"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66acbd4a200457247bd59b03",
    "name":
"externalImg_1722596671115_WhatsApp_Image_20240730_at_54416_PM.jpeg",
    "path": "cases/66acb375301f243894fdb3/
externalImg_1722596671115_WhatsApp_Image_20240730_at_54416_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66acbd4a200457247bd59b04",
    "name":
"externalImg_1722596671517_WhatsApp_Image_20240730_at_54417_PM_1.jpeg",
    "path": "cases/66acb375301f243894fdb3/
externalImg_1722596671517_WhatsApp_Image_20240730_at_54417_PM_1.jpeg",
    "orientation": "portrait"
  },
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66acbd4a200457247bd59b05",
  "name":
"externallmg_1722596672037_WhatsApp_Image_20240730_at_54417_PM.jpeg",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596672037_WhatsApp_Image_20240730_at_54417_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66acbd4a200457247bd59b06",
  "name":
"externallmg_1722596678663_WhatsApp_Image_20240730_at_54418_PM_1.jpeg",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596678663_WhatsApp_Image_20240730_at_54418_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66acbd4a200457247bd59b07",
  "name":
"externallmg_1722596680370_WhatsApp_Image_20240730_at_54418_PM.jpeg",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596680370_WhatsApp_Image_20240730_at_54418_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66acbd4a200457247bd59b08",
  "name":
"externallmg_1722596680559_WhatsApp_Image_20240730_at_54419_PM_1.jpeg",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596680559_WhatsApp_Image_20240730_at_54419_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66acbd4a200457247bd59b09",
  "name":
"externallmg_1722596680680_WhatsApp_Image_20240730_at_54419_PM.jpeg",
```



```
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596680680_WhatsApp_Image_20240730_at_54419_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66acbd4a200457247bd59b0a",
    "name":
"externallmg_1722596681205_WhatsApp_Image_20240730_at_54420_PM_1.jpeg",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681205_WhatsApp_Image_20240730_at_54420_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66acbd4a200457247bd59b0b",
    "name":
"externallmg_1722596681330_WhatsApp_Image_20240730_at_54420_PM.jpeg",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681330_WhatsApp_Image_20240730_at_54420_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66acbd4a200457247bd59b0c",
    "name":
"externallmg_1722596681334_WhatsApp_Image_20240730_at_54421_PM_1.jpeg",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681334_WhatsApp_Image_20240730_at_54421_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66acbd4a200457247bd59b0d",
    "name":
"externallmg_1722596681339_WhatsApp_Image_20240730_at_54421_PM_2.jpeg",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681339_WhatsApp_Image_20240730_at_54421_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66acbd4a200457247bd59b0e",
  "name":
"externallmg_1722596681343_WhatsApp_Image_20240730_at_54421_PM.jpeg",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681343_WhatsApp_Image_20240730_at_54421_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66acbd4a200457247bd59b0f",
  "name":
"externallmg_1722596681386_WhatsApp_Image_20240730_at_54422_PM.jpeg",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681386_WhatsApp_Image_20240730_at_54422_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66acbd4a200457247bd59b10",
  "name":
"externallmg_1722596681853_WhatsApp_Image_20240730_at_54423_PM_1.jpeg",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681853_WhatsApp_Image_20240730_at_54423_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66acbd4a200457247bd59b11",
  "name":
"externallmg_1722596681875_WhatsApp_Image_20240730_at_54423_PM.jpeg",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681875_WhatsApp_Image_20240730_at_54423_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66acbd4a200457247bd59b12",
  "name":
"externallmg_1722596681883_WhatsApp_Image_20240730_at_54424_PM.jpeg",
  "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681883_WhatsApp_Image_20240730_at_54424_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66acbd4a200457247bd59b13",
    "name":
"externallmg_1722596681885_WhatsApp_Image_20240730_at_54425_PM.jpeg",
    "path": "cases/66acbcc375301f243894fdb3/
externallmg_1722596681885_WhatsApp_Image_20240730_at_54425_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-02T11:02:27.257Z",
"updatedAt": "2024-08-02T12:47:28.134Z",
"__v": 0,
"updatedBy": "63f9f4adce84bf289ba9956e",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Nitin Pawar Ozar 123",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Toilet + Bathroom",
"carpetTotal": "337.00",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "370.70",
"finalCarpetArea": "337.00",
"finalSalableArea": "444.84",
"salablePercentage": "20",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
```

```

"finalAsPerArea": "actual site measurement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 337.00",
"buildingServicesRate": "2000",
"flatRate": "4000",
"landOtherRate": "2000",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Bedroom	13'00"	10'00"	130.00
Kitchen	9'00"	9'00"	81.00
Toilet	4'00"	6'00"	24.00
Bathroom	6'00"	5'00"	30.00
Living Room	8'00"	9'00"	72.00
Other Composition :			