

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "r. Mohanty",
    "type": "CREDITOFFICER",
    "_id": "646dc536b05e530fb6c47b3d",
    "lastName": " Sir",
    "mobileNo": "",
    "workMobileNo": "8411020137",
    "email": "rlf.nasik@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2500",
    "discussWithPerson": "r. Mohanty",
    "expectedFees": 1.25,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "643a91f233d16f6b1237a4ee",
```

```
"role": "SITEENGINEER",
"firstName": "Pankaj",
"email": "pankajpachore510@gmail.com",
"lastName": "Pachore",
"mobileNo": "7709956078",
"shortName": "PA",
"workWithDocumentMaker": "",
"profilePhoto": "users/643a91f233d16f6b1237a4ee/
profilePhoto_1717744018409_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
```

```
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "20.086780285104755",
  "longitude": "73.91688665930259"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.91688665930259,
    20.086780285104755
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "9/08/2024 10:53 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Ozar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "2",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Niphad",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": " Kalpataru Baug – Phase-2",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": " Shivaji Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opposite Dynamic Health Club",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```



```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "605",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```

```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "2658/1/1",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422006",
  "label": false
},
"suburb": {
```

```
"status": false,
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
```

```
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```



```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
```

```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66b080fd4f2f48da09c9c3ac",
"ownerName": "Anant Kshirsagar",
"ownerPhoneNo": "9764560215",
"appAddress": "flat no. 605 6th floor building no.2 kalptaru bug phase 2 ozar nashik",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66b080fd4f2f48da09c9c3ac/
document_1722843292272_1722843290434_New_Doc_08052024_1158.pdf",
    "fileName":
"document_1722843292272_1722843290434_New_Doc_08052024_1158.pdf",
    "id": "759801",
    "uploadedBy": "643a91f233d16f6b1237a4ee",
    "createdAt": "Mon Aug 05 2024 13:06:29 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010369",
"createdBy": "643a91f233d16f6b1237a4ee",
"caseHistory": [
  {
    "id": "317863",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Aug 05 2024 13:06:29 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Anant Kshirsagar",
    "phone": "9764560215",
    "ownershipShare": "",
    "email": "",
    "id": "731476"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b5a7fac884d1123345379d",
    "name":
"externalImg_1723181049578_WhatsApp_Image_20240808_at_111226_1.jpeg",
    "path": "cases/66b080fd4f2f48da09c9c3ac/
externalImg_1723181049578_WhatsApp_Image_20240808_at_111226_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b5a7fac884d1123345379e",
    "name":
"externalImg_1723181049728_WhatsApp_Image_20240808_at_111226.jpeg",
    "path": "cases/66b080fd4f2f48da09c9c3ac/
externalImg_1723181049728_WhatsApp_Image_20240808_at_111226.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b5a7fac884d1123345379f",
    "name":
"externalImg_1723181049801_WhatsApp_Image_20240808_at_111227_1.jpeg",
```

```
    "path": "cases/66b080fd4f2f48da09c9c3ac/
externallmg_1723181049801_WhatsApp_Image_20240808_at_111227_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b5a7fac884d112334537a0",
    "name":
"externallmg_1723181049824_WhatsApp_Image_20240808_at_111227.jpeg",
    "path": "cases/66b080fd4f2f48da09c9c3ac/
externallmg_1723181049824_WhatsApp_Image_20240808_at_111227.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b5a7fac884d112334537a1",
    "name":
"externallmg_1723181049844_WhatsApp_Image_20240808_at_111228.jpeg",
    "path": "cases/66b080fd4f2f48da09c9c3ac/
externallmg_1723181049844_WhatsApp_Image_20240808_at_111228.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b5a7fac884d112334537a2",
    "name":
"externallmg_1723181049868_WhatsApp_Image_20240808_at_111229_1.jpeg",
    "path": "cases/66b080fd4f2f48da09c9c3ac/
externallmg_1723181049868_WhatsApp_Image_20240808_at_111229_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b5a7fac884d112334537a3",
    "name":
"externallmg_1723181049893_WhatsApp_Image_20240808_at_111229.jpeg",
    "path": "cases/66b080fd4f2f48da09c9c3ac/
externallmg_1723181049893_WhatsApp_Image_20240808_at_111229.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66b5a7fac884d112334537a4",
  "name":
"externalImg_1723181049921_WhatsApp_Image_20240808_at_111230.jpeg",
  "path": "cases/66b080fd4f2f48da09c9c3ac/
externalImg_1723181049921_WhatsApp_Image_20240808_at_111230.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b5a7fac884d112334537a5",
  "name":
"externalImg_1723181049942_WhatsApp_Image_20240808_at_111240.jpeg",
  "path": "cases/66b080fd4f2f48da09c9c3ac/
externalImg_1723181049942_WhatsApp_Image_20240808_at_111240.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-05T07:36:29.432Z",
"updatedAt": "2024-08-09T05:24:10.048Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 605, 6th Floor, Building No 2, Wing - B, Kalpataru
Baug – Phase-2, Opposite Dynamic Health Club, Shivaji Nagar, Village - Ozar, Gut
No. 2658/1/1, Taluka - Niphad, District - Nashik, Nashik, 422006",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "63f9f4adce84bf289ba9956e",
"contactPersonName": "Anant Kshirsagar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9764560215"
```

}

**Name**

**Length**

**Width**

**Total**

---

Composition :

---

Other

Composition :

---