

```
{
  "typeOfReport": {
    "label": "Lenders_Engineers Report (LIE)",
    "value": "Lenders_Engineers_Report_(LIE)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7d8"
    },
    "firstName": "Rohit",
    "type": "CREDITOFFICER",
    "_id": "665ac40aa424b37b20c06fd4",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7386894585",
    "email": "sbi.04732@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "450000000",
    "discussWithPerson": "Rohit",
    "expectedFees": 225000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7d8",
  "branchCode": "000031",
  "type": "BRANCH",
  "name": "Industrial Finance Branch, Andheri (East)",
  "email": "varsha.bhat@sbi.co.in",
  "mobileNo": "022-26819792",
  "alternateMobileNo": "022-26822158",
  "address": "102, Natraj Building, 194, Sir M. V. Road, W. E. Highway-Metro Junction,
Andheri (East), Mumbai - 400 069, State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - IFB ANDHERI(E)",
  "fax": "022-26831648",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
```

```
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "15.58272657913761",
  "longitude": "73.75267824264522"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.75267824264522,
```

```
15.58272657913761
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "7/08/2024 04:19 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Anjuna",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Goa",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": false,
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Bardez",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "403507",
  "label": false
}
```

```
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "North Goa",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
```

```
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66b340a5c884d1123343aa62",
"ownerName": "MYRAYASH HOTELS PRIVATE LIMITED ",
"ownerPhoneNo": "9833800026",
"appAddress": "village - Anjuna, Bardze, North goa, city - Goa, State - Goa ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66b340a5c884d1123343aa62/
document_1723023501508_627550.pdf",
    "fileName": "document_1723023501508_627550.pdf",
    "id": "252562",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Aug 07 2024 15:08:45 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010433",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "544857",
    "title": "Create Lead",
    "description": "Create Lead",
```

```
    "datetime": "Wed Aug 07 2024 15:08:45 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "MYRAYASH HOTELS PRIVATE LIMITED ",
    "phone": "9833800026",
    "ownershipShare": "",
    "email": "",
    "id": "123082"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472929",
    "name":
"externallmg_1723443471436_20240812_104503AMByGPSMapCamera.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_1723443471436_20240812_104503AMByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d1123347292a",
    "name":
"externallmg_1723443472284_20240812_104507AMByGPSMapCamera.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_1723443472284_20240812_104507AMByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d1123347292b",
    "name":
"externallmg_1723443472612_20240812_104535AMByGPSMapCamera.jpg",
```

```
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_1723443472612_20240812_104535AMByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d1123347292c",
    "name":
"externallmg_1723443472788_20240812_104825AMByGPSMapCamera.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_1723443472788_20240812_104825AMByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d1123347292d",
    "name":
"externallmg_1723443472991_20240812_104826AMByGPSMapCamera.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_1723443472991_20240812_104826AMByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d1123347292e",
    "name": "externallmg_r_1723443474482_IMG_20240812_103729.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443474482_IMG_20240812_103729.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d1123347292f",
    "name": "externallmg_r_1723443476432_IMG_20240812_103731.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443476432_IMG_20240812_103731.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472930",
```

```
    "name": "externalimg_r_1723443475449_IMG_20240812_103730.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443475449_IMG_20240812_103730.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472931",
    "name": "externalimg_r_1723443473168_IMG_20240812_103727.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443473168_IMG_20240812_103727.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472932",
    "name": "externalimg_r_1723443477323_IMG_20240812_103739.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443477323_IMG_20240812_103739.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472933",
    "name": "externalimg_r_1723443478167_IMG_20240812_103747.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443478167_IMG_20240812_103747.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472934",
    "name": "externalimg_r_1723443479263_IMG_20240812_103815.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443479263_IMG_20240812_103815.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472935",
    "name": "externalimg_r_1723443480256_IMG_20240812_103833.jpg",
```

```
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443480256_IMG_20240812_103833.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472936",
    "name": "externallmg_r_1723443483837_IMG_20240812_103849.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443483837_IMG_20240812_103849.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472937",
    "name": "externallmg_r_1723443481926_IMG_20240812_103840.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443481926_IMG_20240812_103840.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472938",
    "name": "externallmg_r_1723443483024_IMG_20240812_103841.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443483024_IMG_20240812_103841.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d11233472939",
    "name": "externallmg_r_1723443484851_IMG_20240812_103911.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443484851_IMG_20240812_103911.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a921c884d1123347293a",
    "name": "externallmg_r_1723443486926_IMG_20240812_103933.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443486926_IMG_20240812_103933.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a921c884d1123347293b",
  "name": "externallmg_r_1723443486059_IMG_20240812_103912.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443486059_IMG_20240812_103912.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a921c884d1123347293c",
  "name": "externallmg_r_1723443487799_IMG_20240812_103934.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443487799_IMG_20240812_103934.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a954da840b1214c581ab",
  "name": "externallmg_r_1723443522615_IMG_20240812_104115.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443522615_IMG_20240812_104115.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a954da840b1214c581ac",
  "name": "externallmg_r_1723443523717_IMG_20240812_104117.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443523717_IMG_20240812_104117.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a954da840b1214c581ad",
  "name": "externallmg_r_1723443520749_IMG_20240812_104005.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443520749_IMG_20240812_104005.jpg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66b9a954da840b1214c581ae",
      "name": "externallmg_r_1723443521620_IMG_20240812_104114.jpg",
      "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443521620_IMG_20240812_104114.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66b9a954da840b1214c581af",
      "name": "externallmg_r_1723443524668_IMG_20240812_104119.jpg",
      "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443524668_IMG_20240812_104119.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66b9a954da840b1214c581b0",
      "name": "externallmg_r_1723443526558_IMG_20240812_104128.jpg",
      "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443526558_IMG_20240812_104128.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66b9a954da840b1214c581b1",
      "name": "externallmg_r_1723443527464_IMG_20240812_104138.jpg",
      "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443527464_IMG_20240812_104138.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66b9a954da840b1214c581b2",
      "name": "externallmg_r_1723443525472_IMG_20240812_104125.jpg",
      "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443525472_IMG_20240812_104125.jpg",
      "orientation": "landscape"
    },
  ],
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a954da840b1214c581b3",
  "name": "externallmg_r_1723443530039_IMG_20240812_104305.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443530039_IMG_20240812_104305.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a954da840b1214c581b4",
  "name": "externallmg_r_1723443528272_IMG_20240812_104302.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443528272_IMG_20240812_104302.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a954da840b1214c581b5",
  "name": "externallmg_r_1723443529138_IMG_20240812_104303.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443529138_IMG_20240812_104303.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a954da840b1214c581b6",
  "name": "externallmg_r_1723443530686_IMG_20240812_104307.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443530686_IMG_20240812_104307.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a954da840b1214c581b7",
  "name": "externallmg_r_1723443531733_IMG_20240812_104308.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443531733_IMG_20240812_104308.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a954da840b1214c581b8",
    "name": "externallmg_r_1723443533648_IMG_20240812_104416.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443533648_IMG_20240812_104416.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a954da840b1214c581b9",
    "name": "externallmg_r_1723443532804_IMG_20240812_104414.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443532804_IMG_20240812_104414.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a954da840b1214c581ba",
    "name": "externallmg_r_1723443534625_IMG_20240812_104420.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443534625_IMG_20240812_104420.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a954da840b1214c581bb",
    "name": "externallmg_r_1723443535461_IMG_20240812_104421.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443535461_IMG_20240812_104421.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a954da840b1214c581bc",
    "name": "externallmg_r_1723443536385_IMG_20240812_105119.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443536385_IMG_20240812_105119.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66b9a954da840b1214c581bd",
  "name": "externalimg_r_1723443537588_IMG_20240812_105120.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443537588_IMG_20240812_105120.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a954da840b1214c581be",
  "name": "externalimg_r_1723443538516_IMG_20240812_105138.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443538516_IMG_20240812_105138.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a98ec884d11233472a51",
  "name": "externalimg_r_1723443583266_IMG_20240812_105215__01.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443583266_IMG_20240812_105215__01.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a98ec884d11233472a52",
  "name": "externalimg_r_1723443581313_IMG_20240812_105157.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443581313_IMG_20240812_105157.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a98ec884d11233472a53",
  "name": "externalimg_r_1723443582326_IMG_20240812_105215.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443582326_IMG_20240812_105215.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66b9a98ec884d11233472a54",
    "name": "externalimg_r_1723443580701_IMG_20240812_105138__01.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443580701_IMG_20240812_105138__01.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a55",
    "name": "externalimg_r_1723443584145_IMG_20240812_105233.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443584145_IMG_20240812_105233.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a56",
    "name": "externalimg_r_1723443586119_IMG_20240812_105241.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443586119_IMG_20240812_105241.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a57",
    "name": "externalimg_r_1723443585350_IMG_20240812_105236.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443585350_IMG_20240812_105236.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a58",
    "name": "externalimg_r_1723443584750_IMG_20240812_105235.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443584750_IMG_20240812_105235.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a59",
```

```
    "name": "externalimg_r_1723443590546_IMG_20240812_105317.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443590546_IMG_20240812_105317.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a5a",
    "name": "externalimg_r_1723443588374_IMG_20240812_105315.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443588374_IMG_20240812_105315.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a5b",
    "name": "externalimg_r_1723443587240_IMG_20240812_105257.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443587240_IMG_20240812_105257.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a5c",
    "name": "externalimg_r_1723443589494_IMG_20240812_105316.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443589494_IMG_20240812_105316.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a5d",
    "name": "externalimg_r_1723443591366_IMG_20240812_105319.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443591366_IMG_20240812_105319.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a5e",
    "name": "externalimg_r_1723443593666_IMG_20240812_105411.jpg",
```

```
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443593666_IMG_20240812_105411.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a5f",
    "name": "externallmg_r_1723443592269_IMG_20240812_105339.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443592269_IMG_20240812_105339.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a60",
    "name": "externallmg_r_1723443594467_IMG_20240812_105412.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443594467_IMG_20240812_105412.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a61",
    "name": "externallmg_r_1723443595127_IMG_20240812_105421.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443595127_IMG_20240812_105421.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a62",
    "name": "externallmg_r_1723443595716_IMG_20240812_105423.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443595716_IMG_20240812_105423.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a98ec884d11233472a63",
    "name": "externallmg_r_1723443596524_IMG_20240812_105424.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443596524_IMG_20240812_105424.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a98ec884d11233472a64",
  "name": "externallmg_r_1723443597298_IMG_20240812_105428.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443597298_IMG_20240812_105428.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c47",
  "name": "externallmg_r_1723443652219_IMG_20240812_105448.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443652219_IMG_20240812_105448.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c48",
  "name": "externallmg_r_1723443649718_IMG_20240812_105438.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443649718_IMG_20240812_105438.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c49",
  "name": "externallmg_r_1723443650862_IMG_20240812_105440.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443650862_IMG_20240812_105440.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c4a",
  "name": "externallmg_r_1723443648715_IMG_20240812_105437.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443648715_IMG_20240812_105437.jpg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c4b",
  "name": "externallmg_r_1723443654024_IMG_20240812_105451.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443654024_IMG_20240812_105451.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c4c",
  "name": "externallmg_r_1723443652963_IMG_20240812_105449.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443652963_IMG_20240812_105449.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c4d",
  "name": "externallmg_r_1723443656838_IMG_20240812_105508.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443656838_IMG_20240812_105508.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c4e",
  "name": "externallmg_r_1723443655286_IMG_20240812_105507.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443655286_IMG_20240812_105507.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c4f",
  "name": "externallmg_r_1723443657909_IMG_20240812_105510.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443657909_IMG_20240812_105510.jpg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c50",
  "name": "externallmg_r_1723443658630_IMG_20240812_105511.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443658630_IMG_20240812_105511.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c51",
  "name": "externallmg_r_1723443659280_IMG_20240812_105525.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443659280_IMG_20240812_105525.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c52",
  "name": "externallmg_r_1723443659958_IMG_20240812_105544.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443659958_IMG_20240812_105544.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c53",
  "name": "externallmg_r_1723443661396_IMG_20240812_105547.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443661396_IMG_20240812_105547.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9a9d34388d81213f60c54",
  "name": "externallmg_r_1723443660632_IMG_20240812_105545.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443660632_IMG_20240812_105545.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a9d34388d81213f60c55",
    "name": "externallmg_r_1723443663098_IMG_20240812_105550.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443663098_IMG_20240812_105550.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a9d34388d81213f60c56",
    "name": "externallmg_r_1723443662227_IMG_20240812_105548.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443662227_IMG_20240812_105548.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a9d34388d81213f60c57",
    "name": "externallmg_r_1723443664411_IMG_20240812_105556.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443664411_IMG_20240812_105556.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a9d34388d81213f60c58",
    "name": "externallmg_r_1723443663646_IMG_20240812_105554.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443663646_IMG_20240812_105554.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9a9d34388d81213f60c59",
    "name": "externallmg_r_1723443665576_IMG_20240812_105608.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externallmg_r_1723443665576_IMG_20240812_105608.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66b9a9d34388d81213f60c5a",
    "name": "externalimg_r_1723443664882_IMG_20240812_105607.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443664882_IMG_20240812_105607.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f23",
    "name": "externalimg_1723443912859_IMG_20240812_111912.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_1723443912859_IMG_20240812_111912.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f24",
    "name": "externalimg_1723443913832_IMG_20240812_111916.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_1723443913832_IMG_20240812_111916.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f25",
    "name": "externalimg_1723443914202_IMG_20240812_111917.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_1723443914202_IMG_20240812_111917.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f26",
    "name": "externalimg_r_1723443876349_IMG_20240812_105609.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443876349_IMG_20240812_105609.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
  "_id": "66b9aacb4388d81213f60f27",
  "name": "externalimg_r_1723443878026_IMG_20240812_105612.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443878026_IMG_20240812_105612.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9aacb4388d81213f60f28",
  "name": "externalimg_r_1723443876921_IMG_20240812_105610.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443876921_IMG_20240812_105610.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9aacb4388d81213f60f29",
  "name": "externalimg_r_1723443878943_IMG_20240812_105648.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443878943_IMG_20240812_105648.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9aacb4388d81213f60f2a",
  "name": "externalimg_r_1723443881397_IMG_20240812_105757.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443881397_IMG_20240812_105757.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9aacb4388d81213f60f2b",
  "name": "externalimg_r_1723443879762_IMG_20240812_105648__01.jpg",
  "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443879762_IMG_20240812_105648__01.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b9aacb4388d81213f60f2c",
```

```
    "name": "externalimg_r_1723443880673_IMG_20240812_105651.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443880673_IMG_20240812_105651.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f2d",
    "name": "externalimg_r_1723443896944_IMG_20240812_105757__01.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443896944_IMG_20240812_105757__01.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f2e",
    "name": "externalimg_r_1723443906429_IMG_20240812_105807__01.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443906429_IMG_20240812_105807__01.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f2f",
    "name": "externalimg_r_1723443905343_IMG_20240812_105807.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443905343_IMG_20240812_105807.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f30",
    "name": "externalimg_r_1723443907806_IMG_20240812_105825.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalimg_r_1723443907806_IMG_20240812_105825.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f31",
    "name": "externalimg_r_1723443909165_IMG_20240812_105826.jpg",
```

```
    "path": "cases/66b340a5c884d1123343aa62/
externalImg_r_1723443909165_IMG_20240812_105826.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f32",
    "name": "externalImg_r_1723443909886_IMG_20240812_105827.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalImg_r_1723443909886_IMG_20240812_105827.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f33",
    "name": "externalImg_r_1723443910772_IMG_20240812_105829.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalImg_r_1723443910772_IMG_20240812_105829.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b9aacb4388d81213f60f34",
    "name": "externalImg_r_1723443911867_IMG_20240812_105838.jpg",
    "path": "cases/66b340a5c884d1123343aa62/
externalImg_r_1723443911867_IMG_20240812_105838.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-07T09:38:45.124Z",
"updatedAt": "2024-08-12T06:25:15.431Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Lenders_Engineers Report (LIE) No. Ground Floor, Bardez,
Village - Anjuna, North Goa, Goa, 403507, State - Goa",
```

"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "MYRAYASH HOTELS PRIVATE LIMITED ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833800026"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			