

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb48"
    },
    "firstName": "Abhishek Anil",
    "type": "CREDITOFFICER",
    "_id": "66ab49cd200457247bd529a7",
    "email": "arb.msm@unionbankofindia.com",
    "lastName": "Taralkar",
    "mobileNo": "",
    "workMobileNo": "8897815935"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
  }
}
```

```
"discussWithPerson": "Abhishek Anil",
"expectedFees": null,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb48",
  "branchCode": "000042",
  "type": "BRANCH",
  "name": "ARB Mumbai Samachar Marg Branch",
  "email": "ubin0553352@unionbankofindia.bank",
  "mobileNo": "02222629454",
  "alternateMobileNo": "",
  "address": "Vinayak Chember ,1st Floor, 66/80 Mumbai Samachar Marg, Dalal
Street,Fort, Mumbai - 400 023, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
```

```
"zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62550ed0aba01e0af98f2f75",
    "role": "SITEENGINEER",
    "firstName": "Chandan",
    "email": "ck06806@gmail.com",
    "lastName": "Singh",
    "mobileNo": "8454863607",
    "designation": "",
    "shortName": "CH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "ACCOUNTANT",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
```

```
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "ACCOUNTANT",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
```

```
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.009909503930132",
  "longitude": "72.82124506677056"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82124506677056,
    19.009909503930132
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-16",
      "remark": "internal visit not allowed"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-06",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"schedule": []
},
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Lower Parel Division ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "10",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
```

```
"name": "District",
"key": "district",
"value": "Mumbai",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "RNA Mirage Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sudam Kalu Ahire Marg, Worli",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
```



```
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1629(Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1001",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "G/S",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 025",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"flooring": {
  "value": "External_site_visit_only",
  "label": "External site visit only"
},
"doors": {
  "value": "External_site_visit_only",
  "label": "External site visit only"
},
"windows": {
  "value": "External_site_visit_only",
  "label": "External site visit only"
},
"fittings": {
  "value": "External_site_visit_only",
  "label": "External site visit only"
},
"finishing": {
  "value": "External_site_visit_only",
  "label": "External site visit only"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot ",
```

```

"west": "Sudam Kalu Ahire Marg",
"south": "Open Plot ",
"east": "Gurukrupa Apartment "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Internal visit not allowed ",
    "east": "Internal visit not allowed ",
    "south": "Internal visit not allowed ",
    "west": "Internal visit not allowed "
  },
  "asPerDocument": {
    "north": "Marginal Space ",
    "east": "Marginal Space ",
    "south": "Marginal Space ",
    "west": "Lift & Lobby"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},

```

"extraDetailOfProperty": "As per Agreement Sale Plan, the composition of flat is 3 Bedrooms + Living Room + Dining + Kitchen + Passage + 2 Toilets + Flower Bed Area. At the time of site visit, building external renovation work is in progress. As per request from Union Bank of India, ARB Mumbai Samachar Marg Branch, our engineer visited the property but internal visit was not allowed hence our report is based on external visit & documents provided by bank to us.",

```

    "dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan",
    "approvePlanVerified": "N.A.",
    "empanelledOfApprovePlan": "N.A.",
    "unauthorizedConstruction": "",
    "extraDetailOfBuilding": "",
    "compoundWall": ""
  },
  "landAndBuildingDetails": {
    "actualBuildingBoundaries": [],
    "documentsBuildingBoundaries": []
  },
  "compositeRate": {
    "remark": "i) At the time of site visit, building external renovation work is in
progress.<br />ii) As per request from Union Bank of India, ARB Mumbai Samachar
Marg Branch, our engineer visited the property but internal visit was not allowed hence
the report is based on external visit & documents provided by bank to us. ",
    "depreciationPercentage": "19.5",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "10",
    "depreciatedCostOfConstruction": "50015",
    "depreciatedBuildingRate": "2415"
  },
  "igrRate": {
    "propertyName": "Residential Flat",
    "rate": "459010",
    "landRate": "194470",
    "igrImage": "cases/66b34e9b4388d81213f376d1/igr_1723878377289_Image.png",
    "squareMeterGuideLineRate": "481961.00",
    "squareFeetGuideLineRate": "44776.00"
  },
  "igrFinalRate": {
    "floorRatePercentage": "5",
    "depreciationPercentage": "87",
    "rate": "41304.00",
    "squareFeetGuideLineRate": "41304.00",
    "squareMeterGuideLineRate": "444587.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Medium",
      "label": "Medium"
    }
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }

```

```
},
"propertyOccupiedByList": {
  "value": "External_Site_Visit_Only",
  "label": "External Site Visit Only"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per MCGM norms ",
"tenantName": "",
"maintenanceOfFlat": "External visit done only "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open / Covered Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
},
```

```
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2011",
  "fullDate": "1/1/2011"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
```

```
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "47",
"ageOfBuilding": "13",
"noOfBasement": "1",
"noOfPodium": "4",
"noOfAmenityFloors": "",
"noOfFloors": "40",
"flatFloorNo": "10",
"noOfLifts": "3",
```



```
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "1579.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66b34e9b4388d81213f376d1/
routeMap_1723886789047_Image.png",
    "routeLat": "19.009668",
    "routeLng": "72.821274",
    "stationName": "Prabhadevi ",
    "routeDistance": "2.2 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "iuhr32",
      "name": "iuhr32",
      "image": "cases/66b34e9b4388d81213f376d1/
routeMap_1723886842732_Image.png"
    }
  ],
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": ""
    }
  }
}
```

```
"totalFairMarketValue": ""
},
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "65819740.00",
"distressValuePercentage": "70",
"realizableValuePercentage": "85",
"bookValue": "0",
"finalValue": "65819740.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Aug 17 2024 15:40:47 GMT+0530 (India Standard Time)",
  "number": "2307738",
  "dayCount": "10",
  "monthCount": "216",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "65227277.00",
  "selectedBuildUpValue": "1579.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66bed7ba0f117327db707c44",
      "name": "externalimg_1723783094200_1723783089454_image_1.jpeg",
      "path": "cases/66b34e9b4388d81213f376d1/
externalimg_1723783094200_1723783089454_image_1.jpeg",
      "orientation": "portrait"
    }
  ]
},
],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "66bed7ba0f117327db707c44",
    "name": "externallmg_1723783094200_1723783089454_image_1.jpeg",
    "path": "cases/66b34e9b4388d81213f376d1/
externallmg_1723783094200_1723783089454_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bed7ba0f117327db707c43",
    "name": "externallmg_1723783093015_1723783089454_image_0.jpeg",
    "path": "cases/66b34e9b4388d81213f376d1/
externallmg_1723783093015_1723783089454_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bed7ba0f117327db707c45",
    "name": "externallmg_1723783095295_1723783089454_image_2.jpeg",
    "path": "cases/66b34e9b4388d81213f376d1/
externallmg_1723783095295_1723783089454_image_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "49340.00",
    "max": "66667.00"
  },
  "builtUpRateRange": {
    "min": "41117.00",
    "max": "55556.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
```

```
"presentValueOfFlat": {
  "title": "Present value of the flat (incl. car parking, if provided)",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
```



```
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "1316.00",
"empanelmentNo": [
  "RO(S):ADV:VAL:012:2018-19"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66b34e9b4388d81213f376d1",
"ownerName": "Mrs. Kanaka L. Poddaar ",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no 1001,10Floor,RNA Mirage Plot 1629, S K Ahire Marg, Off Dr
Annie Basant Road Worli ",
"remark": "internal visit not allowed",
"documents": [
  {
    "documentType": {
      "value": "60ae124faa6d152c1801b30f",
      "label": "Article of Agreement"
    },
    "inputs": {
      "documentDate": "29/05/2015",
      "from": {
        "value": "Developers",
        "label": "Developers"
      }
    }
  }
]
```

```
    },
    "Developers": "M/s. Chamber Constructions Pvt. Ltd. ",
    "to": {
      "value": "Purchasers",
      "label": "Purchasers"
    },
    "Purchasers": "Mrs. Kanaka L. Poddaar "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "434506",
  "path": "cases/66b34e9b4388d81213f376d1/document_1723027062216_1723027059705_Kanaka_PoddaarFlat_no_1001_UBI_ARB_Fort.pdf",
  "fileName": "document_1723027062216_1723027059705_Kanaka_PoddaarFlat_no_1001_UBI_ARB_Fort.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "17/02/2011",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "EB / 9611 / GS / A"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723885747182_440875.pdf",
  "path": "cases/66b34e9b4388d81213f376d1/document_1723885747182_440875.pdf",
  "id": "284382",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Sat Aug 17 2024 14:39:07 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  }
}
```

```
    },
    "inputs": {
      "documentDate": "13/02/2007",
      "nameOfApprovingAuthority": {
        "value": "Municipal_Corporation_of_Greater_Mumbai",
        "label": "Municipal Corporation of Greater Mumbai"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "EB / 9611 / GS / A"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1723885822668_Agreement.pdf",
    "path": "cases/66b34e9b4388d81213f376d1/
document_1723885822668_Agreement.pdf",
    "id": "906416",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Sat Aug 17 2024 14:40:22 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010444",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "226520",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Aug 07 2024 16:08:19 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Kanaka L. Poddaar ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "883798"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
```

```
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae124faa6d152c1801b30f",
      "label": "Article of Agreement"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "190980",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "1316",
    "squareMeterArea": "122.26",
    "docFinalBuiltUp": "1579.2",
    "docFinalBuiltUpSquareMeter": "146.71200000000002",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "2125.83",
      "squareMeterArea": "197.50",
      "expectedRate": "55507.73",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "2551.00",
      "squareMeterArea": "237.00",
      "expectedRate": "46256.37",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "0.00",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printInReport": true,
  "_id": "66c04bf1da840b1214c86c0f",
```

```
"property": "Residential Flat",
"area": "2551",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "118000000",
"expectedRate": "55507.73",
"builtUpExpectedRate": "118000000",
"image": "cases/66b34e9b4388d81213f376d1/
indicator_1723878190686_Image.png",
"squareMeter": "237.00",
"id": "488005"
},
{
"carpetArea": {
"area": "1662.00",
"squareMeterArea": "154.41",
"expectedRate": "49339.35",
"percentage": ""
},
"builtUpArea": {
"area": "1994.40",
"squareMeterArea": "185.29",
"expectedRate": "41116.13",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66c04bf1da840b1214c86c10",
"property": "Residential Flat",
"area": "1662",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "82002000",
```

```
"expectedRate": "49339.35",
"builtUpExpectedRate": "41116.13",
"image": "cases/66b34e9b4388d81213f376d1/
indicator_1723878223580_Image.png",
"squareMeter": "154.41",
"id": "373135"
},
{
"carpetArea": {
"area": "1662.00",
"squareMeterArea": "154.41",
"expectedRate": "49939.83",
"percentage": ""
},
"builtUpArea": {
"area": "1994.40",
"squareMeterArea": "185.29",
"expectedRate": "41616.53",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66c04bf1da840b1214c86c11",
"property": "Residential Flat",
"area": "1662",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "83000000",
"expectedRate": "49939.83",
"builtUpExpectedRate": "41616.53",
"image": "cases/66b34e9b4388d81213f376d1/
indicator_1723878246915_Image.png",
"squareMeter": "154.41",
"id": "965604"
},
{
"carpetArea": {
```

```
"area": "1800.00",
"squareMeterArea": "167.23",
"expectedRate": "52777.78",
"percentage": ""
},
"builtUpArea": {
"area": "2160.00",
"squareMeterArea": "200.67",
"expectedRate": "43981.48",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66c04bf1da840b1214c86c12",
"property": "Residential Flat",
"area": "1800",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "95000000",
"expectedRate": "52777.78",
"builtUpExpectedRate": "43981.48",
"image": "cases/66b34e9b4388d81213f376d1/
indicator_1723878287198_Image.png",
"squareMeter": "167.23",
"id": "961269"
},
{
"carpetArea": {
"area": "1500.00",
"squareMeterArea": "139.35",
"expectedRate": "66666.67",
"percentage": ""
},
"builtUpArea": {
"area": "1800.00",
"squareMeterArea": "167.23",
"expectedRate": "55555.56",
```

```
"percentage": "20"
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "66c04bf1da840b1214c86c13",
"property": "Residential Flat",
"area": "1800",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "100000000",
"expectedRate": "66666.67",
"builtUpExpectedRate": "100000000",
"image": "cases/66b34e9b4388d81213f376d1/
indicator_1723878309534_Image.png",
"squareMeter": "167.23",
"id": "244863"
},
{
  "carpetArea": {
    "area": "1600.00",
    "squareMeterArea": "148.65",
    "expectedRate": "56250.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1920.00",
    "squareMeterArea": "178.37",
    "expectedRate": "46875.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
```



```
"_id": "66c04bf1da840b1214c86c14",
"property": "Residential Flat",
"area": "1600",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "square_yards",
"expectedPrice": "90000000",
"expectedRate": "56250.00",
"builtUpExpectedRate": "46875.00",
"image": "cases/66b34e9b4388d81213f376d1/
indicator_1723878327113_Image.png",
"squareMeter": "148.65",
"id": "163576"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66bed7ba0f117327db707c43",
"name": "externalImg_1723783093015_1723783089454_image_0.jpeg",
"path": "cases/66b34e9b4388d81213f376d1/
externalImg_1723783093015_1723783089454_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66bed7ba0f117327db707c44",
"name": "externalImg_1723783094200_1723783089454_image_1.jpeg",
"path": "cases/66b34e9b4388d81213f376d1/
externalImg_1723783094200_1723783089454_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66bed7ba0f117327db707c45",
"name": "externalImg_1723783095295_1723783089454_image_2.jpeg",
"path": "cases/66b34e9b4388d81213f376d1/
externalImg_1723783095295_1723783089454_image_2.jpeg",
"orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bed7ba0f117327db707c46",
  "name": "externalImg_1723783096465_1723783089454_image_3.jpeg",
  "path": "cases/66b34e9b4388d81213f376d1/
externalImg_1723783096465_1723783089454_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66bed7a20f117327db707c14",
  "name": "externalImg_1723783073660_1723783069154_image_0.jpeg",
  "path": "cases/66b34e9b4388d81213f376d1/
externalImg_1723783073660_1723783069154_image_0.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1723876647746_AGR.pdf",
    "path": "cases/66b34e9b4388d81213f376d1/
processingDocuments/1723876647746_AGR.pdf",
    "size": "2654764",
    "createdAt": "Sat Aug 17 2024 12:07:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "MAIL.pdf",
    "filename": "1723876647784_MAIL.pdf",
    "path": "cases/66b34e9b4388d81213f376d1/
processingDocuments/1723876647784_MAIL.pdf",
    "size": "398007",
    "createdAt": "Sat Aug 17 2024 12:07:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "PREV VAL.pdf",
    "filename": "1723876647786_PREV_VAL.pdf",
    "path": "cases/66b34e9b4388d81213f376d1/
processingDocuments/1723876647786_PREV_VAL.pdf",
    "size": "1206685",
    "createdAt": "Sat Aug 17 2024 12:07:27 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1723876657780_IGR01.pdf",
  "path": "cases/66b34e9b4388d81213f376d1/
processingDocuments/1723876657780_IGR01.pdf",
  "size": "152891",
  "createdAt": "Sat Aug 17 2024 12:07:37 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1723876657783_IGR02.pdf",
  "path": "cases/66b34e9b4388d81213f376d1/
processingDocuments/1723876657783_IGR02.pdf",
  "size": "154380",
  "createdAt": "Sat Aug 17 2024 12:07:37 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1723876657788_IGR03.pdf",
  "path": "cases/66b34e9b4388d81213f376d1/
processingDocuments/1723876657788_IGR03.pdf",
  "size": "156534",
  "createdAt": "Sat Aug 17 2024 12:07:37 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=FLAT NO. 901.xlsx",
  "filename": "1723878394215_Summary_NewFLAT_NO_901.xlsx",
  "path": "cases/66b34e9b4388d81213f376d1/
processingDocuments/1723878394215_Summary_NewFLAT_NO_901.xlsx",
  "size": "2994613",
  "createdAt": "Sat Aug 17 2024 12:36:34 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "ACCOUNTANT",
```

```
    "firstName": "Shyam",
    "lastName": "Kajvilkar",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66bc9bafda840b1214c76c9a",
  "note": "Pending for value confirmation",
  "taskId": "66bc2b53c884d1123348d08e",
  "createdAt": "2024-08-14T11:57:35.285Z"
}
],
"createdAt": "2024-08-07T10:38:19.941Z",
"updatedAt": "2024-08-17T10:29:32.765Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1001, 10th Floor, RNA Mirage Co-Op. Hsg. Soc.
Ltd. , Sudam Kalu Ahire Marg, Worli, Village - Lower Parel Division , Municipality Ward
No. G/S, District - Mumbai, PIN - 400 025, State - Maharashtra, Country - India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Miss. Pratibha ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Banker ",
"siteVisitContactNo": "9769972090",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Article of Agreement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1316.00",
"flatRate": "50600",
"landOtherRate": "47600",
"shopDetails": {
```

```

"typeOfShops": {
  "label": "Independent Building",
  "value": "Independent_Building"
},
"roadFacing": false,
"mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Aug 17 2024 13:43:08 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-08-06"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
