

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "640f306e63e4271bcefdbb9e"
    },
    "firstName": "Narendra",
    "type": "CREDITOFFICER",
    "_id": "640f306e63e4271bcefdbba1",
    "lastName": "Gavale",
    "mobileNo": "",
    "workMobileNo": "9619072773",
    "email": "kalyan@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "640f306e63e4271bcefd9e",
  "name": "Kalyan Khadakpada Branch",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "kalyan@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ground floor, Shiv Villa Apt. Opp. gagangiri Soc. Sai Chowk, Khadakpada
Kalyan West 421301\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
```

```
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      },
      {
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    }
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.24463626016684",
  "longitude": "73.12348019345566"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-08-08",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-08-08",
    "remark": "MANUAL_IN_TASK"
  }
],
"schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Gandhare",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "15",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kedarnath",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Kedarnath & Pashupatinath Co-Op. Hsg. Soc. Ltd., Madhav Sankalp
Complex, Behind Axis Bank, Khadakpada",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "C - 1",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "32/1/2, 26/5/1, 30/1, 32/1/3, 59 & 30/2",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "1505",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 301",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
```

```
"label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Kalyan_Dombivali_Municipal_Corporation",
  "label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road",
  "west": "Wing - C - 2",
  "south": "Singhal Road",
  "east": "Internal Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Flat No. 1506",
    "east": "Flat No. 1504",
    "south": "Compound",
    "west": "Building"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
```

```
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": true
  },
  "auto": {
    "title": "Auto",
    "status": true
  },
  "privateCars": {
    "title": "Private Cars",
    "status": true
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"classOfSanitary": {
  "value": "ordinary",
  "label": "Ordinary"
},
"compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "22.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "11437.5",
  "depreciatedBuildingRate": "1937.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "75800",
```

```
"landRate": "24000",
"igrImage": "cases/66b47bf2c884d11233448e7d/igr_1723187578688_Image.png",
"squareMeterGuideLineRate": "83380.00",
"squareFeetGuideLineRate": "7746.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "85",
  "rate": "6919.00",
  "squareFeetGuideLineRate": "6919.00",
  "squareMeterGuideLineRate": "74473.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Seller_Occupied",
    "label": "Seller Occupied"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per KDMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Stilt / Open Parking",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2009",
"fullDate": "1/1/2009"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
}
```

```
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
```



```
"label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "45",
"ageOfBuilding": "15",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "18",
"flatFloorNo": "15",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "796.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66b47bf2c884d11233448e7d/
routeMap_1723199884250_Image.png",
    "routeLat": "19.257188",
    "routeLng": "73.139094",
    "stationName": "Kalyan",
    "routeDistance": "3.5 Km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
}
```

```
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "bmz8zit",
    "name": "bmz8zit",
    "image": "cases/66b47bf2c884d11233448e7d/
routeMap_1723199908641_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "1992500.00",
    "depreciationPercentage": "22.5",
    "depreciatedCostOfConstruction": "448312.50",
    "totalFairMarketValue": "7519687.50"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
```

```
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "7968000.00",
"finalValue": "7968000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "5513059.00",
  "selectedBuildUpValue": "796.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66b49b89c884d1123344c963",
      "name": "externallmg_1723112327177_1723112317424_image_11.jpeg",
      "path": "cases/66b47bf2c884d11233448e7d/externallmg_1723112327177_1723112317424_image_11.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66b49b89c884d1123344c963",
      "name": "externallmg_1723112327177_1723112317424_image_11.jpeg",
      "path": "cases/66b47bf2c884d11233448e7d/externallmg_1723112327177_1723112317424_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66b49be9da840b1214c3b8bc",
      "name": "externallmg_1723112424846_1723112422462_image_2.jpeg",
      "path": "cases/66b47bf2c884d11233448e7d/externallmg_1723112424846_1723112422462_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66b49b22c884d1123344c8e5",
      "name": "externallmg_1723112225081_1723112194673_image_3.jpeg",
      "path": "cases/66b47bf2c884d11233448e7d/externallmg_1723112225081_1723112194673_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66b49b89c884d1123344c95c",
```

```
    "name": "externallmg_1723112325846_1723112317423_image_4.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112325846_1723112317423_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66b49b22c884d1123344c8e6",
    "name": "externallmg_1723112225331_1723112194673_image_4.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112225331_1723112194673_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66b49b89c884d1123344c958",
    "name": "externallmg_1723112324691_1723112317423_image_0.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112324691_1723112317423_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66b49b89c884d1123344c95b",
    "name": "externallmg_1723112325727_1723112317423_image_3.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112325727_1723112317423_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66b49b89c884d1123344c95f",
    "name": "externallmg_1723112326437_1723112317424_image_7.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112326437_1723112317424_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66b49b89c884d1123344c95e",
    "name": "externallmg_1723112326217_1723112317424_image_6.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112326217_1723112317424_image_6.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "status": false,
    "_id": "66b49b89c884d1123344c95a",
    "name": "externallmg_1723112325721_1723112317423_image_2.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112325721_1723112317423_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66b49b89c884d1123344c959",
    "name": "externallmg_1723112325718_1723112317423_image_1.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112325718_1723112317423_image_1.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10392.00",
    "max": "13889.00"
  },
  "builtUpRateRange": {
    "min": "8660.00",
    "max": "11575.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```

```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
```

```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "664.00",
"empanelmentNo": [
  "HO/CREDIT/67/ 2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66b47bf2c884d11233448e7d",
"ownerName": "Jyoti Hemant Sonawane & Hemant Ramesh Sonawane",
"ownerPhoneNo": "9167886606",
"fullAddress": "Residential Flat No. 1505, 15th Floor, Wing - C - 1, Kedarnath,
Kedarnath & Pashupatinath Co-Op. Hsg. Soc. Ltd., Madhav Sankalp Complex, Behind
Axis Bank, Khadakpada, Village - Gandhare, Taluka - Kalyan, District - Thane, Kalyan
(West), PIN Code - 421 301, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
    "inputs": {
      "documentDate": "07/08/2024",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Tulsidharan Sukumaran & Lalita Tulsidharan ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Jyoti Hemant Sonawane & Hemant Ramesh Sonawane ",
      "number": {
        "value": "No",
```

```
    "label": "No"
  },
  "No": "16037 / 2024"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1723202694039_Untitled_20240807_104957_1.pdf",
"path": "cases/66b47bf2c884d11233448e7d/
document_1723202694039_Untitled_20240807_104957_1.pdf",
"id": "849024",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Aug 09 2024 16:54:54 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "21/03/2009",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / NRV / KV / CC / 572"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1723202781736_1723187713924_OC.pdf",
"path": "cases/66b47bf2c884d11233448e7d/
document_1723202781736_1723187713924_OC.pdf",
"id": "951415",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Aug 09 2024 16:56:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "23/03/2005",
```

```
"nameOfApprovingAuthority": {
  "value": "Kalyan_Dombivli_Municipal_Corporation",
  "label": "Kalyan Dombivli Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "KDMC / NRV / BP / KV / 617 - 266"
},
"isHardCopy": false,
"displayStatus": true,
"id": "978552",
"path": "cases/66b47bf2c884d11233448e7d/
document_1723202873931_1723187713921_CC.pdf",
"fileName": "document_1723202873931_1723187713921_CC.pdf"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "010476",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "579915",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Aug 08 2024 13:34:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Jyoti Hemant Sonawane & Hemant Ramesh Sonawane",
    "phone": "9167886606",
    "ownershipShare": "",
    "email": "",
    "id": "597269"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "532139",
  "name": "Living Room",
  "length": "20.00",
  "length1": "20",
  "length2": "00",
  "width": "12.00",
  "width1": "12",
  "width2": "00",
  "totalArea": "240.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "240.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "102.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "102.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
```

```
"width2": "00",
"totalArea": "119.00",
"images": [],
"extraAreas": [],
"finalArea": "119.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "84.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "84.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "5",
  "name": "WC",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "0",
  "width": "6.00",
  "width1": "6",
  "width2": "0",
  "totalArea": "30.00",
  "images": [],
  "finalArea": "30.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "40.00",
```



```
"images": [],
"extraAreas": [],
"finalArea": "40.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "5.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "5.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Cupboard",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "16.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
```

```
"name": "Balcony",
"length": "3.00",
"length1": "3",
"length2": "00",
"width": "5.00",
"width1": "5",
"width2": "00",
"totalArea": "15.00",
"images": [],
"extraAreas": [],
"finalArea": "15.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "18.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Dry Balcony",
      "value": "Dry_Balcony"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
```

```
"length": "1.00",
"length1": "1",
"length2": "00",
"width": "17.00",
"width1": "17",
"width2": "00",
"totalArea": "17.00",
"images": [],
"extraAreas": [],
"finalArea": "17",
"percentageBeforeTotal": "17.00",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Terrace Area",
    "value": "Terrace_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "59.00",
  "length1": "59",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "59.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "59",
  "percentageBeforeTotal": "59.00",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1246aa6d152c1801b2e4",
```

```
    "label": "Index- II"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "430408",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "664",
  "squareMeterArea": "61.69",
  "docFinalBuiltUp": "796.8",
  "docFinalBuiltUpSquareMeter": "74.02799999999999",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "20",
  "docFinalSaleable": "956.16",
  "docFinalSaleableSquareMeter": "88.83359999999999"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "950.00",
      "squareMeterArea": "88.26",
      "expectedRate": "12315.79",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "1140.00",
      "squareMeterArea": "105.91",
      "expectedRate": "10263.16",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "66b5c24bda840b1214c434dc",
    "property": "Residential Flat",
    "area": "950",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "11700000",
"expectedRate": "12315.79",
"builtUpExpectedRate": "10263.16",
"image": "cases/66b47bf2c884d11233448e7d/
indicator_1723187095050_Image.png",
"squareMeter": "88.26",
"id": "347633"
},
{
"carpetArea": {
"area": "648.00",
"squareMeterArea": "60.20",
"expectedRate": "13888.89",
"percentage": ""
},
"builtUpArea": {
"area": "777.60",
"squareMeterArea": "72.24",
"expectedRate": "11574.07",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66b5c24bda840b1214c434dd",
"property": "Residential Flat",
"area": "648",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "9000000",
"expectedRate": "13888.89",
"builtUpExpectedRate": "11574.07",
"image": "cases/66b47bf2c884d11233448e7d/
indicator_1723187181027_Image.png",
"squareMeter": "60.20",
```

```
"id": "535005"
},
{
  "carpetArea": {
    "area": "664.00",
    "squareMeterArea": "61.69",
    "expectedRate": "10391.57",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "796.80",
    "squareMeterArea": "74.03",
    "expectedRate": "8659.64",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "66b5c24bda840b1214c434de",
  "property": " Residential Flat",
  "area": "664",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6900000",
  "expectedRate": "10391.57",
  "builtUpExpectedRate": "8659.64",
  "image": "cases/66b47bf2c884d11233448e7d/
indicator_1723187390559_Image.png",
  "squareMeter": "61.69",
  "id": "888733"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b49b89c884d1123344c958",
    "name": "externalImg_1723112324691_1723112317423_image_0.jpeg",
```

```
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112324691_1723112317423_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b49b89c884d1123344c959",
    "name": "externallmg_1723112325718_1723112317423_image_1.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112325718_1723112317423_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b49b89c884d1123344c95a",
    "name": "externallmg_1723112325721_1723112317423_image_2.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112325721_1723112317423_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b49b89c884d1123344c95b",
    "name": "externallmg_1723112325727_1723112317423_image_3.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112325727_1723112317423_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b49b89c884d1123344c95c",
    "name": "externallmg_1723112325846_1723112317423_image_4.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112325846_1723112317423_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b49b89c884d1123344c95d",
    "name": "externallmg_1723112325987_1723112317424_image_5.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112325987_1723112317424_image_5.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b49b89c884d1123344c95e",
  "name": "externallmg_1723112326217_1723112317424_image_6.jpeg",
  "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112326217_1723112317424_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b49b89c884d1123344c95f",
  "name": "externallmg_1723112326437_1723112317424_image_7.jpeg",
  "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112326437_1723112317424_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b49b89c884d1123344c963",
  "name": "externallmg_1723112327177_1723112317424_image_11.jpeg",
  "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112327177_1723112317424_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b49be9da840b1214c3b8ba",
  "name": "externallmg_1723112424242_1723112422462_image_0.jpeg",
  "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112424242_1723112422462_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b49be9da840b1214c3b8bb",
  "name": "externallmg_1723112424567_1723112422462_image_1.jpeg",
  "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112424567_1723112422462_image_1.jpeg",
  "orientation": "portrait"
}
```



```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b49be9da840b1214c3b8bc",
    "name": "externallmg_1723112424846_1723112422462_image_2.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112424846_1723112422462_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b49b22c884d1123344c8e2",
    "name": "externallmg_1723112224766_1723112194673_image_0.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112224766_1723112194673_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b49b22c884d1123344c8e3",
    "name": "externallmg_1723112224916_1723112194673_image_1.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112224916_1723112194673_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b49b22c884d1123344c8e4",
    "name": "externallmg_1723112225011_1723112194673_image_2.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112225011_1723112194673_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b49b22c884d1123344c8e5",
    "name": "externallmg_1723112225081_1723112194673_image_3.jpeg",
    "path": "cases/66b47bf2c884d11233448e7d/
externallmg_1723112225081_1723112194673_image_3.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66b49b22c884d1123344c8e6",
  "name": "externalimg_1723112225331_1723112194673_image_4.jpeg",
  "path": "cases/66b47bf2c884d11233448e7d/
externalimg_1723112225331_1723112194673_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66b49b22c884d1123344c8e7",
  "name": "externalimg_1723112225641_1723112194673_image_5.jpeg",
  "path": "cases/66b47bf2c884d11233448e7d/
externalimg_1723112225641_1723112194673_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66b49b22c884d1123344c8e8",
  "name": "externalimg_1723112225956_1723112194673_image_6.jpeg",
  "path": "cases/66b47bf2c884d11233448e7d/
externalimg_1723112225956_1723112194673_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66b49b4f4388d81213f43a94",
  "name": "externalimg_1723112270972_1723112269243_image_0.jpeg",
  "path": "cases/66b47bf2c884d11233448e7d/
externalimg_1723112270972_1723112269243_image_0.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW COSMOS.xlsx",
    "filename": "1723187713895_Calculation_Sheet_NEW_COSMOS.xlsx",
    "path": "cases/66b47bf2c884d11233448e7d/
processingDocuments/1723187713895_Calculation_Sheet_NEW_COSMOS.xlsx",
    "size": "1482251",
    "createdAt": "Fri Aug 09 2024 12:45:13 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "CC.pdf",
  "filename": "1723187713921_CC.pdf",
  "path": "cases/66b47bf2c884d11233448e7d/
processingDocuments/1723187713921_CC.pdf",
  "size": "219363",
  "createdAt": "Fri Aug 09 2024 12:45:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "OC.pdf",
  "filename": "1723187713924_OC.pdf",
  "path": "cases/66b47bf2c884d11233448e7d/
processingDocuments/1723187713924_OC.pdf",
  "size": "146207",
  "createdAt": "Fri Aug 09 2024 12:45:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "Reference Report - Rajesh_Yagyanarayan_Pal.pdf",
  "filename": "1723187713927_Reference_Report__Rajesh_Yagyanarayan_Pal.pdf",
  "path": "cases/66b47bf2c884d11233448e7d/processingDocuments/1723187713927
_Reference_Report__Rajesh_Yagyanarayan_Pal.pdf",
  "size": "1378409",
  "createdAt": "Fri Aug 09 2024 12:45:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "Reference Report - Venkatesh_Bapurao_Nagargoje.pdf",
  "filename":
"1723187713948_Reference_Report__Venkatesh_Bapurao_Nagargoje.pdf",
  "path": "cases/66b47bf2c884d11233448e7d/processingDocuments/1723187713948
_Reference_Report__Venkatesh_Bapurao_Nagargoje.pdf",
  "size": "1009880",
  "createdAt": "Fri Aug 09 2024 12:45:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
```

```
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66b4c1764388d81213f46909",
  "note": "Value Given For The Confirmation",
  "taskId": "66b47c0bda840b1214c38dc0",
  "createdAt": "2024-08-08T13:00:38.372Z"
}
],
"createdAt": "2024-08-08T08:04:02.651Z",
"updatedAt": "2024-08-09T12:34:50.201Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mrs. Lalita Tulsidharan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Seller",
"siteVisitContactNo": "9820293731",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Other",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 664.00",
"flatRate": "12000",
"landOtherRate": "9500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
```

```

},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Bathroom + WC +
Toilet + 2 Passage + Cupboard + 2 Balcony",
"carpetTotal": "701",
"otherCarpetTotal": "76.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "76.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "854.70",
"finalCarpetArea": "777.00",
"finalSalableArea": "940.17",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 668.00\nBalcony Area in Sq. Ft.
= 33.00\nDry Balcony Area in Sq. Ft. = 17.00\nTerrace Area in Sq. Ft. = 59.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Fri Aug 09 2024 15:45:31 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-08-08"
}

```

Name	Length	Width	Total
Composition :			
Living Room	20'00"	12'00"	240.00
Bedroom	17'00"	6'00"	102.00

Bedroom	17'00"	7'00"	119.00
Kitchen	12'00"	7'00"	84.00
Bathroom	4'00"	5'00"	20.00
WC	2'00"	6'00"	12.00
Toilet	5'0"	6'0"	30.00
Passage	5'00"	8'00"	40.00
Passage	5'00"	1'00"	5.00
Cupboard	4'00"	4'00"	16.00
Balcony	3'00"	5'00"	15.00
Balcony	3'00"	6'00"	18.00
Other Composition :			
Dry Balcony	1'00"	17'00"	17.00
Terrace Area	59'00"	1'00"	59.00