

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "66b48f6fda840b1214c3a628"
    },
    "firstName": "Sreewin",
    "type": "CREDITOFFICER",
    "_id": "66b48f95da840b1214c3a645",
    "email": "LokhandwalaAndheriWest.MumbaiNorth@bankofindia.co.in",
    "lastName": "Poduval",
    "mobileNo": "",
    "workMobileNo": "7012551607"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2000000",
  }
}
```

```
"discussWithPerson": "Sreewin",
"expectedFees": 1000,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "66b48f6fda840b1214c3a628",
  "name": "Lokhandwala Andheri Branch",
  "branchCode": "",
  "mobileNo": "02226312074",
  "alternateMobileNo": "02226312073",
  "email": "LokhandwalaAndheriWest.MumbaiNorth@bankofindia.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Silver ARch, Ground Floor, A Wing Indra Darshan Layout, Lokhandwala
Complex, Opp Millat Nagar, Andheri West, Mumbai 400053"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f41b6576061dae4692f3",
  "zoneName": "Mumbai North Zone"
},
```

```
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
    "shortName": "RP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62720a36afd7d55eddedc4a7",
    "role": "SITEENGINEER",
    "firstName": "Anwar",
    "email": "anwar21786@gmail.com",
    "lastName": "Shaikh",
    "mobileNo": "8552884500",
    "designation": "",
    "shortName": "AS",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60f91b6f344e052188ffd1fc",
    "role": "MAKER",
```

```
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",

```

```
    "label": "Wealth Tax"
  },
  "_id": "6084131a13f01f158c6ea1f4",
  "number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.359206761925726",
  "longitude": "72.85424594307936"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85424594307936,
    19.359206761925726
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "8/08/2024 04:05 pm"
    },
    {
      "dateTime": "8/08/2024 12:00 am"
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-08-21",
    "remark": "MANUAL_IN_TASK"
  }
]
},
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Juchandra",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "Q/1A",
```

```
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Naigaon (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "K. D. Saicon Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
```

```
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Opp. Don Bosco School",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "280, 279",
  "label": true
}
```



```
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "307/2, 306/4",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "006",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```

```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 208",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Naigaon",
  "label": false
}
```

```

},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {

```

```
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road & Building No. P/2D",
  "west": "Building No. P/2G",
  "south": "Internal Road & Building No. 8 , Rashmi Pink City",
  "east": "Building No. P/1B"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Staircase Area",
    "east": "Building No. P/1B",
    "south": "Flat No. 007",
    "west": "Lobby / Flat No. 008"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
```

```
"dateOfIssusApprovePlan": "Approved Building Plan were not provided and not
verified.",
"approvePlanVerified": "No",
"empanelledOfApprovePlan": "NO",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"compositeRate": {
"remark": "Flat No. 006 is mentioned in Bank Possession notice affixed on the main
entrance door. Mr. Eshan (Bank Staff) is opened the door for inspection.",
"depreciationPercentage": "9",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "6275",
"depreciatedBuildingRate": "2275"
},
"igrRate": {
"propertyName": "Residential",
"rate": "48200",
"landRate": "2500",
"igrImage": "cases/66b491d7c884d1123344b689/igr_1724306068564_Image.png",
"squareMeterGuideLineRate": "48200.00",
"squareFeetGuideLineRate": "4478.00"
},
"igrFinalRate": {
"floorRatePercentage": "0",
"depreciationPercentage": "94",
"rate": "4223.00",
"squareFeetGuideLineRate": "4223.00",
"squareMeterGuideLineRate": "45458.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
```

```
"value": "Vacant_Bank_Possession",
"label": "Vacant- Bank Possession"
},
"monthlyRent": "N.A",
"assessmentNo": "Information not available",
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per VVCMC norms",
"tenantName": "",
"maintenanceOfFlat": "Vacant flat without maintenance"
},
"marketability": {
"marketabilityList": {
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developing area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "R.C.C._slab",
"label": "R.C.C. slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Parking Space",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2018",
  "fullDate": "1/1/2018"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
```

```
"label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "6",
"totalLifeBuilding": "60",
"estimatedAge": "54",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "Ground",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
```



```
"finalPlinthArea": {
  "area": "312.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66b491d7c884d1123344b689/
routeMap_1724240325111_Image.png",
    "routeLat": "19.358945",
    "routeLng": "72.854231",
    "stationName": "Naigaon",
    "routeDistance": "2.00 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "3pb6mo",
      "name": "3pb6mo",
      "image": "cases/66b491d7c884d1123344b689/
routeMap_1724240184022_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
}
```

```
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "1631500.00",
"distressValuePercentage": "70",
"realizableValuePercentage": "85",
"bookValue": "0",
"finalValue": "1631500.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1317576.00",
  "selectedBuildUpValue": "312.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66c5d006c884d112334dac87",
      "name": "externallmg_1724239877721_externallmg_1724237335347_WhatsApp_I
mage_20240821_at_145351.jpeg",
      "path": "cases/66b491d7c884d1123344b689/externallmg_1724239877721_extern
allmg_1724237335347_WhatsApp_Image_20240821_at_145351.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "66c5d006c884d112334dac8a",
      "name": "externallmg_1724239877743_externallmg_1724237335358_WhatsApp_I
mage_20240821_at_145353_1.jpeg",
```

```
    "path": "cases/66b491d7c884d1123344b689/externallmg_1724239877743_extern
allmg_1724237335358_WhatsApp_Image_20240821_at_145353_1.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "66c5d006c884d112334dac88",
    "name": "externallmg_1724239877722_externallmg_1724237335351_WhatsApp_I
mage_20240821_at_145352_1.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externallmg_1724239877722_extern
allmg_1724237335351_WhatsApp_Image_20240821_at_145352_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c5d006c884d112334dac89",
    "name": "externallmg_1724239877731_externallmg_1724237335355_WhatsApp_I
mage_20240821_at_145352.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externallmg_1724239877731_extern
allmg_1724237335355_WhatsApp_Image_20240821_at_145352.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "66c5d011da840b1214ca9fd7",
    "name": "externallmg_1724239889116_externallmg_1724237355906_WhatsApp_I
mage_20240821_at_145358.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externallmg_1724239889116_extern
allmg_1724237355906_WhatsApp_Image_20240821_at_145358.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "66c5d006c884d112334dac8b",
    "name": "Living Room",
    "path": "cases/66b491d7c884d1123344b689/externallmg_1724239877743_extern
allmg_1724237335360_WhatsApp_Image_20240821_at_145353_2.jpeg",
    "orientation": "portrait"
  },
]
```

```
{
  "status": false,
  "_id": "66c5d006c884d112334dac8d",
  "name": "Living Room",
  "path": "cases/66b491d7c884d1123344b689/externallmg_1724239877749_extern
allmg_1724237335364_WhatsApp_Image_20240821_at_145354_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66c5d011da840b1214ca9fd3",
  "name": "Living Room",
  "path": "cases/66b491d7c884d1123344b689/externallmg_1724239889108_extern
allmg_1724237355890_WhatsApp_Image_20240821_at_145355.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "66c5d011da840b1214ca9fd4",
  "name": "Living Room",
  "path": "cases/66b491d7c884d1123344b689/externallmg_1724239889110_extern
allmg_1724237355891_WhatsApp_Image_20240821_at_145356_1.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "4929.00",
    "max": "6855.00"
  },
  "builtUpRateRange": {
    "min": "4108.00",
    "max": "5713.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "260.00",
"empanelmentNo": [
  "MNZ :C&IC:VA: 19-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66b491d7c884d1123344b689",
"ownerName": "Sanjay Motilal Gupta ",
"ownerPhoneNo": "0000000000",
"appAddress": "flat no - 006, ground floor, Q / 1A, Bldg Name - K,D saicon, Vasai ",
"remark": "contact - 7012551607",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "02/09/2013",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. K. D. Venture",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      }
    }
  },

```

```
"Purchaser": "Sanjay Motilal Gupta",
"number": {
  "value": "Registration_No",
  "label": "Registration No"
},
"Registration_No": "3464/2013"
},
"isHardCopy": false,
"displayStatus": true,
"id": "561022",
"path": "cases/66b491d7c884d1123344b689/
document_1724246451321_Sale_Deed__2013.pdf",
"fileName": "document_1724246451321_Sale_Deed__2013.pdf"
}
],
"caseNumber": "010482",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "676564",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Aug 08 2024 15:07:27 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sanjay Motilal Gupta ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "235458"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "221851",
    "name": "Living Room",
    "length": "9.33",
    "length1": "9",
```

```
"length2": "4",
"width": "15.33",
"width1": "15",
"width2": "4",
"totalArea": "143.11",
"images": [],
"extraAreas": [],
"finalArea": "143.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "8.08",
  "length1": "8",
  "length2": "1",
  "width": "7.08",
  "width1": "7",
  "width2": "1",
  "totalArea": "57.26",
  "images": [],
  "extraAreas": [],
  "finalArea": "57.26"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "4.92",
  "length1": "4",
  "length2": "11",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "19.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.67"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "3",
"name": "WC",
"length": "2.92",
"length1": "2",
"length2": "11",
"width": "3.92",
"width1": "3",
"width2": "11",
"totalArea": "11.42",
"images": [],
"extraAreas": [],
"finalArea": "11.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "15.34",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.34"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "532991",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "260",
  "squareMeterArea": "24.15",
  "docFinalBuiltUp": "312",
  "docFinalBuiltUpSquareMeter": "28.979999999999997",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "372.00",
      "squareMeterArea": "34.56",
      "expectedRate": "6854.84",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "446.40",
      "squareMeterArea": "41.47",
      "expectedRate": "5712.37",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "66c6d528c884d112334e0e11",
    "property": "KD Saicon, Panvel",
    "area": "372",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "Housing.Com",
    "expectedPrice": "2550000",
```

```
"expectedRate": "6854.84",
"builtUpExpectedRate": "5712.37",
"image": "cases/66b491d7c884d1123344b689/
indicator_1724305724600_Image.png",
"squareMeter": "34.56",
"id": "967171"
},
{
  "carpetArea": {
    "area": "242.00",
    "squareMeterArea": "22.48",
    "expectedRate": "6458.68",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "290.40",
    "squareMeterArea": "26.98",
    "expectedRate": "5382.23",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66c6d528c884d112334e0e12",
  "property": "KD Saicon, Panvel",
  "area": "242",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "square_yards",
  "expectedPrice": "1563000",
  "expectedRate": "6458.68",
  "builtUpExpectedRate": "5382.23",
  "image": "cases/66b491d7c884d1123344b689/
indicator_1724305798380_Image.png",
  "squareMeter": "22.48",
  "id": "250397"
},
{
  "carpetArea": {
```

```
"area": "372.00",
"squareMeterArea": "34.56",
"expectedRate": "6048.39",
"percentage": ""
},
"builtUpArea": {
"area": "409.20",
"squareMeterArea": "38.02",
"expectedRate": "5498.53",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66c6d528c884d112334e0e13",
"property": "KD Saicon, Panvel",
"area": "372",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "4",
"source": "Index_no.2",
"expectedPrice": "2250000",
"expectedRate": "6048.39",
"builtUpExpectedRate": "5498.53",
"image": "cases/66b491d7c884d1123344b689/
indicator_1724305873797_Image.png",
"squareMeter": "34.56",
"id": "456852"
},
{
"carpetArea": {
"area": "417.96",
"squareMeterArea": "38.83",
"expectedRate": "4928.70",
"percentage": ""
},
"builtUpArea": {
"area": "501.55",
"squareMeterArea": "46.60",
"expectedRate": "4107.27",
```



```
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66c6ecb9da840b1214cb163a",
  "property": "Apeksha Imperial, Bldg. No. 19, Type - H1",
  "area": "417.96",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "3rd",
  "source": "Index_no.2",
  "expectedPrice": "2060000",
  "expectedRate": "4928.70",
  "builtUpExpectedRate": "4107.27",
  "image": "cases/66b491d7c884d1123344b689/
indicator_1724312761618_Image.jpeg",
  "squareMeter": "38.83",
  "id": "990675"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5c617c884d112334d9d33",
    "name":
"externallmg_1724237335342_WhatsApp_Image_20240821_at_145346_1.jpeg",
    "path": "cases/66b491d7c884d1123344b689/
externallmg_1724237335342_WhatsApp_Image_20240821_at_145346_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5c617c884d112334d9d34",
    "name":
"externallmg_1724237335344_WhatsApp_Image_20240821_at_145346.jpeg",
    "path": "cases/66b491d7c884d1123344b689/
externallmg_1724237335344_WhatsApp_Image_20240821_at_145346.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5c617c884d112334d9d35",
    "name":
"externallmg_1724237335345_WhatsApp_Image_20240821_at_145347.jpeg",
    "path": "cases/66b491d7c884d1123344b689/
externallmg_1724237335345_WhatsApp_Image_20240821_at_145347.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5c62b0f117327db737bca",
    "name":
"externallmg_1724237355895_WhatsApp_Image_20240821_at_145357_1.jpeg",
    "path": "cases/66b491d7c884d1123344b689/
externallmg_1724237355895_WhatsApp_Image_20240821_at_145357_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5c62b0f117327db737bcb",
    "name":
"externallmg_1724237355898_WhatsApp_Image_20240821_at_145357_2.jpeg",
    "path": "cases/66b491d7c884d1123344b689/
externallmg_1724237355898_WhatsApp_Image_20240821_at_145357_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5c62b0f117327db737bcc",
    "name":
"externallmg_1724237355900_WhatsApp_Image_20240821_at_145357.jpeg",
    "path": "cases/66b491d7c884d1123344b689/
externallmg_1724237355900_WhatsApp_Image_20240821_at_145357.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5d006c884d112334dac87",
```

```
    "name": "externalimg_1724239877721_externalimg_1724237335347_WhatsApp_I
mage_20240821_at_145351.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externalimg_1724239877721_external
Img_1724237335347_WhatsApp_Image_20240821_at_145351.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5d006c884d112334dac88",
    "name": "externalimg_1724239877722_externalimg_1724237335351_WhatsApp_I
mage_20240821_at_145352_1.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externalimg_1724239877722_external
Img_1724237335351_WhatsApp_Image_20240821_at_145352_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5d006c884d112334dac89",
    "name": "externalimg_1724239877731_externalimg_1724237335355_WhatsApp_I
mage_20240821_at_145352.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externalimg_1724239877731_external
Img_1724237335355_WhatsApp_Image_20240821_at_145352.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5d006c884d112334dac8a",
    "name": "externalimg_1724239877743_externalimg_1724237335358_WhatsApp_I
mage_20240821_at_145353_1.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externalimg_1724239877743_external
Img_1724237335358_WhatsApp_Image_20240821_at_145353_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5d006c884d112334dac8b",
    "name": "externalimg_1724239877743_externalimg_1724237335360_WhatsApp_I
mage_20240821_at_145353_2.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externalimg_1724239877743_external
Img_1724237335360_WhatsApp_Image_20240821_at_145353_2.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c5d006c884d112334dac8c",
  "name": "externallmg_1724239877745_externallmg_1724237335361_WhatsApp_I
mage_20240821_at_145353.jpeg",
  "path": "cases/66b491d7c884d1123344b689/externallmg_1724239877745_external
lmg_1724237335361_WhatsApp_Image_20240821_at_145353.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c5d006c884d112334dac8d",
  "name": "externallmg_1724239877749_externallmg_1724237335364_WhatsApp_I
mage_20240821_at_145354_1.jpeg",
  "path": "cases/66b491d7c884d1123344b689/externallmg_1724239877749_external
lmg_1724237335364_WhatsApp_Image_20240821_at_145354_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c5d011da840b1214ca9fcf",
  "name": "externallmg_1724239889105_externallmg_1724237355883_WhatsApp_I
mage_20240821_at_145354_2.jpeg",
  "path": "cases/66b491d7c884d1123344b689/externallmg_1724239889105_external
lmg_1724237355883_WhatsApp_Image_20240821_at_145354_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c5d011da840b1214ca9fd0",
  "name": "externallmg_1724239889106_externallmg_1724237355884_WhatsApp_I
mage_20240821_at_145354.jpeg",
  "path": "cases/66b491d7c884d1123344b689/externallmg_1724239889106_external
lmg_1724237355884_WhatsApp_Image_20240821_at_145354.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c5d011da840b1214ca9fd1",
  "name": "externallmg_1724239889106_externallmg_1724237355886_WhatsApp_I
mage_20240821_at_145355_1.jpeg",
```

```
    "path": "cases/66b491d7c884d1123344b689/externallmg_1724239889106_external
lmg_1724237355886_WhatsApp_Image_20240821_at_145355_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5d011da840b1214ca9fd2",
    "name": "externallmg_1724239889107_externallmg_1724237355887_WhatsApp_I
mage_20240821_at_145355_2.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externallmg_1724239889107_external
lmg_1724237355887_WhatsApp_Image_20240821_at_145355_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5d011da840b1214ca9fd3",
    "name": "externallmg_1724239889108_externallmg_1724237355890_WhatsApp_I
mage_20240821_at_145355.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externallmg_1724239889108_external
lmg_1724237355890_WhatsApp_Image_20240821_at_145355.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5d011da840b1214ca9fd4",
    "name": "externallmg_1724239889110_externallmg_1724237355891_WhatsApp_I
mage_20240821_at_145356_1.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externallmg_1724239889110_external
lmg_1724237355891_WhatsApp_Image_20240821_at_145356_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c5d011da840b1214ca9fd5",
    "name": "externallmg_1724239889111_externallmg_1724237355893_WhatsApp_I
mage_20240821_at_145356.jpeg",
    "path": "cases/66b491d7c884d1123344b689/externallmg_1724239889111_external
lmg_1724237355893_WhatsApp_Image_20240821_at_145356.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66c5d011da840b1214ca9fd6",
  "name": "externalImg_1724239889115_externalImg_1724237355902_WhatsApp_I
mage_20240821_at_145358_1.jpeg",
  "path": "cases/66b491d7c884d1123344b689/externalImg_1724239889115_external
Img_1724237355902_WhatsApp_Image_20240821_at_145358_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c5d011da840b1214ca9fd7",
  "name": "externalImg_1724239889116_externalImg_1724237355906_WhatsApp_I
mage_20240821_at_145358.jpeg",
  "path": "cases/66b491d7c884d1123344b689/externalImg_1724239889116_external
Img_1724237355906_WhatsApp_Image_20240821_at_145358.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1720174121221_1709206285749_Calculation.xlsx",
    "filename": "1723814076913_1720174121221_1709206285749_Calculation.xlsx",
    "path": "cases/66b491d7c884d1123344b689/processingDocuments/172381407691
3_1720174121221_1709206285749_Calculation.xlsx",
    "size": "762326",
    "createdAt": "Fri Aug 16 2024 18:44:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_11796.pdf",
    "filename": "1723814077139_igr_11796.pdf",
    "path": "cases/66b491d7c884d1123344b689/
processingDocuments/1723814077139_igr_11796.pdf",
    "size": "154270",
    "createdAt": "Fri Aug 16 2024 18:44:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "Google Location.jpeg",
    "filename": "1724248012712_Google_Location.jpeg",
    "path": "cases/66b491d7c884d1123344b689/
processingDocuments/1724248012712_Google_Location.jpeg",
    "size": "187220",
    "createdAt": "Wed Aug 21 2024 19:16:52 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Possession Notice 2.jpeg",
  "filename": "1724248012715_Possession_Notice_2.jpeg",
  "path": "cases/66b491d7c884d1123344b689/
processingDocuments/1724248012715_Possession_Notice_2.jpeg",
  "size": "176158",
  "createdAt": "Wed Aug 21 2024 19:16:52 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Possession NOtice.jpeg",
  "filename": "1724248012717_Possession_NOtice.jpeg",
  "path": "cases/66b491d7c884d1123344b689/
processingDocuments/1724248012717_Possession_NOtice.jpeg",
  "size": "204277",
  "createdAt": "Wed Aug 21 2024 19:16:52 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Deed - 2013.pdf",
  "filename": "1724248012720_Sale_Deed__2013.pdf",
  "path": "cases/66b491d7c884d1123344b689/
processingDocuments/1724248012720_Sale_Deed__2013.pdf",
  "size": "1260698",
  "createdAt": "Wed Aug 21 2024 19:16:52 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Site Details.jpeg",
  "filename": "1724248012738_Site_Details.jpeg",
  "path": "cases/66b491d7c884d1123344b689/
processingDocuments/1724248012738_Site_Details.jpeg",
  "size": "181237",
  "createdAt": "Wed Aug 21 2024 19:16:52 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sketch & Diamention.jpeg",
  "filename": "1724248012739_Sketch__Diamention.jpeg",
  "path": "cases/66b491d7c884d1123344b689/
processingDocuments/1724248012739_Sketch__Diamention.jpeg",
  "size": "103660",
  "createdAt": "Wed Aug 21 2024 19:16:52 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
```

```
    },
    {
      "originalName": "Society Notice.jpeg",
      "filename": "1724248012740_Society_Notice.jpeg",
      "path": "cases/66b491d7c884d1123344b689/
processingDocuments/1724248012740_Society_Notice.jpeg",
      "size": "153772",
      "createdAt": "Wed Aug 21 2024 19:16:52 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "60f915d3f3dd69653a592199",
        "role": "MAKER + RATE VERIFIER + CHEAKER",
        "firstName": "Shobha",
        "lastName": "Kuperkar",
        "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
      "_id": "66bc8024da840b1214c7438f",
      "note": "Rate verification done, pending for visit",
      "taskId": "66b49f88c884d1123344d068",
      "createdAt": "2024-08-14T10:00:04.928Z"
    }
  ],
  "createdAt": "2024-08-08T09:37:27.246Z",
  "updatedAt": "2024-08-22T11:34:11.472Z",
  "__v": 0,
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  "fullAddress": "Residential Flat No. 006, Ground Floor, Building No Q/1A, K. D. Saicon
Co-op. Hsg. Soc. Ltd., Opp. Don Bosco School, Village - Juchandra, Naigaon, Taluka -
Vasai, District - Palghar, Naigaon (East), PIN - 401 208, State - Maharashtra, India",
  "updatedBy": "60f915d3f3dd69653a592199",
  "addressForMap": "",
  "caseReferredBy": "62723addafd7d55eddeddfe4",
  "contactPersonName": "Mr. Eshan",
```



```
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Representative of Bank",
"siteVisitContactNo": "7985667423",
"briefDescOfProperty": "Living Room + Kitchen + Bathroom + WC + Passage",
"carpetTotal": "246.80",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "296.16",
"finalCarpetArea": "246.80",
"finalSalableArea": "296.16",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "All the above areas are within +/- 5% of the Agreement for Sale Area. The above calculations and detail measurements taken by us prove that the Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for Sale area.\n\n",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 260.00",
"reportGeneratedDate": "Thu Aug 22 2024 09:56:08 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-08-21",
"buildingServicesRate": "2500",
"flatRate": "6500",
"landOtherRate": "4000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
```

```

"lessorName": "",
"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'4"	15'4"	143.11
Kitchen	8'1"	7'1"	57.26
Bathroom	4'11"	4'00"	19.67
WC	2'11"	3'11"	11.42
Passage	3'11"	3'11"	15.34
Other Composition :			