

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Abhijit",
    "type": "CREDITOFFICER",
    "_id": "66581caa2611441081269f7e",
    "lastName": "Adsul",
    "mobileNo": "",
    "workMobileNo": "9833817601",
    "email": "abhijeet.adsul@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Abhijit",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": null,
"checker": null,
"valuers": []
},
"clientType": {
```

```
"label": "BANK",
"value": "BANK"
},
"location": {
  "latitude": "19.05303204480889",
  "longitude": "72.91205406188965"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.91205406188965,
    19.05303204480889
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "12/08/2024 05:50 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
}
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Borla",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "9",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Good Relations CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```

```
"status": true,
"name": "Wing",
"key": "wing",
"value": "C",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "902",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```



```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400088",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Govandi",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
```

```
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
```

```
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```

```
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66b9f27eda840b1214c5ea07",
"ownerName": "Satya Prabhat Prabhakar And Swastika Prabhakar",
"ownerPhoneNo": "9869045986",
"appAddress": "Flat no. 902, 9th Floor, Wing - C, Good Relations CHS, Gowandi ",
"remark": "Urgent Report.. Tomorrow Soft copy Required ",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66b9f27eda840b1214c5ea07/
document_1723462244280_1723462242920_Racpc_Sion_Satya_Prabhakar.pdf",
    "fileName":
"document_1723462244280_1723462242920_Racpc_Sion_Satya_Prabhakar.pdf",
```



```
"id": "503652",
"uploadedBy": "60b7177d2ffdf65bcd65882a",
"createdAt": "Mon Aug 12 2024 17:01:10 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010548",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
{
"id": "948165",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Mon Aug 12 2024 17:01:10 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Satya Prabhat Prabhakar And Swastika Prabhakar",
"phone": "9869045986",
"ownershipShare": "",
"email": "",
"id": "989418"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66bb1bd44388d81213f6f6df",
"name": "externalImg_1723538371210_1723538360281_image_0.jpeg",
"path": "cases/66b9f27eda840b1214c5ea07/externalImg_1723538371210_1723538360281_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66bb1bd44388d81213f6f6e0",
```

```
    "name": "externalImg_1723538382026_1723538368396_image_0.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externalImg_1723538382026_1723538368396_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66bb1bd44388d81213f6f6e1",
    "name": "externalImg_1723538386978_1723538368396_image_1.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externalImg_1723538386978_1723538368396_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f848",
    "name": "externalImg_1723538518310_1723538511504_image_0.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externalImg_1723538518310_1723538511504_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f849",
    "name": "externalImg_1723538519590_1723538511504_image_1.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externalImg_1723538519590_1723538511504_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f84a",
    "name": "externalImg_1723538520067_1723538511504_image_2.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externalImg_1723538520067_1723538511504_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f84b",
    "name": "externalImg_1723538520985_1723538511504_image_3.jpeg",
```

```
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538520985_1723538511504_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f84c",
    "name": "externallmg_1723538521843_1723538511504_image_4.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538521843_1723538511504_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f84d",
    "name": "externallmg_1723538522730_1723538511504_image_5.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538522730_1723538511504_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f84e",
    "name": "externallmg_1723538523847_1723538511504_image_6.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538523847_1723538511504_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f84f",
    "name": "externallmg_1723538524281_1723538511504_image_7.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538524281_1723538511504_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f850",
    "name": "externallmg_1723538525274_1723538511504_image_8.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538525274_1723538511504_image_8.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1c644388d81213f6f851",
  "name": "externallmg_1723538526297_1723538511504_image_9.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538526297_1723538511504_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1c644388d81213f6f852",
  "name": "externallmg_1723538527545_1723538511504_image_10.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538527545_1723538511504_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1c644388d81213f6f853",
  "name": "externallmg_1723538528186_1723538511504_image_11.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538528186_1723538511504_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1c644388d81213f6f854",
  "name": "externallmg_1723538528782_1723538511504_image_12.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538528782_1723538511504_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1c644388d81213f6f855",
  "name": "externallmg_1723538529434_1723538511504_image_13.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538529434_1723538511504_image_13.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f856",
    "name": "externallmg_1723538530339_1723538511504_image_14.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538530339_1723538511504_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1c644388d81213f6f857",
    "name": "externallmg_1723538531787_1723538511504_image_15.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538531787_1723538511504_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1cdec884d112334856e3",
    "name": "externallmg_1723538608120_1723538600925_image_0.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538608120_1723538600925_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1cdec884d112334856e4",
    "name": "externallmg_1723538608795_1723538600925_image_1.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538608795_1723538600925_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1cdec884d112334856e5",
    "name": "externallmg_1723538617525_1723538600925_image_2.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538617525_1723538600925_image_2.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1cdec884d112334856e6",
  "name": "externallmg_1723538624440_1723538600925_image_3.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538624440_1723538600925_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1cdec884d112334856e7",
  "name": "externallmg_1723538625714_1723538600925_image_4.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538625714_1723538600925_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1cdec884d112334856e8",
  "name": "externallmg_1723538627900_1723538600925_image_5.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538627900_1723538600925_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1cdec884d112334856e9",
  "name": "externallmg_1723538630215_1723538600925_image_6.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538630215_1723538600925_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1cdec884d112334856ea",
  "name": "externallmg_1723538630924_1723538600925_image_7.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538630924_1723538600925_image_7.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1cdec884d112334856eb",
    "name": "externallmg_1723538631484_1723538600925_image_8.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538631484_1723538600925_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1cdec884d112334856ec",
    "name": "externallmg_1723538632680_1723538600925_image_9.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538632680_1723538600925_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1cdec884d112334856ed",
    "name": "externallmg_1723538633085_1723538600925_image_10.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538633085_1723538600925_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1cdec884d112334856ee",
    "name": "externallmg_1723538633440_1723538600926_image_11.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538633440_1723538600926_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bb1cdec884d112334856ef",
    "name": "externallmg_1723538639235_1723538600926_image_12.jpeg",
    "path": "cases/66b9f27eda840b1214c5ea07/
externallmg_1723538639235_1723538600926_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66bb1cdec884d112334856f0",
  "name": "externalImg_1723538646176_1723538600926_image_13.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externalImg_1723538646176_1723538600926_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1cdec884d112334856f1",
  "name": "externalImg_1723538648770_1723538600926_image_14.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externalImg_1723538648770_1723538600926_image_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bb1cdec884d112334856f2",
  "name": "externalImg_1723538651100_1723538600926_image_15.jpeg",
  "path": "cases/66b9f27eda840b1214c5ea07/
externalImg_1723538651100_1723538600926_image_15.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-12T11:31:10.176Z",
"updatedAt": "2024-08-13T08:44:14.675Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 902, 9th Floor, Wing - C, Good Relations CHSL,
Village - Borla, Govandi, Mumbai, 400088",
"updatedBy": "648fcad91b499c2d52dc86f3",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Satya Prabhat Prabhakar And Swastika Prabhakar",
"email": "",
"isExternal": "false",
```


"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9869045986"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other
Composition :
