

```
{
  "typeOfReport": {
    "label": "Office",
    "value": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b89a"
    },
    "firstName": "ANAND",
    "type": "CREDITOFFICER",
    "_id": "661a1f7653f88c65a60d6f3f",
    "lastName": "KUMAR",
    "mobileNo": "",
    "workMobileNo": "9818588379",
    "email": "anandkumar1@sbi.co.in"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "150000000",
    "discussWithPerson": "ANAM MALIK",
    "expectedFees": 75000,
    "quotedAmount": "14000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b89a",
  "branchCode": "000106",
  "type": "BRANCH",
  "name": "Bassein Taluka Industrial Estate Branch",
  "email": "sbi.06839@sbi.co.in",
  "mobileNo": "02502456981",
  "alternateMobileNo": "",
  "address": "Bassein Taluka Industrial Estate Branch, Govrai Pada Vasai (East),\r
\nThane - 401 208, State - Maharashtra, Country - India.",
  "ledgerName": "STATE BANK OF INDIA - VASAI",
  "fax": "0250-2455149",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
```

```
},
```

```
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "MAKER",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
```

```
},
```

```
"rateVerifier": null,
```

```
"maker": null,
```

```
"checker": null,
```

```
"valuers": [
```

```
{
```

```
  "valuersRegistrationNumber": [
```

```
    {
```

```
      "value": "IBBI/RV/07/2018/10366",
```

```
      "label": "Registered Valuer"
```

```
    }
```

```
  ],
```

```
"type": "EMPLOYEE",
```

```
"_id": "5ffe92d27737ca4d986b6453",
```

```
"role": "VALUER",
```

```
"firstName": "Manoj",
```

```
"email": "manoj@vastukala.org",
```

```
"lastName": "Chalikwar",
```

```
"mobileNo": "9819597579",
```

```
"designation": "Registered Valuer",
```

```
"registrationNo": [
```

```
{
  "title": {
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
```

```
"latitude": "19.118536360443787",
"longitude": "72.87049830720139"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87049830720139,
    19.118536360443787
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "13/08/2024 04:05 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Mulgaon",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Akruiti Star",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Central Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "MIDC ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```

```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```



```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "1101-1102",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400069",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
  }
}
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```



```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66bb09c54388d81213f6dfe2",
"ownerName": "MRS KAVITA INDRAKUMAR SWAMI",
"ownerPhoneNo": "7045822842",
"appAddress": "OFFICE NO 1101 & 1102 11TH FLOOR AKRUTI STAR CENTRAL
ROAD MIDC ANDHERI EAST MUMBAI 400093",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66bb09c54388d81213f6dfe2/
document_1723533647126_1723533643296_1101_agreement.pdf",
    "fileName": "document_1723533647126_1723533643296_1101_agreement.pdf",
    "id": "729290",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Tue Aug 13 2024 12:52:45 GMT+0530 (India Standard Time)"
  },

```

```
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66bb09c54388d81213f6dfe2/
document_1723533690821_1723533688012_1102_agreement.pdf",
  "fileName": "document_1723533690821_1723533688012_1102_agreement.pdf",
  "id": "899923",
  "uploadedBy": "659ccce98f39506e83489828",
  "createdAt": "Tue Aug 13 2024 12:52:45 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Old Valuation Report ",
    "value": "60ae1296aa6d152c1801b455"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66bb09c54388d81213f6dfe2/
document_1723533717349_1723533714344_1101__1102_valuation_report.pdf",
  "fileName":
"document_1723533717349_1723533714344_1101__1102_valuation_report.pdf",
  "id": "729762",
  "uploadedBy": "659ccce98f39506e83489828",
  "createdAt": "Tue Aug 13 2024 12:52:45 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010565",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "368483",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Aug 13 2024 12:52:45 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "MRS KAVITA INDRAKUMAR SWAMI",
    "phone": "7045822842",
    "ownershipShare": "",
    "email": ""
  }
]
```

```
    "id": "963176"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66be41d7da840b1214c7854b",
    "name": "externalimg_1723744695974_1723744691918_image_0.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externalimg_1723744695974_1723744691918_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66be41d7da840b1214c7854c",
    "name": "externalimg_1723744698955_1723744691918_image_1.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externalimg_1723744698955_1723744691918_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66be41d7da840b1214c7854d",
    "name": "externalimg_1723744701239_1723744691918_image_2.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externalimg_1723744701239_1723744691918_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66be41d7da840b1214c7854e",
    "name": "externalimg_1723744704879_1723744691918_image_3.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externalimg_1723744704879_1723744691918_image_3.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66be41d7da840b1214c7854f",
  "name": "externallmg_1723744708391_1723744691918_image_4.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744708391_1723744691918_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66be41d7da840b1214c78550",
  "name": "externallmg_1723744711600_1723744691918_image_5.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744711600_1723744691918_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66be41d7da840b1214c78551",
  "name": "externallmg_1723744713146_1723744691918_image_6.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744713146_1723744691918_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66be41d7da840b1214c78552",
  "name": "externallmg_1723744714852_1723744691918_image_7.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744714852_1723744691918_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66be41d7da840b1214c78553",
  "name": "externallmg_1723744717346_1723744691918_image_8.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744717346_1723744691918_image_8.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66be41d7da840b1214c78554",
      "name": "externallmg_1723744719794_1723744691918_image_9.jpeg",
      "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744719794_1723744691918_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66be41d7da840b1214c78555",
      "name": "externallmg_1723744723504_1723744691918_image_10.jpeg",
      "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744723504_1723744691918_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66be41d90f117327db706d6e",
      "name": "externallmg_1723744681071_1723744652467_image_0.jpeg",
      "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744681071_1723744652467_image_0.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66be41d90f117327db706d6f",
      "name": "externallmg_1723744682354_1723744652467_image_1.jpeg",
      "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744682354_1723744652467_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66be41d90f117327db706d70",
      "name": "externallmg_1723744683362_1723744652467_image_2.jpeg",
      "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744683362_1723744652467_image_2.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66be41d90f117327db706d71",
  "name": "externallmg_1723744685849_1723744652467_image_3.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744685849_1723744652467_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66be41d90f117327db706d72",
  "name": "externallmg_1723744688032_1723744652467_image_4.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744688032_1723744652467_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66be41d90f117327db706d73",
  "name": "externallmg_1723744690217_1723744652467_image_5.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744690217_1723744652467_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66be41d90f117327db706d74",
  "name": "externallmg_1723744691776_1723744652467_image_6.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744691776_1723744652467_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66be41d90f117327db706d75",
  "name": "externallmg_1723744695182_1723744652468_image_7.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744695182_1723744652468_image_7.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66be41d90f117327db706d76",
    "name": "externallmg_1723744696745_1723744652468_image_8.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744696745_1723744652468_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66be41d90f117327db706d77",
    "name": "externallmg_1723744699438_1723744652468_image_9.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744699438_1723744652468_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66be41d90f117327db706d78",
    "name": "externallmg_1723744703281_1723744652468_image_10.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744703281_1723744652468_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66be41d90f117327db706d79",
    "name": "externallmg_1723744707837_1723744652468_image_11.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744707837_1723744652468_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66be41d90f117327db706d7a",
    "name": "externallmg_1723744708906_1723744652468_image_12.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744708906_1723744652468_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "66be41d90f117327db706d7b",
  "name": "externallmg_1723744713603_1723744652468_image_13.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744713603_1723744652468_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66be41d90f117327db706d7c",
  "name": "externallmg_1723744715599_1723744652468_image_14.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744715599_1723744652468_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66be41d90f117327db706d7d",
  "name": "externallmg_1723744717362_1723744652468_image_15.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744717362_1723744652468_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66be41d90f117327db706d7e",
  "name": "externallmg_1723744719841_1723744652468_image_16.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744719841_1723744652468_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66be41d90f117327db706d7f",
  "name": "externallmg_1723744723279_1723744652468_image_17.jpeg",
  "path": "cases/66bb09c54388d81213f6dfe2/
externallmg_1723744723279_1723744652468_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```



```
    "_id": "66be41d90f117327db706d80",
    "name": "externalimg_1723744725049_1723744652468_image_18.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externalimg_1723744725049_1723744652468_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66be41d90f117327db706d81",
    "name": "externalimg_1723744727222_1723744652468_image_19.jpeg",
    "path": "cases/66bb09c54388d81213f6dfe2/
externalimg_1723744727222_1723744652468_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-13T07:22:45.833Z",
"updatedAt": "2024-08-15T17:58:49.008Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Office No. 1101-1102, 11th Floor, Akruiti Star, Central Road,
MIDC , Village - Mulgaon, Andheri East, Mumbai, 400069",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "MRS KAVITA INDRAKUMAR SWAMI",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7045822842"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			