

```
{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b800"
    },
    "firstName": "Krushna ",
    "type": "CREDITOFFICER",
    "_id": "65ba192e6635d840ef56c043",
    "lastName": "Dhanvij",
    "mobileNo": "",
    "workMobileNo": "8600786009",
    "email": "sbi.15521@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5489000",
    "discussWithPerson": "Krushna ",
    "expectedFees": 2744.5,
    "quotedAmount": ""
  },
}
```

```

"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b800",
  "branchCode": "000073",
  "type": "BRANCH",
  "name": "SME Credit Centre Borivali (West)",
  "email": "sbi.15781@sbi.co.in",
  "mobileNo": "022-28954966",
  "alternateMobileNo": "",
  "address": "SME Centre Borivali (15521) 101, 1st floor,
Landmark Building, S. V. Road, Near Petrol Pump, Borivali (West), Mumbai – 400 092,
State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA-SMECCC BORIVALI",
  "fax": "022-28909092",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {

```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "MAKER",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.189655358349274",
  "longitude": "72.8382354103234"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.8382354103234,
19.189655358349274
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-16",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-16",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Valnai",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Jaswanti Allied Business Centre Premises Co-Op. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Ramchandra Lane Extension Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Malad Industrial Estate, Kanchpada",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "A",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "351, 353, 354, 354/1 to 3 & 348C",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "712",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "P/North",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 064",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Malad (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Glass_Facade_Windows",
    "label": "Glass Facade Windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Industrial Units CHSL",
  "west": "Mahaveer Industrial Estate ",
  "south": "Ramchandra Lane Road ",
  "east": "Slum Area"
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Passage / Lift",
    "east": "Unit No. 701",
    "south": "Unit No. 711",
    "west": "Marginal Space "
  }
},
"asPerDocument": {
  "north": "Details not available ",
  "east": "Details not available ",
  "south": "Details not available ",
  "west": "Details not available "
},
"isDisplay": true,
"title": "Boundaries of The Flat"
```

```
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "The Composition of Industrial Unit is Working Area + Cabin
+ Pantry + 1 Toilet + Loft Area. The Height of Loft is 5 to 5.5 Ft.",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "13.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "21122",
  "depreciatedBuildingRate": "2422"
},
"igrRate": {
  "propertyName": "Office",
  "rate": "190760",
  "landRate": "76250",
  "igrImage": "cases/66bc8adbda840b1214c753e0/igr_1723896113577_Image.png",
  "squareMeterGuideLineRate": "200298.00",
  "squareFeetGuideLineRate": "18608.00"
},
"igrFinalRate": {
```

```
"floorRatePercentage": "5",
"depreciationPercentage": "91",
"rate": "17571.00",
"squareFeetGuideLineRate": "17571.00",
"squareMeterGuideLineRate": "189134.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Industrial",
    "label": "Industrial"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MCGM norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  }
}
```

```
},
"carParking": "Open / Covered Car Parking Space ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2015",
  "fullDate": "1/1/2015"
},
"planningArea": {
  "value": "Industrial",
  "label": "Industrial"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
```

```
"label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Previous_valuation_Report",
  "label": "As Per Previous valuation Report"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "51",
"ageOfBuilding": "9",
```



```
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "8",
"flatFloorNo": "7",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "19"
},
"finalPlinthArea": {
  "area": "300.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66bc8adbda840b1214c753e0/
routeMap_1724131885013_Image.png",
    "routeLat": "19.189583",
    "routeLng": "72.838333",
    "stationName": "Malad West",
    "routeDistance": "650 Mtrs. ",
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "7a4gi4",
    "name": "7a4gi4",
    "image": "cases/66bc8adbda840b1214c753e0/
routeMap_1724131687811_Image.png"
  }
]
```

```
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "6336600.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "6336600.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5271300.00",
  "selectedBuildUpValue": "300.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66bf7f59da840b1214c82b24",
      "name": "externalImg_1723825986787_1723825972682_image_1.jpeg",
      "path": "cases/66bc8adbda840b1214c753e0/
externalImg_1723825986787_1723825972682_image_1.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "66bf7f5ada840b1214c82b4d",
    "name": "externallmg_1723826001072_1723825990120_image_1.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723826001072_1723825990120_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf7f5ada840b1214c82b4c",
    "name": "externallmg_1723825997304_1723825990120_image_0.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825997304_1723825990120_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf7f5ada840b1214c82b4e",
    "name": "externallmg_1723826002456_1723825990120_image_2.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723826002456_1723825990120_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf7f5ada840b1214c82b4f",
    "name": "externallmg_1723826003395_1723825990120_image_3.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723826003395_1723825990120_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf7f59da840b1214c82b24",
    "name": "externallmg_1723825986787_1723825972682_image_1.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825986787_1723825972682_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf7f5ada840b1214c82b50",
```

```
    "name": "externallmg_1723826007364_1723825990120_image_4.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723826007364_1723825990120_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf7f59da840b1214c82b28",
    "name": "externallmg_1723825990946_1723825972682_image_5.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825990946_1723825972682_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf7f59da840b1214c82b29",
    "name": "externallmg_1723825990990_1723825972682_image_6.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825990990_1723825972682_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf7f59da840b1214c82b27",
    "name": "externallmg_1723825990402_1723825972682_image_4.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825990402_1723825972682_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf7f59da840b1214c82b2f",
    "name": "externallmg_1723825997144_1723825972682_image_12.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825997144_1723825972682_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf7f59da840b1214c82b31",
    "name": "externallmg_1723826002668_1723825972682_image_14.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723826002668_1723825972682_image_14.jpeg",
    "orientation": "portrait"
  }
],
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "22143.00",
    "max": "33558.00"
  },
  "builtUpRateRange": {
    "min": "18453.00",
    "max": "27965.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "300.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
```

```
"invoiceIds": [],
"paymentIds": [],
"_id": "66bc8adbda840b1214c753e0",
"ownerName": "Smt. Minal Hemant Mhatre & Shri. Hemant Pralhad Mhatre ",
"ownerPhoneNo": "9867562025",
"appAddress": "Unit no 712 7 th Floor A-wing Jaswanti Allied Business Centre
Ramchandra lean Extension Road Near Malad Industrial Estate Kanchpada Malad
West Mumbai 400064",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "652d16a0316e1359cebd3c15",
      "label": " Agreement"
    },
    "inputs": {
      "documentDate": "25/07/2015",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Ashray Investments",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Smt. Minal Hemant Mhatre & Shri. Hemant Pralhad Mhatre ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "5821 / 132"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "747320",
    "path": "cases/66bc8adbda840b1214c753e0/
document_1723632202565_1723632198623_Minal_Mhatre_Agreement.pdf",
    "fileName":
"document_1723632202565_1723632198623_Minal_Mhatre_Agreement.pdf"
  },
  {
    "documentType": {
      "value": "60ae1279aa6d152c1801b3d4",
      "label": "Amended Commencement Certificate"
    },
  },

```

```
"inputs": {
  "documentDate": "20/04/2018",
  "nameOfApprovingAuthority": {
    "value": "Municipal_Corporation_of_Greater_Mumbai",
    "label": "Municipal Corporation of Greater Mumbai"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "CHE / 9730 / BP(WS) / AP"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1724127203246_429249.pdf",
"path": "cases/66bc8adbda840b1214c753e0/
document_1724127203246_429249.pdf",
"id": "615328",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Aug 20 2024 09:43:23 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "17/08/2021",
    "remark": " in the name of Smt. Minal Hemant Mhatre & Shri. Hemant Pralhad
Mhatre issued by Vastukala Consultants Pvt. Ltd\n"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724127295966_previous_report.pdf",
  "path": "cases/66bc8adbda840b1214c753e0/
document_1724127295966_previous_report.pdf",
  "id": "483864",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Aug 20 2024 09:44:56 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
```

```
"documentDate": "01/01/2018",
"remark": " issued by Jaswanti Allied Business Centre Premises Co-Op. Soc. Ltd",
"to": {
  "value": "Purchasers",
  "label": "Purchasers"
},
"Purchasers": "Smt. Minal Hemant Mhatre & Shri. Hemant Pralhad Mhatre ",
"number": {
  "value": "No",
  "label": "No"
},
"No": "058"
},
"isHardCopy": false,
"displayStatus": false,
"id": "857844",
"path": "cases/66bc8adbda840b1214c753e0/
document_1724128312535_539478.pdf",
"fileName": "document_1724128312535_539478.pdf"
}
],
"caseNumber": "010597",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "138395",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Aug 14 2024 16:15:47 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Smt. Minal Hemant Mhatre & Shri. Hemant Pralhad Mhatre ",
    "phone": "9867562025",
    "ownershipShare": "",
    "email": "",
    "id": "732690"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "434135",
  "name": "Working Area",
  "length": "17.92",
  "length1": "17",
  "length2": "11",
  "width": "10.25",
  "width1": "10",
  "width2": "3",
  "totalArea": "183.65",
  "images": [],
  "extraAreas": [],
  "finalArea": "183.65"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Loft",
      "value": "Loft"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "10.25",
    "length1": "10",
    "length2": "3",
    "width": "10.67",
    "width1": "10",
    "width2": "8",
    "totalArea": "109.33",
    "images": [],
    "extraAreas": [],
    "finalArea": "109.33",
    "percentageBeforeTotal": "109.33",
    "percentage": "100"
  }
],
"externalReport": [],
```

```
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "17.19",
    "totalAreaDocument": "185",
    "docBultupPercentage": "20",
    "docFinalBultUp": "222.00",
    "docFinalBultUpSquareMeter": "20.62",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "953988"
  },
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "27.87",
    "totalAreaDocument": "300",
    "docBultupPercentage": "",
    "docFinalBultUp": "0.00",
    "docFinalBultUpSquareMeter": "0.00",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "229944"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
```

```
"area": "333.33",
"squareMeterArea": "30.97",
"expectedRate": "32400.32",
"percentage": ""
},
"builtUpArea": {
"area": "400.00",
"squareMeterArea": "37.16",
"expectedRate": "27000.00",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66c091b50f117327db71ac65",
"property": "Office",
"area": "400",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "10800000",
"expectedRate": "32400.32",
"builtUpExpectedRate": "10800000",
"image": "cases/66bc8adbda840b1214c753e0/
indicator_1723895903181_Image.png",
"squareMeter": "37.16",
"id": "542504"
},
{
"carpetArea": {
"area": "280.00",
"squareMeterArea": "26.01",
"expectedRate": "22142.86",
"percentage": ""
},
"builtUpArea": {
"area": "336.00",
"squareMeterArea": "31.22",
"expectedRate": "18452.38",
```



```
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66c091b50f117327db71ac66",
  "property": "Office",
  "area": "336",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "6200000",
  "expectedRate": "22142.86",
  "builtUpExpectedRate": "6200000",
  "image": "cases/66bc8adbda840b1214c753e0/
indicator_1723895965257_Image.png",
  "squareMeter": "31.22",
  "id": "782326"
},
{
  "carpetArea": {
    "area": "399.17",
    "squareMeterArea": "37.08",
    "expectedRate": "23786.86",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "479.00",
    "squareMeterArea": "44.50",
    "expectedRate": "19822.55",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
```

```
"_id": "66c091b50f117327db71ac67",
"property": "Office",
"area": "479",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "9495000",
"expectedRate": "23786.86",
"builtUpExpectedRate": "9495000",
"image": "cases/66bc8adbda840b1214c753e0/
indicator_1723896013852_Image.png",
"squareMeter": "44.50",
"id": "817063"
},
{
  "carpetArea": {
    "area": "372.50",
    "squareMeterArea": "34.61",
    "expectedRate": "33557.05",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "447.00",
    "squareMeterArea": "41.53",
    "expectedRate": "27964.21",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66c42facda840b1214c98412",
  "property": "Office",
  "area": "447",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
```

```
    "expectedPrice": "12500000",
    "expectedRate": "33557.05",
    "builtUpExpectedRate": "12500000",
    "image": "cases/66bc8adbda840b1214c753e0/
indicator_1724133292774_Image.png",
    "squareMeter": "41.53",
    "id": "882017"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf7f5ada840b1214c82b4c",
    "name": "externalImg_1723825997304_1723825990120_image_0.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externalImg_1723825997304_1723825990120_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf7f5ada840b1214c82b4d",
    "name": "externalImg_1723826001072_1723825990120_image_1.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externalImg_1723826001072_1723825990120_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf7f5ada840b1214c82b4e",
    "name": "externalImg_1723826002456_1723825990120_image_2.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externalImg_1723826002456_1723825990120_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf7f5ada840b1214c82b4f",
    "name": "externalImg_1723826003395_1723825990120_image_3.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externalImg_1723826003395_1723825990120_image_3.jpeg",
    "orientation": "portrait"
  },
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bf7f5ada840b1214c82b50",
  "name": "externallmg_1723826007364_1723825990120_image_4.jpeg",
  "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723826007364_1723825990120_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66bf7f59da840b1214c82b23",
  "name": "externallmg_1723825985779_1723825972681_image_0.jpeg",
  "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825985779_1723825972681_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66bf7f59da840b1214c82b24",
  "name": "externallmg_1723825986787_1723825972682_image_1.jpeg",
  "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825986787_1723825972682_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66bf7f59da840b1214c82b25",
  "name": "externallmg_1723825988364_1723825972682_image_2.jpeg",
  "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825988364_1723825972682_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66bf7f59da840b1214c82b26",
  "name": "externallmg_1723825989944_1723825972682_image_3.jpeg",
  "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825989944_1723825972682_image_3.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66bf7f59da840b1214c82b27",
    "name": "externallmg_1723825990402_1723825972682_image_4.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825990402_1723825972682_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66bf7f59da840b1214c82b28",
    "name": "externallmg_1723825990946_1723825972682_image_5.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825990946_1723825972682_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66bf7f59da840b1214c82b29",
    "name": "externallmg_1723825990990_1723825972682_image_6.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825990990_1723825972682_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66bf7f59da840b1214c82b2a",
    "name": "externallmg_1723825992355_1723825972682_image_7.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825992355_1723825972682_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66bf7f59da840b1214c82b2b",
    "name": "externallmg_1723825993351_1723825972682_image_8.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825993351_1723825972682_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "66bf7f59da840b1214c82b2c",
  "name": "externallmg_1723825993560_1723825972682_image_9.jpeg",
  "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825993560_1723825972682_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66bf7f59da840b1214c82b2d",
  "name": "externallmg_1723825994703_1723825972682_image_10.jpeg",
  "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825994703_1723825972682_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66bf7f59da840b1214c82b2e",
  "name": "externallmg_1723825996291_1723825972682_image_11.jpeg",
  "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825996291_1723825972682_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66bf7f59da840b1214c82b2f",
  "name": "externallmg_1723825997144_1723825972682_image_12.jpeg",
  "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825997144_1723825972682_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66bf7f59da840b1214c82b30",
  "name": "externallmg_1723825998906_1723825972682_image_13.jpeg",
  "path": "cases/66bc8adbda840b1214c753e0/
externallmg_1723825998906_1723825972682_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "66bf7f59da840b1214c82b31",
    "name": "externalimg_1723826002668_1723825972682_image_14.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externalimg_1723826002668_1723825972682_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66bf7f59da840b1214c82b32",
    "name": "externalimg_1723826005327_1723825972682_image_15.jpeg",
    "path": "cases/66bc8adbda840b1214c753e0/
externalimg_1723826005327_1723825972682_image_15.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2) - minal.xlsx",
    "filename": "1723896235749_Calculation_2__minal.xlsx",
    "path": "cases/66bc8adbda840b1214c753e0/
processingDocuments/1723896235749_Calculation_2__minal.xlsx",
    "size": "16069",
    "createdAt": "Sat Aug 17 2024 17:33:56 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1723896235750_igr1.pdf",
    "path": "cases/66bc8adbda840b1214c753e0/
processingDocuments/1723896235750_igr1.pdf",
    "size": "147881",
    "createdAt": "Sat Aug 17 2024 17:33:56 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
    "filename": "1723896235766_igr2.pdf",
    "path": "cases/66bc8adbda840b1214c753e0/
processingDocuments/1723896235766_igr2.pdf",
    "size": "157039",
    "createdAt": "Sat Aug 17 2024 17:33:56 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
```

```
"originalname": "igr3.pdf",
"filename": "1723896235779_igr3.pdf",
"path": "cases/66bc8adbda840b1214c753e0/
processingDocuments/1723896235779_igr3.pdf",
"size": "156608",
"createdAt": "Sat Aug 17 2024 17:33:56 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
"originalname": "igr4.pdf",
"filename": "1723896235793_igr4.pdf",
"path": "cases/66bc8adbda840b1214c753e0/
processingDocuments/1723896235793_igr4.pdf",
"size": "157646",
"createdAt": "Sat Aug 17 2024 17:33:56 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
"originalname": "Summary - minal.xlsx",
"filename": "1723896235805_Summary__minal.xlsx",
"path": "cases/66bc8adbda840b1214c753e0/
processingDocuments/1723896235805_Summary__minal.xlsx",
"size": "2383171",
"createdAt": "Sat Aug 17 2024 17:33:56 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"lastName": "Sarmalkar",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "66c084c80f117327db719b9e",
"note": "value shared",
"taskId": "66bc9407da840b1214c75f2e",
"createdAt": "2024-08-17T11:08:56.152Z"
```



```
}
],
"createdAt": "2024-08-14T10:45:47.372Z",
"updatedAt": "2024-08-20T06:06:26.497Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Industrial Unit No. 712, 7th Floor, Wing - A, Jaswanti Allied Business
Centre Premises Co-Op. Soc. Ltd. , CTS No. 351, 353, 354, 354/1 to 3 & 348C,
Ramchandra Lane Extension Road, Near Malad Industrial Estate, Kanchpada, Village -
Valnai, Municipality Ward No. P/North, Malad (West), Taluka - Borivali, District - Mumbai
Suburban , PIN - 400 064, State - Maharashtra, Country - India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Shri. Hemant Pralhad Mhatre \n",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9867562025",
"buildingServicesRate": "2800",
"finalAreaType": "Built Up Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 300.00",
"flatRate": "21500",
"landOtherRate": "18700",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"siteVisitDate": "2024-08-16",
"builtupPercentage": "10",
"carpetTotal": "183.65",
"extendOfSiteRemark": "",
"finalBuiltupArea": "322.28",
"finalCarpetArea": "292.98",
```

```

"finalSalableArea": "354.51",
"otherCarpetTotal": "109.33",
"salablePercentage": "10",
"siteMeasurementRemark": "Built Up Area in Sq. Ft. = 184.00\nLoft Area in Sq. Ft. =
79.00 (70% of 113.00 Sq. Ft.)\n\n",
"toBeAdded": "",
"briefDescOfProperty": "Working Area",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "109.33",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Tue Aug 20 2024 09:38:01 GMT+0530 (India Standard Time)"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Working Area	17'11"	10'3"	183.65
Other Composition :			
Loft	10'3"	10'8"	109.33