

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b99c"
    },
    "firstName": "Manisha",
    "type": "CREDITOFFICER",
    "_id": "667e7ffaaf848d643f6b387d",
    "email": "manisha.deshmukh@cosmosbank.in",
    "lastName": "Deshmukh",
    "mobileNo": "",
    "workMobileNo": "8655333687"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6456455",
    "discussWithPerson": "Manisha",
    "expectedFees": 3228.2275,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b99c",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Dadar Branch ",
  "email": "dadar@cosmosbank.in",
  "mobileNo": "02224476018",
  "alternateMobileNo": "8369167372",
  "address": "Horizon Bldg.,1st Floor, Ranade Road & Gokhale Road, Dadar (West),
Mumbai - 400 028, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK - DADAR",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
```

```
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.261815408644587",
  "longitude": "73.12462466449405"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.12462466449405,
```

```
19.261815408644587
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-16",
      "remark": "tomorrow evening soft copy "
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-17",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Wadeghar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "12",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "C Type",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Punyodaya Park C2 Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```



```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C2",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "65, Hissa No. 8, 75, Hissa No. 1, 2 (Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```

```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1201",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "8A",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 301",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kalyan (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  }
}
```

```
    },
    "fittings": {
      "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
      "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
    },
    "finishing": {
      "value": "Cement_Plastering",
      "label": "Cement Plastering"
    }
  },
  "general": {
    "ownership": {
      "value": "Joint_Ownership",
      "label": "Joint Ownership"
    },
    "populationClassList": {
      "value": "MiddleClass",
      "label": "Middle Class"
    },
    "populationGroupList": {
      "value": "Urban",
      "label": "Urban"
    },
    "townplanApprovedByList": {
      "value": "Kalyan_Dombivali_Municipal_Corporation",
      "label": "Kalyan Dombivali Municipal Corporation"
    },
    "whetherCoveredUnderAnyState": {
      "value": "No",
      "label": "No"
    },
    "asPerActualAgreement": {
      "north": "Internal Road & Sai Satyam Residency",
      "west": "Mangla Prastha CHSL",
      "south": "Internal Road",
      "east": "Punyodaya Park B1 B2 B3 CHSL"
    },
    "asPerDocumentAgreement": {
      "north": "-",
      "west": "-",
      "south": "-",
      "east": "-"
    },
    "unitBoundaries": {
      "asPerActual": {
```

```
"north": "-",
"east": "-",
"south": "-",
"west": "-"
},
"asPerDocument": {
  "north": "-",
  "east": "-",
  "south": "-",
  "west": "-"
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": true
  },
  "auto": {
    "title": "Auto",
    "status": true
  },
  "privateCars": {
    "title": "Private Cars",
    "status": true
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Part Occupancy Certificate Document No.
KDMC / NRV / CC / KV / 199 dated 10.08.2011 issued by Kalyan Dombivli Municipal
Corporation",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"classOfSanitary": {
  "value": "ordinary",
  "label": "Ordinary"
},
"compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
},
```

```
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "19.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "546",
  "depreciatedCostOfConstruction": "9654.00",
  "depreciatedBuildingRate": "2254"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "70100",
  "landRate": "14000",
  "igrImage": "cases/66bf1f05da840b1214c7f39d/igr_1723880580387_Image.png",
  "squareMeterGuideLineRate": "77110.00",
  "squareFeetGuideLineRate": "7164.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "87",
  "rate": "6402.00",
  "squareFeetGuideLineRate": "6402.00",
  "squareMeterGuideLineRate": "68906.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "15,000/- Present rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
```

```
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KDMC norms",
"tenantName": "Prakash Deshmukh",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2011",
    "fullDate": "1/1/2011"
  },
}
```

```
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
```



```
"label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "13",
"totalLifeBuilding": "60",
"estimatedAge": "47",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "15",
"flatFloorNo": "12",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66bf1f05da840b1214c7f39d/
routeMap_1723891881037_Image.png",
    "routeLat": "19.261537",
```

```
"routeLng": "73.124673",
"stationName": "Kalyan",
"routeDistance": "4.1 Km.",
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "rva1u",
    "name": "rva1u",
    "image": "cases/66bf1f05da840b1214c7f39d/
routeMap_1723891820083_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "2436000.00",
    "depreciationPercentage": "19.5",
    "depreciatedCostOfConstruction": "475020.00",
    "totalFairMarketValue": "6919980.00"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "7395000.00",
"finalValue": "7395000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "5569740.00",
"selectedBuildUpValue": "870.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "66bf38c5da840b1214c81225",
"name": "externallmg_r_1723807940105_1723807925573_image_18.jpg",
"path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807940105_1723807925573_image_18.jpg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
{
"status": false,
"_id": "66bf38c5da840b1214c8121e",
"name": "externallmg_r_1723807936366_1723807925573_image_11.jpg",
"path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807936366_1723807925573_image_11.jpg",
"orientation": "portrait"
}
],
"externalPhotos": [
{
"status": false,
"_id": "66bf38d4da840b1214c81246",
"name": "externallmg_r_1723807954484_1723807953802_image_0.jpg",
"path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807954484_1723807953802_image_0.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf38c5da840b1214c81222",
    "name": "externallmg_r_1723807938566_1723807925573_image_15.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807938566_1723807925573_image_15.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "66bf38c5da840b1214c81223",
    "name": "externallmg_r_1723807939610_1723807925573_image_17.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807939610_1723807925573_image_17.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "66bf38c5da840b1214c81214",
    "name": "Bedroom",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807932885_1723807925573_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf38c5da840b1214c81217",
    "name": "Bedroom",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807931361_1723807925573_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66bf38c5da840b1214c8121a",
    "name": "Bedroom",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807934141_1723807925573_image_7.jpg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "66bf38c5da840b1214c8121c",
      "name": "Bedroom",
      "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807935370_1723807925573_image_9.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66bf38c5da840b1214c8121d",
      "name": "Bedroom",
      "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807935895_1723807925573_image_10.jpg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9247.00",
    "max": "11286.00"
  },
  "builtUpRateRange": {
    "min": "7706.00",
    "max": "9405.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
```

```
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "725.00",
"empanelmentNo": [
  "HO/CREDIT/67/ 2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66bf1f05da840b1214c7f39d",
"ownerName": "Shekhar Chintaman Zemse & Kavita Shekhar Zemse",
"ownerPhoneNo": "9820943010",
"appAddress": "flat no 1201,12th floor, Bldg - c type, C-2 wing, Bldg Name -
punyodaya park village - wadeghar, Kalyan ",
"remark": "tomorrow evening soft copy ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "06/08/2012",
      "remark": "(8 Pages from Documents)",
      "from": {
        "value": "Builder",
        "label": "Builder"
      },
      "Builder": "M/s. Vastusankalp Developers",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Shekhar Chintaman Zemse & Kavita Shekhar Zemse",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  }
],
```

```
    "Document_No": "5796/2012"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "306840",
  "path": "cases/66bf1f05da840b1214c7f39d/document_1723801334633_57180.pdf",
  "fileName": "document_1723801334633_57180.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "KDMC / NRV / CC / KV / 199 dated 10.08.2011"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1723892588000_91133.pdf",
  "path": "cases/66bf1f05da840b1214c7f39d/document_1723892588000_91133.pdf",
  "id": "511217",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Sat Aug 17 2024 16:33:08 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010626",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "484461",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Aug 16 2024 15:12:29 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shekhar Chintaman Zemse & Kavita Shekhar Zemse",
```

```
"phone": "9820943010",
"ownershipShare": "",
"email": "",
"id": "676269"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "527616",
"name": "Bedroom",
"length": "14.00",
"length1": "14",
"length2": "00",
"width": "12.00",
"width1": "12",
"width2": "00",
"totalArea": "168.00",
"images": [],
"extraAreas": [],
"finalArea": "168.00"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Passage",
"length": "14.67",
"length1": "14",
"length2": "8",
"width": "3.17",
"width1": "3",
"width2": "2",
"totalArea": "46.44",
"images": [],
"extraAreas": [],
"finalArea": "46.44"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "2",
"name": "Bedroom",
"length": "11.17",
"length1": "11",
"length2": "2",
"width": "10.17",
"width1": "10",
"width2": "2",
"totalArea": "113.53",
"images": [],
"extraAreas": [],
"finalArea": "113.53"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "3.08",
  "length1": "3",
  "length2": "1",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "12.85",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.85"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
  "width": "6.50",
```

```
"width1": "6",
"width2": "6",
"totalArea": "27.62",
"images": [],
"extraAreas": [],
"finalArea": "27.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "10.17",
  "length1": "10",
  "length2": "2",
  "width": "10.25",
  "width1": "10",
  "width2": "3",
  "totalArea": "104.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "104.21"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Living Room",
  "length": "18.67",
  "length1": "18",
  "length2": "8",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "186.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "186.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "9.42",
  "width1": "9",
  "width2": "5",
  "totalArea": "39.24",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.24"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "13.50",
  "length1": "13",
  "length2": "6",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "27.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "27",
  "percentageBeforeTotal": "27.00",
  "percentage": "100"
},
{
  "toBeAdded": {
```



```
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "3.42",
  "length1": "3",
  "length2": "5",
  "width": "1.42",
  "width1": "1",
  "width2": "5",
  "totalArea": "4.84",
  "images": [],
  "extraAreas": [],
  "finalArea": "4.84",
  "percentageBeforeTotal": "4.84",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "2.08",
  "length1": "2",
  "length2": "1",
  "width": "4.50",
  "width1": "4",
  "width2": "6",
  "totalArea": "9.37",
```

```
"images": [],
"extraAreas": [],
"finalArea": "9.37",
"percentageBeforeTotal": "9.37",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length": "4.50",
  "length1": "4",
  "length2": "6",
  "width": "2.17",
  "width1": "2",
  "width2": "2",
  "totalArea": "9.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "9.75",
  "percentageBeforeTotal": "9.75",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "4",
"length": "11.08",
"length1": "11",
"length2": "1",
"width": "2.00",
"width1": "2",
"width2": "00",
"totalArea": "22.17",
"images": [],
"extraAreas": [],
"finalArea": "22.17",
"percentageBeforeTotal": "22.17",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
},
"id": "5",
"length": "10.25",
"length1": "10",
"length2": "3",
"width": "2.00",
"width1": "2",
"width2": "00",
"totalArea": "20.50",
"images": [],
"extraAreas": [],
"finalArea": "20.5",
"percentageBeforeTotal": "20.50",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
},
```

```
"name": {
  "label": "Flowerbed",
  "value": "Flowerbed"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "6",
"length": "10.00",
"length1": "10",
"length2": "00",
"width": "2.00",
"width1": "2",
"width2": "00",
"totalArea": "20.00",
"images": [],
"extraAreas": [],
"finalArea": "20",
"percentageBeforeTotal": "20.00",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "862575",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "725",
    "squareMeterArea": "67.35",
    "docFinalBuiltUp": "870",
    "docFinalBuiltUpSquareMeter": "80.82",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "600.00",
      "squareMeterArea": "55.74",
      "expectedRate": "10000.00",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "720.00",
      "squareMeterArea": "66.89",
      "expectedRate": "8333.33",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "66c0568c0f117327db71627c",
    "property": "Vastusankalp Punyodaya Park, Chanakya Nagar, Kalyan West, Thane",
    "area": "600",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "https://www.99acres.com/",
    "expectedPrice": "6000000.00",
    "expectedRate": "10000.00",
    "builtUpExpectedRate": "8333.33",
    "image": "cases/66bf1f05da840b1214c7f39d/
indicator_1723880112802_Image.png",
    "squareMeter": "55.74",
    "id": "554913"
  },
  {
    "carpetArea": {
      "area": "568.00",
      "squareMeterArea": "52.77",
      "expectedRate": "9246.48",
      "percentage": ""
    },
  },

```

```
"builtUpArea": {
  "area": "681.60",
  "squareMeterArea": "63.32",
  "expectedRate": "7705.40",
  "percentage": "20"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "66c0568c0f117327db71627d",
"property": "Punyodaya Park, Chanakya Nagar, Kalyan West, Thane",
"area": "568.00",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "5252000.00",
"expectedRate": "9246.48",
"builtUpExpectedRate": "7705.40",
"image": "cases/66bf1f05da840b1214c7f39d/
indicator_1723880232970_Image.png",
"squareMeter": "52.77",
"id": "208253"
},
{
  "carpetArea": {
    "area": "400.00",
    "squareMeterArea": "37.16",
    "expectedRate": "9750.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "480.00",
    "squareMeterArea": "44.59",
    "expectedRate": "8125.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
```

```
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66c0568c0f117327db71627e",
  "property": "Punyodaya Park, Chanakya Nagar, Kalyan West, Thane",
  "area": "400",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "3900000.00",
  "expectedRate": "9750.00",
  "builtUpExpectedRate": "8125.00",
  "image": "cases/66bf1f05da840b1214c7f39d/
indicator_1723880273001_Image.png",
  "squareMeter": "37.16",
  "id": "141981"
},
{
  "carpetArea": {
    "area": "700.00",
    "squareMeterArea": "65.03",
    "expectedRate": "11285.71",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "840.00",
    "squareMeterArea": "78.04",
    "expectedRate": "9404.76",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66c0568c0f117327db71627f",
  "property": "Padmashree Mangla Prastha, Gauripada, Kalyan West, Thane",
  "area": "700.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
```

```
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "7900000.00",
"expectedRate": "11285.71",
"builtUpExpectedRate": "9404.76",
"image": "cases/66bf1f05da840b1214c7f39d/
indicator_1723880987765_Image.png",
"squareMeter": "65.03",
"id": "425033"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66bf38c5da840b1214c81213",
"name": "externalImg_1723807930961_1723807925573_image_1.png",
"path": "cases/66bf1f05da840b1214c7f39d/
externalImg_1723807930961_1723807925573_image_1.png",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66bf38c5da840b1214c81214",
"name": "externalImg_r_1723807932885_1723807925573_image_4.jpg",
"path": "cases/66bf1f05da840b1214c7f39d/
externalImg_r_1723807932885_1723807925573_image_4.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66bf38c5da840b1214c81215",
"name": "externalImg_r_1723807932281_1723807925573_image_3.jpg",
"path": "cases/66bf1f05da840b1214c7f39d/
externalImg_r_1723807932281_1723807925573_image_3.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66bf38c5da840b1214c81216",
"name": "externalImg_r_1723807928440_1723807925573_image_0.jpg",
```



```
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807928440_1723807925573_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf38c5da840b1214c81217",
    "name": "externallmg_r_1723807931361_1723807925573_image_2.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807931361_1723807925573_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf38c5da840b1214c81218",
    "name": "externallmg_r_1723807933120_1723807925573_image_5.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807933120_1723807925573_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf38c5da840b1214c81219",
    "name": "externallmg_r_1723807933571_1723807925573_image_6.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807933571_1723807925573_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf38c5da840b1214c8121a",
    "name": "externallmg_r_1723807934141_1723807925573_image_7.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807934141_1723807925573_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf38c5da840b1214c8121b",
    "name": "externallmg_r_1723807934835_1723807925573_image_8.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807934835_1723807925573_image_8.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf38c5da840b1214c8121c",
    "name": "externallmg_r_1723807935370_1723807925573_image_9.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807935370_1723807925573_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf38c5da840b1214c8121d",
    "name": "externallmg_r_1723807935895_1723807925573_image_10.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807935895_1723807925573_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf38c5da840b1214c8121e",
    "name": "externallmg_r_1723807936366_1723807925573_image_11.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807936366_1723807925573_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf38c5da840b1214c8121f",
    "name": "externallmg_r_1723807936996_1723807925573_image_12.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807936996_1723807925573_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66bf38c5da840b1214c81220",
    "name": "externallmg_r_1723807938120_1723807925573_image_14.jpg",
    "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807938120_1723807925573_image_14.jpg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66bf38c5da840b1214c81221",
      "name": "externallmg_r_1723807937480_1723807925573_image_13.jpg",
      "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807937480_1723807925573_image_13.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66bf38c5da840b1214c81222",
      "name": "externallmg_r_1723807938566_1723807925573_image_15.jpg",
      "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807938566_1723807925573_image_15.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66bf38c5da840b1214c81223",
      "name": "externallmg_r_1723807939610_1723807925573_image_17.jpg",
      "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807939610_1723807925573_image_17.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66bf38c5da840b1214c81224",
      "name": "externallmg_r_1723807939156_1723807925573_image_16.jpg",
      "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807939156_1723807925573_image_16.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66bf38c5da840b1214c81225",
      "name": "externallmg_r_1723807940105_1723807925573_image_18.jpg",
      "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807940105_1723807925573_image_18.jpg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bf38c5da840b1214c81226",
  "name": "externallmg_r_1723807940696_1723807925573_image_19.jpg",
  "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807940696_1723807925573_image_19.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bf38d4da840b1214c81246",
  "name": "externallmg_r_1723807954484_1723807953802_image_0.jpg",
  "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807954484_1723807953802_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bf38d4da840b1214c81247",
  "name": "externallmg_r_1723807954835_1723807953802_image_1.jpg",
  "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807954835_1723807953802_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66bf38d4da840b1214c81248",
  "name": "externallmg_r_1723807955702_1723807953802_image_2.jpg",
  "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807955702_1723807953802_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66bf38a80f117327db70fb59",
  "name": "externallmg_r_1723807911536_1723807910862_image_0.jpg",
  "path": "cases/66bf1f05da840b1214c7f39d/
externallmg_r_1723807911536_1723807910862_image_0.jpg",
  "orientation": "portrait"
}
],
```

```
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "10626.xlsx",
    "filename": "1723894450311_10626.xlsx",
    "path": "cases/66bf1f05da840b1214c7f39d/
processingDocuments/1723894450311_10626.xlsx",
    "size": "9496",
    "createdAt": "Sat Aug 17 2024 17:04:10 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-16T09:42:29.378Z",
"updatedAt": "2024-08-19T04:59:45.971Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1201, 12th Floor, Building No C Type, Wing - C2,
Punyodaya Park C2 Co-op. Hsg. Soc. Ltd., Village - Wadeghar, Municipality Ward No.
8A, Kalyan (West), Taluka - Kalyan, District - Thane, PIN Code - 421 301, State -
Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Sonali Deshmukh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant's Wife",
"siteVisitContactNo": "8976173678",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Any Other Document",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 725.00",
"flatRate": "10200",
```

```
"landOtherRate": "7400",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + WC +
Bathroom + Toilet",
"carpetTotal": "698.56",
"otherCarpetTotal": "93.63",
"builtupPercentage": "20",
"finalBuiltupArea": "926.03",
"finalCarpetArea": "771.69",
"finalSalableArea": "1018.63",
"salablePercentage": "10",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "73.13",
"otherCompositionSaleableTotal": "0.00",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"reportGeneratedDate": "Mon Aug 19 2024 16:14:21 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-08-17"
}
```

Name	Length	Width	Total
Composition :			
Bedroom	14'00"	12'00"	168.00
Passage	14'8"	3'2"	46.44
Bedroom	11'2"	10'2"	113.53
WC	3'1"	4'2"	12.85
Bathroom	4'3"	6'6"	27.62
Kitchen	10'2"	10'3"	104.21
Living Room	18'8"	10'00"	186.67
Toilet	4'2"	9'5"	39.24
Other Composition :			
Flowerbed	13'6"	2'00"	27.00
Cupboard	3'5"	1'5"	4.84
Cupboard	2'1"	4'6"	9.37
Cupboard	4'6"	2'2"	9.75
Flowerbed	11'1"	2'00"	22.17
Flowerbed	10'3"	2'00"	20.50
Flowerbed	10'00"	2'00"	20.00