

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Nilesh",
    "type": "CREDITOFFICER",
    "_id": "66c2ea88c884d112334bae78",
    "email": "hlst.ghatkopar@sbi.co.in",
    "lastName": "Chaurasia",
    "mobileNo": "",
    "workMobileNo": "8668392343"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Nilesh",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "ACCOUNTANT",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "ACCOUNTANT",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.154859600986832",
  "longitude": "72.94114295393229"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.94114295393229,
19.154859600986832
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-20",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-20",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Bhandup",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "16",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Horizon",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off. Datta Mandir Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "B",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "304A, 304/1-4",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "1603",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "S",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 078",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bhandup (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
```

```
"ownership": {
  "value": "Joint_Ownership",
  "label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road",
  "west": "Slum Area ",
  "south": "Open Plot & Slum Area ",
  "east": "Bakewell House"
},
"asPerDocumentAgreement": {
  "north": "By 18.30 Mtrs Wide DP Road ",
  "west": "By Nalla ",
  "south": "By CTS No. 272",
  "east": "By CTS No. 304B"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Building is under construction ",
    "east": "Building is under construction ",
    "south": "Building is under construction ",
    "west": "Building is under construction "
  },
  "asPerDocument": {
    "north": "Flat No. 1602",
    "east": "Marginal Space",
    "south": "Marginal Space",
    "west": "Flat No. 1604"
  }
},
"isDisplay": true,
```

```
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of Flat will be 1 Bedroom + Living Room + Study Room + Kitchen. (1.5 BHK + 2 Toilets)",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. CHE / ES / 0910 / S / 337 (New) dated 22.12.2023 issued by MCGM. ",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "Building is under construction ",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "142230",
  "landRate": "58050",
  "igrImage": "cases/66c31bcd0f117327db72341a/igr_1724146923116_Image.png",
  "squareMeterGuideLineRate": "156453.00",
  "squareFeetGuideLineRate": "14535.00"
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "142230.00",
  "squareMeterGuideLineRate": "156453.00",
  "squareFeetGuideLineRate": "14535.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MCGM norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Open / Covered Car Parking Space",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
```

```
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "Proposed_Connected_to_Municipal_Sewerage_System_",
"label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
"value": "Building_is_under_construction_",
"label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
"value": "Building_is_under_construction_",
"label": "Building is under construction "
},
"maintenancelssues": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"visibleDamageInBuilding": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
}
```



```
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "2",
"noOfAmenityFloors": "",
"noOfFloors": "21",
"flatFloorNo": "16",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "583.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66c31bcd0f117327db72341a/
routeMap_1724151159945_Image.png",
    "routeLat": "19.154861",
    "routeLng": "72.941139",
    "stationName": "Nahur",
    "routeDistance": "1.8 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
}
```

```
},
"locationMapImg": [
  {
    "id": "zw9boi",
    "name": "zw9boi",
    "image": "cases/66c31bcd0f117327db72341a/
routeMap_1724151018544_Image.png"
  }
],
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "11660000.00",
  "distressValuePercentage": "80",
```

```
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "11660000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "21",
    "percentage": "33.6",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "18",
    "percentage": "5.04",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "18",
    "percentage": "5.04",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "10",
  "percentage": "1.40",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "10",
  "percentage": "1.40",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "10",
  "percentage": "1.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "10",
  "percentage": "1.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "10",
  "percentage": "4.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "62.48",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "8473905.00",
  "selectedBuildUpValue": "583.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
```

```
"frontPageImages": [
  {
    "status": false,
    "_id": "66c4550eda840b1214c9b4ed",
    "name": "externallmg_1724142858678_1724142850897_image_1.jpeg",
    "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142858678_1724142850897_image_1.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "66c454e0da840b1214c9b4bb",
    "name": "externallmg_1724142815124_1724142809409_image_2.jpeg",
    "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142815124_1724142809409_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c454e0da840b1214c9b4ba",
    "name": "externallmg_1724142814232_1724142809408_image_1.jpeg",
    "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142814232_1724142809408_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c4550eda840b1214c9b4ed",
    "name": "externallmg_1724142858678_1724142850897_image_1.jpeg",
    "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142858678_1724142850897_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c454e0da840b1214c9b4b9",
    "name": "externallmg_1724142812680_1724142809408_image_0.jpeg",
    "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142812680_1724142809408_image_0.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
```

```
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "17853.00",
    "max": "22642.00"
  },
  "builtUpRateRange": {
    "min": "16230.00",
    "max": "20584.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "530.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
```

```
"paymentIds": [],
"_id": "66c31bcd0f117327db72341a",
"ownerName": "Mr. Aditya Ashok Shinde & Mrs. Ankita Aditya Shinde ",
"ownerPhoneNo": "9702773762",
"appAddress": "Flat no. 1603, 16th Floor, Wing - B, Horizon, Bhandup West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "07/08/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Ajanta Airavat Infrastructure ",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Aditya Ashok Shinde & Mrs. Ankita Aditya Shinde ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "17817 / 2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "817803",
    "path": "cases/66c31bcd0f117327db72341a/
document_1724062653197_1724062651821_Racpc_GHatkopar_Aditya_Shinde.pdf",
    "fileName":
"document_1724062653197_1724062651821_Racpc_GHatkopar_Aditya_Shinde.pdf"
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "inputs": {
      "documentDate": "22/12/2023",
      "nameOfApprovingAuthority": {
```

```
    "value": "Municipal_Corporation_of_Greater_Mumbai",
    "label": "Municipal Corporation of Greater Mumbai"
  },
  "remark": " (As downloaded from MCGM site)",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "CHE / ES / 0910 / S / 337 (New)"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1724148686219_PLan.pdf",
"path": "cases/66c31bcd0f117327db72341a/document_1724148686219_PLan.pdf",
"id": "990897",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Aug 20 2024 15:41:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "13/02/2024",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / ES / 0910 / S / 337 (NEW) / FCC / 3 / Amend"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724148742387_CC.pdf",
  "path": "cases/66c31bcd0f117327db72341a/document_1724148742387_CC.pdf",
  "id": "692209",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Aug 20 2024 15:42:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
```

```
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "28/11/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51800013296"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724148770394_P51800013296.pdf",
  "path": "cases/66c31bcd0f117327db72341a/
document_1724148770394_P51800013296.pdf",
  "id": "995131",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Aug 20 2024 15:42:50 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010672",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "469447",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Aug 19 2024 15:47:49 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Aditya Ashok Shinde & Mrs. Ankita Aditya Shinde ",
    "phone": "9702773762",
    "ownershipShare": "",
    "email": "",
    "id": "291938"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "512615",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "530",
    "squareMeterArea": "49.24",
    "docFinalBuiltUp": "583",
    "docFinalBuiltUpSquareMeter": "54.164",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "420.00",
      "squareMeterArea": "39.02",
      "expectedRate": "18127.38",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "462.00",
      "squareMeterArea": "42.92",
      "expectedRate": "16479.44",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
```

```
"_id": "66c46545c884d112334ca0cd",
"property": "Residential Flat",
"area": "420",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "7613500",
"expectedRate": "18127.38",
"builtUpExpectedRate": "16479.44",
"image": "cases/66c31bcd0f117327db72341a/
indicator_1724146792245_Image.png",
"squareMeter": "39.02",
"id": "112558"
},
{
  "carpetArea": {
    "area": "630.00",
    "squareMeterArea": "58.53",
    "expectedRate": "17852.38",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "693.00",
    "squareMeterArea": "64.38",
    "expectedRate": "16229.44",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66c46545c884d112334ca0ce",
  "property": "Residential Flat",
  "area": "630",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
```

```
"expectedPrice": "11247000",
"expectedRate": "17852.38",
"builtUpExpectedRate": "16229.44",
"image": "cases/66c31bcd0f117327db72341a/
indicator_1724146823422_Image.png",
"squareMeter": "58.53",
"id": "866749"
},
{
  "carpetArea": {
    "area": "530.00",
    "squareMeterArea": "49.24",
    "expectedRate": "22641.51",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "583.00",
    "squareMeterArea": "54.16",
    "expectedRate": "20583.19",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66c46545c884d112334ca0cf",
  "property": "Residential Flat",
  "area": "530",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "12000000",
  "expectedRate": "22641.51",
  "builtUpExpectedRate": "20583.19",
  "image": "cases/66c31bcd0f117327db72341a/
indicator_1724146845574_Image.png",
  "squareMeter": "49.24",
  "id": "489778"
},
{
```

```
"carpetArea": {
  "area": "632.00",
  "squareMeterArea": "58.71",
  "expectedRate": "21993.67",
  "percentage": ""
},
"builtUpArea": {
  "area": "695.20",
  "squareMeterArea": "64.59",
  "expectedRate": "19994.25",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "66c46545c884d112334ca0d0",
"property": "Residential Flat",
"area": "632",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "13900000",
"expectedRate": "21993.67",
"builtUpExpectedRate": "19994.25",
"image": "cases/66c31bcd0f117327db72341a/
indicator_1724146861320_Image.png",
"squareMeter": "58.71",
"id": "690493"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c454e0da840b1214c9b4b9",
  "name": "externalImg_1724142812680_1724142809408_image_0.jpeg",
  "path": "cases/66c31bcd0f117327db72341a/
externalImg_1724142812680_1724142809408_image_0.jpeg",
  "orientation": "portrait"
}
```



```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66c454e0da840b1214c9b4ba",
      "name": "externallmg_1724142814232_1724142809408_image_1.jpeg",
      "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142814232_1724142809408_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66c454e0da840b1214c9b4bb",
      "name": "externallmg_1724142815124_1724142809409_image_2.jpeg",
      "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142815124_1724142809409_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66c454e0da840b1214c9b4bc",
      "name": "externallmg_1724142815636_1724142809409_image_3.jpeg",
      "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142815636_1724142809409_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66c4550eda840b1214c9b4ec",
      "name": "externallmg_1724142856629_1724142850897_image_0.jpeg",
      "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142856629_1724142850897_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66c4550eda840b1214c9b4ed",
      "name": "externallmg_1724142858678_1724142850897_image_1.jpeg",
      "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142858678_1724142850897_image_1.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c4550eda840b1214c9b4ee",
  "name": "externallmg_1724142860179_1724142850897_image_2.jpeg",
  "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142860179_1724142850897_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66c454d0da840b1214c9b497",
  "name": "externallmg_1724142795145_1724142791620_image_0.jpeg",
  "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142795145_1724142791620_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66c454d0da840b1214c9b498",
  "name": "externallmg_1724142795959_1724142791620_image_1.jpeg",
  "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142795959_1724142791620_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66c454d0da840b1214c9b499",
  "name": "externallmg_1724142796680_1724142791620_image_2.jpeg",
  "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142796680_1724142791620_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66c454d0da840b1214c9b49a",
  "name": "externallmg_1724142797139_1724142791620_image_3.jpeg",
  "path": "cases/66c31bcd0f117327db72341a/
externallmg_1724142797139_1724142791620_image_3.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c454d0da840b1214c9b49b",
    "name": "externalImg_1724142797679_1724142791620_image_4.jpeg",
    "path": "cases/66c31bcd0f117327db72341a/
externalImg_1724142797679_1724142791620_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c454d0da840b1214c9b49c",
    "name": "externalImg_1724142798446_1724142791620_image_5.jpeg",
    "path": "cases/66c31bcd0f117327db72341a/
externalImg_1724142798446_1724142791620_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c454d0da840b1214c9b49d",
    "name": "externalImg_1724142799039_1724142791620_image_6.jpeg",
    "path": "cases/66c31bcd0f117327db72341a/
externalImg_1724142799039_1724142791620_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c454d0da840b1214c9b49e",
    "name": "externalImg_1724142799545_1724142791620_image_7.jpeg",
    "path": "cases/66c31bcd0f117327db72341a/
externalImg_1724142799545_1724142791620_image_7.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalName": "AGR.pdf",
    "filename": "1724147041591_AGR.pdf",
    "path": "cases/66c31bcd0f117327db72341a/
processingDocuments/1724147041591_AGR.pdf",
    "size": "10288712",
    "createdAt": "Tue Aug 20 2024 15:14:01 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
```

```
},
{
  "originalname": "externallmg_1724142795145_1724142791620_image_0.jpeg",
  "filename":
"1724147041709_externallmg_1724142795145_1724142791620_image_0.jpeg",
  "path": "cases/66c31bcd0f117327db72341a/processingDocuments/1724147041709_externallmg_1724142795145_1724142791620_image_0.jpeg",
  "size": "305789",
  "createdAt": "Tue Aug 20 2024 15:14:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1724142795959_1724142791620_image_1.jpeg",
  "filename":
"1724147041717_externallmg_1724142795959_1724142791620_image_1.jpeg",
  "path": "cases/66c31bcd0f117327db72341a/processingDocuments/1724147041717_externallmg_1724142795959_1724142791620_image_1.jpeg",
  "size": "1158941",
  "createdAt": "Tue Aug 20 2024 15:14:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1724147041723_IGR01.pdf",
  "path": "cases/66c31bcd0f117327db72341a/processingDocuments/1724147041723_IGR01.pdf",
  "size": "151311",
  "createdAt": "Tue Aug 20 2024 15:14:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1724147041724_IGR02.pdf",
  "path": "cases/66c31bcd0f117327db72341a/processingDocuments/1724147041724_IGR02.pdf",
  "size": "152002",
  "createdAt": "Tue Aug 20 2024 15:14:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1724147041725_IGR03.pdf",
  "path": "cases/66c31bcd0f117327db72341a/processingDocuments/1724147041725_IGR03.pdf",
  "size": "154546",
  "createdAt": "Tue Aug 20 2024 15:14:01 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1724147041726_IGR04.pdf",
  "path": "cases/66c31bcd0f117327db72341a/
processingDocuments/1724147041726_IGR04.pdf",
  "size": "148449",
  "createdAt": "Tue Aug 20 2024 15:14:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-05.pdf",
  "filename": "1724147041727_IGR05.pdf",
  "path": "cases/66c31bcd0f117327db72341a/
processingDocuments/1724147041727_IGR05.pdf",
  "size": "152056",
  "createdAt": "Tue Aug 20 2024 15:14:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=ADITYA.xlsx",
  "filename": "1724147041730_Summary_NewADITYA.xlsx",
  "path": "cases/66c31bcd0f117327db72341a/
processingDocuments/1724147041730_Summary_NewADITYA.xlsx",
  "size": "1928048",
  "createdAt": "Tue Aug 20 2024 15:14:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "CC.pdf",
  "filename": "1724151197797_CC.pdf",
  "path": "cases/66c31bcd0f117327db72341a/
processingDocuments/1724151197797_CC.pdf",
  "size": "165399",
  "createdAt": "Tue Aug 20 2024 16:23:17 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname": "P51800013296.pdf",
  "filename": "1724151197808_P51800013296.pdf",
  "path": "cases/66c31bcd0f117327db72341a/
processingDocuments/1724151197808_P51800013296.pdf",
  "size": "708774",
  "createdAt": "Tue Aug 20 2024 16:23:17 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
```

```
    },
    {
      "originalName": "PLan.pdf",
      "filename": "1724151197821_PLan.pdf",
      "path": "cases/66c31bcd0f117327db72341a/
processingDocuments/1724151197821_PLan.pdf",
      "size": "6236619",
      "createdAt": "Tue Aug 20 2024 16:23:17 GMT+0530 (India Standard Time)",
      "uploadedBy": "62fe044a48a26047e6552796"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "60eeaeddf3dd69653a581316",
        "role": "ACCOUNTANT",
        "firstName": "Shyam",
        "lastName": "Kajvilkar",
        "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
      "_id": "66c45bdcc884d112334c8c5f",
      "note": "Pending for value confirmation",
      "taskId": "66c320f6c884d112334c046f",
      "createdAt": "2024-08-20T09:03:24.185Z"
    }
  ],
  "createdAt": "2024-08-19T10:17:49.551Z",
  "updatedAt": "2024-08-20T11:06:23.622Z",
  "__v": 0,
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  "fullAddress": "Residential Flat No. 1603, 16th Floor, Wing - B, Horizon, Off. Datta
Mandir Road, Village - Bhandup, Municipality Ward No. S, Bhandup (West), Taluka -
Kurla, District - Mumbai Suburban , PIN - 400 078, State - Maharashtra, Country -
India",
  "updatedBy": "60eeaeddf3dd69653a581316",
  "addressForMap": "",
  "caseReferredBy": "60b7177d2ffdf65bcd65882a",
```

```
"contactPersonName": "Mr. Avinash Waghmare",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Person",
"siteVisitContactNo": "7666288699",
"buildingServicesRate": "3500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 530.00",
"flatRate": "22000",
"landOtherRate": "18500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": ""
  }
}
```

```
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"reportGeneratedDate": "Tue Aug 20 2024 15:16:02 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-08-20"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			