

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa0"
    },
    "firstName": "Rajesh",
    "type": "CREDITOFFICER",
    "_id": "653de381d6fbd83553d3f51a",
    "lastName": "KUMAR",
    "mobileNo": "",
    "workMobileNo": "7892953881",
    "email": "1coorddesk.rasmecbhy@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9500000",
    "discussWithPerson": "Rajesh",
    "expectedFees": 4750,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa0",
  "branchCode": "000286",
  "type": "BRANCH",
  "name": "RASMECCC Bhayandar",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "RASMECCC Bhayandar Branch Unit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, Opp. Maxus Mall, Bhayander
(West), Thane – 401 101, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "66850df5d9f18310ed2e5d98",
  "role": "SITEENGINEER",
  "firstName": "Krishna",
  "email": "krishnagawade9@gmail.com",
  "lastName": "Gawde",
  "mobileNo": "9821646373",
  "designation": "Site Engg",
  "shortName": "Krishna",
  "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "ACCOUNTANT",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "ACCOUNTANT",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.263213702934124",
  "longitude": "72.87346339372833"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87346339372833,
    19.263213702934124
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "21/08/2024 08:42 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-22",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-21",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Mahajanwadi",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "15",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mira Road (East), Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
```

```
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Westin Darvesh Horizon",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Penkar Pada",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Dahisar Check Naka, Opp. Thakur Mall",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
```



```
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "4403, 4436 to 4451, 4481, 4482, 4486 to 4508, 4540 to 4546, 4565 ro
4571, 4599 to 4603 & 4699",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A/1506",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "401107",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
```

```
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Under Construction Building",
    "west": "Mira Bhayandar Municipal Fire Brigade",
    "south": "Road",
    "east": "Service Road & Western Express Highway"
  },
  "asPerDocumentAgreement": {
    "north": "Information not available",
    "west": "Information not available",
    "south": "Information not available",
    "east": "Information not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Flat No. 1505",
      "east": "Marginal Space",
      "south": "Marginal Space",
      "west": "Staircase"
    },
    "asPerDocument": {
      "north": "Building Under Construction",
      "east": "Building Under Construction",
      "south": "Building Under Construction",
    }
  }
}
```

```

    "west": "Building Under Construction"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of residential flat is Living Room + Kitchen + 2 Bedrooms + 2 Toilets + Passage + Balcony (i.e. 2 BHK with 2 Toilets)",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. MBMNP/ NR/5620/2019-20 dated 07.02.2020 issued by Mir - Bhayandar Municipal Corporation.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "As building is under construction, Internal visit not allowed at site. The details about the work progress status has been provided by Ms. Nupur (Contact No. 8830210854)",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",

```

```
"rate": "104300",
"landRate": "30700",
"igrImage": "cases/66c49a71c884d112334cfbc8/igr_1724310396243_Image.png",
"squareMeterGuideLineRate": "114730.00",
"squareFeetGuideLineRate": "10659.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "104300.00",
  "squareMeterGuideLineRate": "114730.00",
  "squareFeetGuideLineRate": "10659.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Building Under Construction",
  "taxPaidHolderName": "Building Under Construction",
  "taxAmount": "Building Under Construction",
  "electricityServiceConnectionNo": "Building Under Construction",
  "meterCardHolderName": "Building Under Construction",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MBMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
```

```
"roof": {
  "value": "Proposed_R.C.C._Slab",
  "label": "Proposed R.C.C. Slab"
},
"partitions": {
  "value": "Proposed_6\"_Thk._Brick_Masonry",
  "label": "Proposed 6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "One Car Parking Space",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
}
```

```
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
```



```
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "1",
"noOfPodium": "3",
"noOfAmenityFloors": "",
"noOfFloors": "17",
"flatFloorNo": "15",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
"area": "717.20",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/66c49a71c884d112334cfbc8/
routeMap_1724318919065_Image.png",
"routeLat": "19.262350",
"routeLng": "72.872862",
"stationName": "Mira Road",
"routeDistance": "2.9 km.",
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
}
},
"finalLatLng": {
"coordinates": [
0,
0
```

```
    ],
    "type": "Point"
  },
  "showLocation": {
    "latlng": false,
    "finallatlng": false
  },
  "locationMapImg": [
    {
      "id": "qjucxi",
      "name": "qjucxi",
      "image": "cases/66c49a71c884d112334cfbc8/
routeMap_1724318797599_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
```

```
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "11214400.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "11214400.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "18",
    "percentage": "31.304347826086957",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "18",
    "percentage": "5.48",
    "isHideFloor": false,
    "status": true
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "18",
  "percentage": "5.48",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "18",
  "percentage": "2.74",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "15",
  "percentage": "2.28",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "57.28",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "7644635.00",
  "selectedBuildUpValue": "717.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66c6c824c884d112334df18d",
      "name":
"externallmg_1724303396835_WhatsApp_Image_20240822_at_101636_1.jpeg",
      "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396835_WhatsApp_Image_20240822_at_101636_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "66c6c824c884d112334df193",
      "name":
"externallmg_1724303396857_WhatsApp_Image_20240822_at_101640_1.jpeg",
      "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396857_WhatsApp_Image_20240822_at_101640_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66c6c824c884d112334df18e",
      "name":
"externallmg_1724303396840_WhatsApp_Image_20240822_at_101636_2.jpeg",
      "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396840_WhatsApp_Image_20240822_at_101636_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "13500.00",
```

```
"max": "18479.00"
},
"builtUpRateRange": {
  "min": "12273.00",
  "max": "16799.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "652.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66c49a71c884d112334cfbc8",
"ownerName": "Mrs. Parul Chaudhary",
"ownerPhoneNo": "8286302443",
"appAddress": "FLAT NO 1506 A WING BLDG NO 1 DARVESH HORIZON WESTIN
DARVESH HORIZON PENKAR PADA NEAR DAHISAR CHEK NAKA OPP THAKUR
```

```
MALL MIRA ROAD EAST THANE 401107",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "09/10/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Darvesh Properties Private Limited & Westin Infra World Private
Limited",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mrs. Parul Chaudhary, Mr. Pushpendra Chaudhary & Mr. Pranit
Chaudhary ",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "18878-2023"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "699456",
    "path": "cases/66c49a71c884d112334cfbc8/
document_1724160130564_1724160126340_A__1506_Scanned_copy.pdf",
    "fileName":
"document_1724160130564_1724160126340_A__1506_Scanned_copy.pdf"
  },
  {
    "documentType": {
      "value": "60ae1256aa6d152c1801b330",
      "label": "Draft Agreement for sale"
    },
    "inputs": {
      "remark": "Made in July 2024",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      }
    }
  }
]
```

```
    },
    "Transferor": "Mrs. Parul Chaudhary, Mr. Pushpendra Chaudhary & Mr. Pranit
Chaudhary",
    "to": {
        "value": "Transferee",
        "label": "Transferee"
    },
    "Transferee": "Mrs. Sangita Lalji Gupta & Mr. Amit Lalji Gupta"
},
"isHardCopy": false,
"displayStatus": true,
"id": "494070",
"path": "cases/66c49a71c884d112334cfbc8/document_1724160458108_172416045
5180_CONFIRMING_PARTY__RESALE_AGREEMENT_OF_FLAT_NO_A__1506__Co
py.docx",
"fileName": "document_1724160458108_1724160455180_CONFIRMING_PARTY__
RESALE_AGREEMENT_OF_FLAT_NO_A__1506__Copy.docx"
},
{
    "documentType": {
        "label": "Approved Building Plan",
        "value": "60ae1277aa6d152c1801b3cc"
    },
    "inputs": {
        "documentDate": "07/02/2020",
        "nameOfApprovingAuthority": {
            "value": "Mira_Bhayander_Municipal_Corporation",
            "label": "Mira Bhayander Municipal Corporation"
        },
        "number": {
            "value": "No",
            "label": "No"
        }
    },
    "No": "MBMNP/NR/5620/2019-20"
},
"isHardCopy": false,
"displayStatus": false,
"id": "297944",
"path": "cases/66c49a71c884d112334cfbc8/document_1724160490372_172416048
6766_Westin_Darvesh_Horizon_Clear_Plans_11zon.pdf",
"fileName": "document_1724160490372_1724160486766_Westin_Darvesh_Horizo
n_Clear_Plans_11zon.pdf"
},
{
    "documentType": {
        "value": "60ae129faa6d152c1801b47d",
```

```
"label": "RERA Certificate"
},
"inputs": {
  "documentDate": "30/01/2023",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "P51700005672"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1724322479379_RERA.pdf",
"path": "cases/66c49a71c884d112334cfbc8/
document_1724322479379_RERA.pdf",
"id": "752294",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Thu Aug 22 2024 15:57:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "07/02/2020",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "MB/MNP/NR/5620/2019-20"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724324002136_CC.pdf",
  "path": "cases/66c49a71c884d112334cfbc8/document_1724324002136_CC.pdf",
  "id": "251965",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
```

```
    "createdAt": "Thu Aug 22 2024 16:23:22 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010708",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "465286",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Aug 20 2024 19:00:25 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Parul Chaudhary",
    "phone": "8286302443",
    "ownershipShare": "",
    "email": "",
    "id": "776729"
  },
  {
    "name": "Mr. Pushpendra Chaudhary",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "301611"
  },
  {
    "name": "Mr. Pranit Chaudhary",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "896110"
  }
],
"proposePurchasers": [
  {
    "name": "Mrs. Sangita Lalji Gupta",
    "phone": "",
    "email": "",
    "ownershipShare": ""
  },
  {
    "name": "Mr. Amit Lalji Gupta",
    "phone": "",

```

```
"email": "",
"ownershipShare": ""
}
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"value": "60ae1256aa6d152c1801b330",
"label": "Draft Agreement for sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"docFinalBuiltUp": "717.2",
"docFinalBuiltUpSquareMeter": "66.627",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "600.00",
"squareMeterArea": "55.74",
"expectedRate": "17666.67",
"percentage": ""
},
"builtUpArea": {
"area": "660.00",
"squareMeterArea": "61.32",
"expectedRate": "16060.61",
"percentage": "10"
},
"saleableArea": {
```

```
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66c6e384da840b1214cb0316",
"property": "Residential Flat",
"area": "600",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "10600000",
"expectedRate": "17666.67",
"builtUpExpectedRate": "16060.61",
"image": "cases/66c49a71c884d112334cfbc8/
indicator_1724309806574_Image.png",
"squareMeter": "55.74",
"id": "578709"
},
{
"carpetArea": {
"area": "828.00",
"squareMeterArea": "76.92",
"expectedRate": "18478.26",
"percentage": ""
},
"builtUpArea": {
"area": "910.80",
"squareMeterArea": "84.62",
"expectedRate": "16798.42",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66c6e384da840b1214cb0317",
"property": "Residential Flat",
"area": "828",
```

```
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "15300000",
"expectedRate": "18478.26",
"builtUpExpectedRate": "16798.42",
"image": "cases/66c49a71c884d112334cfbc8/
indicator_1724309827111_Image.png",
"squareMeter": "76.92",
"id": "388756"
},
{
  "carpetArea": {
    "area": "433.00",
    "squareMeterArea": "40.23",
    "expectedRate": "13660.51",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "476.30",
    "squareMeterArea": "44.25",
    "expectedRate": "12418.64",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66c6e384da840b1214cb0318",
  "property": "Residential Flat",
  "area": "433",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "5915000",
  "expectedRate": "13660.51",
  "builtUpExpectedRate": "12418.64",
```



```
"image": "cases/66c49a71c884d112334cfbc8/
indicator_1724310242856_Image.png",
"squareMeter": "40.23",
"id": "922710"
},
{
"carpetArea": {
"area": "620.00",
"squareMeterArea": "57.60",
"expectedRate": "13500.00",
"percentage": ""
},
"builtUpArea": {
"area": "682.00",
"squareMeterArea": "63.36",
"expectedRate": "12272.73",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66c6e384da840b1214cb0319",
"property": "Residential Flat",
"area": "620",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "8370000",
"expectedRate": "13500.00",
"builtUpExpectedRate": "12272.73",
"image": "cases/66c49a71c884d112334cfbc8/
indicator_1724310325868_Image.png",
"squareMeter": "57.60",
"id": "338076"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66c6c824c884d112334df18b",
  "name":
"externallmg_1724303396833_WhatsApp_Image_20240822_at_101640_2.jpeg",
  "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396833_WhatsApp_Image_20240822_at_101640_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c6c824c884d112334df18c",
  "name":
"externallmg_1724303396835_WhatsApp_Image_20240822_at_101720.jpeg",
  "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396835_WhatsApp_Image_20240822_at_101720.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c6c824c884d112334df18d",
  "name":
"externallmg_1724303396835_WhatsApp_Image_20240822_at_101636_1.jpeg",
  "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396835_WhatsApp_Image_20240822_at_101636_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c6c824c884d112334df18e",
  "name":
"externallmg_1724303396840_WhatsApp_Image_20240822_at_101636_2.jpeg",
  "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396840_WhatsApp_Image_20240822_at_101636_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c6c824c884d112334df18f",
  "name":
"externallmg_1724303396844_WhatsApp_Image_20240822_at_101636.jpeg",
  "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396844_WhatsApp_Image_20240822_at_101636.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c6c824c884d112334df190",
    "name":
"externallmg_1724303396849_WhatsApp_Image_20240822_at_101638_1.jpeg",
    "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396849_WhatsApp_Image_20240822_at_101638_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c6c824c884d112334df191",
    "name":
"externallmg_1724303396851_WhatsApp_Image_20240822_at_101638_2.jpeg",
    "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396851_WhatsApp_Image_20240822_at_101638_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c6c824c884d112334df192",
    "name":
"externallmg_1724303396854_WhatsApp_Image_20240822_at_101638.jpeg",
    "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396854_WhatsApp_Image_20240822_at_101638.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c6c824c884d112334df193",
    "name":
"externallmg_1724303396857_WhatsApp_Image_20240822_at_101640_1.jpeg",
    "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396857_WhatsApp_Image_20240822_at_101640_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c6c824c884d112334df194",
```

```
"name":
"externallmg_1724303396859_WhatsApp_Image_20240822_at_101640.jpeg",
  "path": "cases/66c49a71c884d112334cfbc8/
externallmg_1724303396859_WhatsApp_Image_20240822_at_101640.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "AGR.pdf",
  "filename": "1724310426992_AGR.pdf",
  "path": "cases/66c49a71c884d112334cfbc8/
processingDocuments/1724310426992_AGR.pdf",
  "size": "131183561",
  "createdAt": "Thu Aug 22 2024 12:37:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "DRAFT AGR.docx",
  "filename": "1724310428231_DRAFT_AGR.docx",
  "path": "cases/66c49a71c884d112334cfbc8/
processingDocuments/1724310428231_DRAFT_AGR.docx",
  "size": "54610",
  "createdAt": "Thu Aug 22 2024 12:37:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname":
"externallmg_1724303396835_WhatsApp_Image_20240822_at_101720.jpeg",
  "filename": "1724310428232_externallmg_1724303396835_WhatsApp_Image_202
40822_at_101720.jpeg",
  "path": "cases/66c49a71c884d112334cfbc8/processingDocuments/1724310428232
_externallmg_1724303396835_WhatsApp_Image_20240822_at_101720.jpeg",
  "size": "110361",
  "createdAt": "Thu Aug 22 2024 12:37:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname":
"externallmg_1724303396844_WhatsApp_Image_20240822_at_101636.jpeg",
  "filename": "1724310428233_externallmg_1724303396844_WhatsApp_Image_202
40822_at_101636.jpeg",
  "path": "cases/66c49a71c884d112334cfbc8/processingDocuments/1724310428233
_externallmg_1724303396844_WhatsApp_Image_20240822_at_101636.jpeg",
  "size": "255942",
```

```
"createdAt": "Thu Aug 22 2024 12:37:08 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "igr-01.pdf",
  "filename": "1724310428234_igr01.pdf",
  "path": "cases/66c49a71c884d112334cfbc8/
processingDocuments/1724310428234_igr01.pdf",
  "size": "159289",
  "createdAt": "Thu Aug 22 2024 12:37:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1724310428236_IGR02.pdf",
  "path": "cases/66c49a71c884d112334cfbc8/
processingDocuments/1724310428236_IGR02.pdf",
  "size": "153110",
  "createdAt": "Thu Aug 22 2024 12:37:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1724310428237_IGR03.pdf",
  "path": "cases/66c49a71c884d112334cfbc8/
processingDocuments/1724310428237_IGR03.pdf",
  "size": "153612",
  "createdAt": "Thu Aug 22 2024 12:37:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1724310428238_IGR04.pdf",
  "path": "cases/66c49a71c884d112334cfbc8/
processingDocuments/1724310428238_IGR04.pdf",
  "size": "151680",
  "createdAt": "Thu Aug 22 2024 12:37:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "PLAN.pdf",
  "filename": "1724310428240_PLAN.pdf",
  "path": "cases/66c49a71c884d112334cfbc8/
processingDocuments/1724310428240_PLAN.pdf",
  "size": "6843297",
  "createdAt": "Thu Aug 22 2024 12:37:08 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalName": "Summary New=PARUL.xlsx",
  "filename": "1724310428312_Summary_NewPARUL.xlsx",
  "path": "cases/66c49a71c884d112334cfbc8/
processingDocuments/1724310428312_Summary_NewPARUL.xlsx",
  "size": "2183825",
  "createdAt": "Thu Aug 22 2024 12:37:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-20T13:30:25.277Z",
"updatedAt": "2024-08-22T12:22:58.822Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. A/1506, 15th Floor, Building No 1, Westin Darvesh
Horizon, Penkar Pada, Near Dahisar Check Naka, Opp. Thakur Mall, Village -
Mahajanwadi, Taluka - Thane, District - Thane, Mira Road (East), Thane, 401107, State
- Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Ms. Nupur",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Mrs. Sangita Lalji Gupta",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "8830210854",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Draft Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 652.00",
"flatRate": "17200",
```

```

"landOtherRate": "14700",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 594.00 \nEnclosed Balcony Area in
Sq. Ft. = 58.00\n",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Thu Aug 22 2024 14:42:30 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-08-21",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
