

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "66d03440da840b1214cfa51f"
    },
    "firstName": "Kiran",
    "type": "CREDITOFFICER",
    "_id": "66d034a3c884d11233541d7d",
    "email": "Colaba@cosmosbank.in",
    "lastName": "More",
    "mobileNo": "",
    "workMobileNo": "9022145406"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6454645",
    "discussWithPerson": "Sujay",
    "expectedFees": 3227.3225,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "66d03440da840b1214cfa51f",
  "name": "Colaba Branch",
  "branchCode": "",
  "mobileNo": "02222021934",
  "alternateMobileNo": "",
  "email": "Colaba@cosmosbank.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "8, SHree Sadan ,Lala Nigam Road, Coloba Mumbai 400005"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
```

```
"firstName": "Ramkrishna ",
"email": "rampatakar1991@gmail.com",
"lastName": "Patkar",
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c777a8a5c3051014f4dd1f",
"role": "SITEENGINEER",
"firstName": "Pratik",
"email": "pratikjain2277@gmail.com",
"lastName": "Jain",
"mobileNo": "9619286285",
"designation": "",
"shortName": "Pratik",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": ""
```

```
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "_id": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg",
  "firstName": "Shobha",
  "lastName": "Kuperkar",
  "shortName": "SH",
  "email": "shobha@vastukala.org",
  "designation": "",
  "mobileNo": "9004134140",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        }
      }
    ]
  }
],
```

```
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.278735662368373",
  "longitude": "72.88403663896656"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88403663896656,
    19.278735662368373
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
```

```
"schedule": [
  {
    "dateTime": "22/08/2024 06:24 pm"
  },
  {
    "dateTime": "22/08/2024 12:00 am"
  },
  {
    "dateTime": "22/08/2024 12:00 am"
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-08-21",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
}
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Bhayander",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mira Road (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Thane",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreeji Tower Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Geeta Nagar, Phase II",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Behind Petrol Pump, Mira-Bhayandar Main Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": true,
"name": "Wing",
"key": "wing",
"value": "B",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "531",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "64, Hissa No. 1(pt)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "507",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```

    "name": "Gut No.",
    "key": "GUTNo",
    "value": "",
    "label": true
  },
  "postalCode": {
    "status": true,
    "name": "Postal Code",
    "key": "postalCode",
    "value": "PIN - 401 107",
    "label": false
  },
  "suburb": {
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "MarbleFlooring",
    "label": "Marble Flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}

```

```
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Land",
    "west": "Balaji Mandir Road",
    "south": "Chandan Classic Complex",
    "east": "Govind Nagar Building"
  },
  "asPerDocumentAgreement": {
    "north": "Partly by land bearing Survey No. 531, Hissa No. 1 (pt) & Partly by Survey No. 531, Hissa No. 4",
    "west": "Partly by land bearing Survey No. 529 & Partly by Kutcha Road & Partly by Survey No. 529, Hissa No. 1 (pt)",
    "south": "Partly by land bearing Survey No. 490 & Partly by land bearing Survey No. 529",
    "east": "By Land bearing Survey No. 463"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space",
      "east": "Marginal Open Space",
      "south": "Lift & Lobby",
      "west": "Flat No. 502 'A' Wing"
    },
    "asPerDocument": {
      "north": "Information not available",
```

```

    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": true
  },
  "auto": {
    "title": "Auto",
    "status": true
  },
  "privateCars": {
    "title": "Private Cars",
    "status": true
  }
},
"extraDetailOfProperty": "(i.e. 2 BHK) As per site inspection, Flat No. 507 & 508 are internally amalgamated by removing common wall between both living rooms with common entrance from Flat No. 508 to form a single flat.",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"classOfSanitary": {
  "value": "superior_white",
  "label": "Superior White"
},
"compoundWall": "6'.0\ High, R.C.C. column with B. B. masonry wall"
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "1)\tAs per site inspection, Flat No. 507 & 508 are internally amalgamated

```

to form a single flat. The composition of amalgamated flat is Living Room + Dining Area + 2 Bedrooms + Kitchen + 2 Toilets + WC + Passage. As per request valuation done for Flat No. 507 Only. For the purpose of valuation, we have considered the area as per document. ",

```
"depreciationPercentage": "42",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "10950",
"depreciatedBuildingRate": "1450"
},
"igrRate": {
"propertyName": "Residential",
"rate": "76000",
"landRate": "24600",
"igrImage": "cases/66c736f2186d6d9b72b8317d/igr_1725107537856_Image.png",
"squareMeterGuideLineRate": "79800.00",
"squareFeetGuideLineRate": "7414.00"
},
"igrFinalRate": {
"floorRatePercentage": "5",
"depreciationPercentage": "72",
"rate": "5978.00",
"squareFeetGuideLineRate": "5978.00",
"squareMeterGuideLineRate": "64344.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Information not available",
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per MBMC norms",
```

```
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1996",
    "fullDate": "1/1/1996"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  }
}
```

```
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
```



```
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "As_Per_Part_Occupancy_Certificate",
"label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "32",
"ageOfBuilding": "28",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "5",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "0.00"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/66c736f2186d6d9b72b8317d/
routeMap_1725258404805_Image.png",
"routeLat": "19.289767",
"routeLng": "72.861795",
"stationName": "Mira Road",
"routeDistance": "1.6 km.",
```

```
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "skwud",
    "name": "skwud",
    "image": "cases/66c736f2186d6d9b72b8317d/
routeMap_1725258235743_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "790000.00",
    "depreciationPercentage": "42",
    "depreciatedCostOfConstruction": "331800.00",
    "totalFairMarketValue": "3460200.00"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
```

```
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3792000.00",
"finalValue": "3792000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1889048.00",
  "selectedBuildUpValue": "316.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66d5595300f75047be5fa705",
      "name": "externallmg_1725258067256_externallmg_1724331648252_WhatsApp_I
mage_20240821_at_124848.jpeg",
      "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258067256_externa
llmg_1724331648252_WhatsApp_Image_20240821_at_124848.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "66d55960807b2347dd5965f5",
      "name": "externallmg_1725258079677_externallmg_1724331648264_WhatsApp_I
mage_20240821_at_124850.jpeg",
      "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079677_externa
llmg_1724331648264_WhatsApp_Image_20240821_at_124850.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66d5595300f75047be5fa707",
      "name": "externallmg_1725258067269_externallmg_1724331648258_WhatsApp_I
mage_20240821_at_124849_2.jpeg",
      "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258067269_externa
```

```
llmg_1724331648258_WhatsApp_Image_20240821_at_124849_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66d55960807b2347dd5965f2",
  "name": "externallmg_1725258079651_externallmg_1724331648259_WhatsApp_I
mage_20240821_at_124849.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079651_externa
llmg_1724331648259_WhatsApp_Image_20240821_at_124849.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "66d55979433b95fe09e1897a",
    "name": "externallmg_1725258104860_externallmg_1724331661804_WhatsApp_I
mage_20240821_at_124857_2.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104860_externa
llmg_1724331661804_WhatsApp_Image_20240821_at_124857_2.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "66d55960807b2347dd5965f3",
    "name": "Living Room",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079652_externa
llmg_1724331648261_WhatsApp_Image_20240821_at_124850_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66d55960807b2347dd5965f6",
    "name": "Living Room",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079678_externa
llmg_1724331648267_WhatsApp_Image_20240821_at_124851.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66d55960807b2347dd5965f7",
    "name": "Living Room",
```

```
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079678_externa
llmg_1724331648267_WhatsApp_Image_20240821_at_124851_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66d55979433b95fe09e18971",
    "name": "Living Room",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104692_externa
llmg_1724331661795_WhatsApp_Image_20240821_at_124854_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66d55979433b95fe09e18973",
    "name": "Living Room",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104700_externa
llmg_1724331661797_WhatsApp_Image_20240821_at_124855_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66d55979433b95fe09e18974",
    "name": "Living Room",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104702_externa
llmg_1724331661798_WhatsApp_Image_20240821_at_124855.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66d55979433b95fe09e18978",
    "name": "Living Room",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104858_externa
llmg_1724331661801_WhatsApp_Image_20240821_at_124856.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66d5596a433b95fe09e18929",
    "name": "Living Room",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258089635_externa
llmg_1724331661792_WhatsApp_Image_20240821_at_124853.jpeg",
    "orientation": "landscape"
  }
]
},
```



```
"indicatorRange": {
  "carpetRateRange": {
    "min": "12712.00",
    "max": "15496.00"
  },
  "builtUpRateRange": {
    "min": "10594.00",
    "max": "12913.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "316.00",
"empanelmentNo": [
  "HO/CREDIT/67/ 2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66c736f2186d6d9b72b8317d",
"ownerName": "Mrs. Nirmala Dhananjay Suryavanshi",
```

```
"ownerPhoneNo": "9322565794",
"appAddress": "flat no 508, 5th floor, shreeji tower, off Geeta Nagar, phase 2, Mira
road East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "13/06/2008",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Pradeep K. Parab",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Dhananjay Pandurang Suryavanshi & Ms. Nirmala Dhananjay
Suryavanshi",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "4235/2008"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1725260993029_Sale_Deed__2008.pdf",
    "path": "cases/66c736f2186d6d9b72b8317d/
document_1725260993029_Sale_Deed__2008.pdf",
    "id": "652886",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Mon Sep 02 2024 12:39:53 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1250aa6d152c1801b316",
      "label": "Part Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "30/08/1996",
      "nameOfApprovingAuthority": {
```

```
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "NP/NR/350/0038/96-97 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1725261041812_OC.pdf",
"path": "cases/66c736f2186d6d9b72b8317d/document_1725261041812_OC.pdf",
"id": "535152",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Mon Sep 02 2024 12:40:41 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1254aa6d152c1801b328",
    "label": "Death Certificate"
  },
  "inputs": {
    "remark": "of Mr. Dhananjay Pandurang Suryavanshi dated 02/08/2021 issued by Kolhapur Municipal Corporation, Kolhapur."
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "961809",
  "path": "cases/66c736f2186d6d9b72b8317d/document_1725263344673_Death_Certificate.pdf",
  "fileName": "document_1725263344673_Death_Certificate.pdf"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "documentDate": "17/04/2022",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "041"
},
}
```

```
    "isHardCopy": false,
    "displayStatus": true,
    "fileName":
"document_1725270274665_document_1724327913851_1724327911759_508_B.pdf",
    "path": "cases/66c736f2186d6d9b72b8317d/
document_1725270274665_document_1724327913851_1724327911759_508_B.pdf",
    "id": "232864",
    "uploadedBy": "60f915d3f3dd69653a592199",
    "createdAt": "Mon Sep 02 2024 15:14:37 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010771",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "999550",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Aug 20 2024 16:29:35 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Nirmala Dhananjay Suryavanshi",
    "phone": "9322565794",
    "ownershipShare": "",
    "email": "",
    "id": "121677"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "805075",
    "name": "Living Room",
    "length": "15.83",
    "length1": "15",
    "length2": "10",
    "width": "8.83",
    "width1": "8",
    "width2": "10",
```

```
"totalArea": "139.86",
"images": [],
"extraAreas": [],
"finalArea": "139.86"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "8.08",
  "width1": "8",
  "width2": "1",
  "totalArea": "94.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "94.31"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "62.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "62.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "3",
"name": "Dining",
"length": "15.83",
"length1": "15",
"length2": "10",
"width": "8.67",
"width1": "8",
"width2": "8",
"totalArea": "137.22",
"images": [],
"extraAreas": [],
"finalArea": "137.22"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "25.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "12.83",
  "length1": "12",
  "length2": "10",
  "width": "5.42",
  "width1": "5",
  "width2": "5",
  "totalArea": "69.51",
  "images": [],
```



```
"extraAreas": [],
"finalArea": "69.51"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "5.58",
  "length1": "5",
  "length2": "7",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "22.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "WC",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
```

```
"length": "1.83",
"length1": "1",
"length2": "10",
"width": "2.67",
"width1": "2",
"width2": "8",
"totalArea": "4.89",
"images": [],
"extraAreas": [],
"finalArea": "4.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bedroom",
  "length": "10.58",
  "length1": "10",
  "length2": "7",
  "width": "8.42",
  "width1": "8",
  "width2": "5",
  "totalArea": "89.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "89.08"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "582980",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "316",
    "squareMeterArea": "29.36",
```

```
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltupPercentage": "",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "472.00",
"squareMeterArea": "43.85",
"expectedRate": "12711.86",
"percentage": ""
},
"builtUpArea": {
"area": "566.40",
"squareMeterArea": "52.62",
"expectedRate": "10593.22",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66d30d8e433b95fe09e14496",
"property": "Geeta Nagar",
"area": "472",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Ground",
"source": "Nobroker.com",
"expectedPrice": "6000000",
"expectedRate": "12711.86",
"builtUpExpectedRate": "10593.22",
"image": "cases/66c736f2186d6d9b72b8317d/
indicator_1725106717252_Image.png",
"squareMeter": "43.85",
"id": "550373"
```

```
},
{
  "carpetArea": {
    "area": "423.00",
    "squareMeterArea": "39.30",
    "expectedRate": "13475.18",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "507.60",
    "squareMeterArea": "47.16",
    "expectedRate": "11229.31",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66d30d8e433b95fe09e14497",
  "property": "Geeta Nagar, Mira Road",
  "area": "423",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "4",
  "source": "https://www.99acres.com/",
  "expectedPrice": "5700000",
  "expectedRate": "13475.18",
  "builtUpExpectedRate": "11229.31",
  "image": "cases/66c736f2186d6d9b72b8317d/
indicator_1725107155600_Image.png",
  "squareMeter": "39.30",
  "id": "991863"
},
{
  "carpetArea": {
    "area": "277.50",
    "squareMeterArea": "25.78",
    "expectedRate": "15495.50",
    "percentage": ""
  },
  "builtUpArea": {
```

```
"area": "333.00",
"squareMeterArea": "30.94",
"expectedRate": "12912.91",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66d30d8e433b95fe09e14498",
"property": "Geeta Sarovar, Geeta nagar, Mira Road",
"area": "333",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "4",
"source": "Index_no.2",
"expectedPrice": "4300000",
"expectedRate": "15495.50",
"builtUpExpectedRate": "4300000",
"image": "cases/66c736f2186d6d9b72b8317d/
indicator_1725107269737_Image.png",
"squareMeter": "30.94",
"id": "362575"
},
{
"carpetArea": {
"area": "360.00",
"squareMeterArea": "33.45",
"expectedRate": "13750.00",
"percentage": ""
},
"builtUpArea": {
"area": "432.00",
"squareMeterArea": "40.13",
"expectedRate": "11458.33",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
```

```
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66d30d8e433b95fe09e14499",
  "property": "Geeta Nagar, Mira Road",
  "area": "432",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "4",
  "source": "Index_no.2",
  "expectedPrice": "4950000",
  "expectedRate": "13750.00",
  "builtUpExpectedRate": "4950000",
  "image": "cases/66c736f2186d6d9b72b8317d/
indicator_1725107348927_Image.png",
  "squareMeter": "40.13",
  "id": "645089"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c736800f117327db746a69",
    "name":
"externallmg_1724331648245_WhatsApp_Image_20240821_at_124844.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/
externallmg_1724331648245_WhatsApp_Image_20240821_at_124844.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c736800f117327db746a73",
    "name":
"externallmg_1724331648266_WhatsApp_Image_20240821_at_124851_1.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/
externallmg_1724331648266_WhatsApp_Image_20240821_at_124851_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5595300f75047be5fa701",
```

```
    "name": "externallmg_1725258067225_externallmg_1724331648243_WhatsApp_I
mage_20240821_at_124858_1.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258067225_externall
mg_1724331648243_WhatsApp_Image_20240821_at_124858_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5595300f75047be5fa702",
    "name": "externallmg_1725258067238_externallmg_1724331648244_WhatsApp_I
mage_20240821_at_124858.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258067238_externall
mg_1724331648244_WhatsApp_Image_20240821_at_124858.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5595300f75047be5fa703",
    "name": "externallmg_1725258067239_externallmg_1724331648246_WhatsApp_I
mage_20240821_at_124846.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258067239_externall
mg_1724331648246_WhatsApp_Image_20240821_at_124846.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5595300f75047be5fa704",
    "name": "externallmg_1725258067240_externallmg_1724331648249_WhatsApp_I
mage_20240821_at_124848_1.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258067240_externall
mg_1724331648249_WhatsApp_Image_20240821_at_124848_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5595300f75047be5fa705",
    "name": "externallmg_1725258067256_externallmg_1724331648252_WhatsApp_I
mage_20240821_at_124848.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258067256_externall
mg_1724331648252_WhatsApp_Image_20240821_at_124848.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5595300f75047be5fa706",
  "name": "externallmg_1725258067259_externallmg_1724331648255_WhatsApp_I
mage_20240821_at_124849_1.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258067259_externall
mg_1724331648255_WhatsApp_Image_20240821_at_124849_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5595300f75047be5fa707",
  "name": "externallmg_1725258067269_externallmg_1724331648258_WhatsApp_I
mage_20240821_at_124849_2.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258067269_externall
mg_1724331648258_WhatsApp_Image_20240821_at_124849_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55960807b2347dd5965f2",
  "name": "externallmg_1725258079651_externallmg_1724331648259_WhatsApp_I
mage_20240821_at_124849.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079651_externall
mg_1724331648259_WhatsApp_Image_20240821_at_124849.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55960807b2347dd5965f3",
  "name": "externallmg_1725258079652_externallmg_1724331648261_WhatsApp_I
mage_20240821_at_124850_1.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079652_externall
mg_1724331648261_WhatsApp_Image_20240821_at_124850_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55960807b2347dd5965f4",
  "name": "externallmg_1725258079654_externallmg_1724331648262_WhatsApp_I
mage_20240821_at_124850_2.jpeg",
```



```
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079654_externallmg_1724331648262_WhatsApp_Image_20240821_at_124850_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d55960807b2347dd5965f5",
    "name": "externallmg_1725258079677_externallmg_1724331648264_WhatsApp_Image_20240821_at_124850.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079677_externallmg_1724331648264_WhatsApp_Image_20240821_at_124850.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d55960807b2347dd5965f6",
    "name": "externallmg_1725258079678_externallmg_1724331648267_WhatsApp_Image_20240821_at_124851.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079678_externallmg_1724331648267_WhatsApp_Image_20240821_at_124851.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d55960807b2347dd5965f7",
    "name": "externallmg_1725258079678_externallmg_1724331648267_WhatsApp_Image_20240821_at_124851_2.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079678_externallmg_1724331648267_WhatsApp_Image_20240821_at_124851_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d55960807b2347dd5965f8",
    "name": "externallmg_1725258079683_externallmg_1724331661787_WhatsApp_Image_20240821_at_124851.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258079683_externallmg_1724331661787_WhatsApp_Image_20240821_at_124851.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66d5596a433b95fe09e18924",
    "name": "externallmg_1725258089597_externallmg_1724331661788_WhatsApp_I
mage_20240821_at_124852_1.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258089597_externall
mg_1724331661788_WhatsApp_Image_20240821_at_124852_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5596a433b95fe09e18925",
    "name": "externallmg_1725258089607_externallmg_1724331661789_WhatsApp_I
mage_20240821_at_124852.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258089607_externall
mg_1724331661789_WhatsApp_Image_20240821_at_124852.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5596a433b95fe09e18926",
    "name": "externallmg_1725258089607_externallmg_1724331661789_WhatsApp_I
mage_20240821_at_124852_2.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258089607_externall
mg_1724331661789_WhatsApp_Image_20240821_at_124852_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5596a433b95fe09e18927",
    "name": "externallmg_1725258089608_externallmg_1724331661790_WhatsApp_I
mage_20240821_at_124853_1.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258089608_externall
mg_1724331661790_WhatsApp_Image_20240821_at_124853_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5596a433b95fe09e18928",
    "name": "externallmg_1725258089620_externallmg_1724331661791_WhatsApp_I
mage_20240821_at_124853_2.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258089620_externall
mg_1724331661791_WhatsApp_Image_20240821_at_124853_2.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5596a433b95fe09e18929",
  "name": "externallmg_1725258089635_externallmg_1724331661792_WhatsApp_I
mage_20240821_at_124853.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258089635_externall
mg_1724331661792_WhatsApp_Image_20240821_at_124853.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5596a433b95fe09e1892a",
  "name": "externallmg_1725258089636_externallmg_1724331661793_WhatsApp_I
mage_20240821_at_124854_1.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258089636_externall
mg_1724331661793_WhatsApp_Image_20240821_at_124854_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55979433b95fe09e18970",
  "name": "externallmg_1725258104690_externallmg_1724331661795_WhatsApp_I
mage_20240821_at_124854.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104690_externall
mg_1724331661795_WhatsApp_Image_20240821_at_124854.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55979433b95fe09e18971",
  "name": "externallmg_1725258104692_externallmg_1724331661795_WhatsApp_I
mage_20240821_at_124854_2.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104692_externall
mg_1724331661795_WhatsApp_Image_20240821_at_124854_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55979433b95fe09e18972",
```

```
    "name": "externallmg_1725258104699_externallmg_1724331661796_WhatsApp_I
mage_20240821_at_124855_1.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104699_externall
mg_1724331661796_WhatsApp_Image_20240821_at_124855_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d55979433b95fe09e18973",
    "name": "externallmg_1725258104700_externallmg_1724331661797_WhatsApp_I
mage_20240821_at_124855_2.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104700_externall
mg_1724331661797_WhatsApp_Image_20240821_at_124855_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d55979433b95fe09e18974",
    "name": "externallmg_1725258104702_externallmg_1724331661798_WhatsApp_I
mage_20240821_at_124855.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104702_externall
mg_1724331661798_WhatsApp_Image_20240821_at_124855.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d55979433b95fe09e18975",
    "name": "externallmg_1725258104751_externallmg_1724331661798_WhatsApp_I
mage_20240821_at_124855_3.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104751_externall
mg_1724331661798_WhatsApp_Image_20240821_at_124855_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d55979433b95fe09e18976",
    "name": "externallmg_1725258104857_externallmg_1724331661799_WhatsApp_I
mage_20240821_at_124856_1.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104857_externall
mg_1724331661799_WhatsApp_Image_20240821_at_124856_1.jpeg",
    "orientation": "landscape"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55979433b95fe09e18977",
  "name": "externallmg_1725258104858_externallmg_1724331661800_WhatsApp_I
mage_20240821_at_124856_2.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104858_externall
mg_1724331661800_WhatsApp_Image_20240821_at_124856_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55979433b95fe09e18978",
  "name": "externallmg_1725258104858_externallmg_1724331661801_WhatsApp_I
mage_20240821_at_124856.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104858_externall
mg_1724331661801_WhatsApp_Image_20240821_at_124856.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55979433b95fe09e18979",
  "name": "externallmg_1725258104859_externallmg_1724331661802_WhatsApp_I
mage_20240821_at_124857_1.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104859_externall
mg_1724331661802_WhatsApp_Image_20240821_at_124857_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55979433b95fe09e1897a",
  "name": "externallmg_1725258104860_externallmg_1724331661804_WhatsApp_I
mage_20240821_at_124857_2.jpeg",
  "path": "cases/66c736f2186d6d9b72b8317d/externallmg_1725258104860_externall
mg_1724331661804_WhatsApp_Image_20240821_at_124857_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d55979433b95fe09e1897b",
  "name": "externallmg_1725258104861_externallmg_1724331661805_WhatsApp_I
mage_20240821_at_124857.jpeg",
```

```
    "path": "cases/66c736f2186d6d9b72b8317d/externalImg_1725258104861_external  
mg_1724331661805_WhatsApp_Image_20240821_at_124857.jpeg",  
    "orientation": "landscape"  
  }  
],  
"externalDocuments": [],  
"processingDocuments": [  
  {  
    "originalname": "Untitled.pdf",  
    "filename": "1725107570862_Untitled.pdf",  
    "path": "cases/66c736f2186d6d9b72b8317d/  
processingDocuments/1725107570862_Untitled.pdf",  
    "size": "489061",  
    "createdAt": "Sat Aug 31 2024 18:02:51 GMT+0530 (India Standard Time)",  
    "uploadedBy": "60f915d3f3dd69653a592199"  
  },  
  {  
    "originalname": "11000.pdf",  
    "filename": "1725107571001_11000.pdf",  
    "path": "cases/66c736f2186d6d9b72b8317d/  
processingDocuments/1725107571001_11000.pdf",  
    "size": "152901",  
    "createdAt": "Sat Aug 31 2024 18:02:51 GMT+0530 (India Standard Time)",  
    "uploadedBy": "60f915d3f3dd69653a592199"  
  },  
  {  
    "originalname": "12000.pdf",  
    "filename": "1725107571028_12000.pdf",  
    "path": "cases/66c736f2186d6d9b72b8317d/  
processingDocuments/1725107571028_12000.pdf",  
    "size": "152071",  
    "createdAt": "Sat Aug 31 2024 18:02:51 GMT+0530 (India Standard Time)",  
    "uploadedBy": "60f915d3f3dd69653a592199"  
  },  
  {  
    "originalname": "1719900577742_alculation_123_2.xlsx",  
    "filename": "1725107571105_1719900577742_alculation_123_2.xlsx",  
    "path": "cases/66c736f2186d6d9b72b8317d/  
processingDocuments/1725107571105_1719900577742_alculation_123_2.xlsx",  
    "size": "1216990",  
    "createdAt": "Sat Aug 31 2024 18:02:51 GMT+0530 (India Standard Time)",  
    "uploadedBy": "60f915d3f3dd69653a592199"  
  },  
  {  
    "originalname": "igr_16731.pdf",  
    "filename": "1725107571492_igr_16731.pdf",
```

```
    "path": "cases/66c736f2186d6d9b72b8317d/
processingDocuments/1725107571492_igr_16731.pdf",
    "size": "152661",
    "createdAt": "Sat Aug 31 2024 18:02:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "OC.pdf",
    "filename": "1725263010225_OC.pdf",
    "path": "cases/66c736f2186d6d9b72b8317d/
processingDocuments/1725263010225_OC.pdf",
    "size": "489061",
    "createdAt": "Mon Sep 02 2024 13:13:30 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Deed - 2008.pdf",
    "filename": "1725263010230_Sale_Deed__2008.pdf",
    "path": "cases/66c736f2186d6d9b72b8317d/
processingDocuments/1725263010230_Sale_Deed__2008.pdf",
    "size": "17588533",
    "createdAt": "Mon Sep 02 2024 13:13:30 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details.jpeg",
    "filename": "1725263010467_Site_Details.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/
processingDocuments/1725263010467_Site_Details.jpeg",
    "size": "152198",
    "createdAt": "Mon Sep 02 2024 13:13:30 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sketch & Diamentiaon.jpeg",
    "filename": "1725263010468_Sketch__Diamentiaon.jpeg",
    "path": "cases/66c736f2186d6d9b72b8317d/
processingDocuments/1725263010468_Sketch__Diamentiaon.jpeg",
    "size": "90031",
    "createdAt": "Mon Sep 02 2024 13:13:30 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "OC.pdf",
    "filename": "1725263039763_OC.pdf",
    "path": "cases/66c736f2186d6d9b72b8317d/
processingDocuments/1725263039763_OC.pdf",
```

```
"size": "489061",
"createdAt": "Mon Sep 02 2024 13:13:59 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"lastName": "Kuperkar",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "66c859af0f117327db74d706",
"note": "Rate verification done, Pending for OC",
"taskId": "66c736f2c884d112334ec876",
"createdAt": "2024-08-23T09:43:11.491Z"
}
],
"createdAt": "2024-08-22T13:02:42.162Z",
"updatedAt": "2024-09-02T09:46:05.212Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60f915d3f3dd69653a592199",
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Residential Flat No. 507, 5th Floor, Wing - B, Shreeji Tower Co-op. Hsg.
Soc. Ltd., Geeta Nagar, Phase II, Behind Petrol Pump, Mira-Bhayandar Main Road,
Village - Bhayander, Taluka - Thane, District - Thane, Mira Road (East), PIN - 401 107,
State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mrs. Nirmala Dhananjay Suryavanshi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": ""
```



```
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Ower",
"siteVisitContactNo": "9322565794",
"invoiceId": null,
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Any Other Document",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 316.00",
"flatRate": "12000",
"landOtherRate": "9500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"finalSaleablePercentage": "",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Dining + 2
Passage + WC",
"carpetTotal": "657.12",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "788.54",
"finalCarpetArea": "657.12",
"finalSalableArea": "788.54",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"reportGeneratedDate": "Mon Sep 02 2024 12:58:33 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-08-21",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
```

```

    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	15'10"	8'10"	139.86
Bedroom	11'8"	8'1"	94.31
Toilet	7'10"	8'00"	62.67
Dining	15'10"	8'8"	137.22
Passage	8'5"	3'00"	25.25
Kitchen	12'10"	5'5"	69.51
Toilet	5'7"	4'00"	22.33
WC	4'00"	3'00"	12.00
Passage	1'10"	2'8"	4.89
Bedroom	10'7"	8'5"	89.08
Other Composition :			