

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856babe"
    },
    "firstName": "Sumit Kumar",
    "type": "CREDITOFFICER",
    "_id": "66cf13e60f117327db7828c2",
    "email": "cord.rasmecvns@sbi.co.in",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "7458999574"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856babe",
  "branchCode": "000299",
  "type": "BRANCH",
  "name": "RACPC VARANASI",
  "email": "cord.rasmecvns@sbi.co.in",
  "mobileNo": "05427497369",
  "alternateMobileNo": "",
  "address": "MAIN BRANCH CAMPUS\nNEAR KUTCHEHRY CANTT\nVARANASI
221002\n",
  "ledgerName": "",
  "fax": null,
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "6006d4ce5080a310ac1fdcf2",
  "role": "ADMIN",
  "firstName": "Jagdish ",
  "email": "jagdish.bhatt@vastukala.org",
  "lastName": "Bhatt",
  "mobileNo": "8425864014",
  "shortName": "JB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "66850df5d9f18310ed2e5d98",
  "role": "SITEENGINEER",
  "firstName": "Krishna",
  "email": "krishnagawade9@gmail.com",
  "lastName": "Gawde",
  "mobileNo": "9821646373",
  "designation": "Site Engg",
  "shortName": "Krishna",
  "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
```

```
{
  "title": {
    "value": "Wealth_Tax",
    "label": "Wealth Tax"
  },
  "_id": "6084131a13f01f158c6ea1f4",
  "number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.249889450423726",
  "longitude": "72.86400845722292"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "28/08/2024 06:10 pm"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
}
```

```
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "31",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
```

```
"status": true,
"name": "City",
"key": "city",
"value": "Mumbai",
"label": false
},
"tahsilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahsilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Northern Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "S V Road",
```

```
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Shantinagar",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "1",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
```

```
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "3101",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
}
```



```
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400068",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dahisar East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
```

```
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
}
```

```
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
}
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
```



```
"_id": "66cf1aae0f117327db7831e0",
"ownerName": "Kamlesh Dubey",
"ownerPhoneNo": "9450253184",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9415975538",
"contactPersonName": "Kamlesh Dubey",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Kamlesh Dubey",
    "phone": "9450253184",
    "ownershipShare": "",
    "email": "",
    "id": "710138"
  }
],
"caseReferredBy": "6006d4ce5080a310ac1fdfc2",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 3101, 31st Floor, Wing - 1, Northern Heights, S V
Road, Shantinagar, Dahisar East, Mumbai, 400068, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1724848793349_ats1_0001.pdf",
    "path": "cases/66cf1aae0f117327db7831e0/
document_1724848793349_ats1_0001.pdf",
    "id": "159267",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Wed Aug 28 2024 18:10:14 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1724848808849_ats2_0001.pdf",
    "path": "cases/66cf1aae0f117327db7831e0/
document_1724848808849_ats2_0001.pdf",
```

```
    "id": "132671",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Wed Aug 28 2024 18:10:14 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "010894",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "236559",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Wed Aug 28 2024 18:10:14 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d141820f117327db78f449",
    "name":
"externalImg_1724989826880_WhatsApp_Image_20240830_at_004320_1.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externalImg_1724989826880_WhatsApp_Image_20240830_at_004320_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d141820f117327db78f44a",
```

```
"name":
"externallmg_1724989826880_WhatsApp_Image_20240830_at_004320_2.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826880_WhatsApp_Image_20240830_at_004320_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f44b",
  "name":
"externallmg_1724989826882_WhatsApp_Image_20240830_at_004320_3.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826882_WhatsApp_Image_20240830_at_004320_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f44c",
  "name":
"externallmg_1724989826885_WhatsApp_Image_20240830_at_004320.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826885_WhatsApp_Image_20240830_at_004320.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f44d",
  "name":
"externallmg_1724989826887_WhatsApp_Image_20240830_at_004321.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826887_WhatsApp_Image_20240830_at_004321.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f44e",
  "name":
"externallmg_1724989826890_WhatsApp_Image_20240830_at_004322_1.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826890_WhatsApp_Image_20240830_at_004322_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f44f",
  "name":
"externallmg_1724989826891_WhatsApp_Image_20240830_at_004322_2.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826891_WhatsApp_Image_20240830_at_004322_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f450",
  "name":
"externallmg_1724989826892_WhatsApp_Image_20240830_at_004322.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826892_WhatsApp_Image_20240830_at_004322.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f451",
  "name":
"externallmg_1724989826893_WhatsApp_Image_20240830_at_004323_1.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826893_WhatsApp_Image_20240830_at_004323_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f452",
  "name":
"externallmg_1724989826893_WhatsApp_Image_20240830_at_004323_2.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826893_WhatsApp_Image_20240830_at_004323_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f453",
  "name":
"externallmg_1724989826894_WhatsApp_Image_20240830_at_004323.jpeg",
```

```
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826894_WhatsApp_Image_20240830_at_004323.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d141820f117327db78f454",
    "name":
"externallmg_1724989826895_WhatsApp_Image_20240830_at_004324_1.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826895_WhatsApp_Image_20240830_at_004324_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d141820f117327db78f455",
    "name":
"externallmg_1724989826898_WhatsApp_Image_20240830_at_004324_2.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826898_WhatsApp_Image_20240830_at_004324_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d141820f117327db78f456",
    "name":
"externallmg_1724989826902_WhatsApp_Image_20240830_at_004324.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826902_WhatsApp_Image_20240830_at_004324.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d141820f117327db78f457",
    "name":
"externallmg_1724989826904_WhatsApp_Image_20240830_at_004325_1.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826904_WhatsApp_Image_20240830_at_004325_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66d141820f117327db78f458",
  "name":
"externallmg_1724989826905_WhatsApp_Image_20240830_at_004325_2.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826905_WhatsApp_Image_20240830_at_004325_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f459",
  "name":
"externallmg_1724989826905_WhatsApp_Image_20240830_at_004325.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826905_WhatsApp_Image_20240830_at_004325.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f45a",
  "name":
"externallmg_1724989826907_WhatsApp_Image_20240830_at_004326_1.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826907_WhatsApp_Image_20240830_at_004326_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f45b",
  "name":
"externallmg_1724989826913_WhatsApp_Image_20240830_at_004326_2.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826913_WhatsApp_Image_20240830_at_004326_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d141820f117327db78f45c",
  "name":
"externallmg_1724989826914_WhatsApp_Image_20240830_at_004326.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989826914_WhatsApp_Image_20240830_at_004326.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d14192da840b1214d00544",
    "name":
"externallmg_1724989842722_WhatsApp_Image_20240830_at_004326_2.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842722_WhatsApp_Image_20240830_at_004326_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d14192da840b1214d00545",
    "name":
"externallmg_1724989842723_WhatsApp_Image_20240830_at_004326.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842723_WhatsApp_Image_20240830_at_004326.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d14192da840b1214d00546",
    "name":
"externallmg_1724989842725_WhatsApp_Image_20240830_at_004406.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842725_WhatsApp_Image_20240830_at_004406.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d14192da840b1214d00547",
    "name":
"externallmg_1724989842726_WhatsApp_Image_20240830_at_004203.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842726_WhatsApp_Image_20240830_at_004203.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d14192da840b1214d00548",
```

```
"name":
"externallmg_1724989842729_WhatsApp_Image_20240830_at_004204_1.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842729_WhatsApp_Image_20240830_at_004204_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d14192da840b1214d00549",
  "name":
"externallmg_1724989842730_WhatsApp_Image_20240830_at_004204.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842730_WhatsApp_Image_20240830_at_004204.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d14192da840b1214d0054a",
  "name":
"externallmg_1724989842731_WhatsApp_Image_20240830_at_004311.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842731_WhatsApp_Image_20240830_at_004311.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d14192da840b1214d0054b",
  "name":
"externallmg_1724989842732_WhatsApp_Image_20240830_at_004312.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842732_WhatsApp_Image_20240830_at_004312.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d14192da840b1214d0054c",
  "name":
"externallmg_1724989842736_WhatsApp_Image_20240830_at_004313_1.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842736_WhatsApp_Image_20240830_at_004313_1.jpeg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d14192da840b1214d0054d",
  "name":
"externallmg_1724989842738_WhatsApp_Image_20240830_at_004313_2.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842738_WhatsApp_Image_20240830_at_004313_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d14192da840b1214d0054e",
  "name":
"externallmg_1724989842740_WhatsApp_Image_20240830_at_004313.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842740_WhatsApp_Image_20240830_at_004313.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d14192da840b1214d0054f",
  "name":
"externallmg_1724989842742_WhatsApp_Image_20240830_at_004316_1.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842742_WhatsApp_Image_20240830_at_004316_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d14192da840b1214d00550",
  "name":
"externallmg_1724989842743_WhatsApp_Image_20240830_at_004316.jpeg",
  "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842743_WhatsApp_Image_20240830_at_004316.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d14192da840b1214d00551",
  "name":
"externallmg_1724989842744_WhatsApp_Image_20240830_at_004317_1.jpeg",
```

```
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842744_WhatsApp_Image_20240830_at_004317_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d14192da840b1214d00552",
    "name":
"externallmg_1724989842748_WhatsApp_Image_20240830_at_004317_2.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842748_WhatsApp_Image_20240830_at_004317_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d14192da840b1214d00553",
    "name":
"externallmg_1724989842753_WhatsApp_Image_20240830_at_004317.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842753_WhatsApp_Image_20240830_at_004317.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d14192da840b1214d00554",
    "name":
"externallmg_1724989842755_WhatsApp_Image_20240830_at_004318.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842755_WhatsApp_Image_20240830_at_004318.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d14192da840b1214d00555",
    "name":
"externallmg_1724989842755_WhatsApp_Image_20240830_at_004319.jpeg",
    "path": "cases/66cf1aae0f117327db7831e0/
externallmg_1724989842755_WhatsApp_Image_20240830_at_004319.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-28T12:40:14.694Z",
"updatedAt": "2024-08-30T03:50:42.803Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fdcf2"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			