

```
{
  "typeOfReport": {
    "value": "Unit",
    "label": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b99c"
    },
    "firstName": "Lalita ",
    "type": "CREDITOFFICER",
    "_id": "65000e71a8e9b70221dfa1f3",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9820287285",
    "email": "Lalita@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4615155",
    "discussWithPerson": "Lalita ",
    "expectedFees": 2307.5775,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b99c",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Dadar Branch ",
  "email": "dadar@cosmosbank.in",
  "mobileNo": "02224476018",
  "alternateMobileNo": "8369167372",
  "address": "Horizon Bldg.,1st Floor, Ranade Road & Gokhale Road, Dadar (West),
Mumbai - 400 028, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK - DADAR",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "MAKER",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.140969923355993",
  "longitude": "72.83475363940497"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83475363940497,
    19.140969923355993
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "31/08/2024 12:09 pm"
    },
    {
      "dateTime": "31/08/2024 12:00 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Oshiwara ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Crescent Tower",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Morya Estate Veera Desai Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
```

```
"key": "street2",
"value": "Off New Link Road ",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```



```
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "801-802--803-804",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400053",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    }
  },
}
```

```
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "landAndBuildingDetails": {
    "actualBuildingBoundaries": [],
    "documentsBuildingBoundaries": []
  },
  "igrFinalRate": {
    "floorRatePercentage": "0.00"
  },
  "outgoingDetail": {
    "monthlyRent": ""
  },
  "siteMeasurement": {
    "isSiteVisitAllowed": true
  },
  "finalPlinthArea": {
    "area": "0.00"
  },
  "routeMap": {
    "routeMapDetail": {
      "routeMapImg": "",
      "routeLat": "",
      "routeLng": "",
      "stationName": "",
      "routeDistance": ""
    },
    "finalLatLng": {
      "coordinates": []
    },
    "locationMapImg": []
  },
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": "",
      "totalFairMarketValue": ""
    }
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
}
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
```

```
"carpetRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66d1ad26da840b1214d0a0f4",
"ownerName": "Yogesh JIvanlal Lakhani ",
"ownerPhoneNo": "0000000008",
"appAddress": "OFC no - 801,802,803,804,8th floor, crescent tower co operative housing society Ltd, New link road, near - Maurya house, Andheri West ",
```

```
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66d1ad26da840b1214d0a0f4/document_1725017353775_1725017350695_Bright_13__Yogesh_Lakhani__ofc_801_to_804.pdf",
    "fileName": "document_1725017353775_1725017350695_Bright_13__Yogesh_Lakhani__ofc_801_to_804.pdf",
    "id": "645684",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Fri Aug 30 2024 16:59:42 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010957",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "613684",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Aug 30 2024 16:59:42 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Yogesh JIvanlal Lakhani ",
    "phone": "0000000008",
    "ownershipShare": "",
    "email": "",
    "id": "354953"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66d74a3d433b95fe09e2958c",
  "name": "externallmg_1725385250665_1725385211731_image_0.jpeg",
  "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385250665_1725385211731_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66d74a3d433b95fe09e2958d",
  "name": "externallmg_1725385251664_1725385211731_image_1.jpeg",
  "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385251664_1725385211731_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66d74a3d433b95fe09e2958e",
  "name": "externallmg_1725385252579_1725385211731_image_2.jpeg",
  "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385252579_1725385211731_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66d74a3d433b95fe09e2958f",
  "name": "externallmg_1725385254751_1725385211731_image_3.jpeg",
  "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385254751_1725385211731_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66d74a3d433b95fe09e29590",
  "name": "externallmg_1725385257078_1725385211731_image_4.jpeg",
  "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385257078_1725385211731_image_4.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e29591",
    "name": "externallmg_1725385257704_1725385211731_image_5.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385257704_1725385211731_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e29592",
    "name": "externallmg_1725385259135_1725385211731_image_6.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385259135_1725385211731_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e29593",
    "name": "externallmg_1725385260205_1725385211731_image_7.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385260205_1725385211731_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e29594",
    "name": "externallmg_1725385261511_1725385211731_image_8.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385261511_1725385211731_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e29595",
    "name": "externallmg_1725385262501_1725385211731_image_9.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385262501_1725385211731_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "66d74a3d433b95fe09e29596",
    "name": "externallmg_1725385263224_1725385211731_image_10.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385263224_1725385211731_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e29597",
    "name": "externallmg_1725385263744_1725385211731_image_11.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385263744_1725385211731_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e29598",
    "name": "externallmg_1725385264674_1725385211731_image_12.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385264674_1725385211731_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e29599",
    "name": "externallmg_1725385266492_1725385211731_image_13.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385266492_1725385211731_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e2959a",
    "name": "externallmg_1725385267775_1725385211731_image_14.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385267775_1725385211731_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "66d74a3d433b95fe09e2959b",
    "name": "externallmg_1725385269957_1725385211731_image_15.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385269957_1725385211731_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e2959c",
    "name": "externallmg_1725385270566_1725385211731_image_16.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385270566_1725385211731_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e2959d",
    "name": "externallmg_1725385272038_1725385211731_image_17.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385272038_1725385211731_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e2959e",
    "name": "externallmg_1725385273569_1725385211731_image_18.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385273569_1725385211731_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d74a3d433b95fe09e2959f",
    "name": "externallmg_1725385275086_1725385211731_image_19.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385275086_1725385211731_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295e6",
```

```
    "name": "externalImg_1725385281404_1725385273912_image_0.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externalImg_1725385281404_1725385273912_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295e7",
    "name": "externalImg_1725385287887_1725385273913_image_1.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externalImg_1725385287887_1725385273913_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295e8",
    "name": "externalImg_1725385291459_1725385273913_image_2.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externalImg_1725385291459_1725385273913_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295e9",
    "name": "externalImg_1725385292563_1725385273913_image_3.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externalImg_1725385292563_1725385273913_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295ea",
    "name": "externalImg_1725385293975_1725385273913_image_4.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externalImg_1725385293975_1725385273913_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295eb",
    "name": "externalImg_1725385301401_1725385273913_image_5.jpeg",
```

```
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385301401_1725385273913_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295ec",
    "name": "externallmg_1725385309406_1725385273913_image_6.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385309406_1725385273913_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295ed",
    "name": "externallmg_1725385315049_1725385273913_image_7.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385315049_1725385273913_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295ee",
    "name": "externallmg_1725385317626_1725385273913_image_8.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385317626_1725385273913_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295ef",
    "name": "externallmg_1725385319991_1725385273913_image_9.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385319991_1725385273913_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d74a73433b95fe09e295f0",
    "name": "externallmg_1725385320871_1725385273913_image_10.jpeg",
    "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385320871_1725385273913_image_10.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d74a73433b95fe09e295f1",
  "name": "externallmg_1725385322095_1725385273913_image_11.jpeg",
  "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385322095_1725385273913_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d74a73433b95fe09e295f2",
  "name": "externallmg_1725385322833_1725385273914_image_12.jpeg",
  "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385322833_1725385273914_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d74a73433b95fe09e295f3",
  "name": "externallmg_1725385323568_1725385273914_image_13.jpeg",
  "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385323568_1725385273914_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d74a73433b95fe09e295f4",
  "name": "externallmg_1725385324294_1725385273914_image_14.jpeg",
  "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385324294_1725385273914_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d74a73433b95fe09e295f5",
  "name": "externallmg_1725385324820_1725385273914_image_15.jpeg",
  "path": "cases/66d1ad26da840b1214d0a0f4/
externallmg_1725385324820_1725385273914_image_15.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66d74a73433b95fe09e295f6",
      "name": "externalImg_1725385326015_1725385273914_image_16.jpeg",
      "path": "cases/66d1ad26da840b1214d0a0f4/
externalImg_1725385326015_1725385273914_image_16.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66d74a73433b95fe09e295f7",
      "name": "externalImg_1725385327041_1725385273914_image_17.jpeg",
      "path": "cases/66d1ad26da840b1214d0a0f4/
externalImg_1725385327041_1725385273914_image_17.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66d74a73433b95fe09e295f8",
      "name": "externalImg_1725385328039_1725385273914_image_18.jpeg",
      "path": "cases/66d1ad26da840b1214d0a0f4/
externalImg_1725385328039_1725385273914_image_18.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66d74a73433b95fe09e295f9",
      "name": "externalImg_1725385329245_1725385273914_image_19.jpeg",
      "path": "cases/66d1ad26da840b1214d0a0f4/
externalImg_1725385329245_1725385273914_image_19.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-08-30T11:29:42.160Z",
  "updatedAt": "2024-09-03T17:42:11.364Z",
  "__v": 0,
```

```

"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Commercial Unit No. 801-802--803-804, 8th Floor, Crescent Tower,
Morya Estate Veera Desai Road, Off New Link Road , Village - Oshiwara , Andheri
West, Mumbai, 400053, State - Maharashtra, India",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mr Shekhar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Contact Person",
"siteVisitContactNo": "9930474544"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			