

```
{
  "typeOfReport": {
    "label": "Row House",
    "value": "Row_House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ad7bc4191f7b344b003c51"
    },
    "firstName": "Vinayak",
    "type": "CREDITOFFICER",
    "_id": "66c6c6f5da840b1214cad671",
    "email": "cb221@unionbankofindia.com",
    "lastName": "Patil",
    "mobileNo": "",
    "workMobileNo": "9762793873"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6454615",
    "discussWithPerson": "Vinayak",
    "expectedFees": 3227.3075,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ad7bc4191f7b344b003c51",
  "name": "UBI-Large Corporate Branch Fort Mumbai",
  "branchCode": "",
  "mobileNo": "9967536256",
  "alternateMobileNo": "",
  "email": "dinesh.sharma@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Nanavati Mahalaya,18, Homi Modi Street, Fort Mumbai 400023"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
```

```
"role": "PICKUPPERSON",
"firstName": "Ramkrishna ",
"email": "rampatakar1991@gmail.com",
"lastName": "Patkar",
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62550ed0aba01e0af98f2f75",
"role": "SITEENGINEER",
"firstName": "Chandan",
"email": "ck06806@gmail.com",
"lastName": "Singh",
"mobileNo": "8454863607",
"designation": "",
"shortName": "CH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
]
},
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
```

```
{
  "title": {
    "value": "Wealth_Tax",
    "label": "Wealth Tax"
  },
  "_id": "6084131a13f01f158c6ea1f4",
  "number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.17549320335987",
  "longitude": "72.85399828294953"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85399828294953,
    19.17549320335987
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "31/08/2024 11:06 am"
    },
    {
      "dateTime": "31/08/2024 12:00 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chincholi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",

```

```
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "142",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Grauda HOuse",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
```

```
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
}
```

```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Row House No F",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```



```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Malad East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
```

```
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": ""
  }
}
```

```
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```

```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
},
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
```



```
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66d2aa4dda840b1214d10a28",
"ownerName": "Shalini Agarwal ",
"ownerPhoneNo": "9891689697",
"appAddress": "Row house no - F, plot no 142, cts no - 97 A/36/1, Near - Hanuman
temple, cheerangilal mehta road, Upper govind nagar, Malad East ",
"remark": "Urgent basis \n\ncontact person - Rohit pareek ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66d2aa4dda840b1214d10a28/document_1725082015057_17250820
12242_Shalini__Deed_Of_Conveyance_142.pdf",
    "fileName": "document_1725082015057_1725082012242_Shalini__Deed_Of_Conv
eyance_142.pdf",
    "id": "465088",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Sat Aug 31 2024 10:59:49 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66d2aa4dda840b1214d10a28/document_1725082072150_17250820
68856_Row_House_Chain_Agreement_BDR262262002.pdf",
    "fileName": "document_1725082072150_1725082068856_Row_House_Chain_Agre
ement_BDR262262002.pdf",
    "id": "956200",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Sat Aug 31 2024 10:59:49 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
```

```
    "displayStatus": false,
    "path": "cases/66d2aa4dda840b1214d10a28/
document_1725082117280_1725082113655_Row_House_OC_COPY_142.pdf",
    "fileName":
"document_1725082117280_1725082113655_Row_House_OC_COPY_142.pdf",
    "id": "675740",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Sat Aug 31 2024 10:59:49 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66d2aa4dda840b1214d10a28/
document_1725082179680_1725082176253_Ro_house_valuation.pdf",
    "fileName":
"document_1725082179680_1725082176253_Ro_house_valuation.pdf",
    "id": "889309",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Sat Aug 31 2024 10:59:49 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010967",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "852810",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Aug 31 2024 10:59:49 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shalini Agarwal ",
    "phone": "9891689697",
    "ownershipShare": "",
    "email": "",
    "id": "785690"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```

```
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c5a",
    "name": "externalImg_1725252031802_1725252016227_image_0.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externalImg_1725252031802_1725252016227_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c5b",
    "name": "externalImg_1725252032142_1725252016227_image_1.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externalImg_1725252032142_1725252016227_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c5c",
    "name": "externalImg_1725252033112_1725252016227_image_2.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externalImg_1725252033112_1725252016227_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c5d",
    "name": "externalImg_1725252034262_1725252016227_image_3.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externalImg_1725252034262_1725252016227_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "66d541c300f75047be5f8c5e",
    "name": "externallmg_1725252034263_1725252016227_image_4.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252034263_1725252016227_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c5f",
    "name": "externallmg_1725252034274_1725252016227_image_5.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252034274_1725252016227_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c60",
    "name": "externallmg_1725252034302_1725252016227_image_6.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252034302_1725252016227_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c61",
    "name": "externallmg_1725252034422_1725252016227_image_7.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252034422_1725252016227_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c62",
    "name": "externallmg_1725252035064_1725252016227_image_8.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252035064_1725252016227_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c63",
```

```
    "name": "externallmg_1725252035118_1725252016227_image_9.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252035118_1725252016227_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c64",
    "name": "externallmg_1725252035311_1725252016227_image_10.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252035311_1725252016227_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c65",
    "name": "externallmg_1725252035462_1725252016227_image_11.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252035462_1725252016227_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d541c300f75047be5f8c66",
    "name": "externallmg_1725252035578_1725252016227_image_12.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252035578_1725252016227_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5421900f75047be5f8d33",
    "name": "externallmg_1725252118749_1725252116084_image_0.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252118749_1725252116084_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5421900f75047be5f8d34",
    "name": "externallmg_1725252119023_1725252116084_image_1.jpeg",
```

```
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252119023_1725252116084_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5421900f75047be5f8d35",
    "name": "externallmg_1725252119190_1725252116084_image_2.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252119190_1725252116084_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5421900f75047be5f8d36",
    "name": "externallmg_1725252119415_1725252116084_image_3.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252119415_1725252116084_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5421900f75047be5f8d37",
    "name": "externallmg_1725252120215_1725252116084_image_4.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120215_1725252116084_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5421900f75047be5f8d38",
    "name": "externallmg_1725252120586_1725252116084_image_5.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120586_1725252116084_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d5421900f75047be5f8d39",
    "name": "externallmg_1725252120667_1725252116084_image_6.jpeg",
    "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120667_1725252116084_image_6.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d3a",
  "name": "externallmg_1725252120793_1725252116084_image_7.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120793_1725252116084_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d3b",
  "name": "externallmg_1725252120795_1725252116084_image_8.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120795_1725252116084_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d3c",
  "name": "externallmg_1725252120796_1725252116084_image_9.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120796_1725252116084_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d3d",
  "name": "externallmg_1725252120797_1725252116084_image_10.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120797_1725252116084_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d3e",
  "name": "externallmg_1725252120797_1725252116084_image_11.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120797_1725252116084_image_11.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d3f",
  "name": "externallmg_1725252120814_1725252116084_image_12.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120814_1725252116084_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d40",
  "name": "externallmg_1725252120815_1725252116084_image_13.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120815_1725252116084_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d41",
  "name": "externallmg_1725252120815_1725252116084_image_14.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120815_1725252116084_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d42",
  "name": "externallmg_1725252120863_1725252116084_image_15.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252120863_1725252116084_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d43",
  "name": "externallmg_1725252121022_1725252116084_image_16.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externallmg_1725252121022_1725252116084_image_16.jpeg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d44",
  "name": "externalImg_1725252121158_1725252116084_image_17.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externalImg_1725252121158_1725252116084_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d45",
  "name": "externalImg_1725252121503_1725252116084_image_18.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externalImg_1725252121503_1725252116084_image_18.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d5421900f75047be5f8d46",
  "name": "externalImg_1725252121550_1725252116084_image_19.jpeg",
  "path": "cases/66d2aa4dda840b1214d10a28/
externalImg_1725252121550_1725252116084_image_19.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-31T05:29:49.189Z",
"updatedAt": "2024-09-02T04:42:01.771Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Row House No. Row House No F, Ground Floor, Grauda
H0use, Plot No. 142, Village - Chincholi, Malad East, Mumbai, State - Maharashtra,
India",
"updatedBy": "62550ed0aba01e0af98f2f75",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
```

"contactPersonName": "Shalini Agarwal ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819689697"

}

Name	Length	Width	Total
Composition :			
Other Composition :			