

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "Sagar",
    "type": "CREDITOFFICER",
    "_id": "64d2280087258203eaae5058",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8999588878",
    "email": "rlf.nasik@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
```

```
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
```

```
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.032797",
  "longitude": "73.793682"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-04",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-04",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-04",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Makhmalabad",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "422004",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3 +4",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "ABD Pride",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Samarth Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
}
```



```
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Behind Namco Cancer Hospital, Opposite RTO Road",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "30/3/7",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "604",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
```

```
"value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_",
"label": "Open-Conduit plumbing with Casing Capping Electrical wiring "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "18.00 Mtr DP Road",
    "west": "9 Mtr Road",
    "south": "MSEB Power Station and Plot No.17",
    "east": "Plot No.2"
  },
  "asPerDocumentAgreement": {
    "north": "18.00 Mtr DP Road",
    "west": "9 Mtr Road",
    "south": "MSEB Power Station and Plot No.17",
    "east": "Plot No.2"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space",
      "east": "Flat No.605 & Lobby ",
      "south": "Lobby, Lift, Duct & Flat No.603",
```

```
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Marginal Space",
    "east": "Flat No.605 & Lobby ",
    "south": "Lobby, Lift, Duct & Flat No.603",
    "west": "Marginal Space"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Building Plan Document No.C2/145/2022 Dated
04.07.2022 Issued by Nashik Municipal Corporation.\nNashik Municipal Corporation",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "Yes",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
```

```
"igrRate": {
  "propertyName": "Flat",
  "rate": "35500",
  "landRate": "13300",
  "igrImage": "cases/66d7f973807b2347dd5ae58d/igr_1725430737157_Image.png",
  "squareMeterGuideLineRate": "37275.00",
  "squareFeetGuideLineRate": "3463.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "35500.00",
  "squareMeterGuideLineRate": "37275.00",
  "squareFeetGuideLineRate": "3463.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "11000",
  "assessmentNo": "NA",
  "taxPaidHolderName": "NA",
  "taxAmount": "NA",
  "electricityServiceConnectionNo": "NA",
  "meterCardHolderName": "NA",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "as per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "NA",
  "negativeFactorsOfAffectMarketValue": "NA"
```

```
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Yes",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2023",
    "fullDate": "1/1/2023"
  },
  "planningArea": {
    "value": "Residential_cum_Commercial",
    "label": "Residential cum Commercial"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
  "qualityOfConstruction": {
```

```
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Yes",
"label": "Yes"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
}
```



```
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "1",
"totalLifeBuilding": "60",
"estimatedAge": "59",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "6",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66d7f973807b2347dd5ae58d/
routeMap_1725431970473_Image.png",
    "routeLat": "20.032797",
    "routeLng": "73.793682",
    "stationName": "Nashik Road",
    "routeDistance": "13.8",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
}
```

```
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "jwqmou",
    "name": "jwqmou",
    "image": "cases/66d7f973807b2347dd5ae58d/
routeMap_1725431901236_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
```

```
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5672800.00",
"finalValue": "5672800.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "95",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Sep 04 2024 12:57:31 GMT+0530 (India Standard Time)",
  "number": "2308033",
  "dayCount": "3",
  "monthCount": "39",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "3858821.00",
  "selectedBuildUpValue": "1114.30",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66d8039100f75047be60dba1",
      "name":
"externallmg_1725432720312_WhatsApp_Image_20240903_at_35704_PM_2.jpeg",
      "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720312_WhatsApp_Image_20240903_at_35704_PM_2.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "66d8039100f75047be60db9c",
      "name": "Living Room",
      "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720279_WhatsApp_Image_20240903_at_35701_PM_2.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66d8039100f75047be60db95",
      "name": "Living Room",
      "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720255_WhatsApp_Image_20240903_at_35658_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
```

```
    "_id": "66d8039100f75047be60db9b",
    "name": "Living Room",
    "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720275_WhatsApp_Image_20240903_at_35700_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66d8039100f75047be60db99",
    "name": "Living Room",
    "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720269_WhatsApp_Image_20240903_at_35700_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66d8039100f75047be60dba3",
    "name": "Living Room",
    "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720333_WhatsApp_Image_20240903_at_35705_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66d8039100f75047be60dba2",
    "name": "Living Room",
    "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720323_WhatsApp_Image_20240903_at_35704_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66d8039100f75047be60db9e",
    "name": "Living Room",
    "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720287_WhatsApp_Image_20240903_at_35702_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66d8039100f75047be60db98",
    "name": "Living Room",
    "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720260_WhatsApp_Image_20240903_at_35659_PM.jpeg",
    "orientation": "landscape"
  }
}
```

```
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5398.00",
    "max": "7500.00"
  },
  "builtUpRateRange": {
    "min": "4498.00",
    "max": "6250.00"
  },
  "saleableRateRange": {
    "min": "3748.00",
    "max": "5209.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1013.00",
"empanelmentNo": [
  "ZO :MZ:ADV:46:941\t"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
```

```
"_id": "66d7f973807b2347dd5ae58d",
"ownerName": "Mr.Rohit Balasaheb Patil & Sushmita Narendra Pawar",
"ownerPhoneNo": "9021337843",
"fullAddress": "Residential Flat No. 604, 6th Floor, ABD Pride, Behind Namco Cancer
Hospital, Opposite RTO Road, Plot No. 3 +4, Samarth Nagar, Village - Makhmalabad,
Taluka - Nashik, District - Nashik, 422004, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "30/08/2024",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s.Anup Builders and Developers ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr.Rohit Balasaheb Patil & Sushmita Narendra Pawar",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "9455/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1725429795390_CC_RERA_AGREEMENT.pdf",
    "path": "cases/66d7f973807b2347dd5ae58d/
document_1725429795390_CC_RERA_AGREEMENT.pdf",
    "id": "127674",
    "uploadedBy": "636a1ad14d42487767af3f91",
    "createdAt": "Wed Sep 04 2024 11:38:51 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
```

```
"documentDate": "04/07/2022",
"nameOfApprovingAuthority": {
  "value": "Nashik_Municipal_Corporation",
  "label": "Nashik Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "LND/BP/C2/145/2022"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1725429868323_CC_RERA_AGREEMENT.pdf",
"path": "cases/66d7f973807b2347dd5ae58d/
document_1725429868323_CC_RERA_AGREEMENT.pdf",
"id": "217968",
"uploadedBy": "636a1ad14d42487767af3f91",
"createdAt": "Wed Sep 04 2024 11:38:51 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "inputs": {
    "documentDate": "04/07/2022",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "C2/145/2022"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1725430018068_Building_Plan.pdf",
  "path": "cases/66d7f973807b2347dd5ae58d/
document_1725430018068_Building_Plan.pdf",
  "id": "338766",
  "uploadedBy": "636a1ad14d42487767af3f91",
  "createdAt": "Wed Sep 04 2024 11:38:51 GMT+0530 (India Standard Time)"
},
```

```
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "03/01/2023",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P51600048494"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1725430113274_CC_RERA_AGREEMENT.pdf",
  "path": "cases/66d7f973807b2347dd5ae58d/
document_1725430113274_CC_RERA_AGREEMENT.pdf",
  "id": "917081",
  "uploadedBy": "636a1ad14d42487767af3f91",
  "createdAt": "Wed Sep 04 2024 11:38:51 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "011037",
"createdBy": "636a1ad14d42487767af3f91",
"caseHistory": [
  {
    "id": "260673",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Sep 04 2024 11:38:51 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr.Rohit Balasaheb Patil & Sushmita Narendra Pawar",
    "phone": "9021337843",
    "ownershipShare": "",
    "email": "",
    "id": "788596"
  }
],
```

```
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "270829",
    "name": "Living Room",
    "length": "21.75",
    "length1": "21",
    "length2": "9",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "217.50",
    "images": [],
    "extraAreas": [],
    "finalArea": "217.50"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "17.50",
    "length1": "17",
    "length2": "6",
    "width": "7.50",
    "width1": "7",
    "width2": "6",
    "totalArea": "131.25",
    "images": [],
    "extraAreas": [],
    "finalArea": "131.25"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "name": "Bathroom",
```

```
"length": "9.33",
"length1": "9",
"length2": "4",
"width": "4.42",
"width1": "4",
"width2": "5",
"totalArea": "41.22",
"images": [],
"extraAreas": [],
"finalArea": "41.22"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "12.75",
  "length1": "12",
  "length2": "9",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "63.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "63.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "5.50",
  "width1": "5",
  "width2": "6",
  "totalArea": "22.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.00"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Balcony",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "4.50",
  "width1": "4",
  "width2": "6",
  "totalArea": "43.87",
  "images": [],
  "extraAreas": [],
  "finalArea": "43.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "14.67",
  "length1": "14",
  "length2": "8",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "128.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "128.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "11.08",
  "length1": "11",
```



```
"length2": "1",
"width": "5.67",
"width1": "5",
"width2": "8",
"totalArea": "62.81",
"images": [],
"extraAreas": [],
"finalArea": "62.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "WC",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "21.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.00"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "10",
"name": "Balcony",
"length": "17.00",
"length1": "17",
"length2": "00",
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "68.00",
"images": [],
"extraAreas": [],
"finalArea": "68.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "85.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "85.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Balcony",
  "length": "12.00",
  "length1": "12",
  "length2": "0",
  "width": "10.00",
```

```
"width1": "10",
"width2": "0",
"totalArea": "120.00",
"images": [],
"finalArea": "120.00",
"extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "94.11",
  "totalAreaDocument": "1013",
  "docBuiltpPercentage": "10",
  "docFinalBuiltp": "1114.30",
  "docFinalBuiltpSquareMeter": "103.52",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "356569"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "680.00",
    "squareMeterArea": "63.17",
    "expectedRate": "5397.06",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "816.00",
    "squareMeterArea": "75.81",
    "expectedRate": "4497.55",
    "percentage": "20"
  }
}
```

```
},
"saleableArea": {
  "area": "979.20",
  "squareMeterArea": "90.97",
  "expectedRate": "3747.96",
  "percentage": "20"
},
"printlnReport": true,
"_id": "66d7fc0500f75047be60d12c",
"property": "Flat",
"area": "680",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "3670000",
"expectedRate": "5397.06",
"builtUpExpectedRate": "4497.55",
"image": "cases/66d7f973807b2347dd5ae58d/
indicator_1725430625175_Image.png",
"squareMeter": "63.17",
"id": "187726"
},
{
  "carpetArea": {
    "area": "600.00",
    "squareMeterArea": "55.74",
    "expectedRate": "7500.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "720.00",
    "squareMeterArea": "66.89",
    "expectedRate": "6250.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "864.00",
    "squareMeterArea": "80.27",
    "expectedRate": "5208.33",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "66d7fc0500f75047be60d12d",
```

```
"property": "Flat",
"area": "600",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "4500000",
"expectedRate": "7500.00",
"builtUpExpectedRate": "6250.00",
"image": "cases/66d7f973807b2347dd5ae58d/
indicator_1725430687366_Image.png",
"squareMeter": "55.74",
"id": "978153"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db91",
  "name":
"externallmg_1725432720162_WhatsApp_Image_20240903_at_35657_PM_1.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720162_WhatsApp_Image_20240903_at_35657_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db92",
  "name":
"externallmg_1725432720176_WhatsApp_Image_20240903_at_35657_PM_2.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720176_WhatsApp_Image_20240903_at_35657_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db93",
  "name":
"externallmg_1725432720200_WhatsApp_Image_20240903_at_35657_PM.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720200_WhatsApp_Image_20240903_at_35657_PM.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db94",
  "name":
  "externallmg_1725432720254_WhatsApp_Image_20240903_at_35658_PM_1.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720254_WhatsApp_Image_20240903_at_35658_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db95",
  "name":
  "externallmg_1725432720255_WhatsApp_Image_20240903_at_35658_PM.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720255_WhatsApp_Image_20240903_at_35658_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db96",
  "name":
  "externallmg_1725432720256_WhatsApp_Image_20240903_at_35659_PM_1.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720256_WhatsApp_Image_20240903_at_35659_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db97",
  "name":
  "externallmg_1725432720257_WhatsApp_Image_20240903_at_35659_PM_2.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720257_WhatsApp_Image_20240903_at_35659_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db98",
```

```
    "name":  
    "externallmg_1725432720260_WhatsApp_Image_20240903_at_35659_PM.jpeg",  
    "path": "cases/66d7f973807b2347dd5ae58d/  
externallmg_1725432720260_WhatsApp_Image_20240903_at_35659_PM.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "66d8039100f75047be60db99",  
    "name":  
    "externallmg_1725432720269_WhatsApp_Image_20240903_at_35700_PM_1.jpeg",  
    "path": "cases/66d7f973807b2347dd5ae58d/  
externallmg_1725432720269_WhatsApp_Image_20240903_at_35700_PM_1.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "66d8039100f75047be60db9a",  
    "name":  
    "externallmg_1725432720272_WhatsApp_Image_20240903_at_35700_PM_2.jpeg",  
    "path": "cases/66d7f973807b2347dd5ae58d/  
externallmg_1725432720272_WhatsApp_Image_20240903_at_35700_PM_2.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "66d8039100f75047be60db9b",  
    "name":  
    "externallmg_1725432720275_WhatsApp_Image_20240903_at_35700_PM.jpeg",  
    "path": "cases/66d7f973807b2347dd5ae58d/  
externallmg_1725432720275_WhatsApp_Image_20240903_at_35700_PM.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "66d8039100f75047be60db9c",  
    "name":  
    "externallmg_1725432720279_WhatsApp_Image_20240903_at_35701_PM_2.jpeg",  
    "path": "cases/66d7f973807b2347dd5ae58d/  
externallmg_1725432720279_WhatsApp_Image_20240903_at_35701_PM_2.jpeg",  
    "orientation": "landscape"  
  },  
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db9d",
  "name":
"externallmg_1725432720283_WhatsApp_Image_20240903_at_35701_PM.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720283_WhatsApp_Image_20240903_at_35701_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db9e",
  "name":
"externallmg_1725432720287_WhatsApp_Image_20240903_at_35702_PM.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720287_WhatsApp_Image_20240903_at_35702_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60db9f",
  "name":
"externallmg_1725432720293_WhatsApp_Image_20240903_at_35703_PM.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720293_WhatsApp_Image_20240903_at_35703_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60dba0",
  "name":
"externallmg_1725432720302_WhatsApp_Image_20240903_at_35704_PM_1.jpeg",
  "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720302_WhatsApp_Image_20240903_at_35704_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d8039100f75047be60dba1",
  "name":
"externallmg_1725432720312_WhatsApp_Image_20240903_at_35704_PM_2.jpeg",
```



```
    "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720312_WhatsApp_Image_20240903_at_35704_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d8039100f75047be60dba2",
    "name":
"externallmg_1725432720323_WhatsApp_Image_20240903_at_35704_PM.jpeg",
    "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720323_WhatsApp_Image_20240903_at_35704_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d8039100f75047be60dba3",
    "name":
"externallmg_1725432720333_WhatsApp_Image_20240903_at_35705_PM.jpeg",
    "path": "cases/66d7f973807b2347dd5ae58d/
externallmg_1725432720333_WhatsApp_Image_20240903_at_35705_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-04T06:08:51.519Z",
"updatedAt": "2024-09-04T07:45:55.929Z",
"__v": 0,
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Mr.Rohit Balasaheb Patil & Sushmita Narendra Pawar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9021337843",
"buildingServicesRate": "2000",
```

```
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1013.00",
"flatRate": "5600",
"landOtherRate": "3600",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Bathroom + 3 Passage
+ 4 Balcony + WC",
"carpetTotal": "1032.73",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1136.00",
"finalCarpetArea": "1032.73",
"finalSalableArea": "1249.60",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "",
"reportGeneratedDate": "Wed Sep 04 2024 11:49:58 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-09-04",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
```

```

    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	21'9"	10'00"	217.50
Kitchen	17'6"	7'6"	131.25
Bathroom	9'4"	4'5"	41.22
Passage	12'9"	5'00"	63.75
Passage	4'00"	5'6"	22.00
Balcony	9'9"	4'6"	43.87
Bedroom	14'8"	8'9"	128.33
Bedroom	11'1"	5'8"	62.81
WC	7'00"	4'00"	28.00
Passage	3'00"	7'00"	21.00
Balcony	17'00"	4'00"	68.00
Balcony	17'00"	5'00"	85.00
Balcony	12'0"	10'0"	120.00
Other Composition :			