

SLUM REHABILITATION AUTHORITY

No. SRA/Eng/ MC/ 43/ SRA/ 43/ 131df 13
V Floor, Griha Nirman Bhavan,
Bandra (East), Mumbai 400 051.

Date :

6 JUL 1999.

To,

Shri Madhav R. Parpudi
Architect
19/301, Miranda Bldg.,
N.C.Kelkar Road, Dadar,
Mumbai-400 028.

Sub : Occupation Certificate for Rehab. Bldg. 'B' under SRD
on plot bearing CS No.2/158, Lower Parel Division at
Sitaram Jadhav Marg, Lower Parel, G/South Ward.


Ref : Your letter dtd. 2nd July 1999.

Sir,

With reference to the above, the BCC submitted by you, I have to inform you that the same is rejected for the following reasons.


- 1) Site is not cleared, debris/ building material is not removed.
- 2) Work is not completed in all respects.
- 3) Some of the IOD conditions are not complied with.
- 4) Some of the LOI conditions are not yet complied with.
- 5) Final canvas plan is not submitted.

Yours faithfully,


Executive Engineer (SRA)IV

Eng4/raj/sept99/occparpudi/1

CERTIFIED TRUE COPY.


(MADHAV PARPUDI)

ARCHITECT.

REG. NO. CA/77/3418