

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "firstName": "Naman Agarwal",
    "type": "CREDITOFFICER",
    "_id": "62789cf4b0d7f32a7ac19e1c",
    "lastName": "Agarwal",
    "mobileNo": "",
    "email": "naman.agarwal@sbi.co.in",
    "workMobileNo": "9160388615"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Naman Agarwal",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate No. 1, Horniman Circle, Mumbai
Samachar Marg, Fort, Mumbai, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60af3d172ffdf65bcd6585cd",
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.17760630449814",
  "longitude": "72.97167588025331"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.97167588025331,
    19.17760630449814
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-06",
      "remark": "[Name] Nandu Tilwani Kuber Heights\n[Mobile] 98201 29710"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-06",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mulund East",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "10",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kuber Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Patilwadi",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Hari Om Nagar",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
}
```



```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "68,69 & 70",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "1002",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 081",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mulund (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
```

```
"label": "Sole Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Slum_Rehabilitation_Authority",
  "label": "Slum Rehabilitation Authority"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Under Construction Building ",
  "west": "Chikhala Devi Road",
  "south": "Internal Road ",
  "east": "Soham House "
},
"asPerDocumentAgreement": {
  "north": "Geetanjali Society ",
  "west": "Main Road",
  "south": "Hari Om Nagar",
  "east": "Kshitti Society "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Building is under construction",
    "east": "Building is under construction",
    "south": "Building is under construction",
    "west": "Building is under construction"
  },
  "asPerDocument": {
    "north": "Marginal Space ",
    "east": "Marginal Space ",
    "south": "Flat No. 1003",
    "west": "Flat No. 1001 "
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
```

```
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of Flat will be 1 Bedroom + Living Room + Kitchen + 2 Toilets. (1 BHK)",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. SRA / ENG / 3286 / T / PL / AP dated 19.09.2019 issues by Slum Rehabilitation Authority. ",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "Building is under construction",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": " Residential Flat",
  "rate": "142910",
  "landRate": "70290",
  "igrImage": "cases/66d98ac5433b95fe09e395d1/igr_1725971918007_Image.png",
  "squareMeterGuideLineRate": "150056.00",
  "squareFeetGuideLineRate": "13941.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
```

```
"depreciationPercentage": "0",
"rate": "142910.00",
"squareMeterGuideLineRate": "150056.00",
"squareFeetGuideLineRate": "13941.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per SRA norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
},
```

```
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Along with One Car Parking Space ",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
}
```

```
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
```



```
    "value": "As_per_RERA_Certificate",
    "label": "As per RERA Certificate"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "0",
  "ageOfBuilding": "0",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "23",
  "flatFloorNo": "10",
  "noOfLifts": "2",
  "noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "485.10",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66d98ac5433b95fe09e395d1/
routeMap_1725969316256_Image.png",
    "routeLat": "19.177606",
    "routeLng": "72.971676",
    "stationName": "Thane",
    "routeDistance": "1.1 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
```

```
{
  "id": "rx0zm",
  "name": "rx0zm",
  "image": "cases/66d98ac5433b95fe09e395d1/
routeMap_1725968678916_Image.png"
}
],
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8379000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "98",
  "bookValue": "0",
```

```
"finalValue": "8379000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Sep 11 2024 12:25:56 GMT+0530 (India Standard Time)",
  "number": "2308117",
  "dayCount": "6",
  "monthCount": "123",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "10.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6762779.00",
  "selectedBuildUpValue": "485.10",
```

```
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66dae0842eeecd47e76fee7b",
      "name": "externallmg_1725620352010_1725620324677_image_11.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620352010_1725620324677_image_11.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66dae0842eeecd47e76fee7b",
      "name": "externallmg_1725620352010_1725620324677_image_11.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620352010_1725620324677_image_11.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66dae0842eeecd47e76fee79",
      "name": "externallmg_1725620349756_1725620324676_image_9.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620349756_1725620324676_image_9.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66dae0842eeecd47e76fee7a",
      "name": "externallmg_1725620351266_1725620324676_image_10.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620351266_1725620324676_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66dae0842eeecd47e76fee77",
      "name": "externallmg_1725620344912_1725620324676_image_7.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620344912_1725620324676_image_7.jpeg",
      "orientation": "landscape"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "66dae0842eeecd47e76fee75",
      "name": "externallmg_1725620340970_1725620324676_image_5.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620340970_1725620324676_image_5.jpeg",
      "orientation": "landscape"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16713.00",
    "max": "20410.00"
  },
  "builtUpRateRange": {
    "min": "15197.00",
    "max": "18555.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
```

```
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "441.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66d98ac5433b95fe09e395d1",
"ownerName": "Mr. Sameer Manik Khopade",
"ownerPhoneNo": "9594452266",
"appAddress": "Flat no 1002,10floor, A-wing,Kuber Heights, Patilwadi.Near Hari on
Nagar Mulund East ",
"remark": "[Name] Nandu Tilwani Kuber Heights\n[Mobile] 98201 29710",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "inputs": {
      "documentDate": "27/03/2021",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. United Construction Company ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Sameer Manik Khopade ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "6354 / 2021"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "328094",
    "path": "cases/66d98ac5433b95fe09e395d1/
document_1725532596299_1725532593513_sameer001.pdf",
```

```
"fileName": "document_1725532596299_1725532593513_sameer001.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "19/09/2019",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SRA / ENG / 3286 / T / PL / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1726032654138_Approved_Plan.pdf",
  "path": "cases/66d98ac5433b95fe09e395d1/
document_1726032654138_Approved_Plan.pdf",
  "id": "759937",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Wed Sep 11 2024 11:00:54 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "23/10/2019",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SRA / ENG / 3286 / T / PL / AP "
  },
  "isHardCopy": false,
```

```
"displayStatus": false,
"fileName": "document_1726032703874_CC.pdf",
"path": "cases/66d98ac5433b95fe09e395d1/document_1726032703874_CC.pdf",
"id": "837199",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Wed Sep 11 2024 11:01:43 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51800023657"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1726033085581_RERA.pdf",
  "path": "cases/66d98ac5433b95fe09e395d1/
document_1726033085581_RERA.pdf",
  "id": "773623",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Wed Sep 11 2024 11:08:05 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011074",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "856556",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 05 2024 16:11:09 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
```

```
"name": "Mr. Sameer Manik Khopade",
"phone": "9594452266",
"ownershipShare": "",
"email": "",
"id": "333620"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "40.97",
  "totalAreaDocument": "441",
  "docBultupPercentage": "10",
  "docFinalBultUp": "485.10",
  "docFinalBultUpSquareMeter": "45.07",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "385409"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "300.00",
    "squareMeterArea": "27.87",
    "expectedRate": "20410.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "330.00",
    "squareMeterArea": "30.66",
```

```
    "expectedRate": "18554.55",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "66e03e0754df030e57a46173",
  "property": "Residential Flat ",
  "area": "300",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "square_yards",
  "expectedPrice": "6123000",
  "expectedRate": "20410.00",
  "builtUpExpectedRate": "18554.55",
  "image": "cases/66d98ac5433b95fe09e395d1/
indicator_1725971568493_Image.png",
  "squareMeter": "27.87",
  "id": "406546"
},
{
  "carpetArea": {
    "area": "441.00",
    "squareMeterArea": "40.97",
    "expectedRate": "20408.16",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "485.10",
    "squareMeterArea": "45.07",
    "expectedRate": "18552.88",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
}
```

```
"printlnReport": true,
"_id": "66e03e0754df030e57a46174",
"property": "Residential Flat",
"area": "441",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Dwello.com",
"expectedPrice": "9000000",
"expectedRate": "20408.16",
"builtUpExpectedRate": "18552.88",
"image": "cases/66d98ac5433b95fe09e395d1/
indicator_1725971647079_Image.png",
"squareMeter": "40.97",
"id": "338277"
},
{
  "carpetArea": {
    "area": "679",
    "squareMeterArea": "63.08",
    "expectedRate": "17349.04",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "747.00",
    "squareMeterArea": "69.40",
    "expectedRate": "15769.75",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66e03e0754df030e57a46175",
  "property": "Residential Flat",
  "area": "747",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
```

```
"source": "Index_no.2",
"expectedPrice": "11780000",
"expectedRate": "17349.04",
"builtUpExpectedRate": "11780000",
"image": "cases/66d98ac5433b95fe09e395d1/
indicator_1725971715855_Image.png",
"squareMeter": "69.40",
"id": "414874"
},
{
"carpetArea": {
"area": "441",
"squareMeterArea": "40.97",
"expectedRate": "16712.70",
"percentage": ""
},
"builtUpArea": {
"area": "485.00",
"squareMeterArea": "45.06",
"expectedRate": "15196.49",
"percentage": ""
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66e03e0754df030e57a46176",
"property": " Residential Flat",
"area": "485",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "7370300",
"expectedRate": "16712.70",
"builtUpExpectedRate": "7370300",
"image": "cases/66d98ac5433b95fe09e395d1/
indicator_1725971757240_Image.png",
"squareMeter": "45.06",
"id": "282162"
}
}
```



```
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66dae0842eeecd47e76fee70",
    "name": "externallmg_1725620333278_1725620324676_image_0.jpeg",
    "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620333278_1725620324676_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66dae0842eeecd47e76fee71",
    "name": "externallmg_1725620335483_1725620324676_image_1.jpeg",
    "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620335483_1725620324676_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66dae0842eeecd47e76fee72",
    "name": "externallmg_1725620336529_1725620324676_image_2.jpeg",
    "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620336529_1725620324676_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66dae0842eeecd47e76fee73",
    "name": "externallmg_1725620337396_1725620324676_image_3.jpeg",
    "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620337396_1725620324676_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66dae0842eeecd47e76fee74",
    "name": "externallmg_1725620339443_1725620324676_image_4.jpeg",
    "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620339443_1725620324676_image_4.jpeg",
    "orientation": "landscape"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66dae0842eeecd47e76fee75",
      "name": "externallmg_1725620340970_1725620324676_image_5.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620340970_1725620324676_image_5.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66dae0842eeecd47e76fee76",
      "name": "externallmg_1725620342922_1725620324676_image_6.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620342922_1725620324676_image_6.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66dae0842eeecd47e76fee77",
      "name": "externallmg_1725620344912_1725620324676_image_7.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620344912_1725620324676_image_7.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66dae0842eeecd47e76fee78",
      "name": "externallmg_1725620347275_1725620324676_image_8.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620347275_1725620324676_image_8.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66dae0842eeecd47e76fee79",
      "name": "externallmg_1725620349756_1725620324676_image_9.jpeg",
      "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620349756_1725620324676_image_9.jpeg",
      "orientation": "landscape"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66dae0842eeecd47e76fee7a",
  "name": "externallmg_1725620351266_1725620324676_image_10.jpeg",
  "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620351266_1725620324676_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66dae0842eeecd47e76fee7b",
  "name": "externallmg_1725620352010_1725620324677_image_11.jpeg",
  "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620352010_1725620324677_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66dae0842eeecd47e76fee7c",
  "name": "externallmg_1725620354181_1725620324677_image_12.jpeg",
  "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620354181_1725620324677_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66dae05115784548070ef967",
  "name": "externallmg_1725620286152_1725620277737_image_0.jpeg",
  "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620286152_1725620277737_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66dae05115784548070ef968",
  "name": "externallmg_1725620288612_1725620277737_image_1.jpeg",
  "path": "cases/66d98ac5433b95fe09e395d1/
externallmg_1725620288612_1725620277737_image_1.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66dae05115784548070ef969",
    "name": "externalImg_1725620291112_1725620277737_image_2.jpeg",
    "path": "cases/66d98ac5433b95fe09e395d1/
externalImg_1725620291112_1725620277737_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66dae05115784548070ef96a",
    "name": "externalImg_1725620293952_1725620277737_image_3.jpeg",
    "path": "cases/66d98ac5433b95fe09e395d1/
externalImg_1725620293952_1725620277737_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66dae05115784548070ef96b",
    "name": "externalImg_1725620297182_1725620277737_image_4.jpeg",
    "path": "cases/66d98ac5433b95fe09e395d1/
externalImg_1725620297182_1725620277737_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66dae05115784548070ef96c",
    "name": "externalImg_1725620302032_1725620277737_image_5.jpeg",
    "path": "cases/66d98ac5433b95fe09e395d1/
externalImg_1725620302032_1725620277737_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66dae05115784548070ef96d",
    "name": "externalImg_1725620304032_1725620277737_image_6.jpeg",
    "path": "cases/66d98ac5433b95fe09e395d1/
externalImg_1725620304032_1725620277737_image_6.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1725971962787_Calculation_Sheet_NEW.xlsx",
    "path": "cases/66d98ac5433b95fe09e395d1/
processingDocuments/1725971962787_Calculation_Sheet_NEW.xlsx",
    "size": "2986396",
    "createdAt": "Tue Sep 10 2024 18:09:22 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Approved Plan.pdf",
    "filename": "1726034091107_Approved_Plan.pdf",
    "path": "cases/66d98ac5433b95fe09e395d1/
processingDocuments/1726034091107_Approved_Plan.pdf",
    "size": "1934148",
    "createdAt": "Wed Sep 11 2024 11:24:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "Building composition plan.pdf",
    "filename": "1726034091135_Building_composition_plan.pdf",
    "path": "cases/66d98ac5433b95fe09e395d1/
processingDocuments/1726034091135_Building_composition_plan.pdf",
    "size": "128236",
    "createdAt": "Wed Sep 11 2024 11:24:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1726034091136_CC.pdf",
    "path": "cases/66d98ac5433b95fe09e395d1/
processingDocuments/1726034091136_CC.pdf",
    "size": "341154",
    "createdAt": "Wed Sep 11 2024 11:24:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "RERA.pdf",
    "filename": "1726034091139_RERA.pdf",
    "path": "cases/66d98ac5433b95fe09e395d1/
processingDocuments/1726034091139_RERA.pdf",
    "size": "153337",
    "createdAt": "Wed Sep 11 2024 11:24:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  }
]
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66e02e9d54df030e57a44d31",
    "note": "Revised (Task Reopen)",
    "taskId": "66d98d85807b2347dd5c107a",
    "createdAt": "2024-09-10T11:33:49.032Z"
  }
],
"createdAt": "2024-09-05T10:41:09.695Z",
"updatedAt": "2024-09-11T07:06:00.388Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1002, 10th Floor, Wing - A, Kuber Heights,
Patilwadi, Near Hari Om Nagar, Village - Mulund East, Mulund (East), Taluka - Kurla,
District - Mumbai Suburban, PIN - 400 081, State - Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Mr. Roney Tilwani ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Person ",
"siteVisitContactNo": "9820505154",
"builtupPercentage": "10",
"carpetTotal": "0",
```

```
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Tue Sep 10 2024 17:09:37 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-09-06",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 441.00",
"flatRate": "19000",
"landOtherRate": "16000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"finalSaleablePercentage": "0"
```

}

**Name**

**Length**

**Width**

**Total**

---

Composition :

---

Other

Composition :

---