

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Lata",
    "type": "CREDITOFFICER",
    "_id": "6674079b59d44b137cf64e9b",
    "email": "racpc.sion@sbi.co.in",
    "lastName": "Lobo",
    "mobileNo": "",
    "workMobileNo": " *887909789"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
  }
}
```

```
"discussWithPerson": "Lata",
"expectedFees": null,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
```

```
"_id": "60e03dac6576061dae462469",
"zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63fda584ce84bf289baadaf6",
    "role": "PICKUPPERSON",
    "firstName": "Mahendra",
    "email": "mahindra.bijlaney@gmail.com",
    "lastName": "Bijlaney",
    "mobileNo": "9833016592",
    "shortName": "MB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/63fda584ce84bf289baadaf6/
profilePhoto_1677567364613_WhatsApp_Image_20230228_at_121901_PM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f9343b45132d6a6bdd96e8",
    "role": "SITEENGINEER",
    "firstName": "Rajesh",
    "email": "rajeshb.ghadi@gmail.com",
    "lastName": "Ghadi",
    "mobileNo": "8652092666",
    "designation": "",
    "shortName": "RHG",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "9004437379",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60f91b6f344e052188ffd1fc",
```

```
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
```

```
    "value": "Wealth_Tax",
    "label": "Wealth Tax"
  },
  "_id": "6084131a13f01f158c6ea1f4",
  "number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.11778677254327",
  "longitude": "73.00353704307187"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.00353704307187,
    19.11778677254327
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "6/09/2024 09:30 am"
    },
    {
      "dateTime": "6/09/2024 12:00 am"
    },
    {
      "dateTime": "6/09/2024 12:00 am"
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-09-08",
```

```
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-09-08",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-09-08",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Ghansoli",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "4",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "92 to 96",
  "label": true
}
```

```
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Panchvati ",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "5",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
```



```
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
}
```

```
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
```

```
"value": "PIN - 400 701",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "doors": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "windows": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "fittings": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "finishing": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  }
},
```

```
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "NMMC",
  "label": "Navi Mumbai Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Ambe Bhakti Building",
  "west": "Road",
  "south": "Road",
  "east": "Row House"
},
"asPerDocumentAgreement": {
  "north": "Plot No. 95 & 96",
  "west": "Lay Bye & 15.0 Mtrs. Wide Road\n",
  "south": "Dustbin & Plot No. 91\n",
  "east": "Core Units\n"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  }
}
```

```
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "As per Agreement Sale Plan, the composition of residential flat is Living Room + 2 Bedrooms + Kitchen + WC + Bath + Passage (i.e. 2 BHK with WC & Bath).",
  "dateOfIssusApprovePlan": "Approved Building Plan were not provided and not verified.",
  "approvePlanVerified": "No",
  "empanelledOfApprovePlan": "No",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "28.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "712.5",
  "depreciatedCostOfConstruction": "14987.50",
  "depreciatedBuildingRate": "1787.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "114100",
  "landRate": "49700",
  "igrImage": "cases/66da7cfe2eeecd47e76f6be0/igr_1726313162448_Image.png",
  "squareMeterGuideLineRate": "91280.00",
  "squareFeetGuideLineRate": "8480.00"
},
"igrFinalRate": {
  "floorRatePercentage": "80",
  "depreciationPercentage": "81",
  "rate": "7746.00",
  "squareFeetGuideLineRate": "7746.00",
  "squareMeterGuideLineRate": "83380.00"
```

```
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "External_Site_Visit_Only",
    "label": "External Site Visit Only"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per CIDCO norms",
  "tenantName": "",
  "maintenanceOfFlat": "External site visit only"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  }
},
```

```
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2005",
  "fullDate": "1/1/2005"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
}
```

```
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
```



```
"totalLifeBuilding": "60",
"estimatedAge": "41",
"ageOfBuilding": "19",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "4",
"noOfLifts": "-",
"noOfDwellingUnitsInBuilding": "-"
},
"finalPlinthArea": {
  "area": "550.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66da7cfe2eeecd47e76f6be0/
routeMap_1726317078199_Image.png",
    "routeLat": "19.117361",
    "routeLng": "73.002889",
    "stationName": "Ghansoli",
    "routeDistance": "1.2 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "jvspt4",
    "name": "jvspt4",
    "image": "cases/66da7cfe2eeecd47e76f6be0/
routeMap_1726316968950_Image.png"
```

```
}
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8243400.00",
  "distressValuePercentage": "70",
  "realizableValuePercentage": "85",
  "bookValue": "0",
  "finalValue": "8243400.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
```

```
"date": "Mon Sep 16 2024 09:26:39 GMT+0530 (India Standard Time)",
"number": "2308184",
"dayCount": "1",
"monthCount": "190",
"generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4260300.00",
  "selectedBuildUpValue": "550.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
```

```
    "status": false,
    "_id": "66e29e7c82cbc0762fc67c02",
    "name":
"externallmg_1726127740550_WhatsApp_Image_20240912_at_132206.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
externallmg_1726127740550_WhatsApp_Image_20240912_at_132206.jpeg",
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "66e29e7c82cbc0762fc67bfc",
    "name":
"externallmg_1726127740546_WhatsApp_Image_20240912_at_132205_1.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
externallmg_1726127740546_WhatsApp_Image_20240912_at_132205_1.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "66e29e7c82cbc0762fc67c01",
    "name":
"externallmg_1726127740549_WhatsApp_Image_20240912_at_132206_3.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
externallmg_1726127740549_WhatsApp_Image_20240912_at_132206_3.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16633.00",
    "max": "21539.00"
  },
  "builtUpRateRange": {
    "min": "13861.00",
    "max": "17949.00"
  },
  "saleableRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```



```
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "550.00",
"empanelmentNo": [
  "SME/TCC/2021-22/85/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66da7cfe2eeecd47e76f6be0",
"ownerName": "Mr. Ubale Rahul Dadasaheb",
"ownerPhoneNo": "9820483813",
"appAddress": "C403,Pancwati,Ghansoli",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "28/01/2004",
```

```
"from": {
  "value": "Developers",
  "label": "Developers"
},
"Developers": "Haware Engineers & Builders Pvt. Ltd.",
"to": {
  "value": "Purchaser",
  "label": "Purchaser"
},
"Purchaser": "Mr. Ubale Rahul Dadasaheb & Mr. Ubale Dadasaheb Maruti",
"number": {
  "value": "Registration_No",
  "label": "Registration No"
},
"Registration_No": "1010/2004"
},
"isHardCopy": false,
"displayStatus": true,
"id": "977029",
"path": "cases/66da7cfe2eeecd47e76f6be0/
document_1726286536874_RAHUL_UBALE.pdf",
"fileName": "document_1726286536874_RAHUL_UBALE.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2002",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CIDCO/EE(BP)/ATPO/341"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1726315943632_CC.pdf",
  "path": "cases/66da7cfe2eeecd47e76f6be0/document_1726315943632_CC.pdf",
  "id": "469422",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
```

```
    "createdAt": "Sat Sep 14 2024 17:42:23 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "011086",
"createdBy": "63fda584ce84bf289baadaf6",
"caseHistory": [
  {
    "id": "947795",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 06 2024 09:24:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ubale Rahul Dadasaheb",
    "phone": "9820483813",
    "ownershipShare": "",
    "email": "",
    "id": "479569"
  },
  {
    "name": "Mr. Ubale Dadasaheb Maruti",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "941596"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "143378",
    "selectAreaTypeDocument": "Built_Up",
  }
]
```

```
"totalAreaDocument": "550",
"squareMeterArea": "51.10",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltupPercentage": "",
"docSaleablePercentage": "0",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00"
},
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "218646",
  "selectAreaTypeDocument": "Saleable",
  "totalAreaDocument": "688",
  "squareMeterArea": "63.92",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltupPercentage": "",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "650.00",
      "squareMeterArea": "60.39",
      "expectedRate": "21538.46",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "780.00",
      "squareMeterArea": "72.46",
      "expectedRate": "17948.72",
      "percentage": "20"
    },
    "saleableArea": {
```

```
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66e5730b107b3378fb9dc4af",
"property": "Flat",
"area": "650",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "14000000",
"expectedRate": "21538.46",
"builtUpExpectedRate": "17948.72",
"image": "cases/66da7cfe2eeecd47e76f6be0/
indicator_1726312986730_Image.png",
"squareMeter": "60.39",
"id": "309373"
},
{
"carpetArea": {
"area": "710.00",
"squareMeterArea": "65.96",
"expectedRate": "19577.46",
"percentage": ""
},
"builtUpArea": {
"area": "852.00",
"squareMeterArea": "79.15",
"expectedRate": "16314.55",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66e5730b107b3378fb9dc4b0",
"property": "Flat",
"area": "710",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "RealEstateIndia",
"expectedPrice": "13900000",
"expectedRate": "19577.46",
"builtUpExpectedRate": "16314.55",
"image": "cases/66da7cfe2eeecd47e76f6be0/
indicator_1726313016640_Image.png",
"squareMeter": "65.96",
"id": "144323"
},
{
  "carpetArea": {
    "area": "405.83",
    "squareMeterArea": "37.70",
    "expectedRate": "16632.58",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "487.00",
    "squareMeterArea": "45.24",
    "expectedRate": "13860.37",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66e5730b107b3378fb9dc4b1",
  "property": "Flat",
  "area": "487",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "6750000.00",
  "expectedRate": "16632.58",
  "builtUpExpectedRate": "6750000.00",
```

```
"image": "cases/66da7cfe2eeecd47e76f6be0/
indicator_1726313054671_Image.png",
"squareMeter": "45.24",
"id": "605506"
},
{
"carpetArea": {
"area": "407.50",
"squareMeterArea": "37.86",
"expectedRate": "17177.91",
"percentage": ""
},
"builtUpArea": {
"area": "489.00",
"squareMeterArea": "45.43",
"expectedRate": "14314.93",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
},
"printlnReport": true,
"_id": "66e5730b107b3378fb9dc4b2",
"property": "Flat",
"area": "489",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "7000000.00",
"expectedRate": "17177.91",
"builtUpExpectedRate": "7000000.00",
"image": "cases/66da7cfe2eeecd47e76f6be0/
indicator_1726313090379_Image.png",
"squareMeter": "45.43",
"id": "221358"
}
],
"externallImages": [
{
"type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66e29e7c82cbc0762fc67bfc",
    "name":
"externallmg_1726127740546_WhatsApp_Image_20240912_at_132205_1.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
externallmg_1726127740546_WhatsApp_Image_20240912_at_132205_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e29e7c82cbc0762fc67bfd",
    "name":
"externallmg_1726127740547_WhatsApp_Image_20240912_at_132205_2.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
externallmg_1726127740547_WhatsApp_Image_20240912_at_132205_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e29e7c82cbc0762fc67bfe",
    "name":
"externallmg_1726127740547_WhatsApp_Image_20240912_at_132205.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
externallmg_1726127740547_WhatsApp_Image_20240912_at_132205.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e29e7c82cbc0762fc67bff",
    "name":
"externallmg_1726127740548_WhatsApp_Image_20240912_at_132206_1.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
externallmg_1726127740548_WhatsApp_Image_20240912_at_132206_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e29e7c82cbc0762fc67c00",
    "name":
"externallmg_1726127740549_WhatsApp_Image_20240912_at_132206_2.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
externallmg_1726127740549_WhatsApp_Image_20240912_at_132206_2.jpeg",
```



```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e29e7c82cbc0762fc67c01",
    "name":
"externallmg_1726127740549_WhatsApp_Image_20240912_at_132206_3.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
externallmg_1726127740549_WhatsApp_Image_20240912_at_132206_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e29e7c82cbc0762fc67c02",
    "name":
"externallmg_1726127740550_WhatsApp_Image_20240912_at_132206.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
externallmg_1726127740550_WhatsApp_Image_20240912_at_132206.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)-ubale.xlsx",
    "filename": "1726313191933_Calculation_2ubale.xlsx",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
processingDocuments/1726313191933_Calculation_2ubale.xlsx",
    "size": "16073",
    "createdAt": "Sat Sep 14 2024 16:56:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1726313191936_igr1.pdf",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
processingDocuments/1726313191936_igr1.pdf",
    "size": "161200",
    "createdAt": "Sat Sep 14 2024 16:56:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
    "filename": "1726313191953_igr2.pdf",
```

```
    "path": "cases/66da7cfe2eeecd47e76f6be0/
processingDocuments/1726313191953_igr2.pdf",
    "size": "156278",
    "createdAt": "Sat Sep 14 2024 16:56:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr3.pdf",
    "filename": "1726313191968_igr3.pdf",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
processingDocuments/1726313191968_igr3.pdf",
    "size": "166349",
    "createdAt": "Sat Sep 14 2024 16:56:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - ubale.xlsx",
    "filename": "1726313191981_Summary__ubale.xlsx",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
processingDocuments/1726313191981_Summary__ubale.xlsx",
    "size": "3891916",
    "createdAt": "Sat Sep 14 2024 16:56:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1726318235219_CC.pdf",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
processingDocuments/1726318235219_CC.pdf",
    "size": "167528",
    "createdAt": "Sat Sep 14 2024 18:20:35 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Document - 2004.pdf",
    "filename": "1726318235225_Document__2004.pdf",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
processingDocuments/1726318235225_Document__2004.pdf",
    "size": "1897485",
    "createdAt": "Sat Sep 14 2024 18:20:35 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Location.jpeg",
    "filename": "1726318235250_Location.jpeg",
    "path": "cases/66da7cfe2eeecd47e76f6be0/
processingDocuments/1726318235250_Location.jpeg",
```

```
"size": "115880",
"createdAt": "Sat Sep 14 2024 18:20:35 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Sale Deed - 2004.pdf",
"filename": "1726318235250_Sale_Deed__2004.pdf",
"path": "cases/66da7cfe2eeecd47e76f6be0/
processingDocuments/1726318235250_Sale_Deed__2004.pdf",
"size": "677084",
"createdAt": "Sat Sep 14 2024 18:20:35 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Site Details.jpeg",
"filename": "1726318235255_Site_Details.jpeg",
"path": "cases/66da7cfe2eeecd47e76f6be0/
processingDocuments/1726318235255_Site_Details.jpeg",
"size": "120533",
"createdAt": "Sat Sep 14 2024 18:20:35 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"lastName": "Sarmalkar",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "66e2d6bb68360ec91e340a1f",
"note": "required area details\n",
"taskId": "66da7e5115784548070e5d5b",
"createdAt": "2024-09-12T11:55:39.630Z"
}
],
"createdAt": "2024-09-06T03:54:38.472Z",
"updatedAt": "2024-09-16T04:43:50.787Z",
```

```
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 403, 4th Floor, Wing - C, Panchvati , Plot No. 92 to
96, Sector 5, Village - Ghansoli, Taluka - Thane, District - Thane, Navi Mumbai, PIN -
400 701, State - Maharashtra, India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "63fda584ce84bf289baadaf6",
"contactPersonName": "Mr. Ubale Rahul Dadasaheb",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9820483813",
"reportGeneratedDate": "Mon Sep 16 2024 15:46:37 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-09-08",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 550.00",
"flatRate": "15700",
"landOtherRate": "13200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"finalSaleablePercentage": "0",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
```

```

"siteMeasurementRemark": "",
"toBeAdded": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			