

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "640b6f5d4dda382753e5c230"
    },
    "firstName": "Parag ",
    "type": "CREDITOFFICER",
    "_id": "640b6f5d4dda382753e5c232",
    "lastName": "Patel",
    "mobileNo": "",
    "workMobileNo": "9987354946",
    "email": "bo088210@pnb.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3500000",
    "discussWithPerson": "Parag ",
    "expectedFees": 1750,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "640b6f5d4dda382753e5c230",
  "name": "Mira Road East Branch",
  "branchCode": "",
  "mobileNo": "02225126616",
  "alternateMobileNo": "",
  "email": "bo088210@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mira Road East Branch, Shop No 1 yo 5, Shanti Plaza, Sector 11, Shanti
Nagar, Mira Road ( East), Thane 401107"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "66850df5d9f18310ed2e5d98",
"role": "SITEENGINEER",
"firstName": "Krishna",
"email": "krishnagawade9@gmail.com",
"lastName": "Gawde",
"mobileNo": "9821646373",
"designation": "Site Engg",
"shortName": "Krishna",
"workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "ACCOUNTANT",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
}
]
```

```
],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.27986",
  "longitude": "72.864909"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.864909,
    19.27986
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
}
```

```
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "D 30",
    "label": true
  },
}
```

```
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "MIRA ROAD THANE ",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "POONAM NAGAR D 30/31 CHS LTD POONAM NAGAR PHASE 3
SHANTI PARK ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
```

```
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
}
```

```
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "401",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
```



```
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "401107",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
```

```
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  }
},
```

```
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
```



```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66e03b1ae583410e65277af0",
"ownerName": "MR SONU RAMJIYAVAN JAISWAL",
"ownerPhoneNo": "9930497166",
"appAddress": "FLAT NO 401 BLDG NO D 30 POONAM NAGAR D 30/31 CHS LTD
POONAM NAGAR PHASE 3 SHANTI PARK MIRA ROAD THANE 401107",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66e03b1ae583410e65277af0/
document_1725971181279_1725971174336_Sonu_jayswal_agreement_.pdf",
    "fileName":
"document_1725971181279_1725971174336_Sonu_jayswal_agreement_.pdf",
    "id": "509450",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Tue Sep 10 2024 17:57:06 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "011137",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "525546",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Sep 10 2024 17:57:06 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "MR SONU RAMJIYAVAN JAISWAL",
    "phone": "9930497166",
```

```
    "ownershipShare": "",
    "email": "",
    "id": "269193"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e517018e4fd6c8ff5aa28f",
    "name":
"externalImg_1726289665307_WhatsApp_Image_20240913_at_11004_AM.jpeg",
    "path": "cases/66e03b1ae583410e65277af0/
externalImg_1726289665307_WhatsApp_Image_20240913_at_11004_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e51713eff259c8fe6f2c5e",
    "name":
"externalImg_1726289683351_WhatsApp_Image_20240913_at_11112_AM_1.jpeg",
    "path": "cases/66e03b1ae583410e65277af0/
externalImg_1726289683351_WhatsApp_Image_20240913_at_11112_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e51713eff259c8fe6f2c5f",
    "name":
"externalImg_1726289683351_WhatsApp_Image_20240913_at_11112_AM_2.jpeg",
    "path": "cases/66e03b1ae583410e65277af0/
externalImg_1726289683351_WhatsApp_Image_20240913_at_11112_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66e51713eff259c8fe6f2c60",
  "name":
"externallmg_1726289683352_WhatsApp_Image_20240913_at_11112_AM_3.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683352_WhatsApp_Image_20240913_at_11112_AM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c61",
  "name":
"externallmg_1726289683353_WhatsApp_Image_20240913_at_11112_AM.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683353_WhatsApp_Image_20240913_at_11112_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c62",
  "name":
"externallmg_1726289683354_WhatsApp_Image_20240913_at_11114_AM_1.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683354_WhatsApp_Image_20240913_at_11114_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c63",
  "name":
"externallmg_1726289683361_WhatsApp_Image_20240913_at_11114_AM.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683361_WhatsApp_Image_20240913_at_11114_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c64",
  "name":
"externallmg_1726289683376_WhatsApp_Image_20240913_at_11115_AM_1.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683376_WhatsApp_Image_20240913_at_11115_AM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e51713eff259c8fe6f2c65",
    "name":
"externallmg_1726289683386_WhatsApp_Image_20240913_at_11115_AM_2.jpeg",
    "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683386_WhatsApp_Image_20240913_at_11115_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e51713eff259c8fe6f2c66",
    "name":
"externallmg_1726289683392_WhatsApp_Image_20240913_at_11115_AM.jpeg",
    "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683392_WhatsApp_Image_20240913_at_11115_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e51713eff259c8fe6f2c67",
    "name":
"externallmg_1726289683397_WhatsApp_Image_20240913_at_11117_AM_1.jpeg",
    "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683397_WhatsApp_Image_20240913_at_11117_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e51713eff259c8fe6f2c68",
    "name":
"externallmg_1726289683398_WhatsApp_Image_20240913_at_11117_AM.jpeg",
    "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683398_WhatsApp_Image_20240913_at_11117_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e51713eff259c8fe6f2c69",
```

```
"name":
"externallmg_1726289683399_WhatsApp_Image_20240913_at_11118_AM.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683399_WhatsApp_Image_20240913_at_11118_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c6a",
  "name":
"externallmg_1726289683399_WhatsApp_Image_20240913_at_11119_AM.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683399_WhatsApp_Image_20240913_at_11119_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c6b",
  "name":
"externallmg_1726289683400_WhatsApp_Image_20240913_at_11120_AM.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683400_WhatsApp_Image_20240913_at_11120_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c6c",
  "name":
"externallmg_1726289683402_WhatsApp_Image_20240913_at_11121_AM.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683402_WhatsApp_Image_20240913_at_11121_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c6d",
  "name":
"externallmg_1726289683404_WhatsApp_Image_20240913_at_11122_AM_1.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683404_WhatsApp_Image_20240913_at_11122_AM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c6e",
  "name":
"externallmg_1726289683405_WhatsApp_Image_20240913_at_11122_AM.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683405_WhatsApp_Image_20240913_at_11122_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c6f",
  "name":
"externallmg_1726289683405_WhatsApp_Image_20240913_at_11128_AM_1.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683405_WhatsApp_Image_20240913_at_11128_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c70",
  "name":
"externallmg_1726289683407_WhatsApp_Image_20240913_at_11128_AM.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683407_WhatsApp_Image_20240913_at_11128_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e51713eff259c8fe6f2c71",
  "name":
"externallmg_1726289683408_WhatsApp_Image_20240913_at_11129_AM.jpeg",
  "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289683408_WhatsApp_Image_20240913_at_11129_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e5171a8e4fd6c8ff5aa2fc",
  "name":
"externallmg_1726289690166_WhatsApp_Image_20240913_at_11005_AM_1.jpeg",
```

```
    "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289690166_WhatsApp_Image_20240913_at_11005_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e5171a8e4fd6c8ff5aa2fd",
    "name":
"externallmg_1726289690166_WhatsApp_Image_20240913_at_11005_AM.jpeg",
    "path": "cases/66e03b1ae583410e65277af0/
externallmg_1726289690166_WhatsApp_Image_20240913_at_11005_AM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-10T12:27:06.249Z",
"updatedAt": "2024-09-14T04:54:50.216Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 401, 4th Floor, Building No D 30, POONAM
NAGAR D 30/31 CHS LTD POONAM NAGAR PHASE 3 SHANTI PARK , MIRA ROAD
THANE , 401107",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "MR SONU RAMJIYAVAN JAISWAL",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9930497166"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			