

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "r. Mohanty",
    "type": "CREDITOFFICER",
    "_id": "646dc536b05e530fb6c47b3d",
    "lastName": " Sir",
    "mobileNo": "",
    "workMobileNo": "8411020137",
    "email": "rlf.nasik@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2600000",
    "discussWithPerson": "r. Mohanty",
    "expectedFees": 1300,
    "quotedAmount": "2950"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9f4adce84bf289ba9956e",
```

```
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
```

```
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "20.027507",
  "longitude": "73.790161"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.790161,
    20.027507
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "11/09/2024 12:00 am"
    },
    {
      "dateTime": "11/09/2024 12:00 am"
    },
    {
      "dateTime": "11/09/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-10",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nashik",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "9",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Nashik",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1A",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vraj Landmark 1A ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Vibgyor School, Samarth Nagar",
```



```
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "74/ 2",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "D-902",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "Pincode - 422 004",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  }
},
```

```
"finishing": {
  "value": "Proposed_Cement_Plastering",
  "label": "Proposed Cement Plastering"
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Adj. APMC Plot No. 07",
    "west": "18.00 Mtrs. Road",
    "south": "30.00 Mtrs. Road",
    "east": "Adj. Plot No. 1B"
  },
  "asPerDocumentAgreement": {
    "north": "Adj. APMC Plot No. 07",
    "west": "18.00 Mtrs. Road",
    "south": "30.00 Mtrs. Road",
    "east": "Adj. Plot No. 1B"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Staircase & Flat No. D-901",
      "east": "Side Margin",
      "south": "Side Margin",
      "west": "Lobby & Flat No. D-903"
    },
    "asPerDocument": {
```

```
"north": "Staircase & Flat No. D-901",
"east": "Side Margin",
"south": "Side Margin",
"west": "Lobby & Flat No. D-903"
},
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan Accompanying
CommencementCertificate No. C1 / 481 / 2021 dated 08.10.2021 issued by Executive
Engineer Town Planning Nashik Municipal Corporation, Nashik.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
```

```
"rate": "37500",
"landRate": "14800",
"igrImage": "cases/66e12b9d54df030e57a484bd/igr_1726036274663_Image.png",
"squareMeterGuideLineRate": "39375.00",
"squareFeetGuideLineRate": "3658.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "37500.00",
  "squareMeterGuideLineRate": "39375.00",
  "squareFeetGuideLineRate": "3658.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Building is under construction",
  "taxPaidHolderName": "Building is under construction",
  "taxAmount": "Building is under construction",
  "electricityServiceConnectionNo": "Building is under construction",
  "meterCardHolderName": "Building is under construction",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "As per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
```

```
"roof": {
  "value": "rcc_Slab",
  "label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Covered Car Parking",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
```

```
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
```



```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "9",
"flatFloorNo": "9",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "654.50",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/66e12b9d54df030e57a484bd/
routeMap_1726037736710_Image.png",
"routeLat": "20.027507",
"routeLng": "73.790161",
"stationName": "Nashik Road",
"routeDistance": "13.3",
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
}
},
"finalLatLng": {
"coordinates": [
0,
0
```

```
    ],
    "type": "Point"
  },
  "showLocation": {
    "latlng": true,
    "finallatlng": true
  },
  "locationMapImg": [
    {
      "id": "6jvwz",
      "name": "6jvwz",
      "image": "cases/66e12b9d54df030e57a484bd/
routeMap_1726037673202_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
```

```
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3391500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "95",
"bookValue": "0",
"finalValue": "3391500.00",
"purchaseValueDocument": {
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1726034882352_Scan20240909170802.pdf",
  "path": "cases/66e12b9d54df030e57a484bd/
document_1726034882352_Scan20240909170802.pdf",
  "id": "768042",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Wed Sep 11 2024 11:41:47 GMT+0530 (India Standard Time)",
  "documentDate": "06/09/2024",
  "amount": "2850000",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "Shree Infra Space",
  "to": {
    "value": "buyer",
    "label": "buyer"
  },
  "buyer": "MR. Sachin Bhalerao Salunkhe",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "9015/ 2024"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Sep 11 2024 17:17:18 GMT+0530 (India Standard Time)",
  "number": "2308129",
```

```
"dayCount": "18",
"monthCount": "135",
"generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "11",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "11",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "11",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "11",
```

```
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "11",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "11",
  "percentage": "10.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
}
```

```
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "81.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2394161.00",
  "selectedBuildUpValue": "654.50",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66e134e81f5a2b0e589c6415",
    }
  ]
}
```

```
    "name":
"externallmg_1726035175914_WhatsApp_Image_20240910_at_115924_AM.jpeg",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035175914_WhatsApp_Image_20240910_at_115924_AM.jpeg",
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "66e134e81f5a2b0e589c640c",
    "name": "Living Room",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035173606_WhatsApp_Image_20240910_at_115920_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66e134e81f5a2b0e589c6408",
    "name": "Living Room",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035172906_WhatsApp_Image_20240910_at_115911_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66e134e81f5a2b0e589c6409",
    "name": "Living Room",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035173038_WhatsApp_Image_20240910_at_115911_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66e134e81f5a2b0e589c640b",
    "name": "Living Room",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035173418_WhatsApp_Image_20240910_at_115919_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
```

```
    "_id": "66e134e81f5a2b0e589c640e",
    "name": "Living Room",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035173966_WhatsApp_Image_20240910_at_115920_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66e134e81f5a2b0e589c6406",
    "name": "Living Room",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035172164_WhatsApp_Image_20240910_at_115909_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66e134e81f5a2b0e589c6412",
    "name": "Living Room",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035174932_WhatsApp_Image_20240910_at_115922_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66e134e81f5a2b0e589c6414",
    "name": "Living Room",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035175636_WhatsApp_Image_20240910_at_115922_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66e134e81f5a2b0e589c6413",
    "name": "Living Room",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035175350_WhatsApp_Image_20240910_at_115922_AM_2.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5089.00",
    "max": "6429.00"
  },
  "builtUpRateRange": {
```



```
"min": "4240.00",
"max": "5358.00"
},
"saleableRateRange": {
  "min": "3534.00",
  "max": "4465.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "595.00",
"empanelmentNo": [
  "ZO :MZ:ADV:46:941\t"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66e12b9d54df030e57a484bd",
"ownerName": "MR. Sachin Bhalerao Salunkhe",
"ownerPhoneNo": "9822259225",
"appAddress": "Viraj Landmark Near fruit market",
"remark": "",
"documents": [
  {
    "documentType": {
```

```
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"inputs": {
  "documentDate": "06/09/2024",
  "amount": "2850000",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "Shree Infra Space",
  "to": {
    "value": "buyer",
    "label": "buyer"
  },
  "buyer": "MR. Sachin Bhalerao Salunkhe",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "9015/ 2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "768042",
"path": "cases/66e12b9d54df030e57a484bd/
document_1726034882352_Scan20240909170802.pdf",
"fileName": "document_1726034882352_Scan20240909170802.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "08/10/2021",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "LND/ BP/ C1/ 481/ 2021"
  },
}
```

```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1726035004550_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"path": "cases/66e12b9d54df030e57a484bd/document_1726035004550_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"id": "512974",
"uploadedBy": "647ed1960ab64c23c9fcf71d",
"createdAt": "Wed Sep 11 2024 11:41:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "08/10/2021",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "C1/ 481/ 2021"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1726035059002_3rd_to_9th_floor_plan_no6_1.pdf",
  "path": "cases/66e12b9d54df030e57a484bd/document_1726035059002_3rd_to_9th_floor_plan_no6_1.pdf",
  "id": "243935",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Wed Sep 11 2024 11:41:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    }
  }
}
```

```
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51600027077"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1726035100706_P51600027077.pdf",
  "path": "cases/66e12b9d54df030e57a484bd/
document_1726035100706_P51600027077.pdf",
  "id": "520387",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Wed Sep 11 2024 11:41:47 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011144",
"createdBy": "63f9f4adce84bf289ba9956e",
"caseHistory": [
  {
    "id": "313793",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Sep 11 2024 11:03:17 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sachin Bhalerao Salunkhe",
    "phone": "9822259225",
    "ownershipShare": "",
    "email": "",
    "id": "186161"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "850870",
    "name": "Living Room",
```

```
"length": "14.58",
"length1": "14",
"length2": "7",
"width": "10.08",
"width1": "10",
"width2": "1",
"totalArea": "147.05",
"images": [],
"extraAreas": [],
"finalArea": "147.05"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "11.58",
  "length1": "11",
  "length2": "7",
  "width": "10.67",
  "width1": "10",
  "width2": "8",
  "totalArea": "123.55",
  "images": [],
  "extraAreas": [],
  "finalArea": "123.55"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "10.58",
  "length1": "10",
  "length2": "7",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "103.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "103.19"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "12.33",
  "length1": "12",
  "length2": "4",
  "width": "9.58",
  "width1": "9",
  "width2": "7",
  "totalArea": "118.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "118.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.58",
  "length1": "3",
  "length2": "7",
  "width": "6.50",
  "width1": "6",
  "width2": "6",
  "totalArea": "23.29",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.29"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "5.50",
  "length1": "5",
```



```
"length2": "6",
"width": "6.25",
"width1": "6",
"width2": "3",
"totalArea": "34.37",
"images": [],
"extraAreas": [],
"finalArea": "34.37"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Balcony",
  "length": "10.08",
  "length1": "10",
  "length2": "1",
  "width": "5.50",
  "width1": "5",
  "width2": "6",
  "totalArea": "55.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "55.46"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "55.28",
    "totalAreaDocument": "595",
    "docBUILTUPPercentage": "10",
    "docFinalBUILTUP": "654.50",
    "docFinalBUILTUPSquareMeter": "60.81",
```

```
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "274021"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "520.83",
"squareMeterArea": "48.39",
"expectedRate": "5088.03",
"percentage": ""
},
"builtUpArea": {
"area": "625.00",
"squareMeterArea": "58.06",
"expectedRate": "4240.00",
"percentage": "20"
},
"saleableArea": {
"area": "750.00",
"squareMeterArea": "69.68",
"expectedRate": "3533.33",
"percentage": "20"
},
"printlnReport": true,
"_id": "66e139421f5a2b0e589c69de",
"property": "Flat",
"area": "625",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "2650000",
"expectedRate": "5088.03",
"builtUpExpectedRate": "2650000",
"image": "cases/66e12b9d54df030e57a484bd/
indicator_1726035958311_Image.png",
"squareMeter": "58.06",
"id": "695619"
},
{
```

```
"carpetArea": {
  "area": "777.78",
  "squareMeterArea": "72.26",
  "expectedRate": "6428.55",
  "percentage": ""
},
"builtUpArea": {
  "area": "933.33",
  "squareMeterArea": "86.71",
  "expectedRate": "5357.16",
  "percentage": "20"
},
"saleableArea": {
  "area": "1120.00",
  "squareMeterArea": "104.05",
  "expectedRate": "4464.29",
  "percentage": "20"
},
"printInReport": true,
"_id": "66e139421f5a2b0e589c69df",
"property": "Flat",
"area": "1120",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Saleable",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "5000000",
"expectedRate": "4464.285714285715",
"builtUpExpectedRate": "5357.16",
"image": "cases/66e12b9d54df030e57a484bd/
indicator_1726036225952_Image.png",
"squareMeter": "104.05",
"id": "952108"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e134e81f5a2b0e589c6403",
  "name":
"externallmg_1726035171499_WhatsApp_Image_20240910_at_115908_AM_1.jpeg",
  "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035171499_WhatsApp_Image_20240910_at_115908_AM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e134e81f5a2b0e589c6404",
    "name":
"externallmg_1726035171677_WhatsApp_Image_20240910_at_115908_AM.jpeg",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035171677_WhatsApp_Image_20240910_at_115908_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e134e81f5a2b0e589c6405",
    "name":
"externallmg_1726035171957_WhatsApp_Image_20240910_at_115909_AM_1.jpeg",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035171957_WhatsApp_Image_20240910_at_115909_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e134e81f5a2b0e589c6406",
    "name":
"externallmg_1726035172164_WhatsApp_Image_20240910_at_115909_AM.jpeg",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035172164_WhatsApp_Image_20240910_at_115909_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e134e81f5a2b0e589c6407",
    "name":
"externallmg_1726035172721_WhatsApp_Image_20240910_at_115910_AM.jpeg",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035172721_WhatsApp_Image_20240910_at_115910_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e134e81f5a2b0e589c6408",
```

```
    "name":
"externallmg_1726035172906_WhatsApp_Image_20240910_at_115911_AM_1.jpeg",
  "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035172906_WhatsApp_Image_20240910_at_115911_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e134e81f5a2b0e589c6409",
  "name":
"externallmg_1726035173038_WhatsApp_Image_20240910_at_115911_AM_2.jpeg",
  "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035173038_WhatsApp_Image_20240910_at_115911_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e134e81f5a2b0e589c640a",
  "name":
"externallmg_1726035173208_WhatsApp_Image_20240910_at_115911_AM.jpeg",
  "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035173208_WhatsApp_Image_20240910_at_115911_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e134e81f5a2b0e589c640b",
  "name":
"externallmg_1726035173418_WhatsApp_Image_20240910_at_115919_AM.jpeg",
  "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035173418_WhatsApp_Image_20240910_at_115919_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e134e81f5a2b0e589c640c",
  "name":
"externallmg_1726035173606_WhatsApp_Image_20240910_at_115920_AM_1.jpeg",
  "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035173606_WhatsApp_Image_20240910_at_115920_AM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e134e81f5a2b0e589c640d",
  "name":
"externallmg_1726035173776_WhatsApp_Image_20240910_at_115920_AM_2.jpeg",
  "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035173776_WhatsApp_Image_20240910_at_115920_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e134e81f5a2b0e589c640e",
  "name":
"externallmg_1726035173966_WhatsApp_Image_20240910_at_115920_AM.jpeg",
  "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035173966_WhatsApp_Image_20240910_at_115920_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e134e81f5a2b0e589c640f",
  "name":
"externallmg_1726035174136_WhatsApp_Image_20240910_at_115921_AM_1.jpeg",
  "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035174136_WhatsApp_Image_20240910_at_115921_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e134e81f5a2b0e589c6410",
  "name":
"externallmg_1726035174421_WhatsApp_Image_20240910_at_115921_AM_2.jpeg",
  "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035174421_WhatsApp_Image_20240910_at_115921_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e134e81f5a2b0e589c6411",
  "name":
"externallmg_1726035174746_WhatsApp_Image_20240910_at_115921_AM.jpeg",
```

```
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035174746_WhatsApp_Image_20240910_at_115921_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e134e81f5a2b0e589c6412",
    "name":
"externallmg_1726035174932_WhatsApp_Image_20240910_at_115922_AM_1.jpeg",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035174932_WhatsApp_Image_20240910_at_115922_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e134e81f5a2b0e589c6413",
    "name":
"externallmg_1726035175350_WhatsApp_Image_20240910_at_115922_AM_2.jpeg",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035175350_WhatsApp_Image_20240910_at_115922_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e134e81f5a2b0e589c6414",
    "name":
"externallmg_1726035175636_WhatsApp_Image_20240910_at_115922_AM.jpeg",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035175636_WhatsApp_Image_20240910_at_115922_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e134e81f5a2b0e589c6415",
    "name":
"externallmg_1726035175914_WhatsApp_Image_20240910_at_115924_AM.jpeg",
    "path": "cases/66e12b9d54df030e57a484bd/
externallmg_1726035175914_WhatsApp_Image_20240910_at_115924_AM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [
  {
    "originalName": "Sachin Salunke.xlsx",
    "filename": "1726036338673_Sachin_Salunke.xlsx",
    "path": "cases/66e12b9d54df030e57a484bd/
processingDocuments/1726036338673_Sachin_Salunke.xlsx",
    "size": "593782",
    "createdAt": "Wed Sep 11 2024 12:02:19 GMT+0530 (India Standard Time)",
    "uploadedBy": "647ed1960ab64c23c9fcf71d"
  },
  {
    "originalName": "BOB - MR. Sachin Bhalerao Salunkhe.pdf",
    "filename": "1726038419988_BOB__MR_Sachin_Bhalerao_Salunkhe.pdf",
    "path": "cases/66e12b9d54df030e57a484bd/
processingDocuments/1726038419988_BOB__MR_Sachin_Bhalerao_Salunkhe.pdf",
    "size": "5074455",
    "createdAt": "Wed Sep 11 2024 12:37:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "647ed1960ab64c23c9fcf71d"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-11T05:33:17.146Z",
"updatedAt": "2024-09-11T11:54:24.497Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. D-902, 9th Floor, Wing - D, Vraj Landmark 1A ,
Near Vibgyor School, Samarth Nagar, Plot No. 1A, Village - Nashik, Taluka - Nashik,
District - Nashik, Nashik, Pincode - 422 004, State - Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "63f9ed37ce84bf289ba991ac",
"contactPersonName": "MR. Rohan Sagar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Builder",
"siteVisitContactNo": "9822259225",
"buildingServicesRate": "2000",
```



```
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 595.00",
"flatRate": "5700",
"landOtherRate": "3700",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Balcony",
"carpetTotal": "605.10",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "665.61",
"finalCarpetArea": "605.10",
"finalSalableArea": "732.17",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Sep 11 2024 12:03:02 GMT+0530 (India Standard Time)",
```

"siteVisitDate": "2024-09-10",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Living Room	14'7"	10'1"	147.05
Bedroom	11'7"	10'8"	123.55
Bedroom	10'7"	9'9"	103.19
Kitchen	12'4"	9'7"	118.19
Toilet	3'7"	6'6"	23.29
Toilet	5'6"	6'3"	34.37
Balcony	10'1"	5'6"	55.46
Other Composition :			