

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Education Loan",
    "value": "Education_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Swarup",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312bd",
    "email": "1racpcghatkopar.sanctions@sbi.co.in",
    "mobileNo": "-",
    "workMobileNo": "8668951779",
    "lastName": " Shivane"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Swarup",
    "expectedFees": null,
    "quotedAmount": "3000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "63fda584ce84bf289baadaf6",
  "role": "PICKUPPERSON",
  "firstName": "Mahendra",
  "email": "mahindra.bijlaney@gmail.com",
  "lastName": "Bijlaney",
  "mobileNo": "9833016592",
  "shortName": "MB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63fda584ce84bf289baadaf6/
profilePhoto_1677567364613_WhatsApp_Image_20230228_at_121901_PM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "642bad2b91d7c62df117fef2",
  "role": "SITEENGINEER",
  "firstName": "Abhiraj",
  "email": "abhishekharijan@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8369839430",
  "designation": "",
  "shortName": "AH",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "18.461657133428062",
  "longitude": "73.89294613748083"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.89294613748083,
    18.461657133428062
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "12/09/2024 06:03 pm"
    },
    {
      "dateTime": "12/09/2024 12:00 am"
    },
    {
      "dateTime": "12/09/2024 12:00 am"
    },
    {
      "dateTime": "12/09/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-10",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kondhwa Budruk",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Pune",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Pune",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Haveli",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "11 & 12",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Essenseia Phase-1 Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Behind HP Petrol Pump",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
```



```
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "24/1A/1, 24/1A/2 & 24/1B/3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "601",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 411 048",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "doors": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "windows": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "fittings": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "finishing": {
    "value": "External_site_visit_only",
```

```
    "label": "External site visit only"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Pune_Municipal_Corporation",
    "label": "Pune Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road",
    "west": "Road",
    "south": "Internal Road & Essenseia Phase-II",
    "east": "Essenseia CHSL Block-C"
  },
  "asPerDocumentAgreement": {
    "north": "By Survey No. 24/1A",
    "west": "By Survey No. 13 (Dharmavat) & Internal Road",
    "south": "By Plot No. 10 & 13",
    "east": "By Internal Road & Survey No. 32 (Kamthe)"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Duct Area",
      "east": "Passage",
      "south": "Lift / Flat No. 602",
      "west": "Flat No. 604"
    },
    "asPerDocument": {
      "north": "Information not available",
      "east": "Information not available",
```

```
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per site information it is a 2 BHK flat",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "Internal visit not allowed by the tenant for photographs and measurement.
Hence our report is based on external site visit and documents provided for valuation.\n
\n",
  "depreciationPercentage": "19.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "6512.5",
  "depreciatedBuildingRate": "2012.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "57200",
```

```
"landRate": "17700",
"igrImage": "cases/66e2dc6e8e4fd6c8ff59c3c4/igr_1728561411616_Image.png",
"squareMeterGuideLineRate": "60060.00",
"squareFeetGuideLineRate": "5580.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "87",
  "rate": "5068.00",
  "squareFeetGuideLineRate": "5068.00",
  "squareMeterGuideLineRate": "54553.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per PMC norms",
  "tenantName": "Mr. Rukaiya Halvadwala",
  "maintenanceOfFlat": "External site visit only"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "R.C.C._slab",
"label": "R.C.C. slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Covered Parking Space",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2011",
"fullDate": "1/1/2011"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
}
```

```
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
```



```
"label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "47",
"ageOfBuilding": "13",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "6",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "1123.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66e2dc6e8e4fd6c8ff59c3c4/
routeMap_1728562887585_Image.png",
    "routeLat": "18.459803",
    "routeLng": "73.892969",
    "stationName": "Pune",
    "routeDistance": "9.5 km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
}
```

```
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "t21gc5",
    "name": "t21gc5",
    "image": "cases/66e2dc6e8e4fd6c8ff59c3c4/
routeMap_1728562762252_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
```

```
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "6096168.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "6096168.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Oct 14 2024 18:19:48 GMT+0530 (India Standard Time)",
  "number": "2308615",
  "dayCount": "10",
  "monthCount": "155",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "5692378.00",
  "selectedBuildUpValue": "1123.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6707c57ac691adb224f8ffdf",
      "name": "externalimg_1728562554203_externalimg_1728552232170_WhatsApp_I
mage_20241010_at_144519.jpeg",
      "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externalimg_1728562554203_external
mg_1728552232170_WhatsApp_Image_20241010_at_144519.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6707c57ac691adb224f8ffe3",
      "name": "externalimg_1728562554221_externalimg_1728552232189_WhatsApp_I
mage_20241010_at_144522.jpeg",
      "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externalimg_1728562554221_external
mg_1728552232189_WhatsApp_Image_20241010_at_144522.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6707c57ac691adb224f8ffe5",
      "name": "externalimg_r_1728562554197_externalimg_1728552232162_WhatsApp
_Image_20241010_at_144517.jpeg",
      "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externalimg_r_1728562554197_externa
llmg_1728552232162_WhatsApp_Image_20241010_at_144517.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6707c57ac691adb224f8ffe0",
      "name": "externalimg_1728562554207_externalimg_1728552232177_WhatsApp_I
```

```
mage_20241010_at_144520_2.jpeg",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externallmg_1728562554207_externallmg_1728552232177_WhatsApp_Image_20241010_at_144520_2.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6707c57ac691adb224f8ffdf",
  "name": "externallmg_1728562554203_externallmg_1728552232170_WhatsApp_Image_20241010_at_144519.jpeg",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externallmg_1728562554203_externallmg_1728552232170_WhatsApp_Image_20241010_at_144519.jpeg",
  "orientation": "landscape"
}
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "67079d286d5ad2b2230b7ec4",
    "name":
"externallmg_1728552232160_WhatsApp_Image_20241010_at_144516.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
externallmg_1728552232160_WhatsApp_Image_20241010_at_144516.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5312.00",
    "max": "8821.00"
  },
  "builtUpRateRange": {
    "min": "4426.00",
    "max": "7351.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "936.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66e2dc6e8e4fd6c8ff59c3c4",
"ownerName": "Mrs. Fatema Ebrahim Halvadwala",
"ownerPhoneNo": "7738988421",
"appAddress": "B601, sNo24,Kondhwa BK Pune",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    }
  },
  "inputs": {
    "documentDate": "14/07/2014",
    "from": {
      "value": "Owner",
      "label": "Owner"
    }
  },
  "Owner": "M/s. A. V. Bhat Essenseia",
  "to": {
```

```
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Mrs. Fatema Ebrahim Halvadwala & Mrs. Zaitoon Fakhruddin
Moiyadi",
  "number": {
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": " 4922/2014"
},
"isHardCopy": false,
"displayStatus": true,
"id": "247934",
"path": "cases/66e2dc6e8e4fd6c8ff59c3c4/document_1726143455030_1726143444
455_Fatima_Ebrahim_Halvadwala_7738988421.pdf",
"fileName": "document_1726143455030_1726143444455_Fatima_Ebrahim_Halvad
wala_7738988421.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "22/12/2011",
    "nameOfApprovingAuthority": {
      "value": "Pune_Municipal_Corporation",
      "label": "Pune Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " OCC/1052/11"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "9111149",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/document_1728566882935_OC.pdf",
  "fileName": "document_1728566882935_OC.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
```

```
    },
    "inputs": {
      "documentDate": "04/11/2009",
      "nameOfApprovingAuthority": {
        "value": "Pune_Municipal_Corporation",
        "label": "Pune Municipal Corporation"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": " CC/2475/2009"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "867162",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/document_1728567129338_CC.pdf",
    "fileName": "document_1728567129338_CC.pdf"
  },
  {
    "documentType": {
      "value": "60ae1249aa6d152c1801b2f1",
      "label": "Society Maintenance Bill"
    },
    "inputs": {
      "documentDate": "01/08/2024",
      "remark": "in the name of Mrs. Fatima Halwadwala for Flat No. B-601 issued by  
Essenseia Phase 1 CHSL",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": " 186"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "577843",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/  
document_1728567233403_Maintenance_Bill.pdf",
    "fileName": "document_1728567233403_Maintenance_Bill.pdf"
  },
  {
    "documentType": {
      "value": "60ae1249aa6d152c1801b2f3",
      "label": "Electricity Bill"
    },
  },
```

```
"inputs": {
  "documentDate": "11/08/2024",
  "number": {
    "value": "Consumer_No",
    "label": "Consumer No"
  },
  "Consumer_No": " 160252870595"
},
"isHardCopy": false,
"displayStatus": false,
"id": "567315",
"path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
document_1728567294981_Electricity_Bill.pdf",
"fileName": "document_1728567294981_Electricity_Bill.pdf"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "remark": "bearing Nos. 441 to 450 having 10 Shares of Rs. 50/- each dated
05/11/2019 in the name of Fatema Ebrahim Halvadwala issued by Essenseia Phase
1Co-op. Hsg. Soc. Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " 45"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "255398",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
document_1728567463863_Share_Certificate.pdf",
  "fileName": "document_1728567463863_Share_Certificate.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fb",
    "label": "Title Investigation Report"
  },
  "inputs": {
    "documentDate": "11/09/2024",
    "remark": " Ref. No. RACPC/Ghatkopar/September/TIR-21/24 issued by The
Attorney's."
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "400224",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/document_1728908951841_TIR.pdf",
    "fileName": "document_1728908951841_TIR.pdf"
  }
],
"caseNumber": "011182",
"createdBy": "63fda584ce84bf289baadaf6",
"caseHistory": [
  {
    "id": "207843",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 12 2024 17:49:58 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Fatema Ebrahim Halvadwala",
    "phone": "7738988421",
    "ownershipShare": "",
    "email": "",
    "id": "662896"
  },
  {
    "name": "Mrs. Zaitoon Fakhruddin Moiyadi",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "301737"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    }
  },
  {
    "docMeasurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "86.96",
  "totalAreaDocument": "936",
  "docBuiltpPercentage": "20",
  "docFinalBUILTUp": "1123.20",
  "docFinalBUILTUpSquareMeter": "104.35",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "436537"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "800.00",
      "squareMeterArea": "74.32",
      "expectedRate": "7500.00",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "960.00",
      "squareMeterArea": "89.19",
      "expectedRate": "6250.00",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "6707c136ba5e64b24a32f499",
  "property": "Flat",
  "area": "800",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
```

```
"expectedPrice": "6000000",
"expectedRate": "7500.00",
"builtUpExpectedRate": "6250.00",
"image": "cases/66e2dc6e8e4fd6c8ff59c3c4/indicator_1728561157451_Image.png",
"squareMeter": "74.32",
"id": "695318"
},
{
  "carpetArea": {
    "area": "907.00",
    "squareMeterArea": "84.26",
    "expectedRate": "8820.29",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1088.40",
    "squareMeterArea": "101.12",
    "expectedRate": "7350.24",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6707c136ba5e64b24a32f49a",
  "property": "Flat",
  "area": "907",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "8000000",
  "expectedRate": "8820.29",
  "builtUpExpectedRate": "7350.24",
  "image": "cases/66e2dc6e8e4fd6c8ff59c3c4/indicator_1728561188949_Image.png",
  "squareMeter": "84.26",
  "id": "191869"
},
{
  "carpetArea": {
    "area": "932.00",
```



```
    "squareMeterArea": "86.59",
    "expectedRate": "5311.16",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1118.40",
    "squareMeterArea": "103.90",
    "expectedRate": "4425.97",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6707c136ba5e64b24a32f49b",
  "property": "Flat",
  "area": "932",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "4950000",
  "expectedRate": "5311.16",
  "builtUpExpectedRate": "4425.97",
  "image": "cases/66e2dc6e8e4fd6c8ff59c3c4/indicator_1728561223712_Image.png",
  "squareMeter": "86.59",
  "id": "392224"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67079d286d5ad2b2230b7ec4",
    "name":
"externallmg_1728552232160_WhatsApp_Image_20241010_at_144516.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
externallmg_1728552232160_WhatsApp_Image_20241010_at_144516.jpeg",
    "orientation": "landscape"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67079d286d5ad2b2230b7ecd",
    "name":
"externallmg_1728552232180_WhatsApp_Image_20241010_at_144520.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
externallmg_1728552232180_WhatsApp_Image_20241010_at_144520.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67079d286d5ad2b2230b7ed0",
    "name":
"externallmg_1728552232187_WhatsApp_Image_20241010_at_144522_1.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
externallmg_1728552232187_WhatsApp_Image_20241010_at_144522_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6707c57ac691adb224f8ffdc",
    "name": "externallmg_1728562554197_externallmg_1728552232161_WhatsApp_I
mage_20241010_at_144517_1.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externallmg_1728562554197_externallm
g_1728552232161_WhatsApp_Image_20241010_at_144517_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6707c57ac691adb224f8ffdd",
    "name": "externallmg_1728562554198_externallmg_1728552232163_WhatsApp_I
mage_20241010_at_144518_1.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externallmg_1728562554198_externallm
g_1728552232163_WhatsApp_Image_20241010_at_144518_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6707c57ac691adb224f8ffde",
    "name": "externallmg_1728562554201_externallmg_1728552232169_WhatsApp_I
mage_20241010_at_144519_1.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externallmg_1728562554201_externallm
```

```
g_1728552232169_WhatsApp_Image_20241010_at_144519_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6707c57ac691adb224f8ffdf",
  "name": "externallmg_1728562554203_externallmg_1728552232170_WhatsApp_I
mage_20241010_at_144519.jpeg",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externallmg_1728562554203_externallm
g_1728552232170_WhatsApp_Image_20241010_at_144519.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6707c57ac691adb224f8ffe0",
  "name": "externallmg_1728562554207_externallmg_1728552232177_WhatsApp_I
mage_20241010_at_144520_2.jpeg",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externallmg_1728562554207_externallm
g_1728552232177_WhatsApp_Image_20241010_at_144520_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6707c57ac691adb224f8ffe1",
  "name": "externallmg_1728562554212_externallmg_1728552232181_WhatsApp_I
mage_20241010_at_144521_1.jpeg",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externallmg_1728562554212_externallm
g_1728552232181_WhatsApp_Image_20241010_at_144521_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6707c57ac691adb224f8ffe2",
  "name": "externallmg_1728562554217_externallmg_1728552232184_WhatsApp_I
mage_20241010_at_144521.jpeg",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externallmg_1728562554217_externallm
g_1728552232184_WhatsApp_Image_20241010_at_144521.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6707c57ac691adb224f8ffe3",
    "name": "externalimg_1728562554221_externalimg_1728552232189_WhatsApp_I
mage_20241010_at_144522.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externalimg_1728562554221_externalIm
g_1728552232189_WhatsApp_Image_20241010_at_144522.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6707c57ac691adb224f8ffe4",
    "name": "externalimg_r_1728562554200_externalimg_1728552232167_WhatsApp_
Image_20241010_at_144518.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externalimg_r_1728562554200_external
mg_1728552232167_WhatsApp_Image_20241010_at_144518.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6707c57ac691adb224f8ffe5",
    "name": "externalimg_r_1728562554197_externalimg_1728552232162_WhatsApp_
Image_20241010_at_144517.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externalimg_r_1728562554197_external
mg_1728552232162_WhatsApp_Image_20241010_at_144517.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6707c57ac691adb224f8ffe6",
    "name": "externalimg_r_1728562554206_externalimg_1728552232174_WhatsApp_
Image_20241010_at_144520_1.jpeg",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/externalimg_r_1728562554206_external
mg_1728552232174_WhatsApp_Image_20241010_at_144520_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2) - fatima.xlsx",
    "filename": "1728561456325_Calculation_2__fatima.xlsx",
    "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728561456325_Calculation_2__fatima.xlsx",
    "size": "16083",
```

```
"createdAt": "Thu Oct 10 2024 17:27:36 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "igr1.pdf",
  "filename": "1728561456325_igr1.pdf",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728561456325_igr1.pdf",
  "size": "167330",
  "createdAt": "Thu Oct 10 2024 17:27:36 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary - fatima.xlsx",
  "filename": "1728561456346_Summary__fatima.xlsx",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728561456346_Summary__fatima.xlsx",
  "size": "1111133",
  "createdAt": "Thu Oct 10 2024 17:27:36 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "visit details.xlsx",
  "filename": "1728561456373_visit_details.xlsx",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728561456373_visit_details.xlsx",
  "size": "22995",
  "createdAt": "Thu Oct 10 2024 17:27:36 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Location.jpeg",
  "filename": "1728908699664_Location.jpeg",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728908699664_Location.jpeg",
  "size": "105421",
  "createdAt": "Mon Oct 14 2024 17:55:00 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Maintenance Bill.pdf",
  "filename": "1728908699665_Maintenance_Bill.pdf",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728908699665_Maintenance_Bill.pdf",
  "size": "483023",
  "createdAt": "Mon Oct 14 2024 17:55:00 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "OC.pdf",
  "filename": "1728908699670_OC.pdf",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728908699670_OC.pdf",
  "size": "2201764",
  "createdAt": "Mon Oct 14 2024 17:55:00 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Deed - 2014.pdf",
  "filename": "1728908699705_Sale_Deed__2014.pdf",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728908699705_Sale_Deed__2014.pdf",
  "size": "37197730",
  "createdAt": "Mon Oct 14 2024 17:55:00 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Share Certificate.pdf",
  "filename": "1728908700049_Share_Certificate.pdf",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728908700049_Share_Certificate.pdf",
  "size": "539104",
  "createdAt": "Mon Oct 14 2024 17:55:00 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "TIR.pdf",
  "filename": "1728908700054_TIR.pdf",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728908700054_TIR.pdf",
  "size": "9522508",
  "createdAt": "Mon Oct 14 2024 17:55:00 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Visit Details.xlsx",
  "filename": "1728908700198_Visit_Details.xlsx",
  "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728908700198_Visit_Details.xlsx",
  "size": "25593",
  "createdAt": "Mon Oct 14 2024 17:55:00 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
```

```
    },
    {
      "originalname": "CC.pdf",
      "filename": "1728908718015_CC.pdf",
      "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728908718015_CC.pdf",
      "size": "809237",
      "createdAt": "Mon Oct 14 2024 17:55:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Electricity Bill.pdf",
      "filename": "1728908718024_Electricity_Bill.pdf",
      "path": "cases/66e2dc6e8e4fd6c8ff59c3c4/
processingDocuments/1728908718024_Electricity_Bill.pdf",
      "size": "560567",
      "createdAt": "Mon Oct 14 2024 17:55:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-09-12T12:19:58.580Z",
  "updatedAt": "2024-10-14T12:55:26.117Z",
  "__v": 0,
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  "fullAddress": "Residential Flat No. 601, 6th Floor, Wing - B, Essenseia Phase-1 Co-
op. Hsg. Soc. Ltd., Plot No. 11 & 12, Behind HP Petrol Pump, Village - Kondhwa
Budruk, Taluka - Haveli, District - Pune, Pune, PIN - 411 048, State - Maharashtra,
India",
  "updatedBy": "5fc78e26625ecd20ec1f88e9",
  "addressForMap": "",
  "caseReferredBy": "63fda584ce84bf289baadaf6",
  "contactPersonName": "Mr. Rukaiya Halvadwala",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "Tenant",
  "siteVisitContactNo": "9619651599",
```

```
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 936.00",
"flatRate": "7000",
"landOtherRate": "4500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 865.00\nAttached Terrace Area in Sq.
Ft. = 71.00 (40% of Terrace area 177.00 Sq. Ft.)\n",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Mon Oct 14 2024 17:43:57 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-10-10",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
}
```


}

Name

Length

Width

Total

Composition :

Other

Composition :
