

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ae7544191f7b344b0048fb"
    },
    "firstName": "VIVEK ",
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141ad3",
    "email": "intmum@bankofbaroda.com",
    "mobileNo": "9454708738",
    "workMobileNo": "9454708738",
    "lastName": "SHARMA"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4087976",
    "discussWithPerson": "VIVEK ",
    "expectedFees": 2043.988,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ae7544191f7b344b0048fb",
  "name": "INTERNATIONAL BUISNESS BRANCH- KANDIVALI (WEST)",
  "branchCode": "",
  "mobileNo": "022-28621460",
  "alternateMobileNo": "",
  "email": "intmum@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Jyoti Plaza, Opp. Anandvan Ashram, S.V.Road, Kandivali (West),
\nMumbai - 400 067."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
    "role": "MAKER",
    "firstName": "Bhavika",
    "email": "bhavikachavan0102@gmail.com",
    "lastName": "chavan",
    "mobileNo": "8390804382",
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "9004437379",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
```

```
    "label": "Wealth Tax"
  }
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.22122708172624",
  "longitude": "72.83561445867257"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83561445867257,
    19.22122708172624
  ]
}
},
"siteVisit": {
```

```
"siteVisitStatus": false,
"schedule": [
  {
    "dateTime": "13/09/2024 02:50 pm"
  },
  {
    "dateTime": "13/09/2024 12:00 am"
  }
],
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "21",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Wasabi Grove Building No 5 CHSL",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Chikuwadi",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```

```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2102-2103",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```



```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400092",
  "label": false
},
}
```

```
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Boriwali West",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
```

```
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```



```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66e3fbbedeff259c8fe6ebf78",
"ownerName": "Premila P Bhanushali & Bhavin Bhanushali ",
"ownerPhoneNo": "9702046702",
"appAddress": "Flat no 2102 & 2103 Floor 21 Wasabi Grove Bldg no 5 CO -op HSG
Soc Ltd Chikuwadi Borivali West Mumbai 400092",
"remark": "Documents pending hey",
"documents": [
  {
    "documentType": {
      "label": "Previous Valuation Report",
      "value": "60ae1248aa6d152c1801b2ee"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66e3fbbedeff259c8fe6ebf78/document_1726217178641_1726217174
757_Valuation_ReportValuation_Report_1_1.pdf",
    "fileName": "document_1726217178641_1726217174757_Valuation_ReportValuatio
n_Report_1_1.pdf",
    "id": "839235",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Fri Sep 13 2024 14:16:37 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "011195",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "385666",
    "title": "Create Lead",
```

```
"description": "Create Lead",
"datetime": "Fri Sep 13 2024 14:16:37 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Premila P Bhanushali & Bhavin Bhanushali ",
"phone": "9702046702",
"ownershipShare": "",
"email": "",
"id": "949468"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66e42f1b8e4fd6c8ff5a8062",
"name": "externallmg_1726230268022_1726230264331_image_0.jpeg",
"path": "cases/66e3fbbedeff259c8fe6ebf78/
externallmg_1726230268022_1726230264331_image_0.jpeg",
"orientation": "landscape"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66e42f1b8e4fd6c8ff5a8063",
"name": "externallmg_1726230269479_1726230264331_image_1.jpeg",
"path": "cases/66e3fbbedeff259c8fe6ebf78/
externallmg_1726230269479_1726230264331_image_1.jpeg",
"orientation": "landscape"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66e42f1b8e4fd6c8ff5a8064",
"name": "externallmg_1726230270200_1726230264331_image_2.jpeg",
"path": "cases/66e3fbbedeff259c8fe6ebf78/
externallmg_1726230270200_1726230264331_image_2.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66e42f1b8e4fd6c8ff5a8065",
  "name": "externallmg_1726230272502_1726230264331_image_3.jpeg",
  "path": "cases/66e3fbbedeff259c8fe6ebf78/
externallmg_1726230272502_1726230264331_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66e42f1b8e4fd6c8ff5a8066",
  "name": "externallmg_1726230274950_1726230264332_image_4.jpeg",
  "path": "cases/66e3fbbedeff259c8fe6ebf78/
externallmg_1726230274950_1726230264332_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66e42f1b8e4fd6c8ff5a8067",
  "name": "externallmg_1726230277485_1726230264332_image_5.jpeg",
  "path": "cases/66e3fbbedeff259c8fe6ebf78/
externallmg_1726230277485_1726230264332_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66e42f1b8e4fd6c8ff5a8068",
  "name": "externallmg_1726230279942_1726230264332_image_6.jpeg",
  "path": "cases/66e3fbbedeff259c8fe6ebf78/
externallmg_1726230279942_1726230264332_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66e42f1b8e4fd6c8ff5a8069",
  "name": "externallmg_1726230281232_1726230264332_image_7.jpeg",
  "path": "cases/66e3fbbedeff259c8fe6ebf78/
externallmg_1726230281232_1726230264332_image_7.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66e42f1b8e4fd6c8ff5a806a",
      "name": "externallmg_1726230282517_1726230264332_image_8.jpeg",
      "path": "cases/66e3fbedeff259c8fe6ebf78/
externallmg_1726230282517_1726230264332_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66e42f1b8e4fd6c8ff5a806b",
      "name": "externallmg_1726230282562_1726230264332_image_9.jpeg",
      "path": "cases/66e3fbedeff259c8fe6ebf78/
externallmg_1726230282562_1726230264332_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66e42f1b8e4fd6c8ff5a806c",
      "name": "externallmg_1726230283161_1726230264332_image_10.jpeg",
      "path": "cases/66e3fbedeff259c8fe6ebf78/
externallmg_1726230283161_1726230264332_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66e42f1b8e4fd6c8ff5a806d",
      "name": "externallmg_1726230284734_1726230264332_image_11.jpeg",
      "path": "cases/66e3fbedeff259c8fe6ebf78/
externallmg_1726230284734_1726230264332_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66e42f1b8e4fd6c8ff5a806e",
      "name": "externallmg_1726230286741_1726230264332_image_12.jpeg",
      "path": "cases/66e3fbedeff259c8fe6ebf78/
externallmg_1726230286741_1726230264332_image_12.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66e42f1b8e4fd6c8ff5a806f",
  "name": "externallmg_1726230287386_1726230264332_image_13.jpeg",
  "path": "cases/66e3fbedeff259c8fe6ebf78/
externallmg_1726230287386_1726230264332_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66e42f1b8e4fd6c8ff5a8070",
  "name": "externallmg_1726230288148_1726230264332_image_14.jpeg",
  "path": "cases/66e3fbedeff259c8fe6ebf78/
externallmg_1726230288148_1726230264332_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66e42f1b8e4fd6c8ff5a8071",
  "name": "externallmg_1726230289376_1726230264332_image_15.jpeg",
  "path": "cases/66e3fbedeff259c8fe6ebf78/
externallmg_1726230289376_1726230264332_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66e42f1b8e4fd6c8ff5a8072",
  "name": "externallmg_1726230291855_1726230264332_image_16.jpeg",
  "path": "cases/66e3fbedeff259c8fe6ebf78/
externallmg_1726230291855_1726230264332_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66e42f1b8e4fd6c8ff5a8073",
  "name": "externallmg_1726230294256_1726230264332_image_17.jpeg",
  "path": "cases/66e3fbedeff259c8fe6ebf78/
externallmg_1726230294256_1726230264332_image_17.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66e42f1b8e4fd6c8ff5a8074",
    "name": "externalImg_1726230295571_1726230264332_image_18.jpeg",
    "path": "cases/66e3fbedeff259c8fe6ebf78/
externalImg_1726230295571_1726230264332_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66e42f1b8e4fd6c8ff5a8075",
    "name": "externalImg_1726230297700_1726230264332_image_19.jpeg",
    "path": "cases/66e3fbedeff259c8fe6ebf78/
externalImg_1726230297700_1726230264332_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e42f2b8e4fd6c8ff5a80b8",
    "name": "externalImg_1726230299089_1726230294759_image_0.jpeg",
    "path": "cases/66e3fbedeff259c8fe6ebf78/
externalImg_1726230299089_1726230294759_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e42f2b8e4fd6c8ff5a80b9",
    "name": "externalImg_1726230301363_1726230294759_image_1.jpeg",
    "path": "cases/66e3fbedeff259c8fe6ebf78/
externalImg_1726230301363_1726230294759_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e42f2b8e4fd6c8ff5a80ba",
    "name": "externalImg_1726230303193_1726230294759_image_2.jpeg",
    "path": "cases/66e3fbedeff259c8fe6ebf78/
externalImg_1726230303193_1726230294759_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66e42f2b8e4fd6c8ff5a80bb",
    "name": "externalImg_1726230305735_1726230294759_image_3.jpeg",
    "path": "cases/66e3fbedeff259c8fe6ebf78/
externalImg_1726230305735_1726230294759_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e42f2b8e4fd6c8ff5a80bc",
    "name": "externalImg_1726230307027_1726230294759_image_4.jpeg",
    "path": "cases/66e3fbedeff259c8fe6ebf78/
externalImg_1726230307027_1726230294759_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e42f2b8e4fd6c8ff5a80bd",
    "name": "externalImg_1726230310928_1726230294759_image_5.jpeg",
    "path": "cases/66e3fbedeff259c8fe6ebf78/
externalImg_1726230310928_1726230294759_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e42f2b8e4fd6c8ff5a80be",
    "name": "externalImg_1726230312548_1726230294759_image_6.jpeg",
    "path": "cases/66e3fbedeff259c8fe6ebf78/
externalImg_1726230312548_1726230294759_image_6.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-13T08:46:37.605Z",
"updatedAt": "2024-09-13T12:25:15.076Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
}
```

```
},
"fullAddress": "Residential Flat No. 2102-2103, 21st Floor, Wasabi Grove Building No
5 CHSL, Chikuwadi, Boriwali West, Mumbai, 400092, State - Maharashtra, India",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Premila P Bhanushali & Bhavin Bhanushali ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9702046702"
}
```

}	Name	Length	Width	Total
Composition :				
Other				
Composition :				