

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Carpet_area_Certificate",
    "label": "Carpet area Certificate"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Carpet_Area",
    "label": "Carpet Area"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Dr",
    "expectedFees": 0,
    "quotedAmount": "15000"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "66e7da9ca1f1577e0b25cfff",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Dr Yashda Gondal ",
"displayName": "Dr Yashda Gondal ",
"initial": "D"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ff3ead28cda966090eacbbe",
    "role": "VALUER",
    "firstName": "Umang",
    "email": "umang@vastukala.org",
    "lastName": "Patel",
    "mobileNo": "9819670183",
    "shortName": "umang",
    "workWithDocumentMaker": "5fc75d341095af19d8b34239",
    "profilePhoto": "users/5ff3ead28cda966090eacbbe/
profilePhoto_1678667749982_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "65dee3f79a876858ab30487f",
    "role": "SITEENGINEER",
    "firstName": "Saiprasad",
    "email": "saiprasadpatil1010@gmail.com",
    "lastName": "Patil",
    "mobileNo": "8830049996",
    "designation": "Valuation Engineer",
    "shortName": "SSP",
    "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
    "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5ff3ead28cda966090eacbbe",
    "role": "VALUER",
```

```
"firstName": "Umang",
"email": "umang@vastukala.org",
"lastName": "Patel",
"mobileNo": "9819670183",
"shortName": "umang",
"workWithDocumentMaker": "5fc75d341095af19d8b34239",
"designation": "",
"profilePhoto": "users/5ff3ead28cda966090eachbbe/
profilePhoto_1678667749982_image.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
  "lastName": "Patil",
  "mobileNo": "8830049996",
  "designation": "Valuation Engineer",
  "shortName": "SSP",
  "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
  "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
],
```

```
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
```

```
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.055452234803507",
  "longitude": "72.88989940117689"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "16/09/2024 12:26 pm"
    },
    {
      "dateTime": "16/09/2024 12:00 am"
    },
    {
      "dateTime": "16/09/2024 12:00 am"
    },
    {
      "dateTime": "16/09/2024 12:00 am"
    },
    {
      "dateTime": "16/09/2024 12:00 am"
    },
    {
      "dateTime": "16/09/2024 12:00 am"
    },
    {
      "dateTime": "16/09/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": ""
  }
}
```

```
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ameet Towers",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
```

```
"name": "Street 1",
"key": "street1",
"value": "Next To Wasan House",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Sion Trombay Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
}
```



```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "602",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```

```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400071",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Chembur East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"whichTheLocalityIsServed": {
  "buses": {
```

```
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": ""
  }
}
```

```
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```

```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
},
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": true,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
```

```
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66e7da9ca1f1577e0b25d005",
"ownerName": "Dr Yashda Gondal ",
"ownerPhoneNo": "9220001505",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9220001505",
"contactPersonName": "Dr Yashda Gondal ",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Dr Yashda Gondal ",
    "phone": "9220001505",
    "ownershipShare": "",
    "email": "",
    "id": "973194"
  }
],
"caseReferredBy": "5ff3ead28cda966090eachbbe",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 602, 6th Floor, Ameet Towers, Next To Wasan House, Sion Trombay Road, Chembur East, Mumbai, 400071, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1726487689312_DSOUZA20240626170024_1.pdf",
    "path": "cases/66e7da9ca1f1577e0b25d005/document_1726487689312_DSOUZA20240626170024_1.pdf",
    "id": "177466",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Mon Sep 16 2024 17:24:52 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
```

```
"value": "Retail",
"label": "Retail"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "011227",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "432185",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Mon Sep 16 2024 12:43:32 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1d0",
    "name": "externalImg_1726640725580_IMG20240918WA0001.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externalImg_1726640725580_IMG20240918WA0001.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1d1",
    "name": "externalImg_1726640725584_IMG20240918WA0002.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externalImg_1726640725584_IMG20240918WA0002.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1d2",
    "name": "externalImg_1726640725585_IMG20240918WA0003.jpg",
```

```
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725585_IMG20240918WA0003.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1d3",
    "name": "externallmg_1726640725586_IMG20240918WA0004.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725586_IMG20240918WA0004.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1d4",
    "name": "externallmg_1726640725590_IMG20240918WA0005.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725590_IMG20240918WA0005.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1d5",
    "name": "externallmg_1726640725590_IMG20240918WA0006.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725590_IMG20240918WA0006.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1d6",
    "name": "externallmg_1726640725591_IMG20240918WA0007.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725591_IMG20240918WA0007.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1d7",
    "name": "externallmg_1726640725592_IMG20240918WA0008.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725592_IMG20240918WA0008.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ea7255a1f1577e0b26c1d8",
  "name": "externallmg_1726640725593_IMG20240918WA0009.jpg",
  "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725593_IMG20240918WA0009.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ea7255a1f1577e0b26c1d9",
  "name": "externallmg_1726640725594_IMG20240918WA0010.jpg",
  "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725594_IMG20240918WA0010.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ea7255a1f1577e0b26c1da",
  "name": "externallmg_1726640725595_IMG20240918WA0011.jpg",
  "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725595_IMG20240918WA0011.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ea7255a1f1577e0b26c1db",
  "name": "externallmg_1726640725596_IMG20240918WA0012.jpg",
  "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725596_IMG20240918WA0012.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ea7255a1f1577e0b26c1dc",
  "name": "externallmg_1726640725597_IMG20240918WA0013.jpg",
  "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725597_IMG20240918WA0013.jpg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1dd",
    "name": "externallmg_1726640725598_IMG20240918WA0014.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725598_IMG20240918WA0014.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1de",
    "name": "externallmg_1726640725598_IMG20240918WA0015.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725598_IMG20240918WA0015.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1df",
    "name": "externallmg_1726640725599_IMG20240918WA0016.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725599_IMG20240918WA0016.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1e0",
    "name": "externallmg_1726640725600_IMG20240918WA0017.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725600_IMG20240918WA0017.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ea7255a1f1577e0b26c1e1",
    "name": "externallmg_1726640725601_WhatsApp_Image_20240918_at_115329_7
b7c10ad.jpg",
    "path": "cases/66e7da9ca1f1577e0b25d005/
externallmg_1726640725601_WhatsApp_Image_20240918_at_115329_7b7c10ad.jpg",
    "orientation": "portrait"
  }
}
```

```

    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66ea7255a1f1577e0b26c1e2",
      "name": "externalImg_1726640725602_WhatsApp_Image_20240918_at_115330_9cf9bd8c.jpg",
      "path": "cases/66e7da9ca1f1577e0b25d005/externalImg_1726640725602_WhatsApp_Image_20240918_at_115330_9cf9bd8c.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-09-16T07:13:32.639Z",
  "updatedAt": "2024-09-18T06:25:25.641Z",
  "__v": 0,
  "addressForMap": "",
  "updatedBy": "65dee3f79a876858ab30487f"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			