

```
{
  "typeOfReport": {
    "value": "Godown",
    "label": "Godown"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "firstName": "Amruta ",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f5a",
    "email": "amruta.pathak@cosmosbank.in",
    "mobileNo": "-",
    "workMobileNo": "9769900929",
    "lastName": "Pathak"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) Branch",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhudurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
( East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
  "mobileNo": "9821518537",
  "designation": ""
}
```

```
    "shortName": "PS",
    "workWithDocumentMaker": "60f915d3f3dd69653a592199",
    "profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "checker": null,
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.213703",
  "longitude": "73.098672"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.098672,
    19.213703
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false,
  "area": "1500.00",
  "rate": "8000.00",
  "yearOfConstruction": "2003",
  "compositionOfBuilding": "Ground + 7 Upper Floors"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "G. B. Patharli",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivli (East)",
  "label": false
},
"tahsilNo": {
  "status": false,
```

```
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Samarth Vihar Co.-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```

```
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Shiv Mandir",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "2/5 (Part) & 53A / 3 and As per online Records (Survey No. 2/5/A & 53/3)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```

```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```



```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 201",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "31.499999999999996",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "787.4999999999999",
  "depreciatedCostOfConstruction": "7212.50",
  "depreciatedBuildingRate": "1712.5"
},
"igrRate": {
  "propertyName": "Godown",
  "rate": "74500",
  "landRate": "24500",
  "igrImage": "cases/66ebcdba107b3378fb9fb22c/igr_1726808671624_Image.png",
  "squareMeterGuideLineRate": "74500.00",
  "squareFeetGuideLineRate": "6921.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "79",
  "rate": "5946.00",
  "squareFeetGuideLineRate": "5946.00",
  "squareMeterGuideLineRate": "64000.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
}
```

```
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2003",
  "fullDate": "1/1/2003"
},
"planningArea": {
  "value": "Commercial",
  "label": "Commercial"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
```

```
"totalLifeBuilding": "60",
"estimatedAge": "39",
"ageOfBuilding": "21",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "Ground",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": ""
  }
}
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "8919000.00",
  "selectedBuildUpValue": "1500.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8507.00",
    "max": "176952.00"
  },
  "builtUpRateRange": {
    "min": "7089.00",
    "max": "147466.00"
  }
}
```



```
},
"saleableRateRange": {
  "min": "6343.00",
  "max": "10607.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
```

```
"status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1500.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66ebcdba107b3378fb9fb22c",
"ownerName": "Smt. Manju Savaram Choudhari & Shri. Saka Ram Choudhari",
"ownerPhoneNo": "7977787373",
"fullAddress": "Commercial Godown No. 1, Ground Floor, Samarth Vihar Co.-Op. Hsg.
Soc. Ltd., Near Shiv Mandir, New/Current Survey No. 2/5 (Part) & 53A / 3 and As per
online Records (Survey No. 2/5/A & 53/3), Village - G. B. Patharli, Taluka - Kalyan,
District - Thane, Dombivli (East), PIN Code - 421 201, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
```

```
"label": "Agreement for sale"
},
"inputs": {
  "documentDate": "07/05/2024",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Vijay Enterprises",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Smt. Manju Savaram Choudhari & Shri. Saka Ram Choudhari",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "7587/2024"
},
"isHardCopy": false,
"displayStatus": false,
"id": "862143",
"path": "cases/66ebcdba107b3378fb9fb22c/
document_1726729498277_179582.pdf",
"fileName": "document_1726729498277_179582.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "01/07/2003",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KDMC / NRV / CC / DOV / 174 "
  },
  "isHardCopy": false,
  "displayStatus": true,
}
```

```
"id": "503424",
"path": "cases/66ebcdba107b3378fb9fb22c/
document_1726729527030_169116.pdf",
"fileName": "document_1726729527030_169116.pdf"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "18/07/1999",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / NRV / BP / DOV / 159 – 41 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1726834449147_180853.pdf",
"path": "cases/66ebcdba107b3378fb9fb22c/
document_1726834449147_180853.pdf",
"id": "619628",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Fri Sep 20 2024 17:44:52 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "01/07/2003",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
    "No": "KDMC / NRV / CC / DOV / 174"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1726834492058_122957.pdf",
  "path": "cases/66ebcdba107b3378fb9fb22c/
document_1726834492058_122957.pdf",
  "id": "978973",
  "uploadedBy": "627222afafd7d55eddedd82",
  "createdAt": "Fri Sep 20 2024 17:44:52 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "011282",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "156421",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 19 2024 12:37:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Smt. Manju Savaram Choudhari & Shri. Saka Ram Choudhari",
    "phone": "7977787373",
    "ownershipShare": "",
    "email": "",
    "id": "472106"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  }
],
```

```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"selectAreaTypeDocument": "Built_Up",
"squareMeterArea": "139.35",
"totalAreaDocument": "1500",
"docBuiltpPercentage": "",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "773204"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "3000.00",
    "squareMeterArea": "278.71",
    "expectedRate": "9133.33",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "3600.00",
    "squareMeterArea": "334.45",
    "expectedRate": "7611.11",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "4320.00",
    "squareMeterArea": "401.34",
    "expectedRate": "6342.59",
    "percentage": "20"
  },
  "printInReport": true,
  "_id": "66ed0295ada7094de492e3ac",
  "property": "Godown",
  "area": "3000",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": ""
}
```

```
"source": "Nobroker.com",
"expectedPrice": "27400000",
"expectedRate": "9133.33",
"builtUpExpectedRate": "7611.11",
"image": "cases/66ebcdba107b3378fb9fb22c/
indicator_1726808456187_Image.png",
"squareMeter": "278.71",
"id": "681801"
},
{
"carpetArea": {
"area": "916.67",
"squareMeterArea": "85.16",
"expectedRate": "15272.67",
"percentage": ""
},
"builtUpArea": {
"area": "1100.00",
"squareMeterArea": "102.19",
"expectedRate": "12727.27",
"percentage": "20"
},
"saleableArea": {
"area": "1320.00",
"squareMeterArea": "122.63",
"expectedRate": "10606.06",
"percentage": "20"
},
"printlnReport": true,
"_id": "66ed0295ada7094de492e3ad",
"property": "Godown",
"area": "1100",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "14000000",
"expectedRate": "15272.67",
"builtUpExpectedRate": "14000000",
"image": "cases/66ebcdba107b3378fb9fb22c/
indicator_1726808500343_Image.png",
"squareMeter": "102.19",
"id": "701322"
},
```



```
{
  "carpetArea": {
    "area": "663.27",
    "squareMeterArea": "61.62",
    "expectedRate": "8506.34",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "795.92",
    "squareMeterArea": "73.94",
    "expectedRate": "7088.65",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66ed0295ada7094de492e3ae",
  "property": "Godown",
  "area": "663.27",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "5642000",
  "expectedRate": "8506.34",
  "builtUpExpectedRate": "7088.65",
  "image": "cases/66ebcdba107b3378fb9fb22c/
indicator_1726808562672_Image.png",
  "squareMeter": "61.62",
  "id": "640162"
},
{
  "carpetArea": {
    "area": "90.42",
    "squareMeterArea": "8.4",
    "expectedRate": "176952.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "108.50",
```

```
    "squareMeterArea": "10.08",
    "expectedRate": "147465.44",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66ed0295ada7094de492e3af",
  "property": "Godown",
  "area": "90.42",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "16000000",
  "expectedRate": "176952.00",
  "builtUpExpectedRate": "147465.44",
  "image": "cases/66ebcdba107b3378fb9fb22c/
indicator_1726808617950_Image.png",
  "squareMeter": "8.4",
  "id": "439645"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef50107b3378fb9fe2df",
    "name":
"externalImg_1726738254784_WhatsApp_Image_20240919_at_15205_PM_1.jpeg",
    "path": "cases/66ebcdba107b3378fb9fb22c/
externalImg_1726738254784_WhatsApp_Image_20240919_at_15205_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef50107b3378fb9fe2e0",
    "name":
"externalImg_1726738254812_WhatsApp_Image_20240919_at_15205_PM.jpeg",
```

```
    "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738254812_WhatsApp_Image_20240919_at_15205_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef50107b3378fb9fe2e1",
    "name":
"externallmg_1726738254863_WhatsApp_Image_20240919_at_15206_PM_1.jpeg",
    "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738254863_WhatsApp_Image_20240919_at_15206_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef50107b3378fb9fe2e2",
    "name":
"externallmg_1726738254955_WhatsApp_Image_20240919_at_15206_PM_2.jpeg",
    "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738254955_WhatsApp_Image_20240919_at_15206_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef50107b3378fb9fe2e3",
    "name":
"externallmg_1726738255022_WhatsApp_Image_20240919_at_15206_PM.jpeg",
    "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738255022_WhatsApp_Image_20240919_at_15206_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef50107b3378fb9fe2e4",
    "name":
"externallmg_1726738255383_WhatsApp_Image_20240919_at_15207_PM_1.jpeg",
    "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738255383_WhatsApp_Image_20240919_at_15207_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66ebef50107b3378fb9fe2e5",
  "name":
"externallmg_172673825519_WhatsApp_Image_20240919_at_15207_PM_2.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_172673825519_WhatsApp_Image_20240919_at_15207_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef50107b3378fb9fe2e6",
  "name":
"externallmg_172673825596_WhatsApp_Image_20240919_at_15207_PM.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_172673825596_WhatsApp_Image_20240919_at_15207_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef50107b3378fb9fe2e7",
  "name":
"externallmg_1726738255664_WhatsApp_Image_20240919_at_15208_PM_1.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738255664_WhatsApp_Image_20240919_at_15208_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef50107b3378fb9fe2e8",
  "name":
"externallmg_1726738255758_WhatsApp_Image_20240919_at_15208_PM.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738255758_WhatsApp_Image_20240919_at_15208_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef50107b3378fb9fe2e9",
  "name":
"externallmg_1726738255818_WhatsApp_Image_20240919_at_15209_PM_1.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738255818_WhatsApp_Image_20240919_at_15209_PM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef50107b3378fb9fe2ea",
    "name":
"externallmg_1726738255846_WhatsApp_Image_20240919_at_15209_PM_2.jpeg",
    "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738255846_WhatsApp_Image_20240919_at_15209_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef50107b3378fb9fe2eb",
    "name":
"externallmg_1726738255908_WhatsApp_Image_20240919_at_15209_PM.jpeg",
    "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738255908_WhatsApp_Image_20240919_at_15209_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef50107b3378fb9fe2ec",
    "name":
"externallmg_1726738255941_WhatsApp_Image_20240919_at_15210_PM_1.jpeg",
    "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738255941_WhatsApp_Image_20240919_at_15210_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef63eff259c8fe71d815",
    "name":
"externallmg_1726738274687_WhatsApp_Image_20240919_at_15210_PM_2.jpeg",
    "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738274687_WhatsApp_Image_20240919_at_15210_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ebef63eff259c8fe71d816",
```

```
"name":
"externallmg_1726738274930_WhatsApp_Image_20240919_at_15210_PM.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738274930_WhatsApp_Image_20240919_at_15210_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef63eff259c8fe71d817",
  "name":
"externallmg_1726738274931_WhatsApp_Image_20240919_at_15211_PM_1.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738274931_WhatsApp_Image_20240919_at_15211_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef63eff259c8fe71d818",
  "name":
"externallmg_1726738274932_WhatsApp_Image_20240919_at_15211_PM.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738274932_WhatsApp_Image_20240919_at_15211_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef63eff259c8fe71d819",
  "name":
"externallmg_1726738274945_WhatsApp_Image_20240919_at_15212_PM_1.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738274945_WhatsApp_Image_20240919_at_15212_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef63eff259c8fe71d81a",
  "name":
"externallmg_1726738275011_WhatsApp_Image_20240919_at_15212_PM_2.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738275011_WhatsApp_Image_20240919_at_15212_PM_2.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef63eff259c8fe71d81b",
  "name":
"externallmg_1726738275054_WhatsApp_Image_20240919_at_15212_PM.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738275054_WhatsApp_Image_20240919_at_15212_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef63eff259c8fe71d81c",
  "name":
"externallmg_1726738275129_WhatsApp_Image_20240919_at_15213_PM_1.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738275129_WhatsApp_Image_20240919_at_15213_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef63eff259c8fe71d81d",
  "name":
"externallmg_1726738275173_WhatsApp_Image_20240919_at_15213_PM.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738275173_WhatsApp_Image_20240919_at_15213_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ebef63eff259c8fe71d81e",
  "name":
"externallmg_1726738275192_WhatsApp_Image_20240919_at_15349_PM.jpeg",
  "path": "cases/66ebcdba107b3378fb9fb22c/
externallmg_1726738275192_WhatsApp_Image_20240919_at_15349_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [
  {
    "originalname": "Manju Savaram Choudhari.doc",
    "filename": "1726834075429_Manju_Savaram_Choudhari.doc",
    "path": "cases/66ebcdba107b3378fb9fb22c/
externalDocuments/1726834075429_Manju_Savaram_Choudhari.doc",
```

```
"size": "4459008",
"documentType": {
  "value": "649998c6cab24d3d1a2cc577",
  "label": "Draft Word Report"
},
"createdAt": "Fri Sep 20 2024 17:37:56 GMT+0530 (India Standard Time)",
"uploadedBy": "627222afafd7d55eddedd82"
},
],
"processingDocuments": [
  {
    "originalname": "Manju Savaram Choudhari & Shri. Saka Ram Choudhari - Gala No.
1 - Cosmos Bank ( Dombivali (East) Branch ).xlsx",
    "filename": "1726808703637_Manju_Savaram_Choudhari__Shri_Saka_Ram_Chou
dhari__Gala_No_1__Cosmos_Bank__Dombivali_East_Branch_.xlsx",
    "path": "cases/66ebcdba107b3378fb9fb22c/processingDocuments/1726808703637_
Manju_Savaram_Choudhari__Shri_Saka_Ram_Choudhari__Gala_No_1__Cosmos_Ba
nk__Dombivali_East_Branch_.xlsx",
    "size": "1412542",
    "createdAt": "Fri Sep 20 2024 10:35:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66ed0290bdd9ce4dabce8210",
    "note": "Value Given for confirmation",
    "taskId": "66ebcdc1107b3378fb9fb2ab",
    "createdAt": "2024-09-20T05:05:20.259Z"
  }
],
"createdAt": "2024-09-19T07:07:38.935Z",
"updatedAt": "2024-09-20T12:14:52.114Z",
```



```

    "__v": 0,
    "updatedBy": "627222afafd7d55eddedd82",
    "addressForMap": "",
    "caseReferredBy": "6410199a140f140ffc59b58c",
    "contactPersonName": "Smt. Manju Savaram Choudhari & Shri. Saka Ram Choudhari",
    "email": "",
    "isExternal": "false",
    "isUrgent": "false",
    "ownershipShare": "",
    "proposePurchaserName": "",
    "purchaseValueAsPerDocument": "",
    "relationWithOwner": "self",
    "siteVisitContactNo": "7977787373",
    "buildingServicesRate": "2500",
    "finalAreaType": "Built Up Area",
    "finalAsPerArea": "Agreement for sale",
    "finalBuiltUpPercentage": "0",
    "finalCarpetConvertToBuiltUpPer": "0",
    "finalMeasurementType": "Sq. Ft.",
    "finalValuationAreaString": "Built Up Area in Sq. Ft. = 1500.00",
    "flatRate": "8000",
    "landOtherRate": "5500",
    "shopDetails": {
      "typeOfShops": {
        "label": "Independent Building",
        "value": "Independent_Building"
      },
      "roadFacing": false,
      "mall": false
    }
  }
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			