

```
{
  "typeOfReport": {
    "value": "Unit",
    "label": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b800"
    },
    "firstName": "Krushna ",
    "type": "CREDITOFFICER",
    "_id": "65ba192e6635d840ef56c043",
    "lastName": "Dhanvij",
    "mobileNo": "",
    "workMobileNo": "8600786009",
    "email": "sbi.15521@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Krushna ",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b800",
  "branchCode": "000073",
  "type": "BRANCH",
  "name": "SME Credit Centre Borivali (West)",
  "email": "sbi.15781@sbi.co.in",
  "mobileNo": "022-28954966",
  "alternateMobileNo": "",
  "address": "SME Centre Borivali (15521) 101, 1st floor,
Landmark Building, S. V. Road, Near Petrol Pump, Borivali (West), Mumbai – 400 092,
State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA-SMECCC BORIVALI",
  "fax": "022-28909092",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "667112d324f3ba1343e5ac5c",
  "role": "PICKUPPERSON",
  "firstName": "SAHADEV ",
  "email": "temkarsahdaev@gmail.com",
  "lastName": "TEMKAR",
  "mobileNo": "9869931652",
  "shortName": "SAHADEV",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "MAKER",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
},
"location": {
  "latitude": "19.219189648239663",
  "longitude": "72.86187666073245"
},
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86187666073245,
    19.219189648239663
  ]
},
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-21",
      "remark": ""
    }
  ]
}
```

```
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-21",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Magathane",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
```

```
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Neha Industrial Premises Co-Op. Soc. Ltd.",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Opp. Tata Steel Company ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off. Dattapada Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Neha Industrial Estate",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```

```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "134, H-1(Part), H-2(Part)",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "68C",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "11",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```



```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 066",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
```

```
    "key": "suburb",
    "value": "Borivali (East)",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Carpet",
    "label": "Carpet"
  },
  "doors": {
    "value": "Glass_door_with_MS_Rolling_Shutter",
    "label": "Glass door with MS Rolling Shutter"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
```

```
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Internal Road ",
"west": "Saushish IT Park - Wing B",
"south": "Saushish IT Park ",
"east": "Internal Road "
},
"asPerDocumentAgreement": {
"north": "Khatau Junkers Land",
"west": "Lands of Resham Textiles Pvt. Ltd. & beyond that by lands of Shakti
Insulated Wires Pvt. Ltd. ",
"south": "Lands reserved for Govt. Godown",
"east": "Lands of Lessors & beyond by lands of cable Corporation f India Ltd."
},
"unitBoundaries": {
"asPerActual": {
"north": "Passage ",
"east": "Unit No. 10",
"south": "Marginal Space ",
"west": "Unit No. 12"
},
"asPerDocument": {
"north": "Details not available ",
"east": "Details not available ",
"south": "Details not available ",
"west": "Details not available "
},
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
"buses": {
"title": "Buses"
},
"taxies": {
"title": "Taxies"
},
"auto": {
"title": "Auto"
},
}
```

```

    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "Ground Floor Consist Working Area + 1 Toilet & Mezzanine Floor Consist 2 Cabins + Working Area + Pantry Area. ",
  "dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed that the construction is as per sanctioned plan",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "Construction permission for the Mezzanine area is not provided hence not considered for the purpose of valuation. We have considered the area as per the Article of Agreement for the purpose of valuation.",
  "depreciationPercentage": "31.499999999999996",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "16212.50",
  "depreciatedBuildingRate": "1712.5",
  "buildingServicesDepreciatedRate": "787.4999999999999"
},
"igrRate": {
  "propertyName": " Industrial Unit",
  "rate": "142610",
  "landRate": "61640",
  "igrImage": "cases/66ec0adb364a0f4dac122481/igr_1727093156283_Image.png",
  "squareMeterGuideLineRate": "0.00",
  "squareFeetGuideLineRate": "0.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "79",
  "rate": "1203.00",
  "squareMeterGuideLineRate": "12944.00",
  "squareFeetGuideLineRate": "1203.00"
},
"outgoingDetail": {
  "areaStatusList": {

```

```
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Industrial",
"label": "Industrial"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per MCGM norms ",
"tenantName": "",
"maintenanceOfFlat": "Normal "
},
"marketability": {
"marketabilityList": {
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area ",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
}
```

```
},
"carParking": "Open Car Parking Space ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2003",
  "fullDate": "1/1/2003"
},
"planningArea": {
  "value": "Industrial",
  "label": "Industrial"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
```

```
"label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "39",
"ageOfBuilding": "21",
```

```
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "2",
"flatFloorNo": "Ground",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "24"
},
"finalPlinthArea": {
  "area": "358.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Article of Agreement"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66ec0adb364a0f4dac122481/
routeMap_1727090283642_Image.png",
    "routeLat": "19.218917",
    "routeLng": "72.861556",
    "stationName": "Magathane",
    "routeDistance": "1.00 Km. ",
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "53trwu",
    "name": "53trwu",
    "image": "cases/66ec0adb364a0f4dac122481/
routeMap_1727090211568_Image.png"
  }
]
```



```
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "5804254.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "5804254.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Sep 23 2024 17:17:04 GMT+0530 (India Standard Time)",
  "number": "2308314",
```

```
"dayCount": "19",
"monthCount": "320",
"generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "430674.00",
  "selectedBuildUpValue": "358.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66eeae5eada7094de494ad4a",
    }
  ]
}
```

```
    "name": "externallmg_1726918189330_1726918166675_image_2.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918189330_1726918166675_image_2.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "66ee7e2dbdd9ce4dabcfa1ed",
    "name": "externallmg_1726905809814_1726905805506_image_0.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726905809814_1726905805506_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66ee7e2dbdd9ce4dabcfa1ef",
    "name": "externallmg_1726905820119_1726905805506_image_2.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726905820119_1726905805506_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66ee7e2dbdd9ce4dabcfa1f0",
    "name": "externallmg_1726905826743_1726905805506_image_3.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726905826743_1726905805506_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66ee7e2dbdd9ce4dabcfa1f3",
    "name": "externallmg_1726905883578_1726905805506_image_6.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726905883578_1726905805506_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66eeae5eada7094de494ad4a",
    "name": "externallmg_1726918189330_1726918166675_image_2.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918189330_1726918166675_image_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66eeae5eada7094de494ad53",
    "name": "externallmg_1726918220159_1726918166675_image_11.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918220159_1726918166675_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66eeae5eada7094de494ad57",
    "name": "externallmg_1726918233235_1726918166675_image_15.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918233235_1726918166675_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66eeae5eada7094de494ad59",
    "name": "externallmg_1726918237728_1726918166675_image_17.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918237728_1726918166675_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66eeae5eada7094de494ad4e",
    "name": "externallmg_1726918205928_1726918166675_image_6.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918205928_1726918166675_image_6.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16480.00",
    "max": "25600.00"
  },
  "builtUpRateRange": {
    "min": "13748.00",
```

```
"max": "21334.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "358.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66ec0adb364a0f4dac122481",
"ownerName": "Mr. Gheverchand Mistry ",
"ownerPhoneNo": "9820426974",
"appAddress": "Unit No.11, on Ground Floor, Neha Industrial Eastate, Neha Industrial
premises co-op Society Ltd, Survey No.134,,H-1 part, H-2 part,CTS No. 68,,Village
Magathane,Opp-Tata steel Company, off. Dattapada Road, Borivali East, Mumbai
400066.",
"remark": "",
"documents": [
  {
    "documentType": {
```

```
"value": "60ae124faa6d152c1801b30f",
"label": "Article of Agreement"
},
"inputs": {
  "documentDate": "03/05/2002",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Neha Enterprises ",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Gheverchand Mistry "
},
"isHardCopy": false,
"displayStatus": true,
"id": "902178",
"path": "cases/66ec0adb364a0f4dac122481/document_1726745209358_1726745207178_New_File_Baradwa_Furniture_Goverchand_Mistry.pdf",
"fileName": "document_1726745209358_1726745207178_New_File_Baradwa_Furniture_Goverchand_Mistry.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "03/09/2003",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / 9617 / BP(WS) / AR"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1727087663272_194938.pdf",
  "path": "cases/66ec0adb364a0f4dac122481/document_1727087663272_194938.pdf",
```

```
    "id": "779952",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Mon Sep 23 2024 16:04:23 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "011307",
"createdBy": "667112d324f3ba1343e5ac5c",
"caseHistory": [
  {
    "id": "332810",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 19 2024 16:58:27 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Gheverchand Mistry ",
    "phone": "9820426974",
    "ownershipShare": "",
    "email": "",
    "id": "720755"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "313530",
    "name": "Working Area",
    "length": "13.08",
    "length1": "13",
    "length2": "1",
    "width": "26.08",
    "width1": "26",
    "width2": "1",
    "totalArea": "341.26",
    "images": [],
    "extraAreas": [],
    "finalArea": "341.26"
  },
  {
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"name": "Mezzanine Floor",
"length": "341.00",
"length1": "341",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "341.00",
"images": [],
"extraAreas": [],
"finalArea": "341.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae124faa6d152c1801b30f",
      "label": "Article of Agreement"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "421766",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "358",
    "squareMeterArea": "33.26",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
```

```
"area": "625",
"squareMeterArea": "58.06",
"expectedRate": "25600.00",
"percentage": ""
},
"builtUpArea": {
"area": "750.00",
"squareMeterArea": "69.68",
"expectedRate": "21333.33",
"percentage": ""
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66f11869ada7094de4953b10",
"property": "Industrial Unit",
"area": "750",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "16000000",
"expectedRate": "25600.00",
"builtUpExpectedRate": "16000000",
"image": "cases/66ec0adb364a0f4dac122481/
indicator_1727076108743_Image.png",
"squareMeter": "69.68",
"id": "457186"
},
{
"carpetArea": {
"area": "640",
"squareMeterArea": "59.46",
"expectedRate": "17968.75",
"percentage": ""
},
"builtUpArea": {
"area": "768.00",
"squareMeterArea": "71.35",
"expectedRate": "14973.96",
```

```
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66f11869ada7094de4953b11",
  "property": " Industrial Unit",
  "area": "768",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "11500000",
  "expectedRate": "17968.75",
  "builtUpExpectedRate": "11500000",
  "image": "cases/66ec0adb364a0f4dac122481/
indicator_1727076153333_Image.png",
  "squareMeter": "71.35",
  "id": "506569"
},
{
  "carpetArea": {
    "area": "317",
    "squareMeterArea": "29.45",
    "expectedRate": "16479.50",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "380.00",
    "squareMeterArea": "35.30",
    "expectedRate": "13747.37",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
```

```
"_id": "66f11869ada7094de4953b12",
"property": " Industrial Unit",
"area": "380",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "5224000",
"expectedRate": "16479.50",
"builtUpExpectedRate": "5224000",
"image": "cases/66ec0adb364a0f4dac122481/
indicator_1727076193609_Image.png",
"squareMeter": "35.30",
"id": "243857"
},
{
  "carpetArea": {
    "area": "317",
    "squareMeterArea": "29.45",
    "expectedRate": "16479.50",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "380.00",
    "squareMeterArea": "35.30",
    "expectedRate": "13747.37",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66f11869ada7094de4953b13",
  "property": " Industrial Unit",
  "area": "380",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
```

```
    "expectedPrice": "5224000",
    "expectedRate": "16479.50",
    "builtUpExpectedRate": "5224000",
    "image": "cases/66ec0adb364a0f4dac122481/
indicator_1727076229898_Image.png",
    "squareMeter": "35.30",
    "id": "298965"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee7e2dbdd9ce4dabcfa1ed",
    "name": "externalImg_1726905809814_1726905805506_image_0.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externalImg_1726905809814_1726905805506_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee7e2dbdd9ce4dabcfa1ee",
    "name": "externalImg_1726905812156_1726905805506_image_1.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externalImg_1726905812156_1726905805506_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee7e2dbdd9ce4dabcfa1ef",
    "name": "externalImg_1726905820119_1726905805506_image_2.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externalImg_1726905820119_1726905805506_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee7e2dbdd9ce4dabcfa1f0",
    "name": "externalImg_1726905826743_1726905805506_image_3.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externalImg_1726905826743_1726905805506_image_3.jpeg",
    "orientation": "portrait"
  },
  }
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee7e2dbdd9ce4dabcfa1f1",
  "name": "externallmg_1726905840809_1726905805506_image_4.jpeg",
  "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726905840809_1726905805506_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee7e2dbdd9ce4dabcfa1f2",
  "name": "externallmg_1726905875378_1726905805506_image_5.jpeg",
  "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726905875378_1726905805506_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee7e2dbdd9ce4dabcfa1f3",
  "name": "externallmg_1726905883578_1726905805506_image_6.jpeg",
  "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726905883578_1726905805506_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66eeae5eada7094de494ad48",
  "name": "externallmg_1726918172793_1726918166675_image_0.jpeg",
  "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918172793_1726918166675_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66eeae5eada7094de494ad49",
  "name": "externallmg_1726918182085_1726918166675_image_1.jpeg",
  "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918182085_1726918166675_image_1.jpeg",
  "orientation": "portrait"
},
{
```

```
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66eeae5eada7094de494ad4a",
"name": "externallmg_1726918189330_1726918166675_image_2.jpeg",
"path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918189330_1726918166675_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66eeae5eada7094de494ad4b",
"name": "externallmg_1726918194170_1726918166675_image_3.jpeg",
"path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918194170_1726918166675_image_3.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66eeae5eada7094de494ad4c",
"name": "externallmg_1726918197941_1726918166675_image_4.jpeg",
"path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918197941_1726918166675_image_4.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66eeae5eada7094de494ad4d",
"name": "externallmg_1726918201261_1726918166675_image_5.jpeg",
"path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918201261_1726918166675_image_5.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66eeae5eada7094de494ad4e",
"name": "externallmg_1726918205928_1726918166675_image_6.jpeg",
"path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918205928_1726918166675_image_6.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "66eeae5eada7094de494ad4f",
    "name": "externallmg_1726918209964_1726918166675_image_7.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918209964_1726918166675_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66eeae5eada7094de494ad50",
    "name": "externallmg_1726918213555_1726918166675_image_8.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918213555_1726918166675_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66eeae5eada7094de494ad51",
    "name": "externallmg_1726918215769_1726918166675_image_9.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918215769_1726918166675_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66eeae5eada7094de494ad52",
    "name": "externallmg_1726918217201_1726918166675_image_10.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918217201_1726918166675_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66eeae5eada7094de494ad53",
    "name": "externallmg_1726918220159_1726918166675_image_11.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918220159_1726918166675_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "66eeae5eada7094de494ad54",
    "name": "externallmg_1726918221956_1726918166675_image_12.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918221956_1726918166675_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66eeae5eada7094de494ad55",
    "name": "externallmg_1726918223833_1726918166675_image_13.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918223833_1726918166675_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66eeae5eada7094de494ad56",
    "name": "externallmg_1726918231161_1726918166675_image_14.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918231161_1726918166675_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66eeae5eada7094de494ad57",
    "name": "externallmg_1726918233235_1726918166675_image_15.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918233235_1726918166675_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66eeae5eada7094de494ad58",
    "name": "externallmg_1726918235419_1726918166675_image_16.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externallmg_1726918235419_1726918166675_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66eeae5eada7094de494ad59",
```

```
    "name": "externalImg_1726918237728_1726918166675_image_17.jpeg",
    "path": "cases/66ec0adb364a0f4dac122481/
externalImg_1726918237728_1726918166675_image_17.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalName": "Calculation Sheet NEW.xlsx",
    "filename": "1727092719840_Calculation_Sheet_NEW.xlsx",
    "path": "cases/66ec0adb364a0f4dac122481/
processingDocuments/1727092719840_Calculation_Sheet_NEW.xlsx",
    "size": "1561330",
    "createdAt": "Mon Sep 23 2024 17:28:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66ed50bebdd9ce4dabcf02a4",
    "note": "Value calculated",
    "taskId": "66ec0f77ada7094de49298c4",
    "createdAt": "2024-09-20T10:38:54.743Z"
  },
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    }
  }
]
```

```
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66f0faf7bdd9ce4dabd01f2f",
    "note": "Value given for confirmation ",
    "taskId": "66ec0f77ada7094de49298c4",
    "createdAt": "2024-09-23T05:21:59.877Z"
  },
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66f157a78b982ccac78ed8ff",
    "note": "Revised (Task Reopen)",
    "taskId": "66ec0f77ada7094de49298c4",
    "createdAt": "2024-09-23T11:57:27.700Z"
  }
],
"createdAt": "2024-09-19T11:28:27.943Z",
"updatedAt": "2024-09-24T05:00:48.088Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Industrial Unit No. 11, Ground Floor, Neha Industrial Premises Co-Op.
Soc. Ltd., Neha Industrial Estate, New/Current Survey No. 134, H-1(Part), H-2(Part),
CTS No. 68C, Opp. Tata Steel Company , Off. Dattapada Road, Village - Magathane,
Borivali (East), Taluka - Borivali , PIN - 400 066, State - Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "667112d324f3ba1343e5ac5c",
"contactPersonName": "Mr. Gheverchand Mistry ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": ""
```

```
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9820426974",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Article of Agreement",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 358.00",
"flatRate": "17000",
"landOtherRate": "14500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": true,
  "mall": false
},
"siteVisitDate": "2024-09-21",
"builtupPercentage": "10",
"carpetTotal": "682.26",
"extendOfSiteRemark": "",
"finalBuiltupArea": "750.49",
"finalCarpetArea": "682.26",
"finalSalableArea": "825.53",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 341.00\nMezzanine Floor in Sq.
Ft. = 341.00\n\n",
"toBeAdded": "",
"briefDescOfProperty": "Working Area + Mezzanine Floor",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
```

```

    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Mon Sep 23 2024 15:54:42 GMT+0530 (India Standard
Time)"
}

```

Name	Length	Width	Total
Composition :			
Working Area	13'1"	26'1"	341.26
Mezzanine Floor	341'00"	1'00"	341.00
Other Composition :			