

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b910"
    },
    "firstName": "Radha",
    "type": "CREDITOFFICER",
    "_id": "66c4391f0f117327db727593",
    "email": "bo4093@pnb.co.in",
    "lastName": "Chavan",
    "mobileNo": "",
    "workMobileNo": "9323971341"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Radha",
    "expectedFees": null,
    "quotedAmount": "3500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b910",
  "branchCode": "000026",
  "type": "BRANCH",
  "name": "Ghatkopar (East) Branch",
  "email": "bo4093@pnb.co.in",
  "mobileNo": "25012060 ",
  "alternateMobileNo": "25012335",
  "address": "Siddhi Apart., Tilak Road, Ghatkopar (East), Mumbai - 400 077, State -
Maharashtra, Country - India. \r\n",
  "ledgerName": "",
  "fax": "25011351",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "ACCOUNTANT",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
```

```
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
```

```
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.053549496213915",
  "longitude": "72.87708507584648"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87708507584648,
    19.053549496213915
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-20",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-20",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kurla (3)",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Mumbai Suburban ",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sarita Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Narayan Nagar ",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "V.N. Purav Marg, Chunabhatti",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "292, Hissa No. 1(Part)",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "405",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "205",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 022",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kurla",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  }
},
```

```
"flooring": {
  "value": "Internal_renovation_work_under_progress",
  "label": "Internal renovation work under progress"
},
"doors": {
  "value": "Internal_renovation_work_under_progress",
  "label": "Internal renovation work under progress"
},
"windows": {
  "value": "Internal_renovation_work_under_progress",
  "label": "Internal renovation work under progress"
},
"fittings": {
  "value": "Internal_renovation_work_under_progress",
  "label": "Internal renovation work under progress"
},
"finishing": {
  "value": "Internal_renovation_work_under_progress",
  "label": "Internal renovation work under progress"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "V.N. Purav Marg",
    "west": "Internal Road ",
    "south": "Internal Road ",
```

```
"east": "Bhaktidham Mandir Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space ",
    "east": "Marginal Space ",
    "south": "Flat No. 206",
    "west": "Lift & Passage "
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "N.A.",
"extraDetailOfBuilding": "",
"compoundWall": ""
```

```
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "At the time site visit, internal renovation work was in progress.",
  "depreciationPercentage": "67.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "20975",
  "depreciatedBuildingRate": "975"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "125170",
  "landRate": "49960",
  "igrImage": "cases/66ec1978bdd9ce4dabce56f2/igr_1726833220855_Image.png",
  "squareMeterGuideLineRate": "125170.00",
  "squareFeetGuideLineRate": "11629.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "55",
  "rate": "8484.00",
  "squareFeetGuideLineRate": "8484.00",
  "squareMeterGuideLineRate": "91326.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available "
```

```
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per MCGM norms ",
"tenantName": "",
"maintenanceOfFlat": "Internal renovation work was in progress "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1979",
    "fullDate": "1/1/1979"
  },
}
```

```
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
```

```
"label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_agreement",
  "label": "As per agreement"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "15",
"ageOfBuilding": "45",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "2",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "350.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Sale Deed"
},
"routeMap": {
  "routeMapDetail": {
```



```
"routeMapImg": "cases/66ec1978bdd9ce4dabce56f2/
routeMap_1726897830199_Image.png",
"routeLat": "19.053083",
"routeLng": "72.877167",
"stationName": "Sion ",
"routeDistance": "2.3 Km. ",
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "ml3n1",
    "name": "ml3n1",
    "image": "cases/66ec1978bdd9ce4dabce56f2/
routeMap_1726897581818_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
```

```
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "7341250.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "00.00",
"finalValue": "7341250.00",
"purchaseValueDocument": {
  "documentType": {
    "value": "60ae1245aa6d152c1801b2e3",
    "label": "Sale Deed"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "567916",
  "path": "cases/66ec1978bdd9ce4dabce56f2/document_1726749020791_1726749018682_PNB_GHatkopar_E_Rashmi_Sampat.pdf",
  "fileName": "document_1726749020791_1726749018682_PNB_GHatkopar_E_Rashmi_Sampat.pdf",
  "documentDate": "22/12/2006",
  "amount": "00.00",
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Shri. Pravin Dharmaji Mokal",
  "to": {
    "value": "Transferee",
    "label": "Transferee"
  }
}
```

```
    },
    "Transferee": "Smt. Rashmi Bakul Sampat & Shri. Bakul Sampat ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "8824 / 2006"
  }
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Sep 21 2024 15:07:38 GMT+0530 (India Standard Time)",
  "number": "2308282",
  "dayCount": "15",
  "monthCount": "288",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "2969400.00",
  "selectedBuildUpValue": "350.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66ed5822bdd9ce4dabcf0d9b",
      "name": "externallmg_1726830625301_1726830604341_image_13.jpeg",
      "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830625301_1726830604341_image_13.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66ed5822bdd9ce4dabcf0d8e",
      "name": "externallmg_1726830621212_1726830604341_image_0.jpeg",
      "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830621212_1726830604341_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66ed5822bdd9ce4dabcf0d90",
      "name": "externallmg_1726830621809_1726830604341_image_2.jpeg",
      "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830621809_1726830604341_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66ed5822bdd9ce4dabcf0d91",
      "name": "externallmg_1726830622169_1726830604341_image_3.jpeg",
      "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830622169_1726830604341_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d92",
  "name": "externallmg_1726830622383_1726830604341_image_4.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830622383_1726830604341_image_4.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d95",
  "name": "externallmg_1726830623075_1726830604341_image_7.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830623075_1726830604341_image_7.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d98",
  "name": "externallmg_1726830624093_1726830604341_image_10.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830624093_1726830604341_image_10.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66ed5837ada7094de493998d",
  "name": "externallmg_1726830647293_1726830640311_image_0.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830647293_1726830640311_image_0.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d9b",
  "name": "externallmg_1726830625301_1726830604341_image_13.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830625301_1726830604341_image_13.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d96",
  "name": "externallmg_1726830623442_1726830604341_image_8.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830623442_1726830604341_image_8.jpeg",
```

```
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "22475.00",
    "max": "30770.00"
  },
  "builtUpRateRange": {
    "min": "20432.00",
    "max": "25642.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
}
```

```
"isEditable": true
},
{others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
  "label": "Lead",
  "value": "LEAD"
},
siteVisitType": "PARTIAL",
isExternalReport": false,
isSiteMeasurementAllowed": true,
finalValuationArea": "350.00",
empanelmentNo": [
  "REF:ZO: SAMD:1138"
],
isAdvanceInvoice": false,
```

```
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66ec1978bdd9ce4dabce56f2",
"ownerName": "Smt. Rashmi Bakul Sampat & Shri. Bakul Chhabildas Samapat ",
"ownerPhoneNo": "9833558373",
"appAddress": "Flat no. 205, 2nd Floor, Sarita CHS, Narayan Nagar, Chunabhatti,
Kurla ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    },
    "inputs": {
      "documentDate": "22/12/2006",
      "amount": "00.00",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Shri. Pravin Dharmaji Mokal",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Smt. Rashmi Bakul Sampat & Shri. Bakul Sampat ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "8824 / 2006"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "567916",
    "path": "cases/66ec1978bdd9ce4dabce56f2/document_1726749020791_172674901
8682_PNB_GHatkopar_E_Rashmi_Sampat.pdf",
    "fileName": "document_1726749020791_1726749018682_PNB_GHatkopar_E_Ras
hmi_Sampat.pdf"
  }
],
"caseNumber": "011312",
```

```
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "627552",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 19 2024 18:00:48 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Smt. Rashmi Bakul Sampat & Shri. Bakul Chhabildas Samapat ",
    "phone": "9833558373",
    "ownershipShare": "",
    "email": "",
    "id": "520817"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "3",
    "name": "Living Room",
    "length": "9.92",
    "length1": "9",
    "length2": "11",
    "width": "12.42",
    "width1": "12",
    "width2": "5",
    "totalArea": "123.13",
    "images": [],
    "finalArea": "123.13",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
```

```
"length": "140.00",
"length1": "140",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "140.00",
"images": [],
"extraAreas": [],
"finalArea": "140.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "19.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.44"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "525935",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "350",
    "squareMeterArea": "32.52",
```

```
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltupPercentage": "",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "401.00",
"squareMeterArea": "37.25",
"expectedRate": "23690.77",
"percentage": ""
},
"builtUpArea": {
"area": "441.10",
"squareMeterArea": "40.98",
"expectedRate": "21537.07",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66ed6252ada7094de493b216",
"property": "Residential Flat",
"area": "401",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "9500000",
"expectedRate": "23690.77",
"builtUpExpectedRate": "21537.07",
"image": "cases/66ec1978bdd9ce4dabce56f2/
indicator_1726833094447_Image.png",
"squareMeter": "37.25",
"id": "310224"
```

```
},
{
  "carpetArea": {
    "area": "485.00",
    "squareMeterArea": "45.06",
    "expectedRate": "22474.23",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "533.50",
    "squareMeterArea": "49.56",
    "expectedRate": "20431.12",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66ed6252ada7094de493b217",
  "property": "Residential Flat",
  "area": "485",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "10900000",
  "expectedRate": "22474.23",
  "builtUpExpectedRate": "20431.12",
  "image": "cases/66ec1978bdd9ce4dabce56f2/
indicator_1726833122822_Image.png",
  "squareMeter": "45.06",
  "id": "803867"
},
{
  "carpetArea": {
    "area": "325.00",
    "squareMeterArea": "30.19",
    "expectedRate": "30769.23",
    "percentage": ""
  },
  "builtUpArea": {
```

```
"area": "390.00",
"squareMeterArea": "36.23",
"expectedRate": "25641.03",
"percentage": "20"
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "66ed6252ada7094de493b218",
"property": "Residential Flat",
"area": "390",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "10000000",
"expectedRate": "30769.23",
"builtUpExpectedRate": "10000000",
"image": "cases/66ec1978bdd9ce4dabce56f2/
indicator_1726833143778_Image.png",
"squareMeter": "36.23",
"id": "605298"
},
{
  "carpetArea": {
    "area": "450.00",
    "squareMeterArea": "41.81",
    "expectedRate": "30000.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "540.00",
    "squareMeterArea": "50.17",
    "expectedRate": "25000.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
```



```
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66ed6252ada7094de493b219",
  "property": "Residential Flat",
  "area": "450",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "13500000",
  "expectedRate": "30000.00",
  "builtUpExpectedRate": "25000.00",
  "image": "cases/66ec1978bdd9ce4dabce56f2/
indicator_1726833159635_Image.png",
  "squareMeter": "41.81",
  "id": "452913"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed5822bdd9ce4dabcf0d8e",
    "name": "externallmg_1726830621212_1726830604341_image_0.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830621212_1726830604341_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed5822bdd9ce4dabcf0d8f",
    "name": "externallmg_1726830621604_1726830604341_image_1.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830621604_1726830604341_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed5822bdd9ce4dabcf0d90",
    "name": "externallmg_1726830621809_1726830604341_image_2.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830621809_1726830604341_image_2.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d91",
  "name": "externallmg_1726830622169_1726830604341_image_3.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830622169_1726830604341_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d92",
  "name": "externallmg_1726830622383_1726830604341_image_4.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830622383_1726830604341_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d93",
  "name": "externallmg_1726830622563_1726830604341_image_5.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830622563_1726830604341_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d94",
  "name": "externallmg_1726830622716_1726830604341_image_6.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830622716_1726830604341_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d95",
  "name": "externallmg_1726830623075_1726830604341_image_7.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830623075_1726830604341_image_7.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed5822bdd9ce4dabcf0d96",
    "name": "externallmg_1726830623442_1726830604341_image_8.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830623442_1726830604341_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed5822bdd9ce4dabcf0d97",
    "name": "externallmg_1726830623766_1726830604341_image_9.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830623766_1726830604341_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed5822bdd9ce4dabcf0d98",
    "name": "externallmg_1726830624093_1726830604341_image_10.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830624093_1726830604341_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed5822bdd9ce4dabcf0d99",
    "name": "externallmg_1726830624324_1726830604341_image_11.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830624324_1726830604341_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed5822bdd9ce4dabcf0d9a",
    "name": "externallmg_1726830624858_1726830604341_image_12.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830624858_1726830604341_image_12.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed5822bdd9ce4dabcf0d9b",
  "name": "externallmg_1726830625301_1726830604341_image_13.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830625301_1726830604341_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed5837ada7094de493998d",
  "name": "externallmg_1726830647293_1726830640311_image_0.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830647293_1726830640311_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66ed5868364a0f4dac12f890",
  "name": "externallmg_1726830693401_1726830689909_image_0.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830693401_1726830689909_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66ed5868364a0f4dac12f891",
  "name": "externallmg_1726830694841_1726830689909_image_1.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830694841_1726830689909_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66ed5868364a0f4dac12f892",
  "name": "externallmg_1726830695339_1726830689909_image_2.jpeg",
  "path": "cases/66ec1978bdd9ce4dabce56f2/
externallmg_1726830695339_1726830689909_image_2.jpeg",
  "orientation": "portrait"
}
],
```

```
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1726833255236_AGR.pdf",
    "path": "cases/66ec1978bdd9ce4dabce56f2/
processingDocuments/1726833255236_AGR.pdf",
    "size": "8826436",
    "createdAt": "Fri Sep 20 2024 17:24:15 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1726830693401_1726830689909_image_0.jpeg",
    "filename":
"1726833255336_externallmg_1726830693401_1726830689909_image_0.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/processingDocuments/1726833255336
_externallmg_1726830693401_1726830689909_image_0.jpeg",
    "size": "950383",
    "createdAt": "Fri Sep 20 2024 17:24:15 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1726830694841_1726830689909_image_1.jpeg",
    "filename":
"1726833255340_externallmg_1726830694841_1726830689909_image_1.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/processingDocuments/1726833255340
_externallmg_1726830694841_1726830689909_image_1.jpeg",
    "size": "315486",
    "createdAt": "Fri Sep 20 2024 17:24:15 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1726830695339_1726830689909_image_2.jpeg",
    "filename":
"1726833255342_externallmg_1726830695339_1726830689909_image_2.jpeg",
    "path": "cases/66ec1978bdd9ce4dabce56f2/processingDocuments/1726833255342
_externallmg_1726830695339_1726830689909_image_2.jpeg",
    "size": "544006",
    "createdAt": "Fri Sep 20 2024 17:24:15 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-01.pdf",
    "filename": "1726833255348_IGR01.pdf",
    "path": "cases/66ec1978bdd9ce4dabce56f2/
processingDocuments/1726833255348_IGR01.pdf",
```

```
"size": "155404",
"createdAt": "Fri Sep 20 2024 17:24:15 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "IGR-02.pdf",
"filename": "1726833255349_IGR02.pdf",
"path": "cases/66ec1978bdd9ce4dabce56f2/
processingDocuments/1726833255349_IGR02.pdf",
"size": "147130",
"createdAt": "Fri Sep 20 2024 17:24:15 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "IGR-03.pdf",
"filename": "1726833255350_IGR03.pdf",
"path": "cases/66ec1978bdd9ce4dabce56f2/
processingDocuments/1726833255350_IGR03.pdf",
"size": "151493",
"createdAt": "Fri Sep 20 2024 17:24:15 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "REF REPORT.pdf",
"filename": "1726833255351_REF_REPORT.pdf",
"path": "cases/66ec1978bdd9ce4dabce56f2/
processingDocuments/1726833255351_REF_REPORT.pdf",
"size": "1828421",
"createdAt": "Fri Sep 20 2024 17:24:15 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=RASHMI.xlsx",
"filename": "1726833255369_Summary_NewRASHMI.xlsx",
"path": "cases/66ec1978bdd9ce4dabce56f2/
processingDocuments/1726833255369_Summary_NewRASHMI.xlsx",
"size": "1504776",
"createdAt": "Fri Sep 20 2024 17:24:15 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-19T12:30:48.854Z",
"updatedAt": "2024-09-21T09:43:51.301Z",
```

```
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 205, 2nd Floor, Sarita Co-Op. Hsg. Soc. Ltd. ,
Narayan Nagar , V.N. Purav Marg, Chunabhatti, Village - Kurla (3), Kurla, Taluka -
Kurla , District - Mumbai Suburban , PIN - 400 022, State - Maharashtra, Country -
India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Smt. Rashmi Bakul Sampat",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"siteVisitContactNo": "9833558373",
"buildingServicesRate": "3000",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Sale Deed",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 350.00",
"flatRate": "23000",
"landOtherRate": "20000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "282.57",
"extendOfSiteRemark": "",
"finalBuiltupArea": "310.83",
"finalCarpetArea": "282.57",
"finalSalableArea": "341.91",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
```

```

"siteMeasurementRemark": "",
"toBeAdded": "",
"briefDescOfProperty": "Living Room + Kitchen + Toilet",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Sep 21 2024 10:36:00 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-09-20"
}

```

| Name | Length | Width | Total |
|------------------------|---------------|--------------|--------------|
| Composition : | | | |
| Living Room | 9'11" | 12'5" | 123.13 |
| Kitchen | 140'00" | 1'00" | 140.00 |
| Toilet | 4'8" | 4'2" | 19.44 |
| Other Composition : | | | |