

Vastukala Consultants (I) Pvt. Ltd.

Valuation Report of the Immovable Property



Details of the property under consideration:

Name of Owner: Mrs. Manisha D. Jhaveri and Mr. Dharmesh M. Jhaveri

Residential Bungalow No. 11, Rainbow Manor Co-operative Housing Society Ltd., Survey. No. 47, Hissa No.2, Village – Tungarli, Lonavala, Taluka – Maval, District – Pune, Pin Code – 410 405, State - Maharashtra, Country - India

Longitude Latitude: 18°46'42.6"N 73°24'09.6"E

Intended User:

State Bank of India

Nariman Point Branch

Dalmal House, Jamanalal Bajaj Marg, Nariman Point, Mumbai – 400 021, State - Maharashtra, Country - India



Our Pan India Presence at:

NandedMumbai

Aurangabad
Pune

♥ Thane♥ Nashik

🖓 Ahmedabad 💡 Delhi NCR

♥ Anmedabaa ♥ Rajkot


Raipur

Jaipur

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai**: 400072, (M.S), India







Vastukala Consultants (I) Pvt. Ltd.

Page 2 of 30 Vastu/Mumbai/09/2024/11322/2308382 26/21-388-PY Date: 26.09.2024

VALUATION OPINION REPORT

This is to certify that the property bearing Residential Bungalow No. 11, Rainbow Manor Co-operative Housing Society Ltd., Survey. No. 47, Hissa No.2, Village - Tungarli, Lonavala, Taluka - Maval, District - Pune, Pin Code - 410 405, State - Maharashtra, Country - India belongs to Mrs. Manisha D. Jhaveri and Mr. Dharmesh M. Jhaveri.

Boundaries of the property:

North Internal Road

South Garden and Internal Road

East Bungalow No. 12 West Bungalow No. 10

Considering various parameters recorded, existing economic scenario, and the information that is available with reference to the development of neighborhood and method selected for valuation, we are of the opinion that, the property premises can be assessed and Fair Market Value for this particular purpose at ₹ 3,50,89,675.00 (Rupees Three Crore Fifty Lakh Eighty Nine Thousand Six Hundred Seventy Five Only).

The valuation of the property is based on the documents produced by the concerned. Legal aspects have not been taken into consideration while preparing this valuation report.

Hence certified.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Manoj B. Chalikwar

Registered Valuer Chartered Engineer (India)

Reg. No. IBBI / RV / 07/2018/10366

Reg. No. CAT-I-F-1763

SBI Empanelment No.: SME/TCC/38/IBBI/3

Encl: Valuation report.



Our Pan India Presence at:

Nanded Mumbai

💡 Aurangabad 🛛 🦞 Pune

Thane Nashik Ahmedabad Opelhi NCR

Rajkot

💡 Raipur

Jaipur

Read. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S), India

+91 2247495919

mumbai@vastukala.co.in www.vastukala.co.in

Vastukala Consultants (I) Pvt. Ltd.

B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai, Andheri (East), Mumbai – 400 072

To,
The Branch Manager,
State Bank of India
Nariman Point Branch
Dalmal House, Jamanalal Bajaj Marg,
Nariman Point, Mumbai – 400 021.
State - Maharashtra, Country – India

VALUATION REPORT (IN RESPECT OF BUNGALOW)

		• • •	LOI LOT OF BONGALOW)
<u> </u>	General		
1.	Purpose for which the valuation is made	:	To assess Fair Market Value of the property for Banking Purpose.
2.	a) Date of inspection	:	23.09.2024
	b) Date on which the valuation is Made	:	26.09.2024
3.	List of documents produced for perusal	:	
	 Copy of Registered Sale Agreement No. 51 Copy of Occupation Certificate No. ENG/ Municipal Corporation. Copy of Share Certificate issued by Rainbor 	BP/	70/2006-07/1761 dated 30.10.2010 issued by Lonavala
4.	Name of the owner(s) and his / their address (es) with Phone no. (details of share of each owner in case of joint ownership)		Mrs. Manisha D. Jhaveri and Mr. Dharmesh M. Jhaveri Residential Bungalow No. 11, Rainbow Manor Cooperative Housing Society Ltd., Survey. No. 47, Hissa No.2, Village – Tungarli, Lonavala, Taluka – Maval, District – Pune, Pin Code – 410 405, State – Maharashtra, Country - India Contact Person: Mr. Dharmesh M. Jhaveri Mobile No. 9820094762 Mr. Ajay (Society Supervisor) Mobile No.: 9579483891
5.	Brief description of the property (Including Leasehold / freehold etc.)		Ownership - Joint Ownership The property is a Residential Bungalow. Structure: - It is RCC framed structure of Ground + 1st Upper Floor. Composition: - Ground Floor: - Living Room + Dinning Area + Kitchen + Bedroom + Toilet + Passage + Verandah. First Floor: - 3 Bedrooms + Dressing Room + 3 Toilets + Lobby + Balcony + Terrace. The property is at 3.7 KM. distance from nearest railway station Lonavala.
6.	Location of property	:	- Same y Caston Bonardia
J.	a) Plot No. / Survey No.	:	Survey No. 47, Hissa No. 2
L	a) 1 101 110. / Odi 10 y 110.		- Carroy 110. 11, 11100a 110. 2



Valuers & Appraisers
Valuers & Valuers & Appraisers
Valuers & Valuers &

Valuation Report Prepared For: SBI / Nariman point Branch / Mrs. Manisha D. Jhaveri (11322/2308382) Page 4 of 30

valuation		ort Prepared For: SBI / Nariman point Branch / N	∕Irs.		08382) Page 4 of 30
	b)	Door No.	:	Bungalow No. 11	
	c)	C.T.S. No. / Village	:	Village – Tungarli, Lonava	la
	d)	Ward / Taluka	:	Taluka – Maval	
	e)	Mandal / District	:	District – Pune	
	f)	Date of issue and validity of layout of	Ė		tificate No. ENG/BP/70/2006-
	'/	approved map / plan	•		2010 issued by Lonavala
	g)	Approved map / plan issuing authority		Municipal Corporation.	
	h)	Whether genuineness or authenticity of	Ė	Yes	
	'''	approved map/ plan is verified	•	100	
	i)	Any other comments by our empanelled		N.A.	
	''	valuers on authentic of approved plan	•	14.71.	
7.	Pos	stal address of the property	:	Residential Bungalow N	o. 11, Rainbow Manor Co-
		and property	-		y Ltd., Survey. No. 47, Hissa
			-		Lonavala, Taluka – Maval,
					Code - 410 405, State -
				Maharashtra, Country - In	
8.	City	/ Town		Village – Tungarli, Lonava	
<u> </u>		sidential area	:	Yes	
	+	nmercial area	:	No	
		ustrial area		No	
	IIIu	ustrial area		INO	
9.	Cla	ssification of the area	1		
<u> </u>	_	igh / Middle / Poor	Ė	Middle Class	
		Irban / Semi Urban / Rural	:/	Semi Urban	
10.		ming under Corporation limit / Village	/	Lonavala Municipal Corpo	ration
10.		nchayat / Municipality	(Lonavaia ividinoipai Corpo	ration
11.		ether covered under any State / Central	: No		711
		t. enactments (e.g., Urban Land Ceiling			
		or notified under agency area/ scheduled	7		
	,	a / cantonment area	٧.		
12.		indaries of the property	1	As per Documents	As per Site
12.	Nor		/ -	R S No. 46	Internal Road
	Sou			R S No. 49	Garden and Internal Road
	Eas			R S No. 135	Bungalow No. 12
	We			R S No. 46	Bungalow No. 12
13		nensions of the site	•		
13	זווט	iensions of the site			onsideration is a bungalow
	NI-	46		A As per the Deed	B Actuals
	Nor		<u> </u>		-
	Sou		:		-
	Eas		÷		-
	We		:	-	-
14.	Exte	ent of the site	:	Carpet Area	
				Ground Floor	_
				Carpet Area = 881.00 Sq.	Ft.
				Verandah = 89.00 Sq. Ft.	
			First Floor		
				Carpet Area = 872.00 Sq.	Ft.
				Balcony Area = 56.00 Sq.	
				Terrace Area = 236.00 Sq	
				(Area as per Site Measure	
				Carpet Area = 2,383.00 S	
				(Area as per Sale Agree	ment)





14.1 Latitude, Longitude & Co-ordinates of Bungalow 2 Event of the site considered for Valuation (least of 13A& 13B) Carpet Area = 2,383.00 Sq. Ft. (Area as per Sale Agreement)	/aluatior	n Report Prepared For: SBI / Nariman point Branch / N	/lrs.	Manisha D. Jhaveri (11322/2308382) Page 5 of 30
Bungalow Carpet Area = 2,383.00 Sq. Ft. ((Area as per Sale Agreement)				
Extent of the site considered for Valuation (least of 13A& 13B) Carpet Area = 2,383.09 Sq. Ft. (Area as per Sale Agreement)		I — — — — — — — — — — — — — — — — — — —		
(least of 13A& 13B)	15.		:	Carpet Area = 2,383.00 Sq. Ft.
Whether occupied by the owner / tenant? If occupied by tenant since how long? Rent received per month.		(least of 13A& 13B)		l •
received per month. 1 Nature of the Apartment : Residential : C.T.S. No. : Survey No. 47 Block No. : Survey No. 47 Block No. : Hissa No. 2 Village / Municipality / Corporation : Village / Municipality / Corporation : Village - Tungarli, Lonavala, Lonavala Municipal Corporation : Village - Tungarli, Lonavala, Lonavala Municipal Corporation : Residential Bungalow No. 11, Rainbow Manor Co-operative Housing Society Ltd., Survey, No. 47, Hissa No. 2, Village - Tungarli, Lonavala, Taluka - Maval, District - Pune, Pin Code - 410 405, State - Maharashtra, Country - India : Residential Commercial / Mixed : Residential Commercial Mixed : Residential Mixed : Residential Mixed : Residential Residential Mixed : Residential Residential Residential Residential	16	Whether occupied by the owner / tenant? If	:	
II APARTMENT BUILDING				•
II APARTMENT BUILDING				
2. Location C.T.S. No. C.T.S. No. Block No. Ward No. Village / Municipality / Corporation Corporation Door No., Street or Road (Pin Code) Corporation Residential Bungalow No. 11, Rainbow Manor Cooperative Housing Society Ltd., Survey. No. 47, Hissa No.2, Village – Tungarli, Lonavala, Taluka – Maval, District – Pune, Pin Code – 410 405, State – Maharashtra, Country - India 3. Description of the locality Residential / Commercial / Mixed 4. Year of Construction S. Number of Floors Number of Floors Number of Floors Number of Dwelling units in the building N.A. Quality of Construction Quality of Construction Maintenance of the Building Lift Protected Water Supply Underground Sewerage Car parking - Open / Covered Septic Tank Door No. of the Bungalow Bungalow No. 11 The floor in which the bungalow is situated Door No. of the Bungalow Roof Roof Roof Roof Roof Roof Roof Plooring Doors Filtings Connected aluminum sliding windows Fittings Connected aluminum sliding windows Fittings Connected aluminum sliding windows Fittings Connected aluminum sliding windows Connected aluminum sliding windows Fittings Connected aluminum sliding windows Information not available Tax amount: Information not available	II			
C.T.S. No. Block No. Ward No. Village / Municipality / Corporation Door No., Street or Road (Pin Code) Residential Bungalow No. 11, Rainbow Manor Cooperative Housing Society Ltd., Survey. No. 47, Hissa No.2, Village – Tungarli, Lonavala, Taluka – Maval, District – Pune, Pin Code – 410 405, State – Maharashtra, Country - India Door No., Street or Road (Pin Code) Residential Bungalow No. 11, Rainbow Manor Cooperative Housing Society Ltd., Survey. No. 47, Hissa No.2, Village – Tungarli, Lonavala, Taluka – Maval, District – Pune, Pin Code – 410 405, State – Maharashtra, Country - India Door No. (Street of Pune, Pin Code – 410 405, State – Maharashtra, Country - India Residential	1.	Nature of the Apartment	:	Residential
Block No. Ward No. Ward No. Village / Municipality / Corporation Door No., Street or Road (Pin Code) Door No., Street or Road (Pin Code) Besidential Bungalow No. 11, Rainbow Manor Cooperative Housing Society Ltd., Survey. No. 47, Hissa No. 2, Village — Tungarli, Lonavala, Taluka — Maval, District — Pune, Pin Code — 410 405, State — Maharashtra, Country - India Bescription of the locality Residential / Commercial / Mixed Year of Construction Number of Construction Residential Bungalow No. 11, Rainbow Manor Cooperative Housing Society Ltd., Survey. No. 47, Hissa No. 2, Village — Tungarli, Lonavala, Taluka — Maval, District — Pune, Pin Code — 410 405, State — Maharashtra, Country - India Residential Residential Bungarlow + 1st Upper Floor R.C.C. Framed Structure R.C.C. Framed St	2.	Location	:	
Ward No. Village / Municipality / Corporation Village / Municipality / Corporation Village - Tungarli, Lonavala, Lonavala Municipal Corporation Co		C.T.S. No.	:	Survey No. 47
Village / Municipality / Corporation Door No., Street or Road (Pin Code) Residential Bungalow No. 11, Rainbow Manor Cooperative Housing Society Ltd., Survey. No. 47, Hissa No.2, Village – Tungarli, Lonavala, Taluka – Maval, District – Pune, Pin Code – 410 405, State – Maharashtra, Country - India Description of the locality Residential / Commercial / Mixed Year of Construction Number of Floors Number of Floors Number of Dwelling units in the building No. C.C. Framed Structure Number of Dwelling units in the building No. Quality of Construction Appearance of the Building Maintenance of the Building Maintenance of the Building No. Minitepal Water supply Underground Sewerage Septic Tank Car parking - Open / Covered Septic Tank Car powent laid around the building Wes In Pacifications of the Bungalow The floor in which the bungalow is situated Door No. of the Bungalow Recoff Flooring Doors Residential Bungalow No. 11, Rainbow Manor Cooperative Housing Sciety Ltd., Survey. No. 47, Hissa No.2, Village — Tungarli, Lonavala, Edward, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, No.2, V		Block No.	:	-
Village / Municipality / Corporation Door No., Street or Road (Pin Code) Residential Bungalow No. 11, Rainbow Manor Cooperative Housing Society Ltd., Survey. No. 47, Hissa No.2, Village – Tungarli, Lonavala, Taluka – Maval, District – Pune, Pin Code – 410 405, State – Maharashtra, Country - India Description of the locality Residential / Commercial / Mixed Year of Construction Number of Floors Number of Floors Number of Dwelling units in the building No. C.C. Framed Structure Number of Dwelling units in the building No. Quality of Construction Appearance of the Building Maintenance of the Building Maintenance of the Building No. Minitepal Water supply Underground Sewerage Septic Tank Car parking - Open / Covered Septic Tank Car powent laid around the building Wes In Pacifications of the Bungalow The floor in which the bungalow is situated Door No. of the Bungalow Recoff Flooring Doors Residential Bungalow No. 11, Rainbow Manor Cooperative Housing Sciety Ltd., Survey. No. 47, Hissa No.2, Village — Tungarli, Lonavala, Edward, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, Hissa No.2, Village — Tungarli, Lonavala, Paval, Daview, No. 14, No.2, V		Ward No.	:	Hissa No. 2
Door No., Street or Road (Pin Code) Door No., Street or Road (Pin Code) Residential Bungalow No. 11, Rainbow Manor Coperative Housing Society Ltd., Survey, No. 47, Hissa No.2, Village – Tungarli, Lonavala, Taluka – Maval, District – Pune, Pin Code – 410 405, State – Maharashtra, Country - India Description of the locality Residential / Residential / Commercial / Mixed 4. Year of Construction : 2010 (As per Occupation Certificate) Number of Floors : Ground Floor + 19 Upper Floor Number of Floors : Ground Floor + 19 Upper Floor Number of Dwelling units in the building : N.A. Quality of Construction : Good Quality of Construction : Good Maintenance of the Building : Good Maintenance of the Building : Good Maintenance of the Building : No lift Protected Water Supply : Municipal Water supply Underground Sewerage : Septic Tank Car parking - Open / Covered : Open Car Parking Is Compound wall existing? : Yes Is pavement laid around the building : Yes Is pavement laid around the building : N.A. Door No. of the Bungalow : Bungalow No. 11 Rocf : Residential Bungalow Doors Teak Wood door frame with flush doors Powder coated aluminum sliding windows Concealed Powder coated aluminum sliding windows Information not available Information not available				
Door No., Street or Road (Pin Code) Residential Bungalow No. 11, Rainbow Manor Cooperative Housing Society Ltd., Survey, No. 47, Hissa No.2, Village – Tungarii, Lonavala, Taluka – Maval, District – Pune, Pin Code – 410 405, State – Maharashtra, Country - India		Vinago / Mariioipanty / Gorporation		
operative Housing Society Ltd., Survey. No. 47, Hissa No.2, Village — Tungarli, Lonavala, Taluka — Maval, District — Pune, Pin Code — 410 405, State — Maharashtra, Country - India 3. Description of the locality Residential / Commercial / Mixed 4. Year of Construction : 2010 (As per Occupation Certificate) 5. Number of Floors : Ground Floor + 1st Upper Floor 6. Type of Structure : R.C.C. Framed Structure 7. Number of Dwelling units in the building : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : Lift : No lift Protected Water Supply : Municipal Water supply Underground Sewerage : Septic Tank Car parking - Open / Covered : Open Car Parking Septic Tank Car parking - Open / Covered : Yes Is pavement laid around the building : Yes Is pavement laid around the building : Yes Is pavement laid around the building : Pes In BUNGALOW : N.A. Door No. of the Bungalow : Bungalow No. 11 Specifications of the Bungalow : Bungalow No. 11 Specifications of the Bungalow : Powder coated aluminum sliding windows Flooring : Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing : Cement Plastering + POP finish 4 House Tax Assessment No. : Information not available Tax paid in the name of: : Information not available		Door No. Street or Road (Pin Code)		
No.2, Village — Tungarli, Lonavala, Taluka — Maval, District — Pune, Pin Code — 410 405, State — Maharashtra, Country - India		255. 1.5., 555. 5. 1.000 (1	•	
District - Pune, Pin Code - 410 405, State - Maharashtra, Country - India				
Maharashtra, Country - India 3. Description of the locality Residential / : Residential 4. Year of Construction : 2010 (As per Occupation Certificate) 5. Number of Floors : Ground Floor + 1st Upper Floor 6. Type of Structure : R.C.C. Framed Structure 7. Number of Dwelling units in the building : N.A. 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : No lift Protected Water Supply : Municipal Water supply Underground Sewerage : Septic Tank Car parking - Open / Covered : Open Car Parking Is Compound wall existing? : Yes Is pavement laid around the building : Yes III BUNGALOW 1 The floor in which the bungalow is situated : N.A. 2 Door No. of the Bungalow : Bungalow No. 11 3 Specifications of the Bungalow : Roof : R.C.C. Slab Flooring : Wooden/Verified flooring : Wooden/Verified flooring : Doors : Teak Wood door frame with flush doors Windows : Powder coated aluminum sliding with C.P. fittings. Electrical wiring with concealed. Finishing : Cement Plastering + POP finish 4 House Tax : Information not available : Information not available : Information not available : Information not available				
3. Description of the locality Residential / Commercial / Mixed 4. Year of Construction 5. Number of Floors 6. Type of Structure 7. Number of Dwelling units in the building 8. Quality of Construction 9. Appearance of the Building 10. Maintenance of the Building 11. Facilities Available 12. Lift 13. Protected Water Supply 14. Underground Sewerage 15. Car parking - Open / Covered 16. So Car parking - Open / Covered 17. No lift 18. Protected Water Supply 19. Underground Sewerage 19. Septic Tank 19. Car parking - Open / Covered 19. Septic Tank 19. Septic Tank 19. Septic Tank 20. Door No. of the Bungalow 21. President of the Bungalow 22. Door No. of the Bungalow 23. Specifications of the Bungalow 24. Roof 25. R.C.C. Slab 26. Windows 27. Flooring 28. R.C.C. Slab 29. Wooden/Verified flooring 29. Wooden/Verified flooring 20. Doors 20. Teak Wood door frame with flush doors 20. Windows 21. Flinishing 22. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 29. Finishing 30. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 30. Finishing 31. Finishing 42. Coment Plastering + POP finish 43. Assessment No. 44. House Tax 45. Information not available 46. Information not available 47. Tax amount: 48. Information not available 49. Information not available 40. Information not available 40. Information not available				
Commercial / Mixed 4. Year of Construction 5. Number of Floors 6. Type of Structure 7. Number of Dwelling units in the building 8. Quality of Construction 9. Appearance of the Building 10. Maintenance of the Building 11. Facilities Available 11. Fracilities Available 11. Protected Water Supply 11. Underground Sewerage 12. Car parking - Open / Covered 13. Septic Tank 14. Car parking - Open / Covered 15. Septic Tank 16. Car parking - Open / Covered 17. Specifications of the Bungalow 18. Profected Water Supply 19. Underground wall existing? 19. Septic Tank 19. Septic Tank 19. Septic Tank 20. Door No. of the Bungalow is situated 21. Door No. of the Bungalow 22. Door No. of the Bungalow 23. Roof 24. C.C. Slab 25. Flooring 26. C.C. Slab 26. Flooring 27. Septic Tank 28. Specifications of the Bungalow 29. Specifications of the Bungalow 20. Teak Wood door frame with flush doors 20. Windows 21. Teak Wood door frame with flush doors 22. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 28. Finishing 29. Cement Plastering + POP finish 29. Linformation not available 20. Tax amount: 30. Information not available	3	Description of the locality Residential /		
4. Year of Construction 5. Number of Floors 6. Type of Structure 7. Number of Dwelling units in the building 8. Quality of Construction 9. Appearance of the Building 10. Maintenance of the Building 11. Facilities Available 12. Iff 13. Protected Water Supply 14. Underground Sewerage 15. Septic Tank 16. Car parking - Open / Covered 17. Is goon and the building 18. Supvement laid around the building 19. Sepcifications of the Building 20. Sepcifications of the Building 21. Sepcifications of the Building 22. Door No. of the Bungalow 23. Sepcifications of the Bungalow 24. R.C.C. Slab 25. Flooring 26. R.C.C. Slab 26. Flooring 27. Provided aluminum sliding windows 28. Fittings 29. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 29. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 30. Cement Plastering + POP finish 31. Tax amount: 32. Information not available 33. Information not available 34. House Tax 36. Information not available 36. Information not available 37. Information not available 38. Car parking - Occupant Structure 39. Appearance of the Bungalow 39. Appearance of the Bungalow 40. NA. 40. Supplementation of the Bungalow 40. NA. 41. The floor in which the bungalow is situated 42. Door No. of the Bungalow 43. Specifications of the Bungalow 44. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 45. Concealed plumbing not available 46. Tax amount: 47. Information not available	0.			reducifical
5. Number of Floors 6. Type of Structure 7. Number of Dwelling units in the building 8. Quality of Construction 9. Appearance of the Building 10. Maintenance of the Building 11. Facilities Available 12. Lift 13. Protected Water Supply 14. Underground Sewerage 15. Septic Tank 16. Car parking - Open / Covered 17. Is pavement laid around the building 18. Septic Tank 19. Septic Tank 19. Septic Tank 20. Den Car Parking 20. Septic Tank 21. Septic Tank 22. Door No. of the Bungalow 23. Specifications of the Bungalow 24. Roof 25. R.C.C. Slab 26. Flooring 27. Teak Wood door frame with flush doors 28. Windows 29. Fittings 20. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 29. Finishing 20. Cement Plastering + POP finish 20. Information not available 20. Tax amount: 20. Information not available 21. Information not available 22. Information not available 23. Information not available 34. Assessment No. 35. Information not available 36. Information not available 36. Information not available 37. Information not available 38. R.C.C. Slab 39. Roof 40. Information not available 40. Information not available 41. Information not available 42. Information not available 43. Information not available 44. Information not available 45. Information not available 46. Information not available 47. Information not available 48. R.C.C. Farmed Structure 49. R.C.C. Slab 40. R.C.C. Slab 40. R.C.C. Slab 40. R.C.C. Slab 41. Information not available 41. Information not available 41. Information not available 42. Information not available	4			2010 (As per Occupation Certificate)
6. Type of Structure 7. Number of Dwelling units in the building 8. Quality of Construction 9. Appearance of the Building 10. Maintenance of the Building 11. Facilities Available 12. Lift 13. Protected Water Supply 14. Underground Sewerage 15. Septic Tank 16. Car parking - Open / Covered 16. Sompound wall existing? 17. It a floor in which the building 18. BUNGALOW 19. BUNGALOW 10. The floor in which the bungalow is situated 20. Door No. of the Bungalow 31. Specifications of the Bungalow 42. Plooring 43. Specifications 54. C.C. Slab 55. Windows 56. Teak Wood door frame with flush doors 67. Windows 67. Filtings 68. C.C. Framed Structure 79. Good 79. A.A. 70. Septic Tank 70. Supply 71. The floor in which the bungalow is situated 71. The floor in which the bungalow is situated 72. Door No. of the Bungalow 73. Specifications of the Bungalow 74. R.C.C. Slab 75. Flooring 75. Doors 76. Teak Wood door frame with flush doors 76. Windows 76. Fittings 76. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 76. Cement Plastering + POP finish 77. Information not available 78. Tax amount: 78. Information not available			- /	
7. Number of Dwelling units in the building 8. Quality of Construction 9. Appearance of the Building 10. Maintenance of the Building 11. Facilities Available 12. Lift 13. Protected Water Supply 14. Underground Sewerage 15. Septic Tank 16. Car parking - Open / Covered 17. Is Compound wall existing? 18. Is pavement laid around the building 19. Is pavement laid around the building 10. The floor in which the bungalow is situated 20. Door No. of the Bungalow 21. Bungalow No. 11 22. Door No. of the Bungalow 23. Specifications of the Bungalow 24. Roof 25. Flooring 26. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 26. Finishing 27. Vian description of available 28. Tax amount: 28. Information not available 29. Information not available 39. Information not available 39. Information not available 39. Information not available			1	
8. Quality of Construction 9. Appearance of the Building 10. Maintenance of the Building 11. Facilities Available 12. Lift 13. Protected Water Supply 14. Underground Sewerage 15. Septic Tank 16. Car parking - Open / Covered 17. Is Compound wall existing? 18. Is pavement laid around the building 19. Is pavement laid around the building 10. The floor in which the bungalow is situated 10. Door No. of the Bungalow 11. Roof 12. Door No. of the Bungalow 13. Specifications of the Bungalow 14. Roof 15. Flooring 16. C.C. Slab 17. Flooring 18. Wooden/Verified flooring 19. Doors 10. Teak Wood door frame with flush doors 19. Windows 10. Fittings 10. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 19. Comealed plumbing with C.P. fittings. Electrical wiring with concealed. 19. Comealed plumbing with C.P. fittings. Electrical wiring with concealed. 10. Tax paid in the name of: 10. Information not available 10. Information not available 10. Information not available 10. Information not available			÷	
9. Appearance of the Building 10. Maintenance of the Building 11. Facilities Available 11. Facilities Available 12. Lift 13. Protected Water Supply 14. Underground Sewerage 15. Septic Tank 16. Car parking - Open / Covered 17. Compound wall existing? 18. Compound wall existing? 19. Is pavement laid around the building 10. The floor in which the bungalow is situated 20. Door No. of the Bungalow 21. Roof 22. Roof 33. Specifications of the Bungalow 34. Roof 45. Flooring 46. Doors 47. Teak Wood door frame with flush doors 48. Fittings 49. Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 40. Finishing 41. Finishing 41. Finishing 42. Cement Plastering + POP finish 43. Fix a mount: 44. House Tax 45. Information not available 46. Tax amount: 47. Information not available 48. Information not available 49. Information not available				
10. Maintenance of the Building				
11. Facilities Available Lift Lift Protected Water Supply Underground Sewerage Septic Tank Car parking - Open / Covered Is Compound wall existing? Is pavement laid around the building The floor in which the bungalow is situated Door No. of the Bungalow Roof Flooring Flooring Doors Windows Fittings Fittings Fittings Fittings Finishing Assessment No. Lift Information not available			7	
Lift : No lift Protected Water Supply : Municipal Water supply Underground Sewerage : Septic Tank Car parking - Open / Covered : Open Car Parking Is Compound wall existing? : Yes Is pavement laid around the building : Yes III BUNGALOW : N.A. Door No. of the Bungalow : Bungalow No. 11 Specifications of the Bungalow : R.C.C. Slab Flooring : Wooden/Verified flooring Doors : Teak Wood door frame with flush doors Windows : Powder coated aluminum sliding windows Fittings : Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing : Cement Plastering + POP finish House Tax Assessment No. : Information not available Tax paid in the name of: : Information not available Tax amount: : Information not available	——	<u> </u>	Ψ.	Good
Protected Water Supply Underground Sewerage Septic Tank Car parking - Open / Covered Is Compound wall existing? Is pavement laid around the building The floor in which the bungalow is situated Door No. of the Bungalow Roof Flooring Doors Windows Fittings Fittings Fittings Finishing Finishing Flooring Assessment No. Flooring Flooring Flooring Flooring Finishing Flooring	11.			No lift
Underground Sewerage : Septic Tank Car parking - Open / Covered : Open Car Parking Is Compound wall existing? : Yes Is pavement laid around the building : Yes III BUNGALOW : N.A. Door No. of the Bungalow : Bungalow No. 11 Specifications of the Bungalow : R.C.C. Slab Flooring : Wooden/Verified flooring Doors : Teak Wood door frame with flush doors Windows : Powder coated aluminum sliding windows Fittings : Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing : Cement Plastering + POP finish House Tax Assessment No. : Information not available Tax amount: : Information not available			•	
Car parking - Open / Covered Is Compound wall existing? Is pavement laid around the building Is Dungalow In the floor in which the bungalow is situated In the floor in which the bungalow is situated In the floor in which the bungalow is situated In the floor in which the bungalow is situated In the floor in which the bungalow is situated In the floor in which the bungalow is situated In the floor in which the bungalow is situated In the floor in which the bungalow is situated In the floor in which the bungalow is situated Information not available				
Is Compound wall existing? Yes				
Is pavement laid around the building : Yes III BUNGALOW : N.A. 1 The floor in which the bungalow is situated : N.A. 2 Door No. of the Bungalow : Bungalow No. 11 3 Specifications of the Bungalow : R.C.C. Slab Flooring : Wooden/Verified flooring Doors : Teak Wood door frame with flush doors Windows : Powder coated aluminum sliding windows Fittings : Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing : Cement Plastering + POP finish 4 House Tax : Assessment No. : Information not available Tax amount: : Information not available				
III BUNGALOW 1 The floor in which the bungalow is situated : N.A. 2 Door No. of the Bungalow : Bungalow No. 11 3 Specifications of the Bungalow : Roof : R.C.C. Slab Flooring : Wooden/Verified flooring Doors : Teak Wood door frame with flush doors Windows : Powder coated aluminum sliding windows Fittings : Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing : Cement Plastering + POP finish 4 House Tax Assessment No. : Information not available Tax paid in the name of: : Information not available Tax amount: : Information not available				
1 The floor in which the bungalow is situated 2 Door No. of the Bungalow 3 Bungalow No. 11 3 Specifications of the Bungalow 5 Roof 5 R.C.C. Slab 6 Flooring 6 Wooden/Verified flooring 7 Teak Wood door frame with flush doors 8 Windows 7 Powder coated aluminum sliding windows 9 Fittings 7 Concealed plumbing with C.P. fittings. Electrical wiring with concealed. 9 Finishing 7 Cement Plastering + POP finish 9 Flooring 9 Cement Plastering + POP finish 10 Cement Plastering + POP finish 11 Cement Plastering + POP finish 12 Cement Plastering + POP finish 13 Cement Plastering + POP finish 14 House Tax 15 Information not available 16 Tax amount: 17 Information not available 18 Information not available 19 Informati			Ŀ	res
2 Door No. of the Bungalow : Bungalow No. 11 3 Specifications of the Bungalow : R.C.C. Slab Flooring : Wooden/Verified flooring Doors : Teak Wood door frame with flush doors Windows : Powder coated aluminum sliding windows Fittings : Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing : Cement Plastering + POP finish 4 House Tax : Assessment No. : Information not available Tax amount: : Information not available				N A
Specifications of the Bungalow : R.C.C. Slab			:	
Roof : R.C.C. Slab Flooring : Wooden/Verified flooring Doors : Teak Wood door frame with flush doors Windows : Powder coated aluminum sliding windows Fittings : Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing : Cement Plastering + POP finish House Tax : Assessment No. : Information not available Tax paid in the name of: : Information not available Tax amount: : Information not available				Bungalow No. 11
Flooring Doors : Teak Wood door frame with flush doors Windows : Powder coated aluminum sliding windows Fittings : Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing : Cement Plastering + POP finish House Tax Assessment No. Information not available Tax paid in the name of: Information not available Tax amount: Information not available	3			D 0 0 0 1
Doors Windows Powder coated aluminum sliding windows Fittings Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing Finishing Cement Plastering + POP finish House Tax Assessment No. Information not available Tax paid in the name of: Information not available Tax amount: Information not available				
Windows Fittings Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing Finishing Cement Plastering + POP finish House Tax Assessment No. Information not available Tax paid in the name of: Information not available Tax amount: Information not available		<u> </u>		
Fittings : Concealed plumbing with C.P. fittings. Electrical wiring with concealed. Finishing : Cement Plastering + POP finish House Tax : Assessment No. : Information not available Tax paid in the name of: : Information not available Tax amount: : Information not available	<u> </u>			
with concealed. Finishing : Cement Plastering + POP finish House Tax : Assessment No. : Information not available Tax paid in the name of: : Information not available Tax amount: : Information not available				
4 House Tax : Assessment No. : Information not available Tax paid in the name of: : Information not available Tax amount: : Information not available		Fittings	<u> </u> :	, , , , , , , , , , , , , , , , , , , ,
4 House Tax : Assessment No. : Information not available Tax paid in the name of: : Information not available Tax amount: : Information not available		Finishing	:	Cement Plastering + POP finish
Tax paid in the name of: : Information not available Tax amount: : Information not available	4		<u>:</u>	
Tax amount: : Information not available		Assessment No.	:	Information not available
Tax amount: : Information not available		Tax paid in the name of:	:	Information not available
			_	Information not available
	5	Electricity Service connection No.:		Information not available









V <u>aluatior</u>	Report Prepared For: SBI / Nariman point Branch / N	/Irs.	
	Meter Card is in the name of:	:	Information not available
6	How is the maintenance of the Bungalow?	:	Good
7	Sale Deed executed in the name of	:	Mrs. Manisha D. Jhaveri and Mr. Dharmesh M. Jhaveri
8	What is the undivided area of land as per Sale Deed?	:	Details not available
9	What is the plinth area of the Bungalow?	:	Built Up Area = 2,860.00 Sq. Ft. (Carpet Area as per agreement + 20%)
10	What is the floor space index (app.)	:	Details not provided
11	What is the Carpet Area of the Bungalow?		Carpet Area Ground Floor Carpet Area = 881.00 Sq. Ft. Verandah = 89.00 Sq. Ft. First Floor Carpet Area = 872.00 Sq. Ft. Balcony Area = 56.00 Sq. Ft. Terrace Area = 236.00 Sq. Ft. (Area as per Site Measurement) Carpet Area = 2,383.00 Sq. Ft.
10	Lo it Dook / L Close / Medium / Ordinary?	_	(Area as per Sale Agreement)
12	Is it Posh / I Class / Medium / Ordinary? Is it being used for Residential or Commercial purpose?	:	Middle Class Residential purpose
14	Is it Owner-occupied or let out?	-/	Vacant and under Owner possession
15	If rented, what is the monthly rent?	<u> </u>	₹ 73,000.00 expected rental income from the property per month
IV	MARKETABILITY	•)	
1	How is the marketability?	7	Good
2	What are the factors favouring for an extra Potential Value?	Y. /	Located in developed area
3	Any negative factors are observed which affect the market value in general?		No
٧	Rate		
1	After analyzing the comparable sale instances, what is the composite rate for a similar Bungalow with same specifications in the adjoining locality? - (Along with details / reference of at - least two latest deals / transactions with respect to adjacent properties in the areas)	:	₹ 14,000 to ₹ 16,000.00 per Sq. Ft. on Carpet area
2	Assuming it is a new construction, what is the adopted basic composite rate of the Bungalow under valuation after comparing with the specifications and other factors with the Bungalow under comparison (give details).	:	₹ 15,250.00 per Sq. Ft. on Carpet Area ₹ 14,725.00 per Sq. Ft. (After Depreciation)
3	Break – up for the rate	:	
	I. Building + Services	:	₹ 2,500.00 per Sq. Ft.
	II. Land + others	:	₹ 12,750.00 per Sq. Ft.
4	Guideline rate obtained from the Registrar's office (evidence thereof to be enclosed)	:	₹ 49,950.00 per Sq. M. i.e., ₹ 4,640.00 per Sq. Ft.
	Depreciated Guideline rate obtained from the	:	₹ 44,263.00 per Sq. M. i.e.,







Valuation Report Prepared For: SBI / Nariman point Branch / Mrs. Manisha D. Jhaveri (11322/2308382) Page 7 of 30

	Registrar's office (evidence thereof to be enclosed)		₹ 4,112.00 per Sq. Ft.	
	In case of variation of 20% or more in the valuation proposed by the valuer and the Guideline value provided in the State Govt. notification or Income Tax Gazette justification on variation has to be given.		It is a foregone conclusion that market value is always more than RR prices. As the RR rates are fixed by respective state governments for computing stamp duty / regn. Fees. Thus, the rates differ from place to place and location. Amenities per se as evident from the fact that even RR rates decided by Govt. differ.	
VI	COMPOSITE RATE ADOPTED AFTER DEPR	EC	ATION	
а	Depreciated building rate	:	-	
	Replacement cost of Bungalow with Services (v (3)I)	:	₹ 2,500.00 per Sq. Ft.	
	Age of the building	• •	14 Years	
	Life of the building estimated		49 years Subject to proper, preventive periodic maintenance & structural repairs	
	Depreciation percentage assuming the salvage value as 10%	:	21.00%	
	Depreciated Ratio of the building	:		
b	Total composite rate arrived for Valuation	:		
	Depreciated building rate VI (a)	:	₹ 1,975.00 per Sq. Ft.	
	Rate for Land & other V (3) ii	:	₹ 12,750.00 per Sq. Ft.	
	Total Composite Rate	:	₹ 14,725.00 per Sq. Ft. on Carpet area	

Details of Valuation:

Sr. No.	Description	Carpet Area in Sq. ft.	Rate per unit (₹)	Estimated Value (₹)
1	Present value of the Bungalow	2,383.00	14,725.00	3,50,89,675.00
2	Wardrobes			
3	Showcases	Y		F3/
4	Kitchen arrangements			4//
5	Superfine finish			. 1//
6	Interior Decorations	A		7
7	Electricity deposits / electrical fittings, etc.			/
8	Extra collapsible gates / grill works etc.			
9	Potential value, if any			
10	Others			
	Total			3,50,89,675.00
	Fair Market Value of the property			3,50,89,675.00
	The realizable value of the property	3,15,80,708.00		
	Distress value of the property	2,80,71,740.00		
	Insurable value of the property (2,383.00		85,78,800.00	
	Guideline value of the property (2,383.00	X 1.2 X 4,112.00)		1,17,58,675.00





Justification for price / rate

The Market Value of the property is based on facts of markets discovered by us during our enquiries, however the government rate value in this case is less than the market value arrived by us. We are of the opinion that the value arrive by us will prove to be correct if an Auction of the subject property is carried out. As far as Market Value in Index II is concerned, it is not possible to comment on same, may be government rates are fixed by sampling during same point of time in part and whereas, Market values change every month.

In most of the cases the actual deal amount or Transaction value is not reflected in Index II because of various Market practices. As Valuer, we always try to give a value which is correct reflection of actual transaction value irrespective of any factors in market.

Method of Valuation / Approach

The sales comparison approach uses the market data of sale prices to estimate the value of a real estate property. Property valuation in this method is done by comparing a property to other similar properties that have been recently sold. Comparable properties, also known as comparable, or comps, must share certain features with the property in question. Some of these include physical features such as square footage, number of rooms, condition, and age of the building; however, the most important factor is no doubt the location of the property.

Adjustments are usually needed to account for differences as no two properties are the same. To make proper adjustments when comparing properties, real estate appraisers must know the differences between the comparable properties and how to value these differences. The sales comparison approach is commonly used for Residential Bungalow, where there are typically many comparables available to analyze. As the property is a Residential Bungalow, we have adopted Sales Comparison Approach Method for the purpose of valuation.

The Price for similar type of property in the nearby vicinity is in the range of ₹ 14,500.00 to ₹ 16,500.00 per Sq. Ft. on Carpet area. Considering the rate with attached report, current market conditions, demand and supply position, Bungalow size, location, upswing in real estate prices, sustained demand for Residential Bungalow, all round development of commercial and residential application in the locality etc.,

We estimate ₹ 14,725.00 per Sq. Ft. on Carpet Area for valuation.

Impend	ing threat of acquisition by government for road	N. A. as property under consideration is a residential
widening / publics service purposes, sub merging &		bungalow.
applicability of CRZ provisions (Distance from sea-cost /		
tidal lev	el must be incorporated) and their effect on	
i)	Saleability	Good
ii)	Likely rental values in future in	₹ 73,000.00 Expected rental income from the
,		property per month
iii)	Any likely income it may generate	Rental Income






An ISO 9001: 2015 Certified Company

Actual Site Photographs























Actual Site Photographs






















Actual Site Photographs


















Route Map of the property





Longitude Latitude: 18°46'42.6"N 73°24'09.6"E

Note: The Blue line shows the route to site from nearest railway station (Lonavala 3.7 KM.)





Ready Reckoner Rate

Department of R Government	- Date	ा मुद्राक हाराष्ट्र शास		सत्यमेव जपत		
Annual Statement of Rates Ver. 2.0 (बाजारमूल्य दर पत्रक आवृत्ती 2.0)						
<u>Home</u>		<u>Valu</u>	ation Guide	elines User I	<u>Manual</u>	
Year 2024-2025		Lan	guage E	nalish		
Selected District	Pune					
Select Taluka	Maval					
Select Village	Mauje : Tungarli					
Search By	Survey No. SubZ	Zones				
Enter Survey No	47	Search				
उपविभाग	खुली निवासी जमीन सदनिका	ऑफ़ीस दुकाने औद्योगि	एकक (Rs./)	Attribute		
17 - तुंगार्ली - नगर रचना योजना 10 आर विभाग विभाग)	(सी सेक्टर 13800 50470 १	58070 63830 0	चौ. मीटर	अंतीम प्लॉट नंबर		
20 - तुंगार्ली - गावठाण (सी सेक्टर भाग	46010 50400 0	चौ. मीटर	सि.टी.एस. नंबर			
Stamp Duty Ready Reckoner Market Va	39,960.00		_1 1/			
25% Increase for Bungalow	9,990.00	0. 14	4.040.00	0 5		
Stamp Duty Ready Reckoner Market Va Stamp Duty Ready Reckoner Market Va	49,950.00 9,330.00	Sq. Mtr.	4,640.00	Sq. Ft.		
The difference between land rate and but	40,620.00					
Depreciation Percentage as per table (D	14%					

Row House/ Pent House / Duplex / Bungalow / Flat under Group Housing Project or Row House / Bungalow / Commercial / Industrial use building on independent plot.

While valuing Row House or Pent House or Duplex or Bungalow in Municipal Corporation of Rest of Maharashtra, in Group Housing Project having area more then 120 Sq. M. then it should be valued at 125% of value mentioned for that zone for residential purpose.

44,263

Sq. Mtr.

Table - D: Depreciation Percentage Table

Completed Age of Building in Years	Value in percent after depreciation			
	R.C.C. Structure / other Pukka Structure	Cessed Building, Half or Semi – Pukka Structure & Kaccha Structure.		
0 to 2 Years	100%	100%		
Above 2 & up to 5 Years	95%	95%		
Above 5 Years	After initial 5 year for every year 1% depreciation is to be considered. However maximum deduction available as per this shall be 70% of Market Value rate	After initial 5 year for every year 1.5% depreciation is to be considered. However maximum deduction available as per this shall be 85% of Market Value rate		



Since 1989

Rate to be adopted after considering depreciation [B + (C x D)]





4,112.00 Sq. Ft.

Registered Sale Instances

Built Up Area in Sq. M.	329.69
Built Up Area in Sq. Ft.	3,548.78
Carpet Area in Sq. Ft.	2,957.32
Purchase Price in ₹	5,00,00,000.00
Rate / Sq. Ft. on Carpet Area in ₹	16,907.20
Rate / Sq. Ft. on Built-up Area in ₹	14,089.34

4372427	सूची क्र.2	दुय्यम निबंधक : सह दु.नि. लोणावळा
28-07-2024	-	दस्त क्रमांक : 4372/2024
Note:-Generated Through eSearch Module,For original report please		नोदंणी :
contact concern SRO office.		Regn:63m
	गावाचे नाव : लोणावळा	
(1)विलेखाचा प्रकार	असाईनमेंट डीड	
(2)मोबदला	50000000	
(3) बाजारभाव(भाडेपटटयाच्या बाबतितपटटाकार आकारणी देतो की पटटेदार ते नमुद करावे)	25670814	
(4) भू-मापन,पोटहिस्सा व घरक्रमांक(असल्यास)	1) पालिकेचे नाव:पुणेइतर वर्णन :, इतर जि पुणे येथील सि एस नं.167/1 ते 167/2 अशोक निर्वाण मधील स्वतंत्र व्हीला नं.2 चौ मी सोबत जमिन क्षेत्र 440.58 चौ मी प वापरण्याकरीता(एक्सक्लुझीव्ह राईट टुः Number : १६७/१ ते १६७/२३ सर्व्हे नं-१४ Number : 02;))	.3,सर्वे नं.147,149,154/2 व 155 वरील (व्हीला नं. सी2/2)बांधकाम क्षेत्र 329.69 कक्त तुमच्या युज)गार्डन व स्वीमींग पुल सह((C.T.S.
(5) क्षेत्रफळ	329.69 चौ.मीटर	
(6)आकारणी किंवा जुडी देण्यात असेल तेव्हा.		
(७) दस्तऐवज करुन देणा-या/लिहून ठेवणा-या पक्षकाराचे नाव किंवा दिवाणी न्यायालयाचा हुकुमनामा किंवा आदेश असल्यास,प्रतिवादिचे नाव व पत्ता.	1): नाव:-निलिमा हरीश सलोट वय:-67 पत्ता: नं: -, रोड नं: रा. 3 वखारिया हाऊस, एन.एस. रोड महाराष्ट्र, मुम्बई. पिन कोड:-400049 पॅन नं:-AB	र नं. ९, जे.वी.पी.डी, विलेपार्ले पश्चिम , मुंबई,
(8)दस्तऐवज करून घेणा-या पक्षकाराचे व किंवा दिवाणी न्यायालयाचा हुकुमनामा किंवा आदेश असल्यास,प्रतिवादिचे नाव व पत्ता	-, रोड नं: रा. 3, वखारिया हाऊस, एन.एस. रोड न मुम्बई. पिन कोड:-400049 पॅन नं:-AVEPS088	813 .प्लॉट नं: -, माळा नं: -, इमारतीचे नाव: -, ब्लॉक नं: रोड नं. ९ हवेली मंदिर मागे विलेपार्ले वेस्ट मुंबई ,
(9) दस्तऐवज करुन दिल्याचा दिनांक	11/07/2024	
(10)दस्त नोंदणी केल्याचा दिनांक	16/07/2024	
(11)अनुक्रमांक,खंड व पृष्ठ	4372/2024	
(12)बाजारभावाप्रमाणे मुद्रांक शुल्क	3000000	
(13)बाजारभावाप्रमाणे नोंदणी शुल्क	30000	
(14)शेरा		
मुल्यांकनासाठी विचारात घेतलेला तपशील:-:		





Registered Sale Instances


Built Up Area in Sq. Ft.	4,079.52
Carpet Area in Sq. Ft.	3,399.60
Purchase Price in ₹	5,00,00,000.00
Rate / Sq. Ft. on Carpet Area in ₹	14,707.61
Rate / Sq. Ft. on Built-up Area in ₹	12,256.34

5400427	सूची क्र.2	दुय्यम निबंधक : सह दु.नि. लोणावळा
05-09-2024	**	दस्त क्रमांक : 5400/2024
Note:-Generated Through eSearch Module,For original report please		नोदंणी :
contact concern SRO office.		Regn:63m
	गावाचे नाव: खंडाळा	
(1)विलेखाचा प्रकार	सेल डीड	
(2)मोबदला	50000000	
(3) बाजारभाव(भाडेपटटयाच्या बाबतितपटटाकार आकारणी देतो की पटटेदार ते नमुद करावे)	32933817	
(4) भू-मापन,पोटहिस्सा व घरक्रमांक(असल्यास) इद्दीतील गाव मौजे खंडाळा तालुका मावळ जिल्हा पुणे येथीत यावरील रस्टिक हायलॅंड सेक्टर 3 मधील प्लॉट/प्लिंथ नं 9 ए यार्ड म्हणजेच 855.35 चौ मीटर व त्यावरील बंगला ज्याचा न क्र डब्लूकेएचऽआर012819 यांसी बांधकाम क्षेत्र 4079.52 चै चौ मीटर((Survey Number: 123/1B/1 Plot No 9;))		ळ जिल्हा पुणे येथील सर्व्हें नं 123/1बी/1 त प्लॉट/प्लिंथ नं 9 ए यांसी क्षेत्र 1023 चौ रील बंगला ज्याचा नगरपालिका मिळकत ठाम क्षेत्र 4079.52 चौ फुट म्हणजेच 379
(5) क्षेत्रफळ	855.35 चौ.मीटर	
(6)आकारणी किंवा जुडी देण्यात असेल तेव्हा.		
(७) दस्तऐवज करुन देणा-या/लिहून ठेवणा-या पक्षकाराचे नाव किंवा दिवाणी न्यायालयाचा हुकुमनामा किंवा आदेश असल्यास,प्रतिवादिचे नाव व पत्ता.	1): नाव:-राजीव मधुकर नार्वेकर वय:-64 पत्ता:-प -, रोड नं: 507 कंबाला क्रेस्ट 42 डॉ जी देशमुख रे कोड:-400026 पॅन नं:-AAXPN2488C	लॉंट नं: -, माळा नं: -, इमारतीचे नाव: -, ब्लॉक नं: ोड मुंबई, महाराष्ट्र, मुम्बई. पिन
(8)दस्तऐवज करून घेणा-या पक्षकाराचे व किंवा दिवाणी न्यायालयाचा हुकुमनामा किंवा आदेश असल्यास,प्रतिवादिचे नाव व पत्ता 1): नाव:-रूपा मोहनदास मजेठिया वय:-53; पत्ता:-प्लॉट नं: -, मांव नं: -, रोड नं: शत्रुंजय बिल्डींग पलॅट 5 तिसरा मजला झेनिथ रोड लिंह खालापूर जिल्हा रायगड, महाराष्ट्र, राईगार्:(ः). पिन कोड:-41020 2): नाव:-संदीप वल्लभदास मजेठिया वय:-41; पत्ता:-प्लॉट नं: -, मांब्लॉक नं: -, रोड नं: माजेठिया वाडा खोपोली बझार पेठ तालुका खार राईग्रार्:(ः). पिन कोड:-410203 पॅन नं:-BCFPM1391G 3): नाव:-निरव दिनेश लखानी वय:-38; पत्ता:-प्लॉट नं: -, मांब्रा नं: रोड नं: ए/6 दुसरा मजला सरस्वत को ऑप सोसायटी डॉ के एन मांग्रंत रोड मुंबई, महाराष्ट्र, मुम्बई. पिन कोड:-400007 पॅन नं:-ABY		ला झेनिथ रोड लक्ष्मि नगर कॉर्नर खोपोली तालुका पिन कोड:-410203 पॅन नं:-AJEPM2480M मता:-प्लॉट नं: -, माळा नं: -, इमारतीचे नाव: -, र पेठ तालुका खालापूर जिल्हा रायगड, महाराष्ट्र, PM1391G ॉट नं: -, माळा नं: -, इमारतीचे नाव: -, ब्लॉक नं: -, यटी डॉ के एन मार्ग गम्देवी पोलीस स्टेशन समोर
(9) दस्तऐवज करुन दिल्याचा दिनांक	30/08/2024	
(10)दस्त नोंदणी केल्याचा दिनांक	30/08/2024	
(11)अनुक्रमांक,खंड व पृष्ठ	5400/2024	
(12)बाजारभावाप्रमाणे मुद्रांक शुल्क	3000000	
(13)बाजारभावाप्रमाणे नोंदणी शुल्क	30000	
(14)शेरा		
मुल्यांकनासाठी विचारात घेतलेला तपशील:-:		_






Carpet Area in Sq. Ft.	Ask Price in ₹	Rate / Sq. Ft. on Carpet Area in ₹
1,700.00	2,40,00,000.00	14,117.65








Carpet Area in Sq. Ft.	Ask Price in ₹	Rate / Sq. Ft. on Carpet Area in ₹
900.00	1,50,00,000.00	16,667.00








Carpet Area in Sq. Ft.	Ask Price in ₹	Rate / Sq. Ft. on Carpet Area in ₹
3,000.00	4,67,00,000.00	15,567.00







Carpet Area in Sq. Ft.	Ask Price in ₹	Rate / Sq. Ft. on Carpet Area in ₹
3,000.00	4,50,00,000.00	15,000.00







Justification for price / rate

The Market Value of the property is based on facts of markets discovered by us during our enquiries, however the government rate value in this case is less than the market value arrived by us. We are of the opinion that the value arrive by us will prove to be correct if an Auction of the subject property is carried out. As far as Market Value in Index II is concerned, it is not possible to comment on same, may be government rates are fixed by sampling during same point of time in part and whereas, Market values change every month.

In most of the cases the actual deal amount or Transaction value is not reflected in Index II because of various Market practices. As Valuer, we always try to give a value which is correct reflection of actual transaction value irrespective of any factors in market.

We hope this will satisfy your requirements.





As a result of my appraisal and analysis, it is my considered opinion that the Fair Market Value for this particulars above property in the prevailing condition with aforesaid specification is ₹ 3,50,89,675.00 (Rupees Three Crore Fifty Lakh Eighty Nine Thousand Six Hundred Seventy Five Only). The Realizable Value of the above property is ₹ 3,15,80,708.00 (Rupees Three Crore Fifteen Lakh Eighty Thousand Seven Hundred Eight Only) and The Distress value of the property is ₹ 2,80,71,740.00 (Rupees Two Crore Eighty Lakh Seventy One Thousand Seven Hundred Forty Only).

Place: Mumbai Date: 26.09.2024

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Manoj B. Chalikwar

Registered Valuer Chartered Engineer (India) Reg. No. IBBI / RV / 07/2018/10366

Reg. No. CAT-I-F-1763

SBI Empanelment No.: SME/TCC/38/IBBI/3

The undersigned has	s inspected the property detailed in the	Valuation Report dated	
on	We are satisfied that the	fair and reasonable market value of the pro	perty is
	only).		
Date		Signature (Name & Designation of the Inspecting C	Official/s)

Countersigned (BRANCH MANAGER)

Ī	Enclosures		
Ī		Declaration-cum-undertaking from the valuer (Annexure- I)	Attached
Ī		Model code of conduct for valuer - (Annexure - II)	Attached



Valuers & Appraisers
Architect & Engineers (i)
Constitution Designation
Constitution Designation
Constitution

An ISO 9001: 2015 Certified Company

DECLARATION-CUM-UNDERTAKING

- I, Manoj Chalikwar son of Shri. Baburao Chalikwar do hereby solemnly affirm and state that:
- a. I am a citizen of India.
- b. I will not undertake valuation of any assets in which I have a direct or indirect interest or become so interested at any time during a period of three years prior to my appointment as valuer or three years after the valuation of assets was conducted by me.
- c. The information furnished in my valuation report dated 26.09.2024 is true and correct to the best of my knowledge and belief and I have made an impartial and true valuation of the property.
- d. I/ my authorized representative have personally inspected the property on 23.09.2024. The work is not sub contracted to any other valuer and carried out by myself.
- e. Valuation report is submitted in the format as prescribed by the bank.
- f. I have not been depanelled / delisted by any other bank and in case any such depanelment by other banks during my empanelment with you, I will inform you within 3 days of such depanelment.
- g. I have not been removed / dismissed from service / employment earlier.
- h. I have not been convicted of any offence and sentenced to a term of imprisonment
- i. I have not been found guilty of misconduct in my professional capacity.
- j. I have not been declared to be unsound mind
- k. I am not an undischarged bankrupt, or has not applied to be adjudicated as a bankrupt;
- I. I am not an undischarged insolvent.
- m. I have not been levied a penalty under section 271J of Income-tax Act, 1961 (43 of 1961) and time limit for filing appeal before Commissioner of Income-tax (Appeals) or Income-tax Appellate Tribunal, as the case may be has expired, or such penalty has been confirmed by Income-tax Appellate Tribunal, and five years have not elapsed after levy of such penalty
- n. I have not been convicted of an offence connected with any proceeding under the Income Tax Act 1961, Wealth Tax Act 1957 or Gift Tax Act 1958 and
- o. My PAN Card number as applicable is AERPC9086P
- p. I undertake to keep you informed of any events or happenings which would make me ineligible for empanelment as a valuer
- q. I have not concealed or suppressed any material information, facts and records and I have made a complete and full disclosure





Valuation Report Prepared For: SBI / Nariman point Branch / Mrs. Manisha D. Jhaveri (11322/2308382) Page 23 of 30

- r. I have read the Handbook on Policy, Standards and procedure for Real Estate Valuation, 2011 of the IBA and this report is in conformity to the "Standards" enshrined for valuation in the Part B of the above handbook to the best of my ability.
- s. I have read the International Valuation Standards (IVS) and the report submitted to the Bank for the respective asset class is in conformity to the "Standards" as enshrined for valuation in the IVS in "General Standards" and "Asset Standards" as applicable. The valuation report is submitted in the prescribed format of the bank.
- t. I abide by the Model Code of Conduct for empanelment of valuer in the Bank. (Annexure V A signed copy of same to be taken and kept along with this declaration)
- u. I am valuer registered with Insolvency & Bankruptcy Board of India (IBBI)
- v. My CIBIL Score and credit worthiness is as per Bank's guidelines.
- w. I am Chairman & Managing Director of the company, who is competent to sign this valuation report.
- x. I will undertake the valuation work on receipt of Letter of Engagement generated from the system (i.e., LLMS / LOS) only.
- y. Further, I hereby provide the following information.





Valuation Report Prepared For: SBI / Nariman point Branch / Mrs. Manisha D. Jhaveri (11322/2308382) Page 24 of 30

aluation	uation Report Prepared For: SBI / Nariman point Branch / Mrs. Manisha D. Jhaveri (11322/2308382) Page 24 of 30			
	Particulars	Valuer comment		
1.	Background information of the asset being valued;	The property under consideration was purchased by Mrs. Manisha D. Jhaveri and Mr. Dharmesh M. Jhaveri from Sadguru Properties vide Agreement for Sale dated 14.12.2011.		
2.	Purpose of valuation and appointing authority	As per the request from State Bank of India, Nariman Point Branch, to assess Fair Market Value of the property for Banking purpose		
3.	Identity of the Valuer and any other experts involved in the valuation;	Manoj B. Chalikwar – Regd. Valuer Umang Ashwin Patel – Regd. Valuer Prayush P. Parekh – Senior Valuation Engineer		
4.	Disclosure of Valuer interest or conflict, if any;	We have no interest, either direct or indirect, in the property valued. Further to state that we do not have relation or any connection with property owner / applicant directly or indirectly. Further to state that we are an independent Valuer and in no way related to property owner / applicant		
5.	Date of appointment, valuation date and date of report;	Date of Appointment – 21.09.2024 Valuation Date – 26.09.2024 Date of Report – 26.09.2024		
6.	Inspections and/or investigations undertaken;	Physical Inspection done on date 23.09.2024		
7.	Nature and sources of the information used or relied upon;	 Market Survey at the time of site visit Ready Reckoner rates / Circle rates Online search for Registered Transactions Online Price Indicators on real estate portals Enquiries with Real estate consultants Existing data of Valuation assignments carried out by us 		
8.	Procedures adopted in carrying out the valuation and valuation standards followed;	Sales Comparative Method		
9.	Restrictions on use of the report, if any;	This valuation is for the use of the party to whom it is addressed and for no other purpose. No responsibility is accepted to any third party who may use or rely on the whole or any part of this valuation. The valuer has no pecuniary interest that would conflict with the proper valuation of the property.		
10.	Major factors that were taken into account during the valuation;	Current market conditions, demand and supply position, residential land size, location, sustained demand for residential land, all round development of commercial and residential application in the locality etc.		
11.	Caveats, limitations and disclaimers to the extent they explain or elucidate the limitations faced by valuer, which shall not be for the purpose of limiting his responsibility for the valuation report.	Attached		





Valuation Report Prepared For: SBI / Nariman point Branch / Mrs. Manisha D. Jhaveri (11322/2308382) Page 25 of 30

Assumptions, Disclaimers, Limitations & Qualifications

Value Subject to Change

The subject appraisal exercise is based on prevailing market dynamics as on **26**th **September 2024** and does not take into account any unforeseeable developments which could impact the same in the future.

Our Investigations

We are not engaged to carry out all possible investigations in relation to the subject property. Where in our report we identify certain limitations to our investigations, this is to enable the reliant party to instruct further investigations where considered appropriate or where we recommend as necessary prior to reliance. Vastukala Consultants India Pvt. Ltd. (VCIPL) is not liable for any loss occasioned by a decision not to conduct further investigations

Assumptions

Assumptions are a necessary part of undertaking valuations. VCIPL adopts assumptions for the purpose of providing valuation advise because some matters are not capable of accurate calculations or fall outside the scope of our expertise, or out instructions. The reliant party accepts that the valuation contains certain specific assumptions and acknowledge and accept the risk of that if any of the assumptions adopted in the valuation are incorrect, then this may have an effect on the valuation.

Information Supplied by Others

The appraisal is based on the information provided by the client. The same has been assumed to be correct and has been used for appraisal exercise. Where it is stated in the report that another party has supplied information to VCIPL, this information is believed to be reliable but VCIPL can accept no responsibility if this should prove not to be so.

Future Matters

To the extent that the valuation includes any statement as to a future matter, that statement is provided as an estimate and/or opinion based on the information known to VCIPL at the date of this document. VCIPL does not warrant that such statements are accurate or correct.

Map and Plans

Any sketch, plan or map in this report is included to assist the reader while visualising the property and assume no responsibility in connection with such matters.

Site Details

Based on inputs received from Sales Executive representative and site visit conducted, we understand that the subject property is Residential Bungalow, admeasuring Carpet Area 2,383 Sq. Ft. in the name of **Mrs. Manisha D. Jhaveri and Mr. Dharmesh M. Jhaveri**. Further, VCIPL has assumed that the subject property is free from any encroachment and is available as on the date of the appraisal.

Property Title

Based on our discussion with the Client, we understand that the subject property is owned by Mrs. Manisha D. Jhaveri and Mr. Dharmesh M. Jhaveri. For the purpose of this appraisal exercise, we have assumed that the subject property has a clear title and is free from any encumbrances, disputes and claims. VCIPL has made no further enquiries with the relevant local authorities in this regard and does not certify the property as having a clear and marketable title. Further, no legal advice regarding the title and ownership of the subject property has been obtained for the purpose of this appraisal exercise. It has been assumed that the title deeds are clear and marketable.

Environmental Conditions

We have assumed that the subject property is not contaminated and is not adversely affected by any existing or proposed environmental law and any processes which are carried out on the property are regulated by environmental legislation and are properly licensed by the appropriate authorities.



Valuers & Appraisers
Valuers & Engineers (i)
Chartered Engineers (i)
Lender's Engineer
Valuers & Engineers (ii)
Valuers & Engineers (iii)
Valuers &

Valuation Report Prepared For: SBI / Nariman point Branch / Mrs. Manisha D. Jhaveri (11322/2308382) Page 26 of 30 **Town Planning**

The permissible land use, zoning, achievable FSI, area statement adopted for purpose of this valuation is based on the documents / information provided by the Client's representative and the same has been adopted for this valuation purpose. VCIPL has assumed the same to be correct and permissible. VCIPL has not validated the same from any authority.

Area

Based on the document provided by the Client's representative, we understand that the Residential Bungalow, admeasuring Carpet Area 2,383 Sq. Ft..

Condition & Repair

In the absence of any information to the contrary, we have assumed that there are no abnormal ground conditions, nor archaeological remains present which might adversely affect the current or future occupation, development or value of the property. The property is free from rat, infestation, structural or latent defect. No currently known deleterious or hazardous materials or suspect techniques will be used in the construction of or subsequent alteration or additions to the property and comments made in the property details do not purport to express an opinion about, or advise upon, the condition of uninspected parts and should not be taken as making an implied representation or statement about such parts

Valuation Methodology

For the purpose of this valuation exercise, the valuation methodology used is Direct Comparison Approach Method and proposed Highest and Best Use model is used for analysing development potential.

The Direct Comparison Approach involves a comparison of the property being valued to similar properties that have actually been sold in arms - length transactions or are offered for sale. This approach demonstrates what buyers have historically been willing to pay (and sellers willing to accept) for similar properties in an open and competitive market and is particularly useful in estimating the value of the land and properties that are typically traded on a unit basis.

In case of inadequate recent transaction activity in the subject micro-market, the appraiser would collate details of older transactions. Subsequently, the appraiser would analyse rental / capital value trends in the subject micro-market in order to calculate the percentage increase / decrease in values since the date of the identified transactions. This percentage would then be adopted to project the current value of the same.

Where reliance has been placed upon external sources of information in applying the valuation methodologies, unless otherwise specifically instructed by Client and/or stated in the valuation, VCIPL has not independently verified that information and VCIPL does not advise nor accept it as reliable. The person or entity to whom the report is addressed acknowledges and accepts the risk that if any of the unverified information in the valuation is incorrect, then this may have an effect on the valuation.

Not a Structural Survey

We state that this is a valuation report and not a structural survey

Other

All measurements, areas and ages quoted in our report are approximate

Legal

We have not made any allowances with respect to any existing or proposed local legislation relating to taxation on realization of the sale value of the subject property. VCIPL is not required to give testimony or to appear in court by reason of this appraisal report, with reference to the property in question, unless arrangement has been made thereof. Further, no legal advice on any aspects has been obtained for the purpose of this appraisal exercise

Property specific assumptions

Based on inputs received from the client and site visit conducted, we understand that the Residential Bungalow, admeasuring Carpet Area 2,383 Sq. Ft..



Valuers & Appraisers

Architects & Service Character (I)

Character Characte

Valuation Report Prepared For: SBI / Nariman point Branch / Mrs. Manisha D. Jhaveri (11322/2308382) Page 27 of 30

ASSUMPTIONS, CAVEATS, LIMITATION AND DISCLAIMERS

- 1. We assume no responsibility for matters of legal nature affecting the property appraised or the title thereto, nor do we render our opinion as to the title, which is assumed to be good and marketable.
- 2. The property is valued as though under responsible ownership.
- 3. It is assumed that the property is free of liens and encumbrances.
- 4. It is assumed that there are no hidden or unapparent conditions of the subsoil or structure that would render it more or less valuable. No responsibility is assumed for such conditions or for engineering that might be required to discover such factors.
- 5. There is no direct/ indirect interest in the property valued.
- 6. The rates for valuation of the property are in accordance with the Govt. approved rates and prevailing market rates.







(Annexure - II)

MODEL CODE OF CONDUCT FOR VALUERS

Integrity and Fairness

- 1. A valuer shall, in the conduct of his/its business, follow high standards of integrity and fairness in all his/its dealings with his/its clients and other valuers.
- 2. A valuer shall maintain integrity by being honest, straightforward, and forthright in all professional relationships.
- 3. A valuer shall endeavour to ensure that he/it provides true and adequate information and shall not misrepresent any facts or situations.
- 4. A valuer shall refrain from being involved in any action that would bring disrepute to the profession.
- 5. A valuer shall keep public interest foremost while delivering his services.

Professional Competence and Due Care

- 6. A valuer shall render at all times high standards of service, exercise due diligence, ensure proper care and exercise independent professional judgment.
- 7. A valuer shall carry out professional services in accordance with the relevant technical and professional standards that may be specified from time to time.
- 8. A valuer shall continuously maintain professional knowledge and skill to provide competent professional service based on up-to-date developments in practice, prevailing regulations / quidelines and techniques.
- 9. In the preparation of a valuation report, the valuer shall not disclaim liability for his/its expertise or deny his/its duty of care, except to the extent that the assumptions are based on statements of fact provided by the company or its auditors or consultants or information available in public domain and not generated by the valuer.
- 10. A valuer shall not carry out any instruction of the client insofar as they are incompatible with the requirements of integrity, objectivity and independence.
- 11. A valuer shall clearly state to his client the services that he would be competent to provide and the services for which he would be relying on other valuers or professionals or for which the client can have a separate arrangement with other valuers.

Independence and Disclosure of Interest

- 12. A valuer shall act with objectivity in his/its professional dealings by ensuring that his/its decisions are made without the presence of any bias, conflict of interest, coercion, or undue influence of any party, whether directly connected to the valuation assignment or not.
- 13. A valuer shall not take up an assignment if he/it or any of his/its relatives or associates is not independent in terms of association to the company.
- 14. A valuer shall maintain complete independence in his/its professional relationships and shall conduct the valuation independent of external influences.
- 15. A valuer shall wherever necessary disclose to the clients, possible sources of conflicts of duties and interests, while providing unbiased services.
- 16. A valuer shall not deal in securities of any subject company after any time when he/it first becomes aware of the possibility of his / its association with the valuation, and in accordance with the Securities and Exchange Board of India (Prohibition of Insider Trading)Regulations,2015 or till the time the valuation report becomes public, whichever is earlier.
- 17. A valuer shall not include in "mandate snatching" or offering "convenience valuations" in order to cater to a company or client's needs.
- 18. As an independent valuer, the valuer shall not charge success fee.





Valuation Report Prepared For: SBI / Nariman point Branch / Mrs. Manisha D. Jhaveri (11322/2308382) Page 29 of 30

19. In any fairness opinion or independent expert opinion submitted by a valuer, if there has been a prior engagement in an unconnected transaction, the valuer shall declare the association with the company during the last five years.

Confidentiality

20. A valuer shall not use or divulge to other clients or any other party any confidential information about the subject company, which has come to his / its knowledge without proper and specific authority or unless there is a legal or professional right or duty to disclose.

Information Management

- 21. A valuer shall ensure that he/ it maintains written contemporaneous records for any decision taken, the reasons for taking the decision, and the information and evidence in support of such decision. This shall be maintained so as to sufficiently enable a reasonable person to take a view on the appropriateness of his /its decisions and actions.
- 22. A valuer shall appear, co-operate and be available for inspections and investigations carried out by the authority, any person authorised by the authority, the registered valuers organisation with which he/it is registered or any other statutory regulatory body.
- 23. A valuer shall provide all information and records as may be required by the authority, the Tribunal, Appellate Tribunal, the registered valuers organisation with which he/it is registered, or any other statutory regulatory body.
- 24. A valuer while respecting the confidentiality of information acquired during the course of performing professional services, shall maintain proper working papers for a period of three years or such longer period as required in its contract for a specific valuation, for production before a regulatory authority or for a peer review. In the event of a pending case before the Tribunal or Appellate Tribunal, the record shall be maintained till the disposal of the case.

Gifts and hospitality:

- 25. A valuer or his / its relative shall not accept gifts or hospitality which undermines or affects his independence as a valuer.
- 26. Explanation: For the purposes of this code the term 'relative' shall have the same meaning as defined in clause (77) of Section 2 of the Companies Act, 2013 (18 of 2013).
- 27. A valuer shall not offer gifts or hospitality or a financial or any other advantage to a public servant or any other person with a view to obtain or retain work for himself / itself, or to obtain or retain an advantage in the conduct of profession for himself / itself.

Remuneration and Costs.

- 28. A valuer shall provide services for remuneration which is charged in a transparent manner, is a reasonable reflection of the work necessarily and properly undertaken, and is not inconsistent with the applicable rules.
- 29. A valuer shall not accept any fees or charges other than those which are disclosed in a written contract with the person to whom he would be rendering service.

Occupation, employability and restrictions.

- 30. A valuer shall refrain from accepting too many assignments, if he/it is unlikely to be able to devote adequate time to each of his/ its assignments.
- 31. A valuer shall not conduct business which in the opinion of the authority or the registered valuer organisation discredits the profession.

Miscellaneous

- 32. A valuer shall refrain from undertaking to review the work of another valuer of the same client except under written orders from the bank or housing finance institutions and with knowledge of the concerned valuer.
- 33. A valuer shall follow this code as amended or revised from time to time.



Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001: 2015 Certified Company

Valuation Report Prepared For: SBI / Nariman point Branch / Mrs. Manisha D. Jhaveri (11322/2308382) Page 30 of 30

DEFINITION OF VALUE FOR THIS SPECIFIC PURPOSE

This exercise is to assess Fair Market Value of the property under reference as on 26th September 2024.

The term Fair Market Value is defined as

"The most probable price, as of a specified date, in cash, terms equivalent to cash, or in other precisely revealed terms for which the specified property rights would sell after reasonable exposure in a competitive market under all conditions requisite to a fair sale, with the buyer and seller each acting prudently knowledgeably and for self-interest assuming that neither is under undue duress".

Fundamental assumptions and conditions presumed in this definition are:

- 1. Buyer and seller are motivated by self-interest.
- 2. Buyer and seller are well informed and are acting prudently.
- 3. The property is exposed for a reasonable time on the open market.
- 4. Payment is made in cash or equivalent or in specified financing terms.

DECLARATION OF PROFESSIONAL FEES CHARGED

We hereby declare that, our professional fees are not contingent upon the valuation findings. However, if the statute AND/OR clients demands that, the fees should be charged on the percentage of assessed value then, with the full knowledge of the AND/OR end user, it is being charged accordingly.

VALUATION OF THE PROPERTY PREMISES

Considering various parameters recorded herein above, existing economic scenario, and the information that is available with reference to the development of neighborhood and method selected for valuation, we are of the opinion that, the property premises can be assessed and Fair Market Value for this particular purpose at ₹ 3,50,89,675.00 (Rupees Three Crore Fifty Lakh Eighty Nine Thousand Six Hundred Seventy Five Only).

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Manoj B. Chalikwar

Registered Valuer Chartered Engineer (India) Reg. No. IBBI / RV / 07/2018/10366

Reg. No. CAT-I-F-1763

SBI Empanelment No.: SME/TCC/38/IBBI/3





An ISO 9001: 2015 Certified Company