

```
{
  "typeOfReport": {
    "label": "Gala",
    "value": "Gala"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b800"
    },
    "firstName": "Krushna ",
    "type": "CREDITOFFICER",
    "_id": "65ba192e6635d840ef56c043",
    "lastName": "Dhanvij",
    "mobileNo": "",
    "workMobileNo": "8600786009",
    "email": "sbi.15521@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Krushna ",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b800",
  "branchCode": "000073",
  "type": "BRANCH",
  "name": "SME Credit Centre Borivali (West)",
  "email": "sbi.15781@sbi.co.in",
  "mobileNo": "022-28954966",
  "alternateMobileNo": "",
  "address": "SME Centre Borivali (15521) 101, 1st floor,
Landmark Building, S. V. Road, Near Petrol Pump, Borivali (West), Mumbai – 400 092,
State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA-SMECCC BORIVALI",
  "fax": "022-28909092",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "667112d324f3ba1343e5ac5c",
  "role": "PICKUPPERSON",
  "firstName": "SAHADEV ",
  "email": "temkarsahdaev@gmail.com",
  "lastName": "TEMKAR",
  "mobileNo": "9869931652",
  "shortName": "SAHADEV",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
  "lastName": "Patil",
  "mobileNo": "8830049996",
  "designation": "Valuation Engineer",
  "shortName": "SSP",
  "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
  "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {

```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.104718768165412",
  "longitude": "72.89614859136331"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.89614859136331,
    19.104718768165412
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-23",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-23",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mohili",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "On Ground & Mezzanine ",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla ",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Crescent Industrial Premises Co-Op. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "A.K. Estate, R.C. Loyalka Street, Kherani Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```



```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "3/1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "14",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 072",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Sakinaka",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Plain_Cement_Concrete_Flooring",
    "label": "Plain Cement Concrete Flooring"
  },
  "doors": {
    "value": "MS_Rolling_Shutter",
    "label": "MS Rolling Shutter"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value": "_Open_Electrical_Wiring",
    "label": " Open Electrical Wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
}
```

```
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Gala No. 15",
  "west": "Internal Road ",
  "south": "Gala No. 13",
  "east": "Entrance "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "-",
    "east": "-",
    "south": "-",
    "west": "-"
  },
  "asPerDocument": {
    "north": "-",
    "east": "-",
    "south": "-",
    "west": "-"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
```

```

    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "The Composition of Ground Floor is Working Area only &
1st Floor is Working Area + Cabin + Store Room + 1 Toilet. ",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "As per site inspection, Actual Total Carpet area is 1358.00 Sq. Ft
(included Ground + Mezzanine Floor Area) is more than Built Up Area 750.00 Sq. Ft.
mentioned in the documents. We have considered area mentioned in the documents for
valuation",
  "depreciationPercentage": "64.8",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "12133.6",
  "depreciatedBuildingRate": "633.5999999999999"
},
"igrRate": {
  "propertyName": "Gala",
  "rate": "132030",
  "landRate": "53370",
  "igrImage": "cases/66ed602fbdd9ce4dabcf1c63/igr_1726836972604_Image.png",
  "squareMeterGuideLineRate": "132030.00",
  "squareFeetGuideLineRate": "12266.00"
},
"igrFinalRate": {

```

```
"floorRatePercentage": "0",
"depreciationPercentage": "48.5",
"rate": "8502.00",
"squareMeterGuideLineRate": "91520.00",
"squareFeetGuideLineRate": "8502.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Industrial",
    "label": "Industrial"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MCGM norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  }
}
```

```
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking Space ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1988",
  "fullDate": "1/1/1988"
},
"planningArea": {
  "value": "Industrial",
  "label": "Industrial"
},
"typeOfStructure": {
  "value": "Load-bearing_structure",
  "label": "Load-bearing structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
```

```
"label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
},
```



```
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "50",
"estimatedAge": "14",
"ageOfBuilding": "36",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "1",
"flatFloorNo": "On Ground & Mezzanine ",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": ""
},
"finalPlinthArea": {
  "area": "750.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Allotment Agreement"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66ed602fbdd9ce4dabcf1c63/
routeMap_1727506996018_Image.png",
    "routeLat": "19.103139",
    "routeLng": "72.895611",
    "stationName": "Saki Naka ",
    "routeDistance": "1.4 Km. ",
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
}
```

```
"locationMapImg": [
  {
    "id": "540I5o",
    "name": "540I5o",
    "image": "cases/66ed602fbdd9ce4dabcf1c63/
routeMap_1727506913738_Image.png"
  }
],
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "9100500.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
```

```
"bookValue": "0",
"finalValue": "9100500.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Sep 28 2024 13:47:18 GMT+0530 (India Standard Time)",
  "number": "2308414",
  "dayCount": "3",
  "monthCount": "420",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6376500.00",
```

```
"selectedBuildUpValue": "750.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66f18f1d2d094ed13709e682",
      "name": "externallmg_1727106841821_1727106837575_image_0.jpeg",
      "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106841821_1727106837575_image_0.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66f18f1d2d094ed13709e683",
      "name": "externallmg_1727106842126_1727106837575_image_1.jpeg",
      "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106842126_1727106837575_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f18f1d2d094ed13709e687",
      "name": "externallmg_1727106843583_1727106837575_image_5.jpeg",
      "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106843583_1727106837575_image_5.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66f18f1d2d094ed13709e689",
      "name": "externallmg_1727106843844_1727106837575_image_7.jpeg",
      "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106843844_1727106837575_image_7.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66f18f1d2d094ed13709e68a",
      "name": "externallmg_1727106843931_1727106837575_image_8.jpeg",
      "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106843931_1727106837575_image_8.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66f18f1d2d094ed13709e68b",
    "name": "externallmg_1727106844082_1727106837575_image_9.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106844082_1727106837575_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66f18f1d2d094ed13709e68d",
    "name": "externallmg_1727106844346_1727106837575_image_11.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106844346_1727106837575_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66f18f1d2d094ed13709e68e",
    "name": "externallmg_1727106844836_1727106837575_image_12.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106844836_1727106837575_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66f18f1d2d094ed13709e68f",
    "name": "externallmg_1727106845356_1727106837575_image_13.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106845356_1727106837575_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66f18f1d2d094ed13709e682",
    "name": "externallmg_1727106841821_1727106837575_image_0.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106841821_1727106837575_image_0.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "12000.00",
    "max": "19355.00"
  },
  "builtUpRateRange": {
    "min": "10000.00",
    "max": "16130.00"
  },
  "saleableRateRange": {
    "min": "8334.00",
    "max": "13441.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```



```
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "750.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66ed602fbdd9ce4dabcf1c63",
```

```
"ownerName": "Mr. Ali Shabbar Z.H. Khan ",
"ownerPhoneNo": "9821720651",
"appAddress": "Gala No. 14,on Ground & mezzanine floor,Crescent Industrial
Premises Co-op Society Ltd.(A. K. Estate,)Survey No.3/1, Village -Mohili,Taluka-Kurla,",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1290aa6d152c1801b439",
      "label": "Allotment Agreement"
    },
    "inputs": {
      "documentDate": "24/08/1998",
      "from": {
        "value": "Society_",
        "label": "Society "
      },
      "Society_": "M/s. Crescent Industrial Premises Co-Op. Soc. Ltd. ",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Ali Shabbar Z.H. Khan "
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1727504563040_Allotement_Agreement.pdf",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
document_1727504563040_Allotement_Agreement.pdf",
    "id": "833554",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Sat Sep 28 2024 11:52:43 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ef",
      "label": "Society Share Certificate"
    },
    "inputs": {
      "remark": " issued by Crescent Industrial Premises Co-Op. Soc. Ltd. ",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Ali Shabbar Z.H. Khan ",
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "14"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1727504896290_Share_Certifiacte.pdf",
"path": "cases/66ed602fbdd9ce4dabcf1c63/
document_1727504896290_Share_Certifiacte.pdf",
"id": "302743",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Sat Sep 28 2024 11:58:16 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011343",
"createdBy": "667112d324f3ba1343e5ac5c",
"caseHistory": [
  {
    "id": "826005",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 20 2024 17:14:47 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ali Shabbar Z.H. Khan ",
    "phone": "9821720651",
    "ownershipShare": "",
    "email": "",
    "id": "482893"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "256865",
    "name": "Working Area",
    "length": "44.33",
    "length1": "44",
```

```
"length2": "4",
"width": "15.92",
"width1": "15",
"width2": "11",
"totalArea": "705.64",
"images": [],
"extraAreas": [],
"finalArea": "705.64"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Mezzanine Floor",
  "length": "653.00",
  "length1": "653",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "653.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "653.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1290aa6d152c1801b439",
      "label": "Allotment Agreement"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "202324",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "750",
    "squareMeterArea": "69.68",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
```

```
"docBuiltpPercentage": "",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "516.67",
"squareMeterArea": "48.00",
"expectedRate": "19354.71",
"percentage": ""
},
"builtUpArea": {
"area": "620.00",
"squareMeterArea": "57.60",
"expectedRate": "16129.03",
"percentage": "20"
},
"saleableArea": {
"area": "744.00",
"squareMeterArea": "69.12",
"expectedRate": "13440.86",
"percentage": "20"
},
"printlnReport": true,
"_id": "66ed7124364a0f4dac132cf3",
"property": "Gala",
"area": "620",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "10000000",
"expectedRate": "19354.71",
"builtUpExpectedRate": "10000000",
"image": "cases/66ed602fbdd9ce4dabcf1c63/
indicator_1726836742274_Image.png",
"squareMeter": "57.60",
"id": "333318"
},
{
```

```
"carpetArea": {
  "area": "1635.00",
  "squareMeterArea": "151.90",
  "expectedRate": "13455.66",
  "percentage": ""
},
"builtUpArea": {
  "area": "1962.00",
  "squareMeterArea": "182.28",
  "expectedRate": "11213.05",
  "percentage": "20"
},
"saleableArea": {
  "area": "2354.40",
  "squareMeterArea": "218.73",
  "expectedRate": "9344.21",
  "percentage": "20"
},
"printInReport": true,
"_id": "66ed7124364a0f4dac132cf4",
"property": "Gala",
"area": "1635",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "22000000",
"expectedRate": "13455.66",
"builtUpExpectedRate": "11213.05",
"image": "cases/66ed602fbdd9ce4dabcf1c63/
indicator_1726836783915_Image.png",
"squareMeter": "151.90",
"id": "765679"
},
{
  "carpetArea": {
    "area": "520.83",
    "squareMeterArea": "48.39",
    "expectedRate": "12480.08",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "625.00",
    "squareMeterArea": "58.06",
```

```
    "expectedRate": "10400.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "750.00",
    "squareMeterArea": "69.68",
    "expectedRate": "8666.67",
    "percentage": "20"
  },
  "printInReport": true,
  "_id": "66ed7124364a0f4dac132cf5",
  "property": "Gala",
  "area": "750",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Saleable",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "6500000",
  "expectedRate": "8666.666666666666",
  "builtUpExpectedRate": "10400.00",
  "image": "cases/66ed602fbdd9ce4dabcf1c63/
indicator_1726836854389_Image.png",
  "squareMeter": "69.68",
  "id": "107965"
},
{
  "carpetArea": {
    "area": "750.00",
    "squareMeterArea": "69.68",
    "expectedRate": "12000.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "900.00",
    "squareMeterArea": "83.61",
    "expectedRate": "10000.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1080.00",
    "squareMeterArea": "100.34",
    "expectedRate": "8333.33",
    "percentage": "20"
  },
}
```



```
"printlnReport": true,
  "_id": "66ed7124364a0f4dac132cf6",
  "property": "Gala",
  "area": "750",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "9000000",
  "expectedRate": "12000.00",
  "builtUpExpectedRate": "10000.00",
  "image": "cases/66ed602fbdd9ce4dabcf1c63/
indicator_1726836897329_Image.png",
  "squareMeter": "69.68",
  "id": "828785"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f18f1d2d094ed13709e682",
    "name": "externalImg_1727106841821_1727106837575_image_0.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externalImg_1727106841821_1727106837575_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f18f1d2d094ed13709e683",
    "name": "externalImg_1727106842126_1727106837575_image_1.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externalImg_1727106842126_1727106837575_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f18f1d2d094ed13709e684",
    "name": "externalImg_1727106842554_1727106837575_image_2.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externalImg_1727106842554_1727106837575_image_2.jpeg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f18f1d2d094ed13709e685",
    "name": "externallmg_1727106842908_1727106837575_image_3.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106842908_1727106837575_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f18f1d2d094ed13709e686",
    "name": "externallmg_1727106843286_1727106837575_image_4.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106843286_1727106837575_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f18f1d2d094ed13709e687",
    "name": "externallmg_1727106843583_1727106837575_image_5.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106843583_1727106837575_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f18f1d2d094ed13709e688",
    "name": "externallmg_1727106843767_1727106837575_image_6.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106843767_1727106837575_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f18f1d2d094ed13709e689",
    "name": "externallmg_1727106843844_1727106837575_image_7.jpeg",
    "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106843844_1727106837575_image_7.jpeg",
    "orientation": "landscape"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f18f1d2d094ed13709e68a",
  "name": "externallmg_1727106843931_1727106837575_image_8.jpeg",
  "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106843931_1727106837575_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f18f1d2d094ed13709e68b",
  "name": "externallmg_1727106844082_1727106837575_image_9.jpeg",
  "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106844082_1727106837575_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f18f1d2d094ed13709e68c",
  "name": "externallmg_1727106844240_1727106837575_image_10.jpeg",
  "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106844240_1727106837575_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f18f1d2d094ed13709e68d",
  "name": "externallmg_1727106844346_1727106837575_image_11.jpeg",
  "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106844346_1727106837575_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f18f1d2d094ed13709e68e",
  "name": "externallmg_1727106844836_1727106837575_image_12.jpeg",
  "path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106844836_1727106837575_image_12.jpeg",
  "orientation": "landscape"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66f18f1d2d094ed13709e68f",
"name": "externallmg_1727106845356_1727106837575_image_13.jpeg",
"path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106845356_1727106837575_image_13.jpeg",
"orientation": "landscape"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66f18ef62d094ed13709e658",
"name": "externallmg_1727106805423_1727106802031_image_0.jpeg",
"path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106805423_1727106802031_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66f18ef62d094ed13709e659",
"name": "externallmg_1727106805772_1727106802031_image_1.jpeg",
"path": "cases/66ed602fbdd9ce4dabcf1c63/
externallmg_1727106805772_1727106802031_image_1.jpeg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
"originalname": "Afroz Engineering Works - Mr.Ali Shabbar Khan -Gala No. 14 -
State Bank of India ( SME Credit Centre Borivali (West).xlsx",
"filename": "1727253253010_Afroz_Engineering_Works__MrAli_Shabbar_Khan_Ga
la_No_14__State_Bank_of_India__SME_Credit_Centre_Borivali_West.xlsx",
"path": "cases/66ed602fbdd9ce4dabcf1c63/processingDocuments/1727253253010_
Afroz_Engineering_Works__MrAli_Shabbar_Khan_Gala_No_14__State_Bank_of_India
__SME_Credit_Centre_Borivali_West.xlsx",
"size": "1375480",
"createdAt": "Wed Sep 25 2024 14:04:13 GMT+0530 (India Standard Time)",
"uploadedBy": "64dc7184ccaf1e7b7f637f47"
},
{
"originalname": "SBI - Mr. Ali Shabbar Z.H. Khan (1).pdf",
"filename": "1727509368941_SBI__Mr_Ali_Shabbar_ZH_Khan_1.pdf",
"path": "cases/66ed602fbdd9ce4dabcf1c63/
processingDocuments/1727509368941_SBI__Mr_Ali_Shabbar_ZH_Khan_1.pdf",
```

```
"size": "16354253",
"createdAt": "Sat Sep 28 2024 13:12:49 GMT+0530 (India Standard Time)",
"uploadedBy": "62fe044a48a26047e6552796"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"lastName": "Moozhickal",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "66ed6d49ada7094de493d982",
"note": "Value Checked - Pending for site visit",
"taskId": "66ed61a8364a0f4dac130c66",
"createdAt": "2024-09-20T12:40:41.473Z"
},
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"lastName": "Moozhickal",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "66f3caf17d6d262b2ba81631",
"note": "Value Given for confirmation",
"taskId": "66ed61a8364a0f4dac130c66",
"createdAt": "2024-09-25T08:33:53.679Z"
},
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
```

```
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66f7bf4941b96a0db8470358",
  "note": "value confirmed (Task Reopen)",
  "taskId": "66ed61a8364a0f4dac130c66",
  "createdAt": "2024-09-28T08:33:13.537Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66f7c36941b96a0db8470bc1",
  "note": "value confirmed (Task Reopen)",
  "taskId": "66ed61a8364a0f4dac130c66",
  "createdAt": "2024-09-28T08:50:49.847Z"
}
],
"createdAt": "2024-09-20T11:44:47.007Z",
"updatedAt": "2024-09-28T08:53:41.231Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Industrial Gala No. 14, On Ground & Mezzanine Floor, Crescent
Industrial Premises Co-Op. Soc. Ltd. , New/Current Survey No. 3/1, A.K. Estate, R.C.
Loyalka Street, Kherani Road, Village - Mohili, Sakinaka, Taluka - Kurla , District -
Mumbai Suburban , PIN - 400 072, State - Maharashtra, Country - India",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "667112d324f3ba1343e5ac5c",
"contactPersonName": "Mr. Ali Shabbar Z.H. Khan ",
```

```
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9821720651",
"buildingServicesRate": "1800",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Allotment Agreement",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 750.00",
"flatRate": "13300",
"landOtherRate": "11500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"siteVisitDate": "2024-09-23",
"builtupPercentage": "10",
"carpetTotal": "1358.64",
"extendOfSiteRemark": "",
"finalBuiltupArea": "1494.50",
"finalCarpetArea": "1358.64",
"finalSalableArea": "1643.95",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "Ground Floor in Sq. Ft. = 705.00\nMezzanine Floor in Sq.
Ft. = 653.00\n\n",
"toBeAdded": "",
"briefDescOfProperty": "Working Area + Mezzanine Floor",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
```

```

    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Sep 28 2024 11:41:45 GMT+0530 (India Standard Time)"
}

```

Name	Length	Width	Total
Composition :			
Working Area	44'4"	15'11"	705.64
Mezzanine Floor	653'00"	1'00"	653.00
Other Composition :			