

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b99c"
    },
    "firstName": "Samita",
    "type": "CREDITOFFICER",
    "_id": "66a21fa88414a97fe8862d8d",
    "email": "samita.kumbhar@cosmosbank.in",
    "lastName": "kumbhar",
    "mobileNo": "",
    "workMobileNo": "9821239469"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6454645",
    "discussWithPerson": "Samita",
    "expectedFees": 3227.3225,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b99c",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Dadar Branch ",
  "email": "dadar@cosmosbank.in",
  "mobileNo": "02224476018",
  "alternateMobileNo": "8369167372",
  "address": "Horizon Bldg.,1st Floor, Ranade Road & Gokhale Road, Dadar (West),
Mumbai - 400 028, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK - DADAR",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "ACCOUNTANT",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "MAKER",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
```

```
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
      },
    ]
  }
]
```

```
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.11377802497193",
  "longitude": "72.83964743727743"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83964743727743,
    19.11377802497193
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-26",
      "remark": ""
    }
  ]
}
]
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vile Parle",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
```

```
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Juhu Azadnagar SRA Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
```

```
"status": false,
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "C. D. Burfiwala Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
```



```
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "489 (Pt), 511 (Pt), 512 (Pt)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "309",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
```

```
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400058",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (West)",
  "label": false
}
```

```
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_",
    "label": "Open-Conduit plumbing with Casing Capping Electrical wiring "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Semi_Urban",
    "label": "Semi Urban"
  },
  "townplanApprovedByList": {
    "value": "Slum_Rehabilitation_Authority",
    "label": "Slum Rehabilitation Authority"
  },
  "whetherCoveredUnderAnyState": {
```

```
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
  "north": "Poonam Pearl Building",
  "west": "Juhu Lane Road",
  "south": " Green Court Building & Azad Lane Road",
  "east": "Mayfair Garden 1 CHSL"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Flat No. 309",
    "east": "Passage",
    "south": "Passage",
    "west": "Flat No. 308"
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
```

```
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be
assumed that the construction is as per Sanctioned Plan",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "28.5",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "15287.5",
"depreciatedBuildingRate": "1787.5"
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "294940",
"landRate": "153550",
"igrImage": "cases/66f509c90e53f82b0c605c15/igr_1727427639045_Image.png",
"squareMeterGuideLineRate": "294940.00",
"squareFeetGuideLineRate": "27401.00"
},
"igrFinalRate": {
"floorRatePercentage": "0",
"depreciationPercentage": "80",
"rate": "24774.00",
"squareFeetGuideLineRate": "24774.00",
"squareMeterGuideLineRate": "266662.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Middle_Class",
"label": "Middle Class"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
```

```
"label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per SRA norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
}
```

```
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2005",
  "fullDate": "1/1/2005"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
}
```

```
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "41",
"ageOfBuilding": "19",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "3",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "16"
},
"finalPlinthArea": {
```



```
"area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66f509c90e53f82b0c605c15/
routeMap_1727430131987_Image.png",
    "routeLat": "19.113580",
    "routeLng": "72.839558",
    "stationName": "Andheri",
    "routeDistance": "1.2 Km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finalLatLng": false
  },
  "locationMapImg": [
    {
      "id": "gv584a",
      "name": "gv584a",
      "image": "cases/66f509c90e53f82b0c605c15/
routeMap_1727429993244_Image.png"
    }
  ],
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "675000.00",
      "depreciationPercentage": "28.5",
      "depreciatedCostOfConstruction": "192375.00",
      "totalFairMarketValue": "4127625.00"
    },
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
```

```
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4320000.00",
"finalValue": "4320000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "6688980.00",
"selectedBuildUpValue": "270.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "66f53c06fcad932b0b14f145",
"name": "externallmg_1727347712310_1727347702322_image_6.jpeg",
"path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347712310_1727347702322_image_6.jpeg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
{
"status": false,
"_id": "66f53c06fcad932b0b14f147",
"name": "externallmg_1727347716189_1727347702322_image_8.jpeg",
"path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347716189_1727347702322_image_8.jpeg",
"orientation": "portrait"
}
```

```
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "66f53c307d6d262b2ba96ef8",
      "name": "Kitchen",
      "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347737338_1727347731012_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f53c307d6d262b2ba96ef9",
      "name": "Kitchen",
      "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347743092_1727347731012_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f53c307d6d262b2ba96efa",
      "name": "Kitchen",
      "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347744494_1727347731012_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f53c307d6d262b2ba96f00",
      "name": "Kitchen",
      "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347759763_1727347731012_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f53c06fcad932b0b14f140",
      "name": "Kitchen",
      "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347707966_1727347702322_image_1.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16889.00",
    "max": "20075.00"
  },
  "builtUpRateRange": {
    "min": "14075.00",
    "max": "16729.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "270.00",
"empanelmentNo": [
  "HO/CREDIT/67/ 2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66f509c90e53f82b0c605c15",
```

```
"ownerName": "Mr. Rohan Nagesh Mhatre & Mr. Rohit Nagesh Mahtre",
"ownerPhoneNo": "8169664180",
"appAddress": "flat no - 309, 3rd floor, Bldg Name - Juhu Azad nagar SRA co
operative housing society Ltd, C D Barfiwala road, Andheri West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1251aa6d152c1801b317",
      "label": "Gift Deed"
    },
    "inputs": {
      "documentDate": "13/01/2024",
      "from": {
        "value": "Donor",
        "label": "Donor"
      },
      "Donor": "Mrs. Hemlata Nagesh Mahtre",
      "to": {
        "value": "donee",
        "label": "donee"
      },
      "donee": "Mr. Rohan Nagesh Mhatre & Mr. Rohit Nagesh Mahtre"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "231453",
    "path": "cases/66f509c90e53f82b0c605c15/document_1727334846508_32471.pdf",
    "fileName": "document_1727334846508_32471.pdf"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ef",
      "label": "Society Share Certificate"
    },
    "inputs": {
      "documentDate": "09/05/2024",
      "remark": "issued by Juhu Azadnagar SRA Co-Op. Hsg. Soc. Ltd.",
      "to": {
        "value": "donee",
        "label": "donee"
      },
      "donee": "Mr. Rohan Nagesh Mhatre & Mr. Rohit Nagesh Mahtre",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  }
]
```

```
    },
    "Document_No": "043"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "320363",
  "path": "cases/66f509c90e53f82b0c605c15/document_1727428880612_78049.pdf",
  "fileName": "document_1727428880612_78049.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "11/04/2005",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "SRA / ENG / 811 / KW / PL / AP"
},
  "isHardCopy": false,
  "displayStatus": true,
  "id": "902447",
  "path": "cases/66f509c90e53f82b0c605c15/document_1727429006049_89587.pdf",
  "fileName": "document_1727429006049_89587.pdf"
}
],
"caseNumber": "011494",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "370048",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 26 2024 12:44:17 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Rohan Nagesh Mhatre & Mr. Rohit Nagesh Mahtre",
```

```
"phone": "8169664180",
"ownershipShare": "",
"email": "",
"id": "803903"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "530454",
"name": "Living Room",
"length": "14.50",
"length1": "14",
"length2": "6",
"width": "9.50",
"width1": "9",
"width2": "6",
"totalArea": "137.75",
"images": [],
"extraAreas": [],
"finalArea": "137.75"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "8.67",
"length1": "8",
"length2": "8",
"width": "4.75",
"width1": "4",
"width2": "9",
"totalArea": "41.17",
"images": [],
"extraAreas": [],
"finalArea": "41.17"
}
]
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "4",
"name": "WC",
"length": "3.67",
"length1": "3",
"length2": "8",
"width": "3.25",
"width1": "3",
"width2": "3",
"totalArea": "11.92",
"images": [],
"finalArea": "11.92",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "4.50",
  "length1": "4",
  "length2": "6",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "15.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.75"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1251aa6d152c1801b317",
      "label": "Gift Deed"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "897809",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "225",
  "squareMeterArea": "20.9",
  "docFinalBuiltUp": "270",
  "docFinalBuiltUpSquareMeter": "25.08",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "225.00",
      "squareMeterArea": "20.90",
      "expectedRate": "16888.89",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "270.00",
      "squareMeterArea": "25.08",
      "expectedRate": "14074.07",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "0.00",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "66f6743d7d6d262b2baa445e",
    "property": "Residential Flat",
    "area": "270",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Index_no.2",
    "expectedPrice": "3800000",
```

```
"expectedRate": "16888.89",
"builtUpExpectedRate": "3800000",
"image": "cases/66f509c90e53f82b0c605c15/
indicator_1727427497954_Image.png",
"squareMeter": "25.08",
"id": "504653"
},
{
"carpetArea": {
"area": "225.00",
"squareMeterArea": "20.90",
"expectedRate": "20000.00",
"percentage": ""
},
"builtUpArea": {
"area": "270.00",
"squareMeterArea": "25.08",
"expectedRate": "16666.67",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66f6743d7d6d262b2baa445f",
"property": "Residential Flat",
"area": "225",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "4500000",
"expectedRate": "20000.00",
"builtUpExpectedRate": "16666.67",
"image": "cases/66f509c90e53f82b0c605c15/
indicator_1727427530438_Image.png",
"squareMeter": "20.90",
"id": "932450"
},
{
"carpetArea": {
```

```
    "area": "224.17",
    "squareMeterArea": "20.83",
    "expectedRate": "20074.05",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "269.00",
    "squareMeterArea": "24.99",
    "expectedRate": "16728.62",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66f6743d7d6d262b2baa4460",
  "property": "Residential Flat",
  "area": "269",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "4500000",
  "expectedRate": "20074.05",
  "builtUpExpectedRate": "4500000",
  "image": "cases/66f509c90e53f82b0c605c15/
indicator_1727427544831_Image.png",
  "squareMeter": "24.99",
  "id": "795303"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f53c307d6d262b2ba96ef8",
  "name": "externalImg_1727347737338_1727347731012_image_0.jpeg",
  "path": "cases/66f509c90e53f82b0c605c15/
externalImg_1727347737338_1727347731012_image_0.jpeg",
  "orientation": "portrait"
},
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f53c307d6d262b2ba96ef9",
  "name": "externallmg_1727347743092_1727347731012_image_1.jpeg",
  "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347743092_1727347731012_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f53c307d6d262b2ba96efa",
  "name": "externallmg_1727347744494_1727347731012_image_2.jpeg",
  "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347744494_1727347731012_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f53c307d6d262b2ba96efb",
  "name": "externallmg_1727347753125_1727347731012_image_3.jpeg",
  "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347753125_1727347731012_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f53c307d6d262b2ba96efc",
  "name": "externallmg_1727347753896_1727347731012_image_4.jpeg",
  "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347753896_1727347731012_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f53c307d6d262b2ba96efd",
  "name": "externallmg_1727347755524_1727347731012_image_5.jpeg",
  "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347755524_1727347731012_image_5.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f53c307d6d262b2ba96efe",
    "name": "externallmg_1727347758444_1727347731012_image_6.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347758444_1727347731012_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f53c307d6d262b2ba96eff",
    "name": "externallmg_1727347759119_1727347731012_image_7.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347759119_1727347731012_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f53c307d6d262b2ba96f00",
    "name": "externallmg_1727347759763_1727347731012_image_8.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347759763_1727347731012_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f53c06fcad932b0b14f13f",
    "name": "externallmg_1727347707507_1727347702322_image_0.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347707507_1727347702322_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f53c06fcad932b0b14f140",
    "name": "externallmg_1727347707966_1727347702322_image_1.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347707966_1727347702322_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "66f53c06fcad932b0b14f141",
    "name": "externallmg_1727347708460_1727347702322_image_2.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347708460_1727347702322_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f53c06fcad932b0b14f142",
    "name": "externallmg_1727347709903_1727347702322_image_3.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347709903_1727347702322_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f53c06fcad932b0b14f143",
    "name": "externallmg_1727347710083_1727347702322_image_4.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347710083_1727347702322_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f53c06fcad932b0b14f144",
    "name": "externallmg_1727347710811_1727347702322_image_5.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347710811_1727347702322_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f53c06fcad932b0b14f145",
    "name": "externallmg_1727347712310_1727347702322_image_6.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347712310_1727347702322_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "66f53c06fcad932b0b14f146",
    "name": "externallmg_1727347715871_1727347702322_image_7.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347715871_1727347702322_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f53c06fcad932b0b14f147",
    "name": "externallmg_1727347716189_1727347702322_image_8.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/
externallmg_1727347716189_1727347702322_image_8.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1727427654016_AGR.pdf",
    "path": "cases/66f509c90e53f82b0c605c15/
processingDocuments/1727427654016_AGR.pdf",
    "size": "525005",
    "createdAt": "Fri Sep 27 2024 14:30:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1727347707507_1727347702322_image_0.jpeg",
    "filename":
"1727427654022_externallmg_1727347707507_1727347702322_image_0.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/processingDocuments/1727427654022_
externallmg_1727347707507_1727347702322_image_0.jpeg",
    "size": "79290",
    "createdAt": "Fri Sep 27 2024 14:30:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1727347715871_1727347702322_image_7.jpeg",
    "filename":
"1727427654022_externallmg_1727347715871_1727347702322_image_7.jpeg",
    "path": "cases/66f509c90e53f82b0c605c15/processingDocuments/1727427654022_
externallmg_1727347715871_1727347702322_image_7.jpeg",
    "size": "58486",
    "createdAt": "Fri Sep 27 2024 14:30:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
```

```
    },
    {
      "originalname": "IGR-01.pdf",
      "filename": "1727427654024_IGR01.pdf",
      "path": "cases/66f509c90e53f82b0c605c15/
processingDocuments/1727427654024_IGR01.pdf",
      "size": "143948",
      "createdAt": "Fri Sep 27 2024 14:30:54 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "Summary New=ROHAN.xlsx",
      "filename": "1727427654025_Summary_NewROHAN.xlsx",
      "path": "cases/66f509c90e53f82b0c605c15/
processingDocuments/1727427654025_Summary_NewROHAN.xlsx",
      "size": "1166656",
      "createdAt": "Fri Sep 27 2024 14:30:54 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "60eeaeddf3dd69653a581316",
        "role": "ACCOUNTANT",
        "firstName": "Shyam",
        "lastName": "Kajvilkar",
        "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
      "_id": "66f66e1c7d6d262b2baa3406",
      "note": "Pending for value confirmation ",
      "taskId": "66f50e37fcad932b0b14b0ba",
      "createdAt": "2024-09-27T08:34:36.311Z"
    }
  ],
  "createdAt": "2024-09-26T07:14:17.306Z",
  "updatedAt": "2024-09-27T09:48:10.259Z",
  "__v": 0,
  "assignmentType": {
    "value": "Retail",
```

```
"label": "Retail"
},
"fullAddress": "Residential Flat No. 309, 3rd Floor, Juhu Azadnagar SRA Co-Op. Hsg.
Soc. Ltd., C. D. Burfiwala Road, Village - Vile Parle, Andheri (West), Taluka - Andheri,
District - Mumbai Suburban, 400058, State - Maharashtra, India",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mr. Rohan Nagesh Mhatre",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8169664180",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Any Other Document",
"finalBuiltUpPercentage": "",
"finalCarpetConvertToBuiltUpPer": "",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 270.00",
"flatRate": "16000",
"landOtherRate": "13500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
},
"siteVisitDate": "2024-09-26",
"briefDescOfProperty": "Living Room + Kitchen + WC + Bathroom",
"carpetTotal": "206.59",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "227.25",
"finalCarpetArea": "206.59",
"finalSalableArea": "249.97",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
```

```

"finalSaleablePercentage": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	14'6"	9'6"	137.75
Kitchen	8'8"	4'9"	41.17
WC	3'8"	3'3"	11.92
Bathroom	4'6"	3'6"	15.75
Other Composition :			