

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6667dc1309a0de7b00a3c814"
    },
    "firstName": "Prashant",
    "type": "CREDITOFFICER",
    "_id": "6667dc1309a0de7b00a3c816",
    "lastName": "Kudtalkar",
    "mobileNo": "",
    "workMobileNo": "9867402532",
    "email": "virar_west@jansevabank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2500000",
    "discussWithPerson": "Prashant",
    "expectedFees": 1250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank (Borivali) LTD",
  "displayName": "Janaseva Sahakari Bank (Borivali) LTD",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6667dc1309a0de7b00a3c814",
  "name": "Virar West",
  "branchCode": "",
  "mobileNo": "9890880229",
  "alternateMobileNo": "",
  "email": "virar_west@jansevabank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Virar Nand Dham CHSL, Old Viva Collage Road, Near Ram Nagar, Virar
West Palghar 401303"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62720a36afd7d55eddedc4a7",
"role": "SITEENGINEER",
"firstName": "Anwar",
"email": "anwar21786@gmail.com",
"lastName": "Shaikh",
"mobileNo": "8552884500",
"designation": "",
"shortName": "AS",
"workWithDocumentMaker": "",
"profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.45147427863966",
  "longitude": "72.82247706107839"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82247706107839,
    19.45147427863966
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "27/09/2024 10:50 am"
    },
    {
      "dateTime": "27/09/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-27",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Virar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Vasai",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vastu Kruti Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "110, 111, 127, 128, 252 & Hissa No. 13, 14 & others ",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B/201",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 305",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Virar (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
```

```
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "CIDCO"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Late Shri Shashikant Patil Road ",
    "west": "Open Plot ",
    "south": "Wing -C",
    "east": "Lambodar CHSL "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Lobby ",
      "east": "Staircase ",
      "south": "Marginal Space",
      "west": "Flat No. 202"
    },
    "asPerDocument": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
    }
  }
}
```

```
    "west": "Details not available "
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "As per actual site measurement, the Carpet area is 220.00 sq. ft and Built
up area mentioned in the agreement is 340.00 sq. ft The loading on Carpet to Super
Built up is 54%. We have considered area mentioned in the documents.",
  "depreciationPercentage": "25.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "5662.5",
  "depreciatedBuildingRate": "1862.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "57600",
  "landRate": "11700",
```

```
"igrImage": "cases/66f63d3ffcad932b0b153a44/igr_1727504272198_Image.png",
"squareMeterGuideLineRate": "51840.00",
"squareFeetGuideLineRate": "4816.00"
},
"igrFinalRate": {
  "floorRatePercentage": "90",
  "depreciationPercentage": "83",
  "rate": "4182.00",
  "squareFeetGuideLineRate": "4182.00",
  "squareMeterGuideLineRate": "45016.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per CIDCO norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking Space ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2007",
  "fullDate": "1/1/2007"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
```

```
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
}
```



```
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "43",
"ageOfBuilding": "17",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "2",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "340.00",
  "areaType": "Saleable",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66f63d3ffcad932b0b153a44/
routeMap_1727519406417_Image.png",
    "routeLat": "19.450861",
    "routeLng": "72.822556",
    "stationName": "Virar",
    "routeDistance": "1.5 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
}
```

```
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "p3zjtn",
    "name": "p3zjtn",
    "image": "cases/66f63d3ffc932b0b153a44/
routeMap_1727519220283_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
```

```
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "1925420.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "1925420.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Sep 28 2024 16:11:42 GMT+0530 (India Standard Time)",
  "number": "2308423",
  "dayCount": "12",
  "monthCount": "429",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "1421880.00",
  "selectedBuildUpValue": "340.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66f666adfcad932b0b157f5c",
      "name":
"externallmg_1727424173008_WhatsApp_Image_20240927_at_132747_1.jpeg",
      "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424173008_WhatsApp_Image_20240927_at_132747_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66f666adfcad932b0b157f4a",
      "name":
"externallmg_1727424172979_WhatsApp_Image_20240927_at_132748_1.jpeg",
      "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172979_WhatsApp_Image_20240927_at_132748_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f666adfcad932b0b157f4c",
      "name":
"externallmg_1727424172982_WhatsApp_Image_20240927_at_132749.jpeg",
      "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172982_WhatsApp_Image_20240927_at_132749.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66f666adfcad932b0b157f50",
      "name":
"externallmg_1727424172990_WhatsApp_Image_20240927_at_132751_1.jpeg",
      "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172990_WhatsApp_Image_20240927_at_132751_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66f666adfcad932b0b157f51",
    "name":
"externallmg_1727424172991_WhatsApp_Image_20240927_at_132751_2.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172991_WhatsApp_Image_20240927_at_132751_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66f666adfcad932b0b157f55",
    "name":
"externallmg_1727424172999_WhatsApp_Image_20240927_at_132752.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172999_WhatsApp_Image_20240927_at_132752.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66f666adfcad932b0b157f57",
    "name":
"externallmg_1727424173001_WhatsApp_Image_20240927_at_132753_2.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424173001_WhatsApp_Image_20240927_at_132753_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7225.00",
    "max": "10000.00"
  },
  "builtUpRateRange": {
    "min": "6023.00",
    "max": "8334.00"
  },
  "saleableRateRange": {
    "min": "5020.00",
    "max": "6945.00"
  }
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```

```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "340.00",
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66f63d3ffcad932b0b153a44",
"ownerName": "Mr. Dattatray Pandurang More & Mrs. Dipika Dattatray More",
"ownerPhoneNo": "8830786582",
"appAddress": "FLAT NO 201 B WING VASTU KRUTI CHS LTD VIRAR EAST
PALGHAR 410305",
"remark": "OC not provide",
"documents": [
  {
    "documentType": {
      "value": "60ae1268aa6d152c1801b385",
      "label": "Agreement of Resale"
    },
  },
  "inputs": {
    "documentDate": "27/02/2017",
```

```
"from": {
  "value": "Transferor",
  "label": "Transferor"
},
"Transferor": "Mr. Anant Bala Mistri ",
"to": {
  "value": "Transferee",
  "label": "Transferee"
},
"Transferee": "Mr. Dattatray Pandurang More & Mrs. Dipika Dattatray More"
},
"isHardCopy": false,
"displayStatus": true,
"id": "891550",
"path": "cases/66f63d3ffcad932b0b153a44/
document_1727413514156_1727413512698_Dattatray_more_agreement.pdf",
"fileName":
"document_1727413514156_1727413512698_Dattatray_more_agreement.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "06/07/2007",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CIDCO / VVSR / POC / BP - 3362 / E / 2828"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1727516811799_122078.pdf",
  "path": "cases/66f63d3ffcad932b0b153a44/
document_1727516811799_122078.pdf",
  "id": "949240",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Sat Sep 28 2024 15:16:51 GMT+0530 (India Standard Time)"
},
{
```

```
"documentType": {
  "value": "60ae1247aa6d152c1801b2ea",
  "label": "Commencement Certificate"
},
"inputs": {
  "documentDate": "15/06/2004",
  "nameOfApprovingAuthority": {
    "value": "CIDCO",
    "label": "CIDCO"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "CIDCO / VVSR / CC / BP - 3362 / E / 787"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1727517109629_Agreement.pdf",
"path": "cases/66f63d3ffcad932b0b153a44/
document_1727517109629_Agreement.pdf",
"id": "782101",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Sat Sep 28 2024 15:21:49 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011506",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "608692",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 27 2024 10:36:07 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Dattatray Pandurang More & Mrs. Dipika Dattatray More",
    "phone": "8830786582",
    "ownershipShare": "",
    "email": "",
    "id": "519592"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "5",
    "name": "Living Room",
    "length": "8.17",
    "length1": "8",
    "length2": "2",
    "width": "14.50",
    "width1": "14",
    "width2": "6",
    "totalArea": "118.42",
    "images": [],
    "finalArea": "118.42",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "7.83",
    "length1": "7",
    "length2": "10",
    "width": "7.00",
    "width1": "7",
    "width2": "0",
    "totalArea": "54.83",
    "images": [],
    "extraAreas": [],
    "finalArea": "54.83"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "name": "Passage",
    "length": "3.67",
```

```
"length1": "3",
"length2": "8",
"width": "3.50",
"width1": "3",
"width2": "6",
"totalArea": "12.83",
"images": [],
"extraAreas": [],
"finalArea": "12.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "5.17",
  "length1": "5",
  "length2": "2",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "22.82",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.82"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
}
```

```
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Saleable",
    "squareMeterArea": "31.59",
    "totalAreaDocument": "340",
    "docBultupPercentage": "",
    "docFinalBultUp": "0.00",
    "docFinalBultUpSquareMeter": "0.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "811562"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "450.00",
      "squareMeterArea": "41.81",
      "expectedRate": "9333.33",
      "percentage": ""
    },
    "bultUpArea": {
      "area": "540.00",
      "squareMeterArea": "50.17",
      "expectedRate": "7777.78",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "648.00",
      "squareMeterArea": "60.20",
      "expectedRate": "6481.48",
      "percentage": "20"
    }
  },
]
```

```
"printlnReport": true,
"_id": "66f79fa812fe5c0dc6cd58d1",
"property": "Residential Flat ",
"area": "450",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "4200000",
"expectedRate": "9333.33",
"builtUpExpectedRate": "7777.78",
"image": "cases/66f63d3ffcad932b0b153a44/
indicator_1727503947654_Image.png",
"squareMeter": "41.81",
"id": "325423"
},
{
  "carpetArea": {
    "area": "400.00",
    "squareMeterArea": "37.16",
    "expectedRate": "10000.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "480.00",
    "squareMeterArea": "44.59",
    "expectedRate": "8333.33",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "576.00",
    "squareMeterArea": "53.51",
    "expectedRate": "6944.44",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "66f79fa812fe5c0dc6cd58d2",
  "property": "Residential Flat",
  "area": "400",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
```



```
"source": "Housing.Com",
"expectedPrice": "4000000",
"expectedRate": "10000.00",
"builtUpExpectedRate": "8333.33",
"image": "cases/66f63d3ffcad932b0b153a44/
indicator_1727504009040_Image.png",
"squareMeter": "37.16",
"id": "842436"
},
{
"carpetArea": {
"area": "422",
"squareMeterArea": "39.21",
"expectedRate": "8293.84",
"percentage": ""
},
"builtUpArea": {
"area": "506.00",
"squareMeterArea": "47.01",
"expectedRate": "6917.00",
"percentage": ""
},
"saleableArea": {
"area": "607.20",
"squareMeterArea": "56.41",
"expectedRate": "5764.16",
"percentage": "20"
},
"printlnReport": true,
"_id": "66f79fa812fe5c0dc6cd58d3",
"property": "Residential Flat",
"area": "506",
"builtUpPercentage": "0",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "3500000",
"expectedRate": "8293.84",
"builtUpExpectedRate": "3500000",
"image": "cases/66f63d3ffcad932b0b153a44/
indicator_1727504057763_Image.png",
"squareMeter": "47.01",
"id": "243953"
},
```

```
{
  "carpetArea": {
    "area": "436",
    "squareMeterArea": "40.51",
    "expectedRate": "7224.77",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "523.00",
    "squareMeterArea": "48.59",
    "expectedRate": "6022.94",
    "percentage": ""
  },
  "saleableArea": {
    "area": "627.60",
    "squareMeterArea": "58.31",
    "expectedRate": "5019.12",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "66f79fa812fe5c0dc6cd58d4",
  "property": "Residential Flat",
  "area": "523",
  "builtUpPercentage": "0",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "3150000",
  "expectedRate": "7224.77",
  "builtUpExpectedRate": "3150000",
  "image": "cases/66f63d3ffcad932b0b153a44/
indicator_1727504095673_Image.png",
  "squareMeter": "48.59",
  "id": "784422"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f666adfcad932b0b157f4a",
    "name":
"externalImg_1727424172979_WhatsApp_Image_20240927_at_132748_1.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externalImg_1727424172979_WhatsApp_Image_20240927_at_132748_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f666adfcad932b0b157f4b",
    "name":
"externallmg_1727424172980_WhatsApp_Image_20240927_at_132748.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172980_WhatsApp_Image_20240927_at_132748.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f666adfcad932b0b157f4c",
    "name":
"externallmg_1727424172982_WhatsApp_Image_20240927_at_132749.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172982_WhatsApp_Image_20240927_at_132749.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f666adfcad932b0b157f4d",
    "name":
"externallmg_1727424172985_WhatsApp_Image_20240927_at_132750_1.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172985_WhatsApp_Image_20240927_at_132750_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f666adfcad932b0b157f4e",
    "name":
"externallmg_1727424172986_WhatsApp_Image_20240927_at_132750_2.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172986_WhatsApp_Image_20240927_at_132750_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f666adfcad932b0b157f4f",
```

```
    "name":
"externallmg_1727424172988_WhatsApp_Image_20240927_at_132750.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172988_WhatsApp_Image_20240927_at_132750.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f666adfcad932b0b157f50",
  "name":
"externallmg_1727424172990_WhatsApp_Image_20240927_at_132751_1.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172990_WhatsApp_Image_20240927_at_132751_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f666adfcad932b0b157f51",
  "name":
"externallmg_1727424172991_WhatsApp_Image_20240927_at_132751_2.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172991_WhatsApp_Image_20240927_at_132751_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f666adfcad932b0b157f52",
  "name":
"externallmg_1727424172993_WhatsApp_Image_20240927_at_132751.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172993_WhatsApp_Image_20240927_at_132751.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f666adfcad932b0b157f53",
  "name":
"externallmg_1727424172995_WhatsApp_Image_20240927_at_132752_1.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172995_WhatsApp_Image_20240927_at_132752_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f666adfcad932b0b157f54",
  "name":
"externallmg_1727424172997_WhatsApp_Image_20240927_at_132752_2.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172997_WhatsApp_Image_20240927_at_132752_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f666adfcad932b0b157f55",
  "name":
"externallmg_1727424172999_WhatsApp_Image_20240927_at_132752.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424172999_WhatsApp_Image_20240927_at_132752.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f666adfcad932b0b157f56",
  "name":
"externallmg_1727424173000_WhatsApp_Image_20240927_at_132753_1.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424173000_WhatsApp_Image_20240927_at_132753_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f666adfcad932b0b157f57",
  "name":
"externallmg_1727424173001_WhatsApp_Image_20240927_at_132753_2.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424173001_WhatsApp_Image_20240927_at_132753_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f666adfcad932b0b157f58",
  "name":
"externallmg_1727424173003_WhatsApp_Image_20240927_at_132753.jpeg",
```

```
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424173003_WhatsApp_Image_20240927_at_132753.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f666adfcad932b0b157f59",
    "name":
"externallmg_1727424173004_WhatsApp_Image_20240927_at_132745_1.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424173004_WhatsApp_Image_20240927_at_132745_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f666adfcad932b0b157f5a",
    "name":
"externallmg_1727424173006_WhatsApp_Image_20240927_at_132745_2.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424173006_WhatsApp_Image_20240927_at_132745_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f666adfcad932b0b157f5b",
    "name":
"externallmg_1727424173007_WhatsApp_Image_20240927_at_132745.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424173007_WhatsApp_Image_20240927_at_132745.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f666adfcad932b0b157f5c",
    "name":
"externallmg_1727424173008_WhatsApp_Image_20240927_at_132747_1.jpeg",
    "path": "cases/66f63d3ffcad932b0b153a44/
externallmg_1727424173008_WhatsApp_Image_20240927_at_132747_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66f666adfcad932b0b157f5d",
  "name":
"externalImg_1727424173010_WhatsApp_Image_20240927_at_132747.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/
externalImg_1727424173010_WhatsApp_Image_20240927_at_132747.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "Calculation Sheet NEW.xlsx",
  "filename": "1727504305244_Calculation_Sheet_NEW.xlsx",
  "path": "cases/66f63d3ffcad932b0b153a44/
processingDocuments/1727504305244_Calculation_Sheet_NEW.xlsx",
  "size": "1380819",
  "createdAt": "Sat Sep 28 2024 11:48:25 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "WhatsApp Image 2024-09-28 at 11.12.55 AM (1).jpeg",
  "filename":
"1727504305272_WhatsApp_Image_20240928_at_111255_AM_1.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/processingDocuments/1727504305272_
WhatsApp_Image_20240928_at_111255_AM_1.jpeg",
  "size": "122078",
  "createdAt": "Sat Sep 28 2024 11:48:25 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "WhatsApp Image 2024-09-28 at 11.12.55 AM.jpeg",
  "filename": "1727504305276_WhatsApp_Image_20240928_at_111255_AM.jpeg",
  "path": "cases/66f63d3ffcad932b0b153a44/processingDocuments/1727504305276_
WhatsApp_Image_20240928_at_111255_AM.jpeg",
  "size": "123988",
  "createdAt": "Sat Sep 28 2024 11:48:25 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "64cde526dc9f3034f3fefa49",
```

```
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66f7990b41b96a0db846d141",
  "note": "Value given for confirmation",
  "taskId": "66f640b5fcad932b0b1540fb",
  "createdAt": "2024-09-28T05:50:03.133Z"
}
],
"createdAt": "2024-09-27T05:06:07.543Z",
"updatedAt": "2024-09-28T10:52:18.917Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. B/201, 2nd Floor, Wing - B, Vastu Kruti Co-Op.
Hsg. Soc. Ltd. , Village - Virar, Virar (East), Taluka - Vasai, District - Palghar, PIN - 401
305, State - Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mrs. Dipika Dattatray More\n",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"siteVisitContactNo": "8830786582",
"buildingServicesRate": "2500",
"finalAreaType": "Saleable Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Saleable Area in Sq. Ft. = 340.00",
"flatRate": "6300",
"landOtherRate": "3800",
```



```

"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "220.9",
"extendOfSiteRemark": "",
"finalBuiltupArea": "242.99",
"finalCarpetArea": "220.90",
"finalSalableArea": "267.29",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"briefDescOfProperty": "Living Room + Kitchen + Passage + Bathroom + WC",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Sep 28 2024 14:53:51 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-09-27"
}

```

Name	Length	Width	Total
Composition :			

Living Room	8'2"	14'6"	118.42
Kitchen	7'10"	7'0"	54.83
Passage	3'8"	3'6"	12.83
Bathroom	5'2"	4'5"	22.82
WC	12'00"	1'00"	12.00
Other Composition :			