

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "firstName": "Sayali",
    "type": "CREDITOFFICER",
    "_id": "64bb68b0a87c525d5c04abb3",
    "lastName": "Bangar",
    "mobileNo": "",
    "workMobileNo": "8097275708",
    "email": "cord.racpckalyan@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "cord.racpckalyan@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Ground Floor, 1 st Floor, Millenium Heights, Opp. Patedar Bhawan
Marriage Hall, Shahad Mohone Road, Shahad, Kalyan (West) - 421 103 \n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
  "mobileNo": "9821518537",
  "designation": ""
}
```

```
    "shortName": "PS",
    "workWithDocumentMaker": "60f915d3f3dd69653a592199",
    "profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "email": "rashmijadhav14feb@gmail.com",
    "lastName": "Jadhav",
    "mobileNo": "7738144625",
    "designation": "Back Office Coordination",
    "shortName": "RJ",
    "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
          "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.194735610937798",
  "longitude": "72.95958277481667"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-27",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-24",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Vasind",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Shahapur",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Morya Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Station Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Swami Vivekananda Nagar, Near Vasind Railway Station",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```



```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "108/1/4/1, 108/1/2/B, 108/1/11/3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "608",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 601",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "sole_ownership",
```

```
"label": "sole ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Town_Planner,_Thane",
  "label": "Town Planner, Thane"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Hemachandra Nehate Housing Complex",
  "west": "Internal Road",
  "south": "Yashwantrao Residence Housing Society",
  "east": "Internal Road"
},
"asPerDocumentAgreement": {
  "north": "Plot No. 3 & 1 of Layout",
  "west": "Property of adjacent Survey\nNumber",
  "south": "Plot No. 1, 2 & 3 of Layout",
  "east": "9 Mtr. Wide Road of Layout"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Flat No. 607",
    "east": "Marginal Space",
    "south": "Flat No. 609",
    "west": "Passage"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
```

```
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No.BS / RK / BP /
Vasind / Shahapur / SSThane / 4037 Dated 25.03.2023 issued by Directorate of Town
Planning and Pricing- State Maharashtra, Thane (As Download from RERA Site).",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "Building is under construction",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": " Residential Flat",
  "rate": "36300",
  "landRate": "4190",
  "igrImage": "cases/66f65754fcad932b0b1566a0/igr_1727507132953_Image.png",
  "squareMeterGuideLineRate": "38115.00",
  "squareFeetGuideLineRate": "3541.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
```

```
"depreciationPercentage": "0",
"rate": "36300.00",
"squareMeterGuideLineRate": "38115.00",
"squareFeetGuideLineRate": "3541.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per Local norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6"_Thk._Brick_Masonry",
    "label": "Proposed 6" Thk. Brick Masonry"
  }
},
```

```
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Open Parking",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2026",
  "fullDate": "1/1/2026"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C._Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
}
```

```
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
```



```
    "value": "As_per_RERA_Certificate",
    "label": "As per RERA Certificate"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "0",
  "ageOfBuilding": "0",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "7",
  "flatFloorNo": "6",
  "noOfLifts": "2",
  "noOfDwellingUnitsInBuilding": "9"
},
"finalPlinthArea": {
  "area": "442.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66f65754fcad932b0b1566a0/
routeMap_1727508092186_Image.png",
    "routeLat": "19.406000",
    "routeLng": "73.269472",
    "stationName": "Vasind",
    "routeDistance": "500M",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
```

```
{
  "id": "ktck7",
  "name": "ktck7",
  "image": "cases/66f65754fcad932b0b1566a0/
routeMap_1727508037739_Image.png"
}
],
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "2894400.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "98",
  "bookValue": "0",

```

```
"finalValue": "2894400.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Sep 28 2024 14:14:03 GMT+0530 (India Standard Time)",
  "number": "2308415",
  "dayCount": "4",
  "monthCount": "421",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "9",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "9",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "9",
```

```
"percentage": "7.00",
"isHideFloor": false,
"status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "9",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "9",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "71.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1565830.00",
  "selectedBuildUpValue": "442.20",
```

```
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a195",
      "name": "externallmg_1727428425889_1727428422917_image_1.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428425889_1727428422917_image_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a199",
      "name": "externallmg_1727428427500_1727428422917_image_5.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428427500_1727428422917_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a19e",
      "name": "externallmg_1727428429670_1727428422917_image_10.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428429670_1727428422917_image_10.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a19c",
      "name": "externallmg_1727428428865_1727428422917_image_8.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428428865_1727428422917_image_8.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a19a",
      "name": "externallmg_1727428427940_1727428422917_image_6.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428427940_1727428422917_image_6.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a198",
      "name": "externallmg_1727428426955_1727428422917_image_4.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428426955_1727428422917_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a194",
      "name": "externallmg_1727428425274_1727428422917_image_0.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428425274_1727428422917_image_0.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a195",
      "name": "externallmg_1727428425889_1727428422917_image_1.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428425889_1727428422917_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a1a1",
      "name": "externallmg_1727428431390_1727428422917_image_13.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428431390_1727428422917_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a1a2",
      "name": "externallmg_1727428431985_1727428422917_image_14.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428431985_1727428422917_image_14.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66f67751fcad932b0b15a1a4",
      "name": "externallmg_1727428433250_1727428422917_image_16.jpeg",
      "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428433250_1727428422917_image_16.jpeg",
```

```
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6483.00",
    "max": "7693.00"
  },
  "builtUpRateRange": {
    "min": "5894.00",
    "max": "6411.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "402.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
```

```
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66f65754fcad932b0b1566a0",
"ownerName": "Urmila Prakash Budhar",
"ownerPhoneNo": "9260030903",
"fullAddress": "Residential Flat No. 608, 6th Floor, Morya Heights, Swami Vivekananda
Nagar, Near Vasind Railway Station, Station Road, Village - Vasind, Taluka - Shahapur,
District - Thane, PIN Code - 421 601, State - Maharashtra, India",
"remark": "",
"documents": [
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "19/09/2024",
    "from": {
      "value": "Developers",
      "label": "Developers"
    },
    "Developers": "M/s. Morya Developers",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Urmila Prakash Budhar",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "4278 / 2024"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1727510822576_Urmila_Budhar.pdf",
  "path": "cases/66f65754fcad932b0b1566a0/
document_1727510822576_Urmila_Budhar.pdf",
  "id": "660299",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Sat Sep 28 2024 13:37:03 GMT+0530 (India Standard Time)"
},
{
```

```
"documentType": {
  "value": "60ae129faa6d152c1801b47d",
  "label": "RERA Certificate"
},
"inputs": {
  "documentDate": "23/10/2023",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "P51700053294"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1727510897494_RERA_0001.pdf",
"path": "cases/66f65754fcad932b0b1566a0/
document_1727510897494_RERA_0001.pdf",
"id": "392167",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Sat Sep 28 2024 13:38:17 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "06/07/2023",
    "remark": " issued by District Collector office, Thane (As Download from RERA
Site).",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "Revenue / K-1 / T- 11 / BP / Vasind / Shahapur / SR - 10 / 2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1727511138673_1_Commencement_Certificates___NA_Order_for_plotted_development__20240514T153140383.pdf",
  "path": "cases/66f65754fcad932b0b1566a0/document_1727511138673_1_Commen
cement_Certificates___NA_Order_for_plotted_development__20240514T153140383.p
```

```
df",
  "id": "294813",
  "uploadedBy": "627222afafd7d55eddedd82",
  "createdAt": "Sat Sep 28 2024 13:42:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "25/03/2023",
    "remark": " issued by Directorate of Town Planning and Pricing- State Maharashtra, Thane (As Download from RERA Site).",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "BS / RK / BP / Vasind / Shahapur / SSThane / 4037"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1727511226299_1133214.pdf",
  "path": "cases/66f65754fcad932b0b1566a0/
document_1727511226299_1133214.pdf",
  "id": "882910",
  "uploadedBy": "627222afafd7d55eddedd82",
  "createdAt": "Sat Sep 28 2024 13:43:46 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "011519",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "373030",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 27 2024 12:27:24 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
```

```
"name": "Urmila Prakash Budhar",
"phone": "9260030903",
"ownershipShare": "",
"email": "",
"id": "795946"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "960600",
  "name": "Living Room",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "135.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "135.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "105.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "105.00"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "56.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "56.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "0",
  "width": "5.00",
  "width1": "5",
  "width2": "0",
  "totalArea": "25.00",
  "images": [],
  "finalArea": "25.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
```

```
"width": "5.00",
"width1": "5",
"width2": "00",
"totalArea": "25.00",
"images": [],
"extraAreas": [],
"finalArea": "25.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "22.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Balcony",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "24.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.00"
},
{
  "measurementType": {
```



```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Balcony",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "34.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "34.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "175785",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "402",
    "squareMeterArea": "37.35",
    "docFinalBuiltUp": "442.2",
    "docFinalBuiltUpSquareMeter": "41.085",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "325",
```

```
"squareMeterArea": "30.19",
"expectedRate": "7692.31",
"percentage": ""
},
"builtUpArea": {
  "area": "390.00",
  "squareMeterArea": "36.23",
  "expectedRate": "6410.26",
  "percentage": ""
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "66f7c2e412fe5c0dc6cd922d",
"property": "Residential Flat ",
"area": "390",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "2500000",
"expectedRate": "7692.31",
"builtUpExpectedRate": "2500000",
"image": "cases/66f65754fcad932b0b1566a0/
indicator_1727506943918_Image.png",
"squareMeter": "36.23",
"id": "147789"
},
{
  "carpetArea": {
    "area": "617.00",
    "squareMeterArea": "57.32",
    "expectedRate": "6969.53",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "678.70",
    "squareMeterArea": "63.05",
    "expectedRate": "6335.94",
    "percentage": "10"
```

```
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "66f7aadf12fe5c0dc6cd7451",
"property": "Residential Flat",
"area": "617",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4300200",
"expectedRate": "6969.53",
"builtUpExpectedRate": "6335.94",
"image": "cases/66f65754fcad932b0b1566a0/
indicator_1727507037304_Image.png",
"squareMeter": "57.32",
"id": "793675"
},
{
  "carpetArea": {
    "area": "617.00",
    "squareMeterArea": "57.32",
    "expectedRate": "6482.98",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "678.70",
    "squareMeterArea": "63.05",
    "expectedRate": "5893.62",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66f7aadf12fe5c0dc6cd7452",
```

```
"property": " Residential Flat",
"area": "617",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4000000",
"expectedRate": "6482.98",
"builtUpExpectedRate": "5893.62",
"image": "cases/66f65754fcad932b0b1566a0/
indicator_1727507071851_Image.png",
"squareMeter": "57.32",
"id": "992708"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f67751fcad932b0b15a194",
  "name": "externalImg_1727428425274_1727428422917_image_0.jpeg",
  "path": "cases/66f65754fcad932b0b1566a0/
externalImg_1727428425274_1727428422917_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f67751fcad932b0b15a195",
  "name": "externalImg_1727428425889_1727428422917_image_1.jpeg",
  "path": "cases/66f65754fcad932b0b1566a0/
externalImg_1727428425889_1727428422917_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f67751fcad932b0b15a196",
  "name": "externalImg_1727428426255_1727428422917_image_2.jpeg",
  "path": "cases/66f65754fcad932b0b1566a0/
externalImg_1727428426255_1727428422917_image_2.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a198",
    "name": "externallmg_1727428426955_1727428422917_image_4.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428426955_1727428422917_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a199",
    "name": "externallmg_1727428427500_1727428422917_image_5.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428427500_1727428422917_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a19a",
    "name": "externallmg_1727428427940_1727428422917_image_6.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428427940_1727428422917_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a19b",
    "name": "externallmg_1727428428500_1727428422917_image_7.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428428500_1727428422917_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a19c",
    "name": "externallmg_1727428428865_1727428422917_image_8.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428428865_1727428422917_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66f67751fcad932b0b15a19d",
    "name": "externallmg_1727428429115_1727428422917_image_9.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428429115_1727428422917_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a19e",
    "name": "externallmg_1727428429670_1727428422917_image_10.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428429670_1727428422917_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a19f",
    "name": "externallmg_1727428430195_1727428422917_image_11.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428430195_1727428422917_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a1a0",
    "name": "externallmg_1727428430790_1727428422917_image_12.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428430790_1727428422917_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a1a1",
    "name": "externallmg_1727428431390_1727428422917_image_13.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428431390_1727428422917_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "66f67751fcad932b0b15a1a2",
    "name": "externallmg_1727428431985_1727428422917_image_14.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428431985_1727428422917_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a1a3",
    "name": "externallmg_1727428432510_1727428422917_image_15.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428432510_1727428422917_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f67751fcad932b0b15a1a4",
    "name": "externallmg_1727428433250_1727428422917_image_16.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727428433250_1727428422917_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f669590e53f82b0c613714",
    "name": "externallmg_1727424857017_1727424853970_image_0.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727424857017_1727424853970_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f669590e53f82b0c613715",
    "name": "externallmg_1727424857195_1727424853970_image_1.jpeg",
    "path": "cases/66f65754fcad932b0b1566a0/
externallmg_1727424857195_1727424853970_image_1.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
```

```
"originalname": "Calculation Sheet NEW.xlsx",
"filename": "1727507166173_Calculation_Sheet_NEW.xlsx",
"path": "cases/66f65754fcad932b0b1566a0/
processingDocuments/1727507166173_Calculation_Sheet_NEW.xlsx",
"size": "927315",
"createdAt": "Sat Sep 28 2024 12:36:06 GMT+0530 (India Standard Time)",
"uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
"originalname": "Final report - SBI - Shri . Navnath Ratan Pagare & Smt. Kalpna
Navnath Pagare.pdf",
"filename": "1727507166191_Final_report__SBI__Shri__Navnath_Ratan_Pagare__
Smt__Kalpna_Navnath_Pagare.pdf",
"path": "cases/66f65754fcad932b0b1566a0/processingDocuments/1727507166191
_Final_report__SBI__Shri__Navnath_Ratan_Pagare__Smt__Kalpna_Navnath_Pagare.
pdf",
"size": "17639950",
"createdAt": "Sat Sep 28 2024 12:36:06 GMT+0530 (India Standard Time)",
"uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"lastName": "Jadhav",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "66f794f612fe5c0dc6cd45a1",
"note": "Value given for confirmation",
"taskId": "66f6575dfcad932b0b156711",
"createdAt": "2024-09-28T05:32:38.132Z"
}
],
"createdAt": "2024-09-27T06:57:24.511Z",
"updatedAt": "2024-09-28T08:49:14.320Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
```



```
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Vikas Somavate ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Supervisor",
"siteVisitContactNo": "9260030903",
"siteVisitDate": "2024-09-24",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Index- II",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 402.00",
"flatRate": "7200",
"landOtherRate": "4700",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
}
```

"reportGeneratedDate": "Sat Sep 28 2024 12:42:11 GMT+0530 (India Standard Time)",
 "finalSaleablePercentage": "0",
 "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Toilet + Passage + 2 Balcony",
 "carpetTotal": "426.00",
 "otherCarpetTotal": "0.00",
 "builtupPercentage": "10",
 "finalBuiltupArea": "468.60",
 "finalCarpetArea": "426.00",
 "finalSalableArea": "515.46",
 "salablePercentage": "10",
 "toBeAdded": "",
 "extendOfSiteRemark": "",
 "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 368.00\nBalcony Area in Sq. Ft. = 58.00\n\n"}

Name	Length	Width	Total
Composition :			
Living Room	15'00"	9'00"	135.00
Bedroom	15'00"	7'00"	105.00
Kitchen	7'00"	8'00"	56.00
Toilet	5'0"	5'0"	25.00
Toilet	5'00"	5'00"	25.00
Passage	2'00"	11'00"	22.00
Balcony	3'00"	8'00"	24.00
Balcony	17'00"	2'00"	34.00
Other Composition :			