

```
{
  "typeOfReport": {
    "value": "Row_House",
    "label": "Row House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80d"
    },
    "firstName": "Adit",
    "type": "CREDITOFFICER",
    "_id": "66a4de608b202f344c320353",
    "email": "adit.shah@sbi.co.in",
    "lastName": "Shah",
    "mobileNo": "",
    "workMobileNo": "9967862082"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "55000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80d",
  "branchCode": "000086",
  "type": "BRANCH",
  "name": "Wagle Ind. Est. Branch",
  "email": "sbi.01053@sbi.co.in",
  "mobileNo": "022-25817818",
  "alternateMobileNo": "",
  "address": "Regional Business Office, Region-II, Wagle Ind. Area, Plot No. B-35, 2nd
Floor, Wagle Circle, Thane (West) - 400 604, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - WAGLE ESTATE",
  "fax": "25817831 / 32",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
```

```
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "AM161706-3",
        "label": "Chartered Engineer"
      },
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.19479691044953",
  "longitude": "72.96065124585148"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Accolade CHS",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Hajuri Darga Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Behind Jeevan Chintamani LIC Building",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "RH 3",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400604",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
```

```
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66f659dafcad932b0b156cd9",
"ownerName": "Mr. Anil G. Pandit & Mrs. Archita Anil Pandit",
"ownerPhoneNo": "8369679993",
"fullAddress": "Residential Row House No. RH 3, Ground Floor, Accolade CHS,
Behind Jeevan Chintamani LIC Building, Hajuri Darga Road, Thane (West), 400604",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1727420863091_1_ACCOLADE_CHS_AGREEMENT_COPY.pdf",
    "path": "cases/66f659dafcad932b0b156cd9/
document_1727420863091_1_ACCOLADE_CHS_AGREEMENT_COPY.pdf",
    "id": "437400",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Fri Sep 27 2024 12:38:10 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
```

```
    "displayStatus": false,
    "fileName":
"document_1727420872855_ACCOLADE_CHS_ELECTRICITY_BILL.pdf",
    "path": "cases/66f659dafcad932b0b156cd9/
document_1727420872855_ACCOLADE_CHS_ELECTRICITY_BILL.pdf",
    "id": "648991",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Fri Sep 27 2024 12:38:10 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1727420884856_ACCOLADE_MAINTENANCE.pdf",
    "path": "cases/66f659dafcad932b0b156cd9/
document_1727420884856_ACCOLADE_MAINTENANCE.pdf",
    "id": "207956",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Fri Sep 27 2024 12:38:10 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "011523",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "505712",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 27 2024 12:38:10 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Anil G. Pandit & Mrs. Archita Anil Pandit",
    "phone": "8369679993",
    "ownershipShare": "",
    "email": "",
    "id": "537333"
  }
]
```

```
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f65e397d6d262b2baa19b4",
    "name": "externalImg_1727421995284_1727421990921_image_0.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externalImg_1727421995284_1727421990921_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f65e397d6d262b2baa19b5",
    "name": "externalImg_1727421996886_1727421990921_image_1.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externalImg_1727421996886_1727421990921_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f65e397d6d262b2baa19b6",
    "name": "externalImg_1727421998258_1727421990921_image_2.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externalImg_1727421998258_1727421990921_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f65e397d6d262b2baa19b7",
    "name": "externalImg_1727421999005_1727421990921_image_3.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externalImg_1727421999005_1727421990921_image_3.jpeg",
    "orientation": "landscape"
  },
  ],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66f65e397d6d262b2baa19b8",
  "name": "externallmg_1727421999638_1727421990921_image_4.jpeg",
  "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727421999638_1727421990921_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66f65e397d6d262b2baa19b9",
  "name": "externallmg_1727421999946_1727421990921_image_5.jpeg",
  "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727421999946_1727421990921_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66f65e397d6d262b2baa19ba",
  "name": "externallmg_1727422000738_1727421990921_image_6.jpeg",
  "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422000738_1727421990921_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66f65e397d6d262b2baa19bb",
  "name": "externallmg_1727422001724_1727421990921_image_7.jpeg",
  "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422001724_1727421990921_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66f65e397d6d262b2baa19bc",
  "name": "externallmg_1727422002967_1727421990921_image_8.jpeg",
  "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422002967_1727421990921_image_8.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f65e397d6d262b2baa19bd",
    "name": "externallmg_1727422003491_1727421990921_image_9.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422003491_1727421990921_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f65e397d6d262b2baa19be",
    "name": "externallmg_1727422004137_1727421990921_image_10.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422004137_1727421990921_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f65e397d6d262b2baa19bf",
    "name": "externallmg_1727422004659_1727421990921_image_11.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422004659_1727421990921_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f65e397d6d262b2baa19c0",
    "name": "externallmg_1727422005987_1727421990921_image_12.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422005987_1727421990921_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f65e397d6d262b2baa19c1",
    "name": "externallmg_1727422007401_1727421990921_image_13.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422007401_1727421990921_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a15",
    "name": "externallmg_1727422041494_1727422035882_image_0.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422041494_1727422035882_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a16",
    "name": "externallmg_1727422041727_1727422035882_image_1.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422041727_1727422035882_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a17",
    "name": "externallmg_1727422041883_1727422035882_image_2.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422041883_1727422035882_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a18",
    "name": "externallmg_1727422042136_1727422035882_image_3.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422042136_1727422035882_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a19",
    "name": "externallmg_1727422042452_1727422035882_image_4.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422042452_1727422035882_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "66f65e5c7d6d262b2baa1a1a",
    "name": "externallmg_1727422043088_1727422035882_image_5.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422043088_1727422035882_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a1b",
    "name": "externallmg_1727422043211_1727422035882_image_6.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422043211_1727422035882_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a1c",
    "name": "externallmg_1727422043254_1727422035882_image_7.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422043254_1727422035882_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a1d",
    "name": "externallmg_1727422043255_1727422035882_image_8.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422043255_1727422035882_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a1e",
    "name": "externallmg_1727422043761_1727422035882_image_9.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422043761_1727422035882_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a1f",
```



```
    "name": "externallmg_1727422043762_1727422035882_image_10.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422043762_1727422035882_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a20",
    "name": "externallmg_1727422043922_1727422035882_image_11.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422043922_1727422035882_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a21",
    "name": "externallmg_1727422043983_1727422035882_image_12.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422043983_1727422035882_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a22",
    "name": "externallmg_1727422043984_1727422035882_image_13.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422043984_1727422035882_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a23",
    "name": "externallmg_1727422043985_1727422035882_image_14.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externallmg_1727422043985_1727422035882_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a24",
    "name": "externallmg_1727422043986_1727422035882_image_15.jpeg",
```

```
    "path": "cases/66f659dafcad932b0b156cd9/
externalImg_1727422043986_1727422035882_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a25",
    "name": "externalImg_1727422044287_1727422035882_image_16.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externalImg_1727422044287_1727422035882_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a26",
    "name": "externalImg_1727422044288_1727422035882_image_17.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externalImg_1727422044288_1727422035882_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a27",
    "name": "externalImg_1727422044289_1727422035882_image_18.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externalImg_1727422044289_1727422035882_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65e5c7d6d262b2baa1a28",
    "name": "externalImg_1727422044366_1727422035882_image_19.jpeg",
    "path": "cases/66f659dafcad932b0b156cd9/
externalImg_1727422044366_1727422035882_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
```

"createdAt": "2024-09-27T07:08:10.331Z",
"updatedAt": "2024-09-27T07:27:24.813Z",
"__v": 0,
"updatedBy": "62550ed0aba01e0af98f2f75",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "Mr. Anil G. Pandit & Mrs. Archita Anil Pandit",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8369679993"

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			