

```
{
  "typeOfReport": {
    "label": "Lenders_Engineers Report (LIE)",
    "value": "Lenders_Engineers_Report_(LIE)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7d8"
    },
    "firstName": "Rohit",
    "type": "CREDITOFFICER",
    "_id": "665ac40aa424b37b20c06fd4",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7386894585",
    "email": "sbi.04732@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6454645",
    "discussWithPerson": "Rohit",
    "expectedFees": 3227.3225,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7d8",
  "branchCode": "000031",
  "type": "BRANCH",
  "name": "Industrial Finance Branch, Andheri (East)",
  "email": "varsha.bhat@sbi.co.in",
  "mobileNo": "022-26819792",
  "alternateMobileNo": "022-26822158",
  "address": "102, Natraj Building, 194, Sir M. V. Road, W. E. Highway-Metro Junction,
Andheri (East), Mumbai - 400 069, State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - IFB ANDHERI(E)",
  "fax": "022-26831648",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
```

```
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "15.593521402183974",
  "longitude": "73.74436775188589"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.74436775188589,
```

```
15.593521402183974
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "30/09/2024 12:00 am"
    },
    {
      "dateTime": "30/09/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Anjuna",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Goa",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Bardez",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "403507",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "North Goa",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
  }
}
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66fa444841b96a0db847ab5d",
"ownerName": "MYRAYASH HOTELS PRIVATE LIMITED ",
"ownerPhoneNo": "9833800026",
"appAddress": "Ground floor, Bardez, village - Anjuna, North goa,Goa, ",
"remark": "quarterly report ",
"documents": [],
"caseNumber": "011552",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "708444",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Sep 30 2024 11:55:12 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "MYRAYASH HOTELS PRIVATE LIMITED ",
    "phone": "9833800026",
    "ownershipShare": ""
  }
]
```

```
    "email": "",
    "id": "819886"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6718f709fd14bf9350aabfd7",
    "name": "externallmg_1729689128815_1729689050646_image_0.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689128815_1729689050646_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6718f709fd14bf9350aabfd8",
    "name": "externallmg_1729689130759_1729689050646_image_1.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689130759_1729689050646_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6718f709fd14bf9350aabfd9",
    "name": "externallmg_1729689131731_1729689050646_image_2.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689131731_1729689050646_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6718f709fd14bf9350aabfda",
    "name": "externallmg_1729689138402_1729689050646_image_3.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689138402_1729689050646_image_3.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6718f709fd14bf9350aabfdb",
  "name": "externallmg_1729689139133_1729689050646_image_4.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689139133_1729689050646_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6718f709fd14bf9350aabfdc",
  "name": "externallmg_1729689140753_1729689050646_image_5.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689140753_1729689050646_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6718f709fd14bf9350aabfdd",
  "name": "externallmg_1729689147323_1729689050646_image_6.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689147323_1729689050646_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6718f709fd14bf9350aabfde",
  "name": "externallmg_1729689217704_1729689050646_image_7.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689217704_1729689050646_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6718f709fd14bf9350aabfdf",
  "name": "externallmg_1729689236105_1729689050646_image_8.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689236105_1729689050646_image_8.jpeg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6718f709fd14bf9350aabfe0",
      "name": "externallmg_1729689243646_1729689050646_image_9.jpeg",
      "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689243646_1729689050646_image_9.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6718f709fd14bf9350aabfe1",
      "name": "externallmg_1729689252443_1729689050646_image_10.jpeg",
      "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689252443_1729689050646_image_10.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6718f709fd14bf9350aabfe2",
      "name": "externallmg_1729689256915_1729689050646_image_11.jpeg",
      "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689256915_1729689050646_image_11.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6718f709fd14bf9350aabfe3",
      "name": "externallmg_1729689262958_1729689050646_image_12.jpeg",
      "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689262958_1729689050646_image_12.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6718f709fd14bf9350aabfe4",
      "name": "externallmg_1729689265406_1729689050646_image_13.jpeg",
      "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689265406_1729689050646_image_13.jpeg",
      "orientation": "landscape"
    },
  },
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6718f709fd14bf9350aabfe5",
  "name": "externallmg_1729689281642_1729689050646_image_14.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689281642_1729689050646_image_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6718f709fd14bf9350aabfe6",
  "name": "externallmg_1729689294791_1729689050646_image_15.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689294791_1729689050646_image_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6718f709fd14bf9350aabfe7",
  "name": "externallmg_1729689334537_1729689050646_image_16.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689334537_1729689050646_image_16.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6718f709fd14bf9350aabfe8",
  "name": "externallmg_1729689343544_1729689050646_image_17.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689343544_1729689050646_image_17.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6718f709fd14bf9350aabfe9",
  "name": "externallmg_1729689346842_1729689050646_image_18.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689346842_1729689050646_image_18.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6718f709fd14bf9350aabfea",
    "name": "externallmg_1729689349020_1729689050646_image_19.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689349020_1729689050646_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de05",
    "name": "externallmg_1729689420877_1729689234420_image_0.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689420877_1729689234420_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de06",
    "name": "externallmg_1729689430208_1729689234420_image_1.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689430208_1729689234420_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de07",
    "name": "externallmg_1729689434915_1729689234420_image_2.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689434915_1729689234420_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de08",
    "name": "externallmg_1729689462835_1729689234420_image_3.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689462835_1729689234420_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6718f7bc772666934f23de09",
  "name": "externallmg_1729689471991_1729689234420_image_4.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689471991_1729689234420_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718f7bc772666934f23de0a",
  "name": "externallmg_1729689473869_1729689234420_image_5.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689473869_1729689234420_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718f7bc772666934f23de0b",
  "name": "externallmg_1729689475399_1729689234420_image_6.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689475399_1729689234420_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718f7bc772666934f23de0c",
  "name": "externallmg_1729689477640_1729689234420_image_7.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689477640_1729689234420_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718f7bc772666934f23de0d",
  "name": "externallmg_1729689480697_1729689234420_image_8.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689480697_1729689234420_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "6718f7bc772666934f23de0e",
    "name": "externallmg_1729689483993_1729689234420_image_9.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689483993_1729689234420_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de0f",
    "name": "externallmg_1729689489951_1729689234420_image_10.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689489951_1729689234420_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de10",
    "name": "externallmg_1729689494480_1729689234420_image_11.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689494480_1729689234420_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de11",
    "name": "externallmg_1729689497654_1729689234420_image_12.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689497654_1729689234420_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de12",
    "name": "externallmg_1729689500221_1729689234420_image_13.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689500221_1729689234420_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de13",
```

```
    "name": "externallmg_1729689511005_1729689234420_image_14.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689511005_1729689234420_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de14",
    "name": "externallmg_1729689514290_1729689234420_image_15.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689514290_1729689234420_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de15",
    "name": "externallmg_1729689519688_1729689234420_image_16.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689519688_1729689234420_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de16",
    "name": "externallmg_1729689522486_1729689234420_image_17.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689522486_1729689234420_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f7bc772666934f23de17",
    "name": "externallmg_1729689525225_1729689234420_image_18.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689525225_1729689234420_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f81003856193623184fd",
    "name": "externallmg_1729689589537_1729689585696_image_0.jpeg",
```

```
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689589537_1729689585696_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f81003856193623184fe",
    "name": "externallmg_1729689594039_1729689585696_image_1.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689594039_1729689585696_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f81003856193623184ff",
    "name": "externallmg_1729689596541_1729689585696_image_2.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689596541_1729689585696_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f8100385619362318500",
    "name": "externallmg_1729689599402_1729689585696_image_3.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689599402_1729689585696_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f8100385619362318501",
    "name": "externallmg_1729689601901_1729689585696_image_4.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689601901_1729689585696_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6718f8100385619362318502",
    "name": "externallmg_1729689603961_1729689585696_image_5.jpeg",
    "path": "cases/66fa444841b96a0db847ab5d/
externallmg_1729689603961_1729689585696_image_5.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718f8100385619362318503",
  "name": "externalImg_1729689606733_1729689585696_image_6.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externalImg_1729689606733_1729689585696_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6718f8100385619362318504",
  "name": "externalImg_1729689612144_1729689585696_image_7.jpeg",
  "path": "cases/66fa444841b96a0db847ab5d/
externalImg_1729689612144_1729689585696_image_7.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-30T06:25:12.865Z",
"updatedAt": "2024-10-23T13:20:16.535Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Industrial Lenders_Engineers Report (LIE) No. Ground Floor, Bardez,
Village - Anjuna, North Goa, Goa, 403507, State - Maharashtra, India",
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "MYRAYASH HOTELS PRIVATE LIMITED ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

"siteVisitContactNo": "9833800026"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other
Composition :
