

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8fa"
    },
    "firstName": "Amrish Kumar",
    "type": "CREDITOFFICER",
    "_id": "659294c9545844510d0e60d7",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "8757380668",
    "email": "1agmmums1067@centralbank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2000000",
    "discussWithPerson": "Amrish Kumar",
    "expectedFees": 1000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8fa",
  "branchCode": "000018",
  "type": "BRANCH",
  "name": "Nariman Point Branch",
  "email": "agmmums1067@centralbank.co.in",
  "mobileNo": "(+91-22) 66387501",
  "alternateMobileNo": "",
  "address": "Chandermukhi, Ground Floor, Barrister Rajni Patel Marg, Mahatma Phule
Nagar, Nariman Point, Mumbai - 400 021, State - Maharashtra, Country - India.",
  "ledgerName": "CENTRAL BANK OF INDIA - NARIMAN POINT",
  "fax": "(+91-22)66361919, 22852657",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
  "lastName": "Patil",
  "mobileNo": "8830049996",
  "designation": "Valuation Engineer",
  "shortName": "SSP",
  "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
  "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
```

```
"lastName": "Shilvanta",
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
      },
    ]
  }
]
```

```
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.06198029218199",
  "longitude": "72.83094125566997"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83094125566997,
    19.06198029218199
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-19",
      "remark": ""
    },
    {
      "status": "COMPLETED",
```

```
    "dateTime": "2024-10-18",
    "remark": "MANUAL_IN_TASK"
  }
],
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bandra (West)",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bandra (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "65, TPS III",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "Queens Corner Premises Co-Op. Hsg. Soc. Ltd.",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "16th & 29th Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```



```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "51",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```

```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 050",
  "label": false
},
"suburb": {
```

```

    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "MarbleFlooring",
    "label": "Marble Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_with_POP_false_Celling",
    "label": "Cement Plastering with POP false Celling"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  }
}

```

```
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Cadra Building",
  "west": "16th Road",
  "south": "29th Road",
  "east": "Kaypee Mansion"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Flat No. 51",
    "east": "Lift & Staircase",
    "south": "Passage & Flat No. 51",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  }
}
```

```
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "70.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "45526",
  "depreciatedBuildingRate": "826"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "315250",
  "landRate": "180310",
  "igrImage": "cases/66fe4b58aaff3e49689f2e2e/igr_1729851497995_Image.png",
  "squareMeterGuideLineRate": "331013.00",
  "squareFeetGuideLineRate": "30752.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "53",
  "rate": "24172.00",
  "squareFeetGuideLineRate": "24172.00",
  "squareMeterGuideLineRate": "260183.00"
},
"outgoingDetail": {
```

```
"areaStatusList": {
  "value": "I_Class",
  "label": "I Class"
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
```

```
"label": "Yes"
},
"carParking": "Open / Stilt Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1977",
  "fullDate": "1/1/1977"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
```

```
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "13",
```



```
"ageOfBuilding": "47",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "8",
"flatFloorNo": "5",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "1245.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66fe4b58aaff3e49689f2e2e/
routeMap_1729944104780_Image.png",
    "routeLat": "19.061735",
    "routeLng": "72.831094",
    "stationName": "Bandra",
    "routeDistance": "1.8 Km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "3z782",
    "name": "3z782",
    "image": "cases/66fe4b58aaff3e49689f2e2e/
routeMap_1729943956627_Image.png"
  }
]
```

```
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "56679870.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "56679870.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
}
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "30094140.00",
  "selectedBuildUpValue": "1245.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67136dc6726e053a21bfc840",
      "name": "externallmg_1729326532388_1729326521544_image_17.jpeg",
      "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326532388_1729326521544_image_17.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "67136dc6726e053a21bfc836",
    "name": "externallmg_1729326529707_1729326521543_image_7.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326529707_1729326521543_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67136dc6726e053a21bfc839",
    "name": "externallmg_1729326530280_1729326521543_image_10.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326530280_1729326521543_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67136dc6726e053a21bfc841",
    "name": "externallmg_1729326532720_1729326521544_image_18.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326532720_1729326521544_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67136dc6726e053a21bfc830",
    "name": "externallmg_1729326527316_1729326521543_image_1.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326527316_1729326521543_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67136dc6726e053a21bfc83d",
    "name": "externallmg_1729326531451_1729326521544_image_14.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326531451_1729326521544_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
```

```
    "_id": "67136de0c6eb1c39d992a180",
    "name": "externallmg_1729326559132_1729326549777_image_8.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326559132_1729326549777_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67136de0c6eb1c39d992a17e",
    "name": "externallmg_1729326558123_1729326549777_image_6.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326558123_1729326549777_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67136dc6726e053a21bfc82f",
    "name": "externallmg_1729326527131_1729326521543_image_0.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326527131_1729326521543_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67136de0c6eb1c39d992a17d",
    "name": "externallmg_1729326556931_1729326549777_image_5.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326556931_1729326549777_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67136dc6726e053a21bfc838",
    "name": "externallmg_1729326530165_1729326521543_image_9.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326530165_1729326521543_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67136de0c6eb1c39d992a178",
    "name": "externallmg_1729326552061_1729326549777_image_0.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326552061_1729326549777_image_0.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "status": false,
  "_id": "67136dc6726e053a21bfc837",
  "name": "externallmg_1729326529982_1729326521543_image_8.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326529982_1729326521543_image_8.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "67136dc6726e053a21bfc835",
  "name": "externallmg_1729326528847_1729326521543_image_6.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326528847_1729326521543_image_6.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "67136dc6726e053a21bfc842",
  "name": "externallmg_1729326532920_1729326521544_image_19.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326532920_1729326521544_image_19.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67136dc6726e053a21bfc83e",
  "name": "externallmg_1729326531652_1729326521544_image_15.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326531652_1729326521544_image_15.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "52575.00",
    "max": "61936.00"
  },
  "builtUpRateRange": {
    "min": "43812.00",
    "max": "51613.00"
  }
},
}
```



```
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```

```
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1245.00",
"empanelmentNo": [
  "SMRO /CREDIT/2017-18/1311"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66fe4b58aaff3e49689f2e2e",
"ownerName": "Mr. Tulsidas Lakhmichand Vanwari, Mr. Mahesh Tulsidas Vanwari & Smt. Geeta Tulsidas Vanwari",
"ownerPhoneNo": "9820135632",
"appAddress": "queen corner Premises \nFlat no 51\n16 & 29 th Road \nBandra West \nMumbai 400 050\n\n",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1254aa6d152c1801b326",
```

```
"label": "Agreement For Sale"
},
"inputs": {
  "documentDate": "16/09/1986",
  "from": {
    "value": "Vendor",
    "label": "Vendor"
  },
  "Vendor": "Smt. Padmani Keshavdas Navani",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Tulsidas Lakhmichand Vanwari, Mr. Mahesh Tulsidas Vanwari &
Smt. Geeta Tulsidas Vanwari",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "Not mentioned"
},
"isHardCopy": false,
"displayStatus": true,
"id": "190289",
"path": "cases/66fe4b58aaff3e49689f2e2e/document_1728026361130_1728026354
246_vastu_Kala_51_queen_corner_Vanrai_CBI_Np.pdf",
"fileName": "document_1728026361130_1728026354246_vastu_Kala_51_queen_c
orner_Vanrai_CBI_Np.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "12/03/2014",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / WS / 0627 / H / 337 (New)"
  },
}
```

```
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1729941051664_197514.pdf",
"path": "cases/66fe4b58aaff3e49689f2e2e/document_1729941051664_197514.pdf",
"id": "942029",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Sat Oct 26 2024 11:10:51 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "documentDate": "20/07/1992",
    "remark": " in the name of Shri. Tulsidas L. Wanwari issued by Queens Corner
Premises Co-Op. Hsg. Soc. Ltd. ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "803"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "195092",
  "path": "cases/66fe4b58aaff3e49689f2e2e/document_1729941376918_131228.pdf",
  "fileName": "document_1729941376918_131228.pdf"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "30/03/2017",
    "remark": " issued Vastukala Consultants (I) Pvt. Ltd."
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "840370",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
document_1729941527777_Valuation_Report.pdf",
  "fileName": "document_1729941527777_Valuation_Report.pdf"
}
],
```

```
"caseNumber": "011584",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "823570",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Oct 03 2024 13:14:24 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Tulsidas Lakhmichand Vanwari, Mr. Mahesh Tulsidas Vanwari & Smt.
Geeta Tulsidas Vanwari",
    "phone": "9820135632",
    "ownershipShare": "",
    "email": "",
    "id": "179384"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "932688",
    "name": "Living Room",
    "length": "19.00",
    "length1": "19",
    "length2": "00",
    "width": "23.00",
    "width1": "23",
    "width2": "00",
    "totalArea": "437.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "437.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
]
```

```
"id": "1",
"name": "Bedroom",
"length": "15.00",
"length1": "15",
"length2": "00",
"width": "9.00",
"width1": "9",
"width2": "00",
"totalArea": "135.00",
"images": [],
"extraAreas": [],
"finalArea": "135.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "14.00",
  "length1": "14",
  "length2": "0",
  "width": "10.00",
  "width1": "10",
  "width2": "0",
  "totalArea": "140.00",
  "images": [],
  "finalArea": "140.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "15.00",
  "length1": "15",
  "length2": "0",
  "width": "10.00",
  "width1": "10",
  "width2": "0",
  "totalArea": "150.00",
  "images": [],
```

```
"finalArea": "150.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "81.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "81.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "27.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
```



```
"length": "3.00",
"length1": "3",
"length2": "00",
"width": "9.00",
"width1": "9",
"width2": "00",
"totalArea": "27.00",
"images": [],
"extraAreas": [],
"finalArea": "27.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "0",
  "width": "7.00",
  "width1": "7",
  "width2": "0",
  "totalArea": "28.00",
  "images": [],
  "finalArea": "28.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "0",
  "width": "4.00",
  "width1": "4",
  "width2": "0",
  "totalArea": "20.00",
  "images": [],
  "finalArea": "20.00",
  "extraAreas": []
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Passage",
  "length": "",
  "length1": "3",
  "length2": "0",
  "width": "",
  "width1": "9",
  "width2": "0",
  "totalArea": "27.00",
  "images": [],
  "finalArea": "27.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Passage",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "54.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "54.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
```

```
"length2": "00",
"width": "8.00",
"width1": "8",
"width2": "00",
"totalArea": "24.00",
"images": [],
"extraAreas": [],
"finalArea": "24.00"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "18.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "18",
  "percentageBeforeTotal": "18.00",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae1254aa6d152c1801b326",
    "label": "Agreement For Sale"
  },
}
```

```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"selectAreaTypeDocument": "Built_Up",
"squareMeterArea": "115.66",
"totalAreaDocument": "1245",
"docBuiltpPercentage": "",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docSaleablePercentage": "0",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "481305"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "833.33",
    "squareMeterArea": "77.42",
    "expectedRate": "60000.24",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1000.00",
    "squareMeterArea": "92.90",
    "expectedRate": "50000.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "671b7091fd14bf9350ac217d",
  "property": "Flat",
  "area": "1000",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": ""
}
```

```
"source": "_",
"expectedPrice": "50000000",
"expectedRate": "60000.24",
"builtUpExpectedRate": "50000000",
"image": "cases/66fe4b58aaff3e49689f2e2e/indicator_1729851128590_Image.png",
"squareMeter": "92.90",
"id": "911859"
},
{
  "carpetArea": {
    "area": "645.83",
    "squareMeterArea": "60.00",
    "expectedRate": "61935.80",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "775.00",
    "squareMeterArea": "72.00",
    "expectedRate": "51612.90",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "671b7091fd14bf9350ac217e",
  "property": "Flat",
  "area": "775",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "40000000",
  "expectedRate": "61935.80",
  "builtUpExpectedRate": "40000000",
  "image": "cases/66fe4b58aaff3e49689f2e2e/indicator_1729851176838_Image.png",
  "squareMeter": "72.00",
  "id": "748797"
},
{
  "carpetArea": {
```

```
"area": "760.83",
"squareMeterArea": "70.68",
"expectedRate": "52574.16",
"percentage": ""
},
"builtUpArea": {
"area": "913.00",
"squareMeterArea": "84.82",
"expectedRate": "43811.61",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "671b7091fd14bf9350ac217f",
"property": "Flat",
"area": "913",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "40000000.00",
"expectedRate": "52574.16",
"builtUpExpectedRate": "40000000.00",
"image": "cases/66fe4b58aaff3e49689f2e2e/indicator_1729851227007_Image.png",
"squareMeter": "84.82",
"id": "412524"
},
{
"carpetArea": {
"area": "941.67",
"squareMeterArea": "87.48",
"expectedRate": "53362.64",
"percentage": ""
},
"builtUpArea": {
"area": "1130.00",
"squareMeterArea": "104.98",
"expectedRate": "44469.03",
"percentage": "20"
}
```

```
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "671b7091fd14bf9350ac2180",
"property": "Flat",
"area": "1130",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "50250000.00",
"expectedRate": "53362.64",
"builtUpExpectedRate": "50250000.00",
"image": "cases/66fe4b58aaff3e49689f2e2e/indicator_1729851262480_Image.png",
"squareMeter": "104.98",
"id": "747050"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc82f",
    "name": "externalImg_1729326527131_1729326521543_image_0.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externalImg_1729326527131_1729326521543_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc830",
    "name": "externalImg_1729326527316_1729326521543_image_1.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externalImg_1729326527316_1729326521543_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67136dc6726e053a21bfc831",
  "name": "externalimg_1729326527514_1729326521543_image_2.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externalimg_1729326527514_1729326521543_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67136dc6726e053a21bfc832",
  "name": "externalimg_1729326527716_1729326521543_image_3.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externalimg_1729326527716_1729326521543_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67136dc6726e053a21bfc833",
  "name": "externalimg_1729326527951_1729326521543_image_4.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externalimg_1729326527951_1729326521543_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67136dc6726e053a21bfc834",
  "name": "externalimg_1729326528097_1729326521543_image_5.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externalimg_1729326528097_1729326521543_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67136dc6726e053a21bfc835",
  "name": "externalimg_1729326528847_1729326521543_image_6.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externalimg_1729326528847_1729326521543_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "67136dc6726e053a21bfc836",
    "name": "externallmg_1729326529707_1729326521543_image_7.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326529707_1729326521543_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc837",
    "name": "externallmg_1729326529982_1729326521543_image_8.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326529982_1729326521543_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc838",
    "name": "externallmg_1729326530165_1729326521543_image_9.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326530165_1729326521543_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc839",
    "name": "externallmg_1729326530280_1729326521543_image_10.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326530280_1729326521543_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc83a",
    "name": "externallmg_1729326530454_1729326521543_image_11.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326530454_1729326521543_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc83b",
```

```
    "name": "externallmg_1729326531202_1729326521543_image_12.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326531202_1729326521543_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc83c",
    "name": "externallmg_1729326531280_1729326521544_image_13.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326531280_1729326521544_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc83d",
    "name": "externallmg_1729326531451_1729326521544_image_14.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326531451_1729326521544_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc83e",
    "name": "externallmg_1729326531652_1729326521544_image_15.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326531652_1729326521544_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc83f",
    "name": "externallmg_1729326532277_1729326521544_image_16.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326532277_1729326521544_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc840",
    "name": "externallmg_1729326532388_1729326521544_image_17.jpeg",
```

```
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326532388_1729326521544_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc841",
    "name": "externallmg_1729326532720_1729326521544_image_18.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326532720_1729326521544_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136dc6726e053a21bfc842",
    "name": "externallmg_1729326532920_1729326521544_image_19.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326532920_1729326521544_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136de0c6eb1c39d992a178",
    "name": "externallmg_1729326552061_1729326549777_image_0.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326552061_1729326549777_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136de0c6eb1c39d992a179",
    "name": "externallmg_1729326552901_1729326549777_image_1.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326552901_1729326549777_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136de0c6eb1c39d992a17a",
    "name": "externallmg_1729326554648_1729326549777_image_2.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326554648_1729326549777_image_2.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67136de0c6eb1c39d992a17b",
  "name": "externallmg_1729326554977_1729326549777_image_3.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326554977_1729326549777_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67136de0c6eb1c39d992a17c",
  "name": "externallmg_1729326556332_1729326549777_image_4.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326556332_1729326549777_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67136de0c6eb1c39d992a17d",
  "name": "externallmg_1729326556931_1729326549777_image_5.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326556931_1729326549777_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67136de0c6eb1c39d992a17e",
  "name": "externallmg_1729326558123_1729326549777_image_6.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326558123_1729326549777_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67136de0c6eb1c39d992a17f",
  "name": "externallmg_1729326558408_1729326549777_image_7.jpeg",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326558408_1729326549777_image_7.jpeg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67136de0c6eb1c39d992a180",
    "name": "externallmg_1729326559132_1729326549777_image_8.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326559132_1729326549777_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67136d8f853e2039d846556a",
    "name": "externallmg_1729326475308_1729326472875_image_0.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326475308_1729326472875_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67136d8f853e2039d846556b",
    "name": "externallmg_1729326475497_1729326472875_image_1.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326475497_1729326472875_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67136d8f853e2039d846556c",
    "name": "externallmg_1729326476094_1729326472875_image_2.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326476094_1729326472875_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67136d8f853e2039d846556d",
    "name": "externallmg_1729326477667_1729326472875_image_3.jpeg",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
externallmg_1729326477667_1729326472875_image_3.jpeg",
    "orientation": "landscape"
  }
}
```

```
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "igr1.pdf",
    "filename": "1728119326379_igr1.pdf",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
processingDocuments/1728119326379_igr1.pdf",
    "size": "149128",
    "createdAt": "Sat Oct 05 2024 14:38:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
    "filename": "1728119326380_igr2.pdf",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
processingDocuments/1728119326380_igr2.pdf",
    "size": "151655",
    "createdAt": "Sat Oct 05 2024 14:38:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr3.pdf",
    "filename": "1728119326382_igr3.pdf",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
processingDocuments/1728119326382_igr3.pdf",
    "size": "149001",
    "createdAt": "Sat Oct 05 2024 14:38:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Previous report - 2022.pdf",
    "filename": "1728119326384_Previous_report__2022.pdf",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
processingDocuments/1728119326384_Previous_report__2022.pdf",
    "size": "8885568",
    "createdAt": "Sat Oct 05 2024 14:38:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Calculation (2)-tulsidas.xlsx",
    "filename": "1729843950959_Calculation_2tulsidas.xlsx",
    "path": "cases/66fe4b58aaff3e49689f2e2e/
processingDocuments/1729843950959_Calculation_2tulsidas.xlsx",
    "size": "16058",
    "createdAt": "Fri Oct 25 2024 08:12:31 GMT+0000 (Coordinated Universal Time)",
```

```
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "igr4.pdf",
  "filename": "1729843950960_igr4.pdf",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
processingDocuments/1729843950960_igr4.pdf",
  "size": "156125",
  "createdAt": "Fri Oct 25 2024 08:12:31 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary-tulsidas.xlsx",
  "filename": "1729843962478_Summarytulsidas.xlsx",
  "path": "cases/66fe4b58aaff3e49689f2e2e/
processingDocuments/1729843962478_Summarytulsidas.xlsx",
  "size": "3655315",
  "createdAt": "Fri Oct 25 2024 08:12:43 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67010209c514c90d38664c49",
    "note": "working done. visit pending",
    "taskId": "66fe6785aaff3e49689f4274",
    "createdAt": "2024-10-05T09:08:25.834Z"
  },
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
```

```
    "lastName": "Sarmalkar",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "671b5306857cdb68fa97f0c5",
  "note": "Value shared 5.66 cr.\n",
  "taskId": "66fe6785aaff3e49689f4274",
  "createdAt": "2024-10-25T08:12:54.860Z"
}
],
"createdAt": "2024-10-03T07:44:24.461Z",
"updatedAt": "2024-10-26T12:41:45.103Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 51, 5th Floor, Queens Corner Premises Co-Op.
Hsg. Soc. Ltd., Plot No. 65, TPS III, 16th & 29th Road, Village - Bandra (West), Taluka -
Andheri, District - Mumbai Suburban, Bandra (West), PIN Code - 400 050, State -
Maharashtra, India",
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mr. Deepak Matta",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Representative",
"siteVisitContactNo": "9892530656",
"buildingServicesRate": "2800",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 1245.00",
"flatRate": "47500",
"landOtherRate": "44700",
"shopDetails": {
```



```

"typeOfShops": null,
"roadFacing": false,
"mall": false
},
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 3 Toilet + 4 Passage",
"carpetTotal": "1150",
"otherCarpetTotal": "18.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1265.00",
"finalCarpetArea": "1150.00",
"finalSalableArea": "1391.50",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Oct 26 2024 10:43:23 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-10-18"
}

```

Name	Length	Width	Total
Composition :			
Living Room	19'00"	23'00"	437.00

Bedroom	15'00"	9'00"	135.00
Bedroom	14'0"	10'0"	140.00
Bedroom	15'0"	10'0"	150.00
Kitchen	9'00"	9'00"	81.00
Toilet	3'00"	9'00"	27.00
Toilet	3'00"	9'00"	27.00
Toilet	4'0"	7'0"	28.00
Passage	5'0"	4'0"	20.00
Passage	3'0"	9'0"	27.00
Passage	6'00"	9'00"	54.00
Passage	3'00"	8'00"	24.00
Other Composition :			
Flower Bed Area	3'00"	6'00"	18.00