

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "651bcdd92c6c0778ddf28f58"
    },
    "firstName": "Tanaji ",
    "type": "CREDITOFFICER",
    "_id": "651bcdd92c6c0778ddf28f5a",
    "lastName": "Khapre",
    "mobileNo": "",
    "workMobileNo": "7588090679",
    "email": "bmthan3253@centralbank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4000000",
    "discussWithPerson": "Tanaji ",
    "expectedFees": 2000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "651bcdd92c6c0778ddf28f58",
  "name": "Mira Road Branch",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "bmthan3253@centralbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Sai Riddhi Complex, 1st Floor, Opp New Post Office, Mira Road Railway
Station, Thane"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "66850df5d9f18310ed2e5d98",
"role": "SITEENGINEER",
"firstName": "Krishna",
"email": "krishnagawade9@gmail.com",
"lastName": "Gawde",
"mobileNo": "9821646373",
"designation": "Site Engg",
"shortName": "Krishna",
"workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": ""
```

```
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
},
],
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.27918291219716",
  "longitude": "72.85722373425686"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85722373425686,
    19.27918291219716
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "8/10/2024 12:25 pm"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
```

```
"value": "1BHK",
"label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bhayandar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
```

```
"name": "District",
"key": "district",
"value": "Thane",
"label": true
},
"city": {
"status": true,
"name": "City",
"key": "city",
"value": "Mira Road (East)",
"label": false
},
"tahasilNo": {
"status": false,
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Thane",
"label": true
},
"plotNo": {
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Rajashree Shopping Centre Co-op. Hsg. Soc. Ltd.",
"label": false
},
"selectArea": {
"status": false,
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Station Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B1",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "511-A/1",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
```



```
"key": "newSurveyNumber",
"value": "137/1",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "201",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "J, Zone No. 1/13",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 107",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
```

```
"label": "R.C.C. slab"
},
"flooring": {
  "value": "MosaicTileFlooring",
  "label": "Mosaic Tile Flooring"
},
"doors": {
  "value": "Teak_Wood_door_frame,_Flush_doors_shutters",
  "label": "Teak Wood door frame, Flush doors shutters"
},
"windows": {
  "value": "Alluminum_sliding_windows_with_M._S._Grills",
  "label": "Alluminum sliding windows with M. S. Grills"
},
"fittings": {
  "value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_",
  "label": "Open-Conduit plumbing with Casing Capping Electrical wiring "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Shakti Nagar CHSL",
```

```
"west": "Internal Road",
"south": "Road",
"east": "Shakti Nagar "
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.\n\n",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
```

```
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MBMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Vacant flat in poor condition"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  }
}
```

```
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Paring Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1991",
  "fullDate": "1/1/1991"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
```

```
"label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
```

```
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "27",
"ageOfBuilding": "33",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "2",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "624.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6704d56fba5e64b24a30fe19/
routeMap_1728474477967_Image.png",
    "routeLat": "19.279109",
    "routeLng": "72.857249",
    "stationName": "Mira Road",
    "routeDistance": "130m",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
```



```
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "te3eq",
    "name": "te3eq",
    "image": "cases/6704d56fba5e64b24a30fe19/
routeMap_1728474391679_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "624.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "670669acc691adb224f8667d",
      "name": "externallmg_1728473515924_externallmg_1728443483434_WhatsApp_I
mage_20241009_at_002446.jpeg",
      "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473515924_externa
lmg_1728443483434_WhatsApp_Image_20241009_at_002446.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "670669b96d5ad2b2230b1100",
      "name": "externallmg_1728473528555_externallmg_1728443483442_WhatsApp_I
mage_20241009_at_002449_1.jpeg",
      "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473528555_externa
lmg_1728443483442_WhatsApp_Image_20241009_at_002449_1.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "670669acc691adb224f8667c",
      "name": "externallmg_1728473515923_externallmg_1728443483433_WhatsApp_I
mage_20241009_at_002443.jpeg",
      "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473515923_externa
```

```
Img_1728443483433_WhatsApp_Image_20241009_at_002443.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "670669b96d5ad2b2230b10fe",
    "name": "externalImg_1728473528554_externalImg_1728443483439_WhatsApp_I
image_20241009_at_002448_2.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externalImg_1728473528554_external
Img_1728443483439_WhatsApp_Image_20241009_at_002448_2.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "670669a16d5ad2b2230b108c",
    "name": "Kitchen",
    "path": "cases/6704d56fba5e64b24a30fe19/externalImg_1728473504619_external
Img_1728443473182_WhatsApp_Image_20241009_at_002451_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "670669a16d5ad2b2230b108f",
    "name": "Kitchen",
    "path": "cases/6704d56fba5e64b24a30fe19/externalImg_1728473504622_external
Img_1728443473185_WhatsApp_Image_20241009_at_002453_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "670669b96d5ad2b2230b1101",
    "name": "Kitchen",
    "path": "cases/6704d56fba5e64b24a30fe19/externalImg_1728473528556_external
Img_1728443483444_WhatsApp_Image_20241009_at_002449.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "670669b96d5ad2b2230b1102",
    "name": "Kitchen",
    "path": "cases/6704d56fba5e64b24a30fe19/externalImg_1728473528556_external
```

```
Img_1728443483448_WhatsApp_Image_20241009_at_002450.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "670669b96d5ad2b2230b1104",
  "name": "Kitchen",
  "path": "cases/6704d56fba5e64b24a30fe19/externalImg_1728473528560_external
Img_1728443483449_WhatsApp_Image_20241009_at_002451.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
```



```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "520.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6704d56fba5e64b24a30fe19",
"ownerName": "Mr. Mukesh Jayram Gupta",
"ownerPhoneNo": "7039539380",
"appAddress": "FLAT NO 201 2ND FLOOR WING B-1 RAJASHREE SHOPPING
CENTRE CHS LTD STATION ROAD MIRA ROAD THANE 401107",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "24/09/2024",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mrs. Maurya C. R.",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Mukesh Jayram Gupta",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "17265/2024"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1728476914658_Sale_Deed__2024.pdf",
    "path": "cases/6704d56fba5e64b24a30fe19/
document_1728476914658_Sale_Deed__2024.pdf",
    "id": "833884",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
```

```
"createdAt": "Wed Oct 09 2024 17:58:34 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "29/06/1991",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "27/91-92"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1728477069966_OC.pdf",
  "path": "cases/6704d56fba5e64b24a30fe19/document_1728477069966_OC.pdf",
  "id": "635007",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Wed Oct 09 2024 18:01:10 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011672",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "143520",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Oct 08 2024 12:17:11 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Mukesh Jayram Gupta",
    "phone": "7039539380",
    "ownershipShare": "",
    "email": "",
    "id": "547605"
  }
]
```

```
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "397542",
    "name": "Kitchen",
    "length": "8.58",
    "length1": "8",
    "length2": "7",
    "width": "7.00",
    "width1": "7",
    "width2": "00",
    "totalArea": "60.08",
    "images": [],
    "extraAreas": [],
    "finalArea": "60.08"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Bathroom",
    "length": "4.83",
    "length1": "4",
    "length2": "10",
    "width": "3.25",
    "width1": "3",
    "width2": "3",
    "totalArea": "15.71",
    "images": [],
    "extraAreas": [],
    "finalArea": "15.71"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
```

```
"name": "WC",
"length": "4.58",
"length1": "4",
"length2": "7",
"width": "3.00",
"width1": "3",
"width2": "0",
"totalArea": "13.75",
"images": [],
"finalArea": "13.75",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "22.85",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.85"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "",
  "length1": "17",
  "length2": "5",
  "width": "",
  "width1": "8",
  "width2": "6",
  "totalArea": "148.04",
  "images": [],
  "finalArea": "148.04",
```

```
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "18.33",
  "length1": "18",
  "length2": "4",
  "width": "9.33",
  "width1": "9",
  "width2": "4",
  "totalArea": "171.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "171.11"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "546052",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "520",
    "squareMeterArea": "48.31",
    "docFinalBuiltUp": "624",
    "docFinalBuiltUpSquareMeter": "57.972",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6705f45b6d5ad2b2230a9147",
    "name":
"externallmg_1728443483425_WhatsApp_Image_20241009_at_002440.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/
externallmg_1728443483425_WhatsApp_Image_20241009_at_002440.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6705f45b6d5ad2b2230a9148",
    "name":
"externallmg_1728443483426_WhatsApp_Image_20241009_at_002441.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/
externallmg_1728443483426_WhatsApp_Image_20241009_at_002441.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6705f45b6d5ad2b2230a914a",
    "name":
"externallmg_1728443483432_WhatsApp_Image_20241009_at_002442.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/
externallmg_1728443483432_WhatsApp_Image_20241009_at_002442.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669a16d5ad2b2230b108b",
    "name": "externallmg_1728473504618_externallmg_1728443473180_WhatsApp_I
mage_20241009_at_002451_1.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473504618_externall
mg_1728443473180_WhatsApp_Image_20241009_at_002451_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669a16d5ad2b2230b108c",
```

```
    "name": "externallmg_1728473504619_externallmg_1728443473182_WhatsApp_I
mage_20241009_at_002451_2.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473504619_externall
mg_1728443473182_WhatsApp_Image_20241009_at_002451_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669a16d5ad2b2230b108d",
    "name": "externallmg_1728473504620_externallmg_1728443473183_WhatsApp_I
mage_20241009_at_002452_1.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473504620_externall
mg_1728443473183_WhatsApp_Image_20241009_at_002452_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669a16d5ad2b2230b108e",
    "name": "externallmg_1728473504621_externallmg_1728443473184_WhatsApp_I
mage_20241009_at_002452.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473504621_externall
mg_1728443473184_WhatsApp_Image_20241009_at_002452.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669a16d5ad2b2230b108f",
    "name": "externallmg_1728473504622_externallmg_1728443473185_WhatsApp_I
mage_20241009_at_002453_1.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473504622_externall
mg_1728443473185_WhatsApp_Image_20241009_at_002453_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669a16d5ad2b2230b1090",
    "name": "externallmg_1728473504623_externallmg_1728443483422_WhatsApp_I
mage_20241009_at_002453_2.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473504623_externall
mg_1728443483422_WhatsApp_Image_20241009_at_002453_2.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670669a16d5ad2b2230b1091",
  "name": "externallmg_1728473504624_externallmg_1728443483423_WhatsApp_I
mage_20241009_at_002453.jpeg",
  "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473504624_externall
mg_1728443483423_WhatsApp_Image_20241009_at_002453.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670669acc691adb224f86679",
  "name": "externallmg_1728473515919_externallmg_1728443483424_WhatsApp_I
mage_20241009_at_002454.jpeg",
  "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473515919_externall
mg_1728443483424_WhatsApp_Image_20241009_at_002454.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670669acc691adb224f8667a",
  "name": "externallmg_1728473515920_externallmg_1728443483427_WhatsApp_I
mage_20241009_at_002442_1.jpeg",
  "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473515920_externall
mg_1728443483427_WhatsApp_Image_20241009_at_002442_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670669acc691adb224f8667b",
  "name": "externallmg_1728473515921_externallmg_1728443483432_WhatsApp_I
mage_20241009_at_002443_1.jpeg",
  "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473515921_externall
mg_1728443483432_WhatsApp_Image_20241009_at_002443_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670669acc691adb224f8667c",
  "name": "externallmg_1728473515923_externallmg_1728443483433_WhatsApp_I
mage_20241009_at_002443.jpeg",
```



```
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473515923_externallmg_1728443483433_WhatsApp_Image_20241009_at_002443.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669acc691adb224f8667d",
    "name": "externallmg_1728473515924_externallmg_1728443483434_WhatsApp_Image_20241009_at_002446.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473515924_externallmg_1728443483434_WhatsApp_Image_20241009_at_002446.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669acc691adb224f8667e",
    "name": "externallmg_1728473515926_externallmg_1728443483437_WhatsApp_Image_20241009_at_002447.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473515926_externallmg_1728443483437_WhatsApp_Image_20241009_at_002447.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669acc691adb224f8667f",
    "name": "externallmg_1728473515928_externallmg_1728443483438_WhatsApp_Image_20241009_at_002448_1.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473515928_externallmg_1728443483438_WhatsApp_Image_20241009_at_002448_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669b96d5ad2b2230b10fe",
    "name": "externallmg_1728473528554_externallmg_1728443483439_WhatsApp_Image_20241009_at_002448_2.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473528554_externallmg_1728443483439_WhatsApp_Image_20241009_at_002448_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "670669b96d5ad2b2230b10ff",
    "name": "externallmg_1728473528554_externallmg_1728443483440_WhatsApp_I
mage_20241009_at_002448.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473528554_externall
mg_1728443483440_WhatsApp_Image_20241009_at_002448.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669b96d5ad2b2230b1100",
    "name": "externallmg_1728473528555_externallmg_1728443483442_WhatsApp_I
mage_20241009_at_002449_1.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473528555_externall
mg_1728443483442_WhatsApp_Image_20241009_at_002449_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669b96d5ad2b2230b1101",
    "name": "externallmg_1728473528556_externallmg_1728443483444_WhatsApp_I
mage_20241009_at_002449.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473528556_externall
mg_1728443483444_WhatsApp_Image_20241009_at_002449.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669b96d5ad2b2230b1102",
    "name": "externallmg_1728473528556_externallmg_1728443483448_WhatsApp_I
mage_20241009_at_002450.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473528556_externall
mg_1728443483448_WhatsApp_Image_20241009_at_002450.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670669b96d5ad2b2230b1103",
    "name": "externallmg_1728473528558_externallmg_1728443483448_WhatsApp_I
mage_20241009_at_002450_1.jpeg",
    "path": "cases/6704d56fba5e64b24a30fe19/externallmg_1728473528558_externall
mg_1728443483448_WhatsApp_Image_20241009_at_002450_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670669b96d5ad2b2230b1104",
  "name": "externalImg_1728473528560_externalImg_1728443483449_WhatsApp_I
mage_20241009_at_002451.jpeg",
  "path": "cases/6704d56fba5e64b24a30fe19/externalImg_1728473528560_externalI
mg_1728443483449_WhatsApp_Image_20241009_at_002451.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6704e2d96d5ad2b2230a3035",
    "note": "Rate verification done pending visit",
    "taskId": "6704d75bc691adb224f77c8f",
    "createdAt": "2024-10-08T07:44:25.471Z"
  }
],
"createdAt": "2024-10-08T06:47:11.410Z",
"updatedAt": "2024-10-09T12:41:36.603Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 201, 2nd Floor, Wing - B1, Rajashree Shopping
Centre Co-op. Hsg. Soc. Ltd., Station Road, Village - Bhayandar, Municipality Ward No.
J, Zone No. 1/13, Taluka - Thane, District - Thane, Mira Road (East), PIN - 401 107,
```

State - Maharashtra, India",
 "updatedBy": "60f91b6f344e052188ffd1fc",
 "addressForMap": "",
 "caseReferredBy": "659ccce98f39506e83489828",
 "contactPersonName": "Mr. Mukesh Jayram Gupta",
 "email": "",
 "isExternal": "false",
 "isUrgent": "false",
 "ownershipShare": "",
 "proposePurchaserName": "",
 "purchaseValueAsPerDocument": "",
 "relationWithOwner": "Owner",
 "siteVisitContactNo": "7039539380",
 "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Bathroom + WC + Passage",
 "carpetTotal": "431.53999999999996",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "0.00",
 "builtupPercentage": "10",
 "finalBuiltupArea": "474.69",
 "finalCarpetArea": "431.54",
 "finalSalableArea": "474.69",
 "salablePercentage": "0",
 "toBeAdded": "",
 "extendOfSiteRemark": "",
 "siteMeasurementRemark": "",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement for sale",
 "finalBuiltUpPercentage": "20",
 "finalCarpetConvertToBuiltUpPer": "20",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 520.00"

| Name | Length | Width | Total |
|---------------|--------|-------|--------|
| Composition : | | | |
| Kitchen | 8'7" | 7'00" | 60.08 |
| Bathroom | 4'10" | 3'3" | 15.71 |
| WC | 4'7" | 3'0" | 13.75 |
| Passage | 7'10" | 2'11" | 22.85 |
| Bedroom | 17'5" | 8'6" | 148.04 |

Living Room

18'4"

9'4"

171.11

Other

Composition :
