

```
{
  "typeOfReport": {
    "label": "Row House",
    "value": "Row_House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65e979baf9222577acbe667a"
    },
    "firstName": "Abhishek ",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312b5",
    "email": "abk@sbi.co.in",
    "mobileNo": "0000000000",
    "workMobileNo": "9920665690",
    "lastName": "kumar"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Abhishek ",
    "expectedFees": null,
    "quotedAmount": "12000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65e979baf9222577acbe667a",
  "name": "SME Panvel Branch ",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "sbi.19254@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "MTNL Building, Ground Floor, Plot No 229, Near Shivaji Chouk, M G
ROad Panvel-410206"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60af3d172ffdf65bcd6585cd",
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "MAKER",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
```

```
"title": {
  "label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.244453439406794",
```

```
"longitude": "72.8388024564072"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8388024564072,
    19.244453439406794
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "9/10/2024 01:15 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Eksar",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Narayan Bhuwan",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Road No 7",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```



```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "67062932c691adb224f80f27",
"ownerName": "Devang Kiritkumar Vora ",
"ownerPhoneNo": "0000000000",
"appAddress": "Plot no 43,Narayan Bhuvan Road No 7,Daulat Nagar,Eksar Village",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67062932c691adb224f80f27/document_1728456831738_1728456813597_Narayan_Bhuvan_Agreement__1957.pdf",
    "fileName": "document_1728456831738_1728456813597_Narayan_Bhuvan_Agreement__1957.pdf",
    "id": "765087",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Wed Oct 09 2024 12:26:50 GMT+0530 (India Standard Time)"
  },
  {
```

```
"documentType": {
  "label": " Agreement",
  "value": "652d16a0316e1359cebd3c15"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/67062932c691adb224f80f27/document_1728456854768_172845685
2180_Narayan_Bhuvan_Agreement__1971.pdf",
"fileName": "document_1728456854768_1728456852180_Narayan_Bhuvan_Agree
ment__1971.pdf",
"id": "153359",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Wed Oct 09 2024 12:26:50 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67062932c691adb224f80f27/
document_1728456881723_1728456877080_Narayan_Bhuvan_Agreement.pdf",
  "fileName":
"document_1728456881723_1728456877080_Narayan_Bhuvan_Agreement.pdf",
  "id": "416605",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Wed Oct 09 2024 12:26:50 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67062932c691adb224f80f27/
document_1728457004926_1728457000232_Narayan_Bhuvan_property_card.pdf",
  "fileName":
"document_1728457004926_1728457000232_Narayan_Bhuvan_property_card.pdf",
  "id": "318785",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Wed Oct 09 2024 12:26:50 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011694",
```

```
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "681051",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 09 2024 12:26:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Devang Kiritkumar Vora ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "107245"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874645",
    "name": "externalImg_1728903991008_1728903833393_image_0.jpeg",
    "path": "cases/67062932c691adb224f80f27/externalImg_1728903991008_1728903833393_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874646",
    "name": "externalImg_1728903991411_1728903833397_image_1.jpeg",
    "path": "cases/67062932c691adb224f80f27/externalImg_1728903991411_1728903833397_image_1.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874647",
    "name": "externallmg_1728903991793_1728903833397_image_2.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903991793_1728903833397_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874648",
    "name": "externallmg_1728903991795_1728903833397_image_3.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903991795_1728903833397_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874649",
    "name": "externallmg_1728903992207_1728903833397_image_4.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903992207_1728903833397_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b987464a",
    "name": "externallmg_1728903992733_1728903833397_image_5.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903992733_1728903833397_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b987464b",
    "name": "externallmg_1728903993109_1728903833397_image_6.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903993109_1728903833397_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "670cfb3d3ab4fe23b987464c",
  "name": "externallmg_1728903993120_1728903833397_image_7.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728903993120_1728903833397_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "670cfb3d3ab4fe23b987464d",
  "name": "externallmg_1728903993522_1728903833397_image_8.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728903993522_1728903833397_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "670cfb3d3ab4fe23b987464e",
  "name": "externallmg_1728903993792_1728903833397_image_9.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728903993792_1728903833397_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "670cfb3d3ab4fe23b987464f",
  "name": "externallmg_1728903994244_1728903833397_image_10.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728903994244_1728903833397_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "670cfb3d3ab4fe23b9874650",
  "name": "externallmg_1728903994749_1728903833397_image_11.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728903994749_1728903833397_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "670cfb3d3ab4fe23b9874651",
    "name": "externallmg_1728903995183_1728903833397_image_12.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903995183_1728903833397_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874652",
    "name": "externallmg_1728903995351_1728903833397_image_13.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903995351_1728903833397_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874653",
    "name": "externallmg_1728903995515_1728903833397_image_14.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903995515_1728903833397_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874654",
    "name": "externallmg_1728903995647_1728903833397_image_15.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903995647_1728903833397_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874655",
    "name": "externallmg_1728903995744_1728903833397_image_16.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903995744_1728903833397_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874656",
```

```
    "name": "externallmg_1728903995978_1728903833397_image_17.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903995978_1728903833397_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874657",
    "name": "externallmg_1728903996117_1728903833397_image_18.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903996117_1728903833397_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "670cfb3d3ab4fe23b9874658",
    "name": "externallmg_1728903996340_1728903833397_image_19.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728903996340_1728903833397_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670cfb7f3ab4fe23b9874752",
    "name": "externallmg_1728904057014_1728904014671_image_0.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728904057014_1728904014671_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670cfb7f3ab4fe23b9874753",
    "name": "externallmg_1728904057709_1728904014674_image_1.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728904057709_1728904014674_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670cfb7f3ab4fe23b9874754",
    "name": "externallmg_1728904057840_1728904014674_image_2.jpeg",
```

```
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728904057840_1728904014674_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670cfb7f3ab4fe23b9874755",
    "name": "externallmg_1728904058247_1728904014674_image_3.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728904058247_1728904014674_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670cfb7f3ab4fe23b9874756",
    "name": "externallmg_1728904058313_1728904014674_image_4.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728904058313_1728904014674_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670cfb7f3ab4fe23b9874757",
    "name": "externallmg_1728904058822_1728904014674_image_5.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728904058822_1728904014674_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670cfb7f3ab4fe23b9874758",
    "name": "externallmg_1728904058925_1728904014674_image_6.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728904058925_1728904014674_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670cfb7f3ab4fe23b9874759",
    "name": "externallmg_1728904059243_1728904014674_image_7.jpeg",
    "path": "cases/67062932c691adb224f80f27/
externallmg_1728904059243_1728904014674_image_7.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b987475a",
  "name": "externallmg_1728904059461_1728904014674_image_8.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728904059461_1728904014674_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b987475b",
  "name": "externallmg_1728904059739_1728904014674_image_9.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728904059739_1728904014674_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b987475c",
  "name": "externallmg_1728904060102_1728904014674_image_10.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728904060102_1728904014674_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b987475d",
  "name": "externallmg_1728904060292_1728904014674_image_11.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728904060292_1728904014674_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b987475e",
  "name": "externallmg_1728904060623_1728904014674_image_12.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728904060623_1728904014674_image_12.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b987475f",
  "name": "externallmg_1728904060891_1728904014674_image_13.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728904060891_1728904014674_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b9874760",
  "name": "externallmg_1728904060993_1728904014674_image_14.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728904060993_1728904014674_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b9874761",
  "name": "externallmg_1728904061083_1728904014674_image_15.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728904061083_1728904014674_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b9874762",
  "name": "externallmg_1728904061543_1728904014674_image_16.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728904061543_1728904014674_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b9874763",
  "name": "externallmg_1728904061853_1728904014674_image_17.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externallmg_1728904061853_1728904014674_image_17.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b9874764",
  "name": "externalImg_1728904062280_1728904014674_image_18.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externalImg_1728904062280_1728904014674_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670cfb7f3ab4fe23b9874765",
  "name": "externalImg_1728904062639_1728904014674_image_19.jpeg",
  "path": "cases/67062932c691adb224f80f27/
externalImg_1728904062639_1728904014674_image_19.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-10-09T06:56:50.332Z",
"updatedAt": "2024-10-14T11:07:43.127Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Row House No. Ground Floor, Narayan Bhuwan, Road No
7, Village - Eksar, Borivali, Mumbai",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Devang Kiritkumar Vora ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			