

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Rent",
    "label": "Fair Market Rent"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3000"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "67065ad0ba5e64b24a320c84",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Pritam Ashok Kachore And Kulashree Pritam Kachore",
"displayname": "Pritam Ashok Kachore And Kulashree Pritam Kachore",
"initial": "P"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "email": "jagdish.bhatt@vastukala.org",
    "lastName": "Bhatt",
    "mobileNo": "8425864014",
    "shortName": "JB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62550ed0aba01e0af98f2f75",
    "role": "SITEENGINEER",
    "firstName": "Chandan",
    "email": "ck06806@gmail.com",
    "lastName": "Singh",
    "mobileNo": "8454863607",
    "designation": "",
    "shortName": "CH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "ACCOUNTANT",
```

```
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
  "designation": "",
  "shortName": "JA",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ],
  },

```

```
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.130425059086264",
  "longitude": "72.84182268263278"
},
"geo": {
```

```
"type": "Point",
"coordinates": [
  0,
  0
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-11",
      "remark": "since casting is in progress.... internal visit not allowed"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-11",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Ambivali",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Andheri (West), Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
```

```
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sanghvi Palazzo",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Caesar Road Cross Lane",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Amboli",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
```

```
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "2A/3 & 2A/4",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "264, 264/1 & 264/2",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```



```
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "602",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "K/W",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 058",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Mhatarpada Road",
    "west": "Meri Ellen Society",
    "south": "Mithila CHSL",
    "east": "Amit Naik Marg"
  },
  "asPerDocumentAgreement": {
    "north": "Jyoti Villa Building Plot",
    "west": "Mary Ellan Building Plot",
    "south": "Yashodhan Building Plot",
    "east": "D.P. Road"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Building Under Construction",
      "east": "Building Under Construction",
      "south": "Building Under Construction",
      "west": "Building Under Construction"
    },
    "asPerDocument": {
      "north": "Lift Lobby",
      "east": "Lift & Flat No. 601",
      "south": "Marginal Space",
      "west": "Lift & Flat No. 603"
    }
  }
}
```

```
    },
    "isDisplay": true,
    "title": "Boundaries of The Flat"
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "As per Approved Building Plan, the composition of residential flat is Living Room + Bedroom + Kitchen + 2 Toilets (i.e. 1 BHK with 2 Toilets)",
  "dateOfIssusApprovePlan": "Copy of Approved Building Plan No.P-10498/2022/(264)/K/W Ward/Ambivali/337/1/New dated 16.12.2022 issued by Municipal Corporation of Greater Mumbai (MCGM) - Downloaded from RERA website.",
  "approvePlanVerified": "Yes",
  "empanelledOfApprovePlan": "No",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "26000.00",
  "depreciatedBuildingRate": "2700"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "194450",
```

```
"landRate": "104590",
"igrImage": "cases/67065ad0ba5e64b24a320c8a/igr_1729146875654_Image.png",
"squareMeterGuideLineRate": "204173.00",
"squareFeetGuideLineRate": "18968.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "194450.00",
  "squareMeterGuideLineRate": "204173.00",
  "squareFeetGuideLineRate": "18968.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Building Under Construction",
  "taxPaidHolderName": "Building Under Construction",
  "taxAmount": "Building Under Construction",
  "electricityServiceConnectionNo": "Building Under Construction",
  "meterCardHolderName": "Building Under Construction",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "Proposed_R.C.C._Slab",
"label": "Proposed R.C.C. Slab"
},
"partitions": {
"value": "Proposed_6"_Thk._Brick_Masonry",
"label": "Proposed 6" Thk. Brick Masonery"
},
"waterTank": {
"value": "Proposed_Municipal_Water_Supply",
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"carParking": "Proposed Covered Parking Space",
"constructionWorkStatus": {
"value": "InProgress",
"label": "Under Construction"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "",
"month": "1",
"year": "2027",
"fullDate": "1/1/2027"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "Proposed_R.C.C._Framed_Structure",
"label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
```

```
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"groundStilt": {
  "value": "Proposed_Stilt",
  "label": "Proposed Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "9",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "405.90",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67065ad0ba5e64b24a320c8a/
routeMap_1729148214952_Image.png",
    "routeLat": "19.130146",
    "routeLng": "72.841393",
    "stationName": "Andheri",
    "routeDistance": "1.7 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
}
```



```
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "cjzvra",
    "name": "cjzvra",
    "image": "cases/67065ad0ba5e64b24a320c8a/
routeMap_1729147979225_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
```

```
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "9594000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "9594000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "7",
    "percentage": "25.454545454545453",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "5",
    "percentage": "3.18",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
```

```
"label": "External Brick Work",
"floorsCompleted": "5",
"percentage": "3.18",
"isHideFloor": false,
"status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "2",
  "percentage": "0.64",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
```

```
"status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "42.45",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
```

```
"finalGuidelineValue": "7699111.00",
"selectedBuildUpValue": "405.90",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "670907a26d5ad2b2230c30c2",
      "name": "externallmg_1728645025902_1728645021158_image_5.jpeg",
      "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025902_1728645021158_image_5.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6709078d6d5ad2b2230c308e",
      "name": "externallmg_1728645004802_1728645000078_image_2.jpeg",
      "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645004802_1728645000078_image_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "670907a26d5ad2b2230c30c0",
      "name": "externallmg_1728645025637_1728645021158_image_3.jpeg",
      "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025637_1728645021158_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "670907a26d5ad2b2230c30bf",
      "name": "externallmg_1728645025498_1728645021158_image_2.jpeg",
      "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025498_1728645021158_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "670907a26d5ad2b2230c30c1",
      "name": "externallmg_1728645025749_1728645021158_image_4.jpeg",
```

```
    "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025749_1728645021158_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "670907a26d5ad2b2230c30bd",
    "name": "externallmg_1728645025116_1728645021158_image_0.jpeg",
    "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025116_1728645021158_image_0.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "22581.00",
    "max": "27654.00"
  },
  "builtUpRateRange": {
    "min": "20528.00",
    "max": "25140.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
```



```
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "369.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "67065ad0ba5e64b24a320c8a",
"ownerName": "Mr. Pritam Ashok Kachore",
"ownerPhoneNo": "9987965111",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9820099983",
"contactPersonName": "Mr. Aadesh Shah",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Pritam Ashok Kachore",
    "phone": "9987965111",
    "ownershipShare": "",
    "email": "",
    "id": "514291"
  },
  {
    "name": "Mrs. Kulshree Pritam Kachore",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "578323"
  }
],
"caseReferredBy": "6006d4ce5080a310ac1fd2",
"relationWithOwner": "Sales Manager",
"fullAddress": "Residential Flat No. 602, 6th Floor, Sanghvi Palazzo, Caesar Road Cross Lane, Amboli, Village - Ambivali, Municipality Ward No. K/W, District - Mumbai Suburban, Andheri (West), Mumbai, PIN - 400 058, State - Maharashtra, India",
"remark": "since casting is in progress.... internal visit not allowed",
"documents": [
  {
    "documentType": {
```

```
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"inputs": {
  "documentDate": "07/10/2024",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Sanghvi Green LLP",
  "to": {
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Mr. Pritam Ashok Kachore & Mrs. Kulshree Pritam Kachore",
  "number": {
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": "16992/2024"
},
"isHardCopy": false,
"displayStatus": false,
"id": "125900",
"path": "cases/67065ad0ba5e64b24a320c8a/document_1728968290053_FLAT_NO_602_SANGHVI_PALAZZO_MR_PRITAM_KACHORE.pdf",
"fileName": "document_1728968290053_FLAT_NO_602_SANGHVI_PALAZZO_MR_PRITAM_KACHORE.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "18/12/2023",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " P51800053991"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "122458",
  "path": "cases/67065ad0ba5e64b24a320c8a/document_1729150473791_Certificate.pdf",
```

```
"fileName": "document_1729150473791_Certificate.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "30/09/2024",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": " P-10498/2022/(264)/K/W Ward/Ambivali/CC/1/Amend"
},
"isHardCopy": false,
"displayStatus": false,
"id": "223655",
"path": "cases/67065ad0ba5e64b24a320c8a/document_1729150694568_CC.pdf",
"fileName": "document_1729150694568_CC.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "16/12/2022",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": " P-10498/2022/(264)/K/W Ward/Ambivali/337/1/New"
},
"isHardCopy": false,
"displayStatus": false,
"id": "111881",
"path": "cases/67065ad0ba5e64b24a320c8a/
document_1729151691622_Plan_2.pdf",
```

```
"fileName": "document_1729151691622_Plan_2.pdf"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "011704",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "372972",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Wed Oct 09 2024 15:58:32 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "913771",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "369",
    "squareMeterArea": "34.28",
    "docFinalBuiltUp": "405.9",
    "docFinalBuiltUpSquareMeter": "37.708",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
]
```

```
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "687.00",
      "squareMeterArea": "63.82",
      "expectedRate": "22580.06",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "755.70",
      "squareMeterArea": "70.21",
      "expectedRate": "20527.33",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "6710affe47c6f80b8c4f3c6c",
    "property": "Residential Flat",
    "area": "687",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "",
    "source": "Index_no.2",
    "expectedPrice": "15512500",
    "expectedRate": "22580.06",
    "builtUpExpectedRate": "20527.33",
    "image": "cases/67065ad0ba5e64b24a320c8a/
indicator_1729146781463_Image.png",
    "squareMeter": "63.82",
    "id": "351097"
  },
  {
    "carpetArea": {
      "area": "770.00",
      "squareMeterArea": "71.54",
      "expectedRate": "25610.39",
```

```
    "percentage": ""
  },
  "builtUpArea": {
    "area": "847.00",
    "squareMeterArea": "78.69",
    "expectedRate": "23282.17",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6710affe47c6f80b8c4f3c6d",
  "property": "Residential Flat",
  "area": "770",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "19720000",
  "expectedRate": "25610.39",
  "builtUpExpectedRate": "23282.17",
  "image": "cases/67065ad0ba5e64b24a320c8a/
indicator_1729146813587_Image.png",
  "squareMeter": "71.54",
  "id": "599220"
},
{
  "carpetArea": {
    "area": "358.00",
    "squareMeterArea": "33.26",
    "expectedRate": "27653.63",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "393.80",
    "squareMeterArea": "36.59",
    "expectedRate": "25139.66",
    "percentage": "10"
  },
  "saleableArea": {
```

```
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6710affe47c6f80b8c4f3c6e",
"property": "Residential Flat",
"area": "358",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "9900000",
"expectedRate": "27653.63",
"builtUpExpectedRate": "25139.66",
"image": "cases/67065ad0ba5e64b24a320c8a/
indicator_1729146830257_Image.png",
"squareMeter": "33.26",
"id": "683347"
},
{
"carpetArea": {
"area": "358.00",
"squareMeterArea": "33.26",
"expectedRate": "27653.63",
"percentage": ""
},
"builtUpArea": {
"area": "393.80",
"squareMeterArea": "36.59",
"expectedRate": "25139.66",
"percentage": "10"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6710affe47c6f80b8c4f3c6f",
"property": "Residential Flat",
"area": "358",
```

```
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "square_yards",
"expectedPrice": "9900000",
"expectedRate": "27653.63",
"builtUpExpectedRate": "25139.66",
"image": "cases/67065ad0ba5e64b24a320c8a/
indicator_1729146844726_Image.png",
"squareMeter": "33.26",
"id": "957373"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "670907a26d5ad2b2230c30bd",
"name": "externallmg_1728645025116_1728645021158_image_0.jpeg",
"path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025116_1728645021158_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "670907a26d5ad2b2230c30be",
"name": "externallmg_1728645025374_1728645021158_image_1.jpeg",
"path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025374_1728645021158_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "670907a26d5ad2b2230c30bf",
"name": "externallmg_1728645025498_1728645021158_image_2.jpeg",
"path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025498_1728645021158_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```



```
    "_id": "670907a26d5ad2b2230c30c0",
    "name": "externallmg_1728645025637_1728645021158_image_3.jpeg",
    "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025637_1728645021158_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670907a26d5ad2b2230c30c1",
    "name": "externallmg_1728645025749_1728645021158_image_4.jpeg",
    "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025749_1728645021158_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670907a26d5ad2b2230c30c2",
    "name": "externallmg_1728645025902_1728645021158_image_5.jpeg",
    "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645025902_1728645021158_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6709078d6d5ad2b2230c308c",
    "name": "externallmg_1728645004172_1728645000078_image_0.jpeg",
    "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645004172_1728645000078_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6709078d6d5ad2b2230c308d",
    "name": "externallmg_1728645004622_1728645000078_image_1.jpeg",
    "path": "cases/67065ad0ba5e64b24a320c8a/
externallmg_1728645004622_1728645000078_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6709078d6d5ad2b2230c308e",
```

```
    "name": "externalImg_1728645004802_1728645000078_image_2.jpeg",
    "path": "cases/67065ad0ba5e64b24a320c8a/
externalImg_1728645004802_1728645000078_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6709078d6d5ad2b2230c308f",
    "name": "externalImg_1728645004902_1728645000078_image_3.jpeg",
    "path": "cases/67065ad0ba5e64b24a320c8a/
externalImg_1728645004902_1728645000078_image_3.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1729143170404_AGR.pdf",
    "path": "cases/67065ad0ba5e64b24a320c8a/
processingDocuments/1729143170404_AGR.pdf",
    "size": "63241809",
    "createdAt": "Thu Oct 17 2024 11:02:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-01.pdf",
    "filename": "1729143171520_IGR01.pdf",
    "path": "cases/67065ad0ba5e64b24a320c8a/
processingDocuments/1729143171520_IGR01.pdf",
    "size": "154269",
    "createdAt": "Thu Oct 17 2024 11:02:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-02.pdf",
    "filename": "1729143171521_IGR02.pdf",
    "path": "cases/67065ad0ba5e64b24a320c8a/
processingDocuments/1729143171521_IGR02.pdf",
    "size": "152937",
    "createdAt": "Thu Oct 17 2024 11:02:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "INDEX.pdf",
```

```
    "filename": "1729143171522_INDEX.pdf",
    "path": "cases/67065ad0ba5e64b24a320c8a/
processingDocuments/1729143171522_INDEX.pdf",
    "size": "857956",
    "createdAt": "Thu Oct 17 2024 11:02:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Summary New=PRITAM.xlsx",
    "filename": "1729143171532_Summary_NewPRITAM.xlsx",
    "path": "cases/67065ad0ba5e64b24a320c8a/
processingDocuments/1729143171532_Summary_NewPRITAM.xlsx",
    "size": "1579345",
    "createdAt": "Thu Oct 17 2024 11:02:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Certificate.pdf",
    "filename": "1729152491196_Certificate.pdf",
    "path": "cases/67065ad0ba5e64b24a320c8a/
processingDocuments/1729152491196_Certificate.pdf",
    "size": "709117",
    "createdAt": "Thu Oct 17 2024 13:38:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Details.pdf",
    "filename": "1729152491223_Details.pdf",
    "path": "cases/67065ad0ba5e64b24a320c8a/
processingDocuments/1729152491223_Details.pdf",
    "size": "1118287",
    "createdAt": "Thu Oct 17 2024 13:38:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Plan 1.pdf",
    "filename": "1729152491249_Plan_1.pdf",
    "path": "cases/67065ad0ba5e64b24a320c8a/
processingDocuments/1729152491249_Plan_1.pdf",
    "size": "1649834",
    "createdAt": "Thu Oct 17 2024 13:38:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Plan 2.pdf",
    "filename": "1729152491279_Plan_2.pdf",
```

```
"path": "cases/67065ad0ba5e64b24a320c8a/
processingDocuments/1729152491279_Plan_2.pdf",
"size": "1865609",
"createdAt": "Thu Oct 17 2024 13:38:11 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Plan 3.pdf",
"filename": "1729152491315_Plan_3.pdf",
"path": "cases/67065ad0ba5e64b24a320c8a/
processingDocuments/1729152491315_Plan_3.pdf",
"size": "1362589",
"createdAt": "Thu Oct 17 2024 13:38:11 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-10-09T10:28:32.876Z",
"updatedAt": "2024-10-17T08:14:56.407Z",
"__v": 0,
"addressForMap": "",
"updatedAt": "60f91b6f344e052188ffd1fc",
"siteVisitDate": "2024-10-11",
"buildingServicesRate": "2700",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 369.00",
"flatRate": "26000",
"landOtherRate": "23300",
"shopDetails": {
"typeOfShops": {
"label": "Independent Building",
"value": "Independent_Building"
}
},
"roadFacing": false,
"mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
```

```

"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Thu Oct 17 2024 12:04:57 GMT+0530 (India Standard
Time)",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			