

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b807"
    },
    "firstName": "Deepathy",
    "type": "CREDITOFFICER",
    "_id": "661e19817e1d7332c87ceae5",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "7506648339",
    "email": "1sbi.60347@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "47000000",
    "discussWithPerson": "Deepathy",
    "expectedFees": 23500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b807",
  "branchCode": "000081",
  "type": "BRANCH",
  "name": "SME Vashi Turbhe Branch (Sector 19)",
  "email": "sbi.60347@sbi.co.in",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "address": "Sector No. 19, Vashi Branch, Central Facility Bldg., Phase - II, Market II,
Vashi, Navi Mumbai, State - Maharashtra, Country - India. ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
  "lastName": "Patil",
  "mobileNo": "8830049996",
  "designation": "Valuation Engineer",
  "shortName": "SSP",
  "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
  "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
```

```
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
}
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.901460517326292",
  "longitude": "73.17346963028952"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.17346963028952,
```

```
18.901460517326292
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-18",
      "remark": "Bankar Deepthy madam "
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Patalganga",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi MUmbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "F-9/1",
  "label": true
}
```

```
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "M I D C",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Additional Patalganga Industrial Area",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
```



```
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
}
```

```
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
```

```
"value": "410207",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```



```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```

```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6707f98fba5e64b24a33042d",
"ownerName": "Kore Suhas Shankar",
"ownerPhoneNo": "9664698744",
"appAddress": "Flat no 9/1 Ground floor patal Gagnga Industrial village chavane
panvel ",
"remark": "Bankar Deepthy madam ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6707f98fba5e64b24a33042d/
document_1728575880286_1728575880760_Suhas_s_kore_SME_vashi.pdf",
    "fileName":
"document_1728575880286_1728575880760_Suhas_s_kore_SME_vashi.pdf",
    "id": "257471",
    "uploadedBy": "60b7189d2ffdf65bcd65882b",
    "createdAt": "Thu Oct 10 2024 21:28:07 GMT+0530 (India Standard Time)"
  },

```

```
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6707f98fba5e64b24a33042d/
document_1729331010258_1729331007604_ReAllotment_Order_22052015.pdf",
  "fileName":
"document_1729331010258_1729331007604_ReAllotment_Order_22052015.pdf",
  "id": "978857",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Sat Oct 19 2024 15:14:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6707f98fba5e64b24a33042d/
document_1729331024007_1729331013982_OC_F91signed.pdf",
  "fileName": "document_1729331024007_1729331013982_OC_F91signed.pdf",
  "id": "580074",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Sat Oct 19 2024 15:14:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6707f98fba5e64b24a33042d/
document_1729331032974_1729331028637_F91_Drawing_Sign.pdf",
  "fileName": "document_1729331032974_1729331028637_F91_Drawing_Sign.pdf",
  "id": "982679",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Sat Oct 19 2024 15:14:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
```

```
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6707f98fba5e64b24a33042d/
document_1729331043043_1729331039341_Allotment_Order_08082013.pdf",
  "fileName":
"document_1729331043043_1729331039341_Allotment_Order_08082013.pdf",
  "id": "590841",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Sat Oct 19 2024 15:14:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6707f98fba5e64b24a33042d/
document_1729331055054_1729331049780_CC_Letter_240221.pdf",
  "fileName": "document_1729331055054_1729331049780_CC_Letter_240221.pdf",
  "id": "361705",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Sat Oct 19 2024 15:14:15 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011735",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "795820",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Oct 10 2024 21:28:07 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Kore Suhas Shankar",
    "phone": "9664698744",
    "ownershipShare": "",
    "email": "",
    "id": "236648"
  }
],
```

```
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94d7",
    "name": "externalImg_1729250330115_1729250326253_image_0.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externalImg_1729250330115_1729250326253_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94d8",
    "name": "externalImg_1729250330290_1729250326253_image_1.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externalImg_1729250330290_1729250326253_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94d9",
    "name": "externalImg_1729250330521_1729250326253_image_2.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externalImg_1729250330521_1729250326253_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94da",
    "name": "externalImg_1729250330653_1729250326253_image_3.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externalImg_1729250330653_1729250326253_image_3.jpeg",
    "orientation": "landscape"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94db",
    "name": "externallmg_1729250330807_1729250326253_image_4.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250330807_1729250326253_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94dc",
    "name": "externallmg_1729250330971_1729250326253_image_5.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250330971_1729250326253_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94dd",
    "name": "externallmg_1729250331128_1729250326253_image_6.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250331128_1729250326253_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94de",
    "name": "externallmg_1729250331307_1729250326253_image_7.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250331307_1729250326253_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94df",
    "name": "externallmg_1729250331487_1729250326253_image_8.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250331487_1729250326253_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67124422477b35348d3f94e0",
  "name": "externallmg_1729250331684_1729250326253_image_9.jpeg",
  "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250331684_1729250326253_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67124422477b35348d3f94e1",
  "name": "externallmg_1729250331919_1729250326253_image_10.jpeg",
  "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250331919_1729250326253_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67124422477b35348d3f94e2",
  "name": "externallmg_1729250332108_1729250326253_image_11.jpeg",
  "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250332108_1729250326253_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67124422477b35348d3f94e3",
  "name": "externallmg_1729250332340_1729250326253_image_12.jpeg",
  "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250332340_1729250326253_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67124422477b35348d3f94e4",
  "name": "externallmg_1729250332621_1729250326253_image_13.jpeg",
  "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250332621_1729250326253_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67124422477b35348d3f94e5",
    "name": "externallmg_1729250332925_1729250326253_image_14.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250332925_1729250326253_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94e6",
    "name": "externallmg_1729250335291_1729250326253_image_15.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250335291_1729250326253_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94e7",
    "name": "externallmg_1729250337097_1729250326253_image_16.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250337097_1729250326253_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94e8",
    "name": "externallmg_1729250337459_1729250326253_image_17.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250337459_1729250326253_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94e9",
    "name": "externallmg_1729250337775_1729250326253_image_18.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250337775_1729250326253_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67124422477b35348d3f94ea",
```



```
    "name": "externallmg_1729250338018_1729250326253_image_19.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250338018_1729250326253_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671244422c873c3471469d8f",
    "name": "externallmg_1729250366160_1729250362713_image_0.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250366160_1729250362713_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671244422c873c3471469d90",
    "name": "externallmg_1729250368239_1729250362713_image_1.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250368239_1729250362713_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671244422c873c3471469d91",
    "name": "externallmg_1729250368437_1729250362713_image_2.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250368437_1729250362713_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671244422c873c3471469d92",
    "name": "externallmg_1729250368666_1729250362713_image_3.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250368666_1729250362713_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671244422c873c3471469d93",
    "name": "externallmg_1729250368870_1729250362713_image_4.jpeg",
```

```
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250368870_1729250362713_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671244422c873c3471469d94",
    "name": "externallmg_1729250369097_1729250362713_image_5.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250369097_1729250362713_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671244422c873c3471469d95",
    "name": "externallmg_1729250369280_1729250362713_image_6.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250369280_1729250362713_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671244422c873c3471469d96",
    "name": "externallmg_1729250369443_1729250362713_image_7.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250369443_1729250362713_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671244422c873c3471469d97",
    "name": "externallmg_1729250369899_1729250362713_image_8.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250369899_1729250362713_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "671243d22c873c3471469b44",
    "name": "externallmg_1729250256992_1729250255029_image_0.jpeg",
    "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250256992_1729250255029_image_0.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "671243d22c873c3471469b45",
  "name": "externallmg_1729250257192_1729250255029_image_1.jpeg",
  "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250257192_1729250255029_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "671243d22c873c3471469b46",
  "name": "externallmg_1729250257277_1729250255029_image_2.jpeg",
  "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250257277_1729250255029_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "671243d22c873c3471469b47",
  "name": "externallmg_1729250257451_1729250255029_image_3.jpeg",
  "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250257451_1729250255029_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "671243d22c873c3471469b48",
  "name": "externallmg_1729250257754_1729250255029_image_4.jpeg",
  "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250257754_1729250255029_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "671243d22c873c3471469b49",
  "name": "externallmg_1729250257968_1729250255029_image_5.jpeg",
  "path": "cases/6707f98fba5e64b24a33042d/
externallmg_1729250257968_1729250255029_image_5.jpeg",
  "orientation": "landscape"
}
```

```

    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-10-10T15:58:07.233Z",
  "updatedAt": "2024-10-19T09:44:15.873Z",
  "__v": 0,
  "assignmentType": {
    "value": "Commercial",
    "label": "Commercial"
  },
  },
  "fullAddress": "Industrial Land and Building No. Ground Floor, Plot No. F-9/1, M I D C,
Additional Patalganga Industrial Area, Village - Patalganga, Navi MUmbai, 410207,
State - Maharashtra, India",
  "updatedBy": "65dee3f79a876858ab30487f",
  "addressForMap": "",
  "caseReferredBy": "60b7189d2ffdf65bcd65882b",
  "contactPersonName": "Kore Suhas Shankar",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "9664698744",
  "rerald": "",
  "siteVisitDate": "2024-10-18"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			