

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Abhijit",
    "type": "CREDITOFFICER",
    "_id": "66581caa2611441081269f7e",
    "lastName": "Adsul",
    "mobileNo": "",
    "workMobileNo": "9833817601",
    "email": "abhijeet.adsul@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Abhijit",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"deliveryPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
```

```
    "designation": "",
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "627222afafd7d55eddeddd82",
    "role": "FRONTDESK",
    "firstName": "Pratibha",
    "email": "shilvanta_pratibha@yahoo.co.in",
    "lastName": "Shilvanta",
    "mobileNo": "9821518537",
    "designation": "",
    "shortName": "PS",
    "workWithDocumentMaker": "60f915d3f3dd69653a592199",
    "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "checker": {
    "_id": "60f9147bf3dd69653a591e8c",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg",
    "firstName": "Vinita",
    "lastName": "Surve",
    "shortName": "V",
    "email": "vinita.surve@vastukala.org",
    "designation": "",
    "mobileNo": "9820652818",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "type": "EMPLOYEE",
    "workWithDocumentMaker": ""
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    },
    {
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
```

```
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
```

```
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.17775801071105",
  "longitude": "73.21992811276452"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.21992811276452,
    19.17775801071105
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "11/10/2024 05:13 pm"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-16",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
```

```
"audioNotes": [],
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Belavali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "1",
    "label": true
  }
}
```

```
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Badlapur (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambarnath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kendale Emeralds Phase I",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
```



```
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Badlapur Katai Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
}
```

```
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "69/1, 69/2/1",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "205",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
```

```
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 503",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
```

```
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_with_POP_false_Celling",
    "label": "Cement Plastering with POP false Celling"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kulgaon_Badlapur_Municipal_Council",
    "label": "Kulgaon Badlapur Municipal Council"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
```

```
"label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road",
  "west": "Wing - B",
  "south": "Open Plot",
  "east": "Phase - 2"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Flat No. 204",
    "east": "Marginal Space",
    "south": "Marginal Space",
    "west": "Passage"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Part Occupancy Certificate is received may be
```

```
assumed that the construction is as per sanctioned plan",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "48700",
  "landRate": "9440",
  "igrImage": "cases/670902c6ba5e64b24a3391ca/igr_1728992191259_Image.png",
  "squareMeterGuideLineRate": "48700.00",
  "squareFeetGuideLineRate": "4524.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "48700.00",
  "squareMeterGuideLineRate": "48700.00",
  "squareFeetGuideLineRate": "4524.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
}
```

```
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KBMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt / Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
},
```

```
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
```



```
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "8",
"flatFloorNo": "2",
"noOfLifts": "2",
```

```
    "noOfDwellingUnitsInBuilding": "8"
  },
  "finalPlinthArea": {
    "area": "652.30",
    "areaType": "Built Up",
    "measurementType": "Sq. Ft.",
    "areaAsPer": "Carpet Area + 10%"
  },
  "routeMap": {
    "routeMapDetail": {
      "routeMapImg": "cases/670902c6ba5e64b24a3391ca/
routeMap_1729079744090_Image.png",
      "routeLat": "19.177306",
      "routeLng": "73.219111",
      "stationName": "Badlapur",
      "routeDistance": "2.7 Km",
      "routeStation": {
        "value": "Railway_Station",
        "label": "Railway Station"
      }
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "uz9unn",
      "name": "uz9unn",
      "image": "cases/670902c6ba5e64b24a3391ca/
routeMap_1729079405613_Image.png"
    }
  ],
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": ""
    }
  }
}
```

```
"totalFairMarketValue": ""
},
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4566100.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "4566100.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Oct 17 2024 11:39:36 GMT+0530 (India Standard Time)",
  "number": "2308655",
  "dayCount": "4",
  "monthCount": "195",
  "generatedBy": "60f9147bf3dd69653a591e8c"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2951005.00",
  "selectedBuildUpValue": "652.30",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "670f9c2c9f905c0b8b757f49",
      "name":
"externalImg_1729076268775_WhatsApp_Image_20241016_at_162256.jpeg",
      "path": "cases/670902c6ba5e64b24a3391ca/
externalImg_1729076268775_WhatsApp_Image_20241016_at_162256.jpeg",
      "orientation": "landscape"
    }
  ]
}
```

```
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "670f9c219f905c0b8b757f02",
    "name":
"externallmg_1729076257546_WhatsApp_Image_20241016_at_162257_1.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076257546_WhatsApp_Image_20241016_at_162257_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "670f9c219f905c0b8b757f01",
    "name":
"externallmg_1729076257545_WhatsApp_Image_20241016_at_162256_2.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076257545_WhatsApp_Image_20241016_at_162256_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f3d",
    "name":
"externallmg_1729076268755_WhatsApp_Image_20241016_at_162259.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268755_WhatsApp_Image_20241016_at_162259.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f37",
    "name":
"externallmg_1729076268747_WhatsApp_Image_20241016_at_162257.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268747_WhatsApp_Image_20241016_at_162257.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f39",
    "name":
"externallmg_1729076268749_WhatsApp_Image_20241016_at_162258_2.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268749_WhatsApp_Image_20241016_at_162258_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f3a",
    "name":
"externallmg_1729076268751_WhatsApp_Image_20241016_at_162258.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268751_WhatsApp_Image_20241016_at_162258.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f3b",
    "name":
"externallmg_1729076268752_WhatsApp_Image_20241016_at_162259_1.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268752_WhatsApp_Image_20241016_at_162259_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f40",
    "name":
"externallmg_1729076268761_WhatsApp_Image_20241016_at_162300.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268761_WhatsApp_Image_20241016_at_162300.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f3e",
    "name":
"externallmg_1729076268756_WhatsApp_Image_20241016_at_162300_1.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268756_WhatsApp_Image_20241016_at_162300_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f41",
    "name":
"externallmg_1729076268769_WhatsApp_Image_20241016_at_162301.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268769_WhatsApp_Image_20241016_at_162301.jpeg",
    "orientation": "landscape"
  }
}
```



```
    },
    {
      "status": false,
      "_id": "670f9c2c9f905c0b8b757f49",
      "name":
"externallmg_1729076268775_WhatsApp_Image_20241016_at_162256.jpeg",
      "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268775_WhatsApp_Image_20241016_at_162256.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "670f9c2c9f905c0b8b757f47",
      "name":
"externallmg_1729076268773_WhatsApp_Image_20241016_at_162255.jpeg",
      "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268773_WhatsApp_Image_20241016_at_162255.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "670f9c2c9f905c0b8b757f46",
      "name":
"externallmg_1729076268772_WhatsApp_Image_20241016_at_162255_2.jpeg",
      "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268772_WhatsApp_Image_20241016_at_162255_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6803.00",
    "max": "7918.00"
  },
  "builtUpRateRange": {
    "min": "6185.00",
    "max": "7198.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```

```
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "593.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "670902c6ba5e64b24a3391ca",
"ownerName": "Mrs. Pratiksha Chandansingh Thakur & Mr. Chandansingh R. Thakur",
"ownerPhoneNo": "9867276268",
"appAddress": "Flat no. 205, 2nd Floor, Building 1, Wing - A, Phase 1, Kendale
Emerald, Village - Belvali, Ambernath ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "24/11/2021",
      "from": {
```

```
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Kendale Developers",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mrs. Pratiksha Chandansingh Thakur & Mr. Chandansingh R.
Thakur",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "7971 / 2021"
},
"isHardCopy": false,
"displayStatus": true,
"id": "223678",
"path": "cases/670902c6ba5e64b24a3391ca/document_1728643749537_17286437
48143_Racpc_Sion_Chandan_Singh_Thakur.pdf",
"fileName": "document_1728643749537_1728643748143_Racpc_Sion_Chandan_S
ingh_Thakur.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "07/10/2019",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KBNP / BP / 2019 - 2020 / 8996 / Unik No. 80"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1729140762603_1728992591115_1_Commencement_Certi
ficates__NA_Order_for_plotted_development.pdf",
  "path": "cases/670902c6ba5e64b24a3391ca/document_1729140762603_17289925
```

```
91115_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
  "id": "413072",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu Oct 17 2024 10:22:42 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "09/05/2024",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KBNP / NRV / 772 / 2024 - 2025"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1729140842030_OC.pdf",
  "path": "cases/670902c6ba5e64b24a3391ca/document_1729140842030_OC.pdf",
  "id": "647306",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu Oct 17 2024 10:24:02 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "02/12/2019",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51700023128"
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1729140922333_157393.pdf",
    "path": "cases/670902c6ba5e64b24a3391ca/
document_1729140922333_157393.pdf",
    "id": "428601",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Thu Oct 17 2024 10:25:22 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "011759",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "539080",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 11 2024 16:19:42 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Pratiksha Chandansingh Thakur & Mr. Chandansingh R. Thakur",
    "phone": "9867276268",
    "ownershipShare": "",
    "email": "",
    "id": "281105"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "11",
    "name": "Living Room",
    "length": "16.00",
    "length1": "16",
    "length2": "0",
    "width": "9.00",
    "width1": "9",
    "width2": "0",
```

```

"totalArea": "144.00",
"images": [],
"finalArea": "144.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "15.00",
  "width1": "15",
  "width2": "00",
  "totalArea": "75.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "75.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "102.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "102.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },

```



```
"id": "3",
"name": "Kitchen",
"length": "7.00",
"length1": "7",
"length2": "00",
"width": "8.00",
"width1": "8",
"width2": "00",
"totalArea": "56.00",
"images": [],
"extraAreas": [],
"finalArea": "56.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "30.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "9.00",
  "width1": "9",
  "width2": "0",
  "totalArea": "27.00",
  "images": [],
```

```
"finalArea": "27.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "0",
  "width": "7.00",
  "width1": "7",
  "width2": "0",
  "totalArea": "35.00",
  "images": [],
  "finalArea": "35.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Passage",
  "length": "4.00",
  "length1": "4",
  "length2": "0",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "12.00",
  "images": [],
  "finalArea": "12.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Balcony",
```

```
"length": "4.00",
"length1": "4",
"length2": "00",
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "16.00",
"images": [],
"extraAreas": [],
"finalArea": "16.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Balcony",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "16.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Balcony",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "17.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.00"
```

```
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Dry Balcony Area",
      "value": "Dry_Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "3.00",
    "length1": "3",
    "length2": "00",
    "width": "4.00",
    "width1": "4",
    "width2": "00",
    "totalArea": "12.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "12",
    "percentageBeforeTotal": "12.00",
    "percentage": "100"
  },
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Terrace Area",
      "value": "Terrace_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "length": "7.00",
    "length1": "7",
```

```
"length2": "00",
"width": "10.00",
"width1": "10",
"width2": "00",
"totalArea": "70.00",
"images": [],
"extraAreas": [],
"finalArea": "70",
"percentageBeforeTotal": "70.00",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "55.09",
  "totalAreaDocument": "593",
  "docBuiltpupPercentage": "10",
  "docFinalBuiltpup": "652.30",
  "docFinalBuiltpupSquareMeter": "60.60",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "390301"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "605.00",
    "squareMeterArea": "56.21",
    "expectedRate": "7917.36",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "665.50",
```

```
"squareMeterArea": "61.83",
"expectedRate": "7197.60",
"percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "6735c5f977990f3be0115935",
"property": "Residential Flat",
"area": "605",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "4790000",
"expectedRate": "7917.36",
"builtUpExpectedRate": "7197.60",
"image": "cases/670902c6ba5e64b24a3391ca/
indicator_1731577263277_Image.png",
"squareMeter": "56.21",
"id": "544051"
},
{
  "carpetArea": {
    "area": "452.00",
    "squareMeterArea": "41.99",
    "expectedRate": "6969.03",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "497.20",
    "squareMeterArea": "46.19",
    "expectedRate": "6335.48",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  }
}
```

```
},
"printlnReport": true,
"_id": "670e5626c844c39d22ee7c7b",
"property": "Residential Flat",
"area": "452",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "3150000",
"expectedRate": "6969.03",
"builtUpExpectedRate": "6335.48",
"image": "cases/670902c6ba5e64b24a3391ca/
indicator_1728990997570_Image.png",
"squareMeter": "41.99",
"id": "520841"
},
{
  "carpetArea": {
    "area": "588.00",
    "squareMeterArea": "54.63",
    "expectedRate": "6802.72",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "646.80",
    "squareMeterArea": "60.09",
    "expectedRate": "6184.29",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "670e5626c844c39d22ee7c7c",
  "property": "Residential Flat",
  "area": "588",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
```

```
"floor": "4th Floor",
"source": "Index_no.2",
"expectedPrice": "4000000",
"expectedRate": "6802.72",
"builtUpExpectedRate": "6184.29",
"image": "cases/670902c6ba5e64b24a3391ca/
indicator_1728991077989_Image.png",
"squareMeter": "54.63",
"id": "403133"
},
{
  "carpetArea": {
    "area": "632.00",
    "squareMeterArea": "58.71",
    "expectedRate": "7753.16",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "695.20",
    "squareMeterArea": "64.59",
    "expectedRate": "7048.33",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6735c5f977990f3be0115938",
  "property": "Residential Flat",
  "area": "632",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "4900000",
  "expectedRate": "7753.16",
  "builtUpExpectedRate": "7048.33",
  "image": "cases/670902c6ba5e64b24a3391ca/
indicator_1731577337449_Image.png",
  "squareMeter": "58.71",
  "id": "967551"
```



```
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c219f905c0b8b757f01",
    "name":
"externalImg_1729076257545_WhatsApp_Image_20241016_at_162256_2.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externalImg_1729076257545_WhatsApp_Image_20241016_at_162256_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c219f905c0b8b757f02",
    "name":
"externalImg_1729076257546_WhatsApp_Image_20241016_at_162257_1.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externalImg_1729076257546_WhatsApp_Image_20241016_at_162257_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c219f905c0b8b757f03",
    "name":
"externalImg_1729076257566_WhatsApp_Image_20241016_at_162257_2.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externalImg_1729076257566_WhatsApp_Image_20241016_at_162257_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f37",
    "name":
"externalImg_1729076268747_WhatsApp_Image_20241016_at_162257.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externalImg_1729076268747_WhatsApp_Image_20241016_at_162257.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "670f9c2c9f905c0b8b757f38",
    "name":
"externallmg_1729076268747_WhatsApp_Image_20241016_at_162258_1.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268747_WhatsApp_Image_20241016_at_162258_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f39",
    "name":
"externallmg_1729076268749_WhatsApp_Image_20241016_at_162258_2.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268749_WhatsApp_Image_20241016_at_162258_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f3a",
    "name":
"externallmg_1729076268751_WhatsApp_Image_20241016_at_162258.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268751_WhatsApp_Image_20241016_at_162258.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f3b",
    "name":
"externallmg_1729076268752_WhatsApp_Image_20241016_at_162259_1.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268752_WhatsApp_Image_20241016_at_162259_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f3c",
    "name":
"externallmg_1729076268754_WhatsApp_Image_20241016_at_162259_2.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268754_WhatsApp_Image_20241016_at_162259_2.jpeg",
    "orientation": "portrait"
  }
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f3d",
    "name":
"externallmg_1729076268755_WhatsApp_Image_20241016_at_162259.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268755_WhatsApp_Image_20241016_at_162259.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f3e",
    "name":
"externallmg_1729076268756_WhatsApp_Image_20241016_at_162300_1.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268756_WhatsApp_Image_20241016_at_162300_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f3f",
    "name":
"externallmg_1729076268757_WhatsApp_Image_20241016_at_162300_2.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268757_WhatsApp_Image_20241016_at_162300_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f40",
    "name":
"externallmg_1729076268761_WhatsApp_Image_20241016_at_162300.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268761_WhatsApp_Image_20241016_at_162300.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f41",
    "name":
"externallmg_1729076268769_WhatsApp_Image_20241016_at_162301.jpeg",
```

```
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268769_WhatsApp_Image_20241016_at_162301.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f42",
    "name":
"externallmg_1729076268770_WhatsApp_Image_20241016_at_162253.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268770_WhatsApp_Image_20241016_at_162253.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f43",
    "name":
"externallmg_1729076268771_WhatsApp_Image_20241016_at_162254_1.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268771_WhatsApp_Image_20241016_at_162254_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f44",
    "name":
"externallmg_1729076268771_WhatsApp_Image_20241016_at_162254.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268771_WhatsApp_Image_20241016_at_162254.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f9c2c9f905c0b8b757f45",
    "name":
"externallmg_1729076268772_WhatsApp_Image_20241016_at_162255_1.jpeg",
    "path": "cases/670902c6ba5e64b24a3391ca/
externallmg_1729076268772_WhatsApp_Image_20241016_at_162255_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "670f9c2c9f905c0b8b757f46",
  "name":
"externalImg_1729076268772_WhatsApp_Image_20241016_at_162255_2.jpeg",
  "path": "cases/670902c6ba5e64b24a3391ca/
externalImg_1729076268772_WhatsApp_Image_20241016_at_162255_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670f9c2c9f905c0b8b757f47",
  "name":
"externalImg_1729076268773_WhatsApp_Image_20241016_at_162255.jpeg",
  "path": "cases/670902c6ba5e64b24a3391ca/
externalImg_1729076268773_WhatsApp_Image_20241016_at_162255.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670f9c2c9f905c0b8b757f48",
  "name":
"externalImg_1729076268774_WhatsApp_Image_20241016_at_162256_1.jpeg",
  "path": "cases/670902c6ba5e64b24a3391ca/
externalImg_1729076268774_WhatsApp_Image_20241016_at_162256_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670f9c2c9f905c0b8b757f49",
  "name":
"externalImg_1729076268775_WhatsApp_Image_20241016_at_162256.jpeg",
  "path": "cases/670902c6ba5e64b24a3391ca/
externalImg_1729076268775_WhatsApp_Image_20241016_at_162256.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [
  {
    "originalname": "Pratiksha Chandansingh Thakur & Mr. Chandansingh R.
Thakur.pdf",
    "filename": "1729148130274_Pratiksha_Chandansingh_Thakur__Mr_Chandansingh
_R_Thakur.pdf",
    "path": "cases/670902c6ba5e64b24a3391ca/externalDocuments/1729148130274_P
```

```
ratiksha_Chandansingh_Thakur__Mr_Chandansingh_R_Thakur.pdf",
  "size": "1904167",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
  "createdAt": "Thu Oct 17 2024 12:25:30 GMT+0530 (India Standard Time)",
  "uploadedBy": "63f31d626f9c2254a9b39144"
},
{
  "originalname": "Valuation_Report_Pratiksha Chandansingh Thakur & Mr.
Chandansingh R. Thakur.pdf",
  "filename": "1729153562585_Valuation_Report_Pratiksha_Chandansingh_Thakur__
Mr_Chandansingh_R_Thakur.pdf",
  "path": "cases/670902c6ba5e64b24a3391ca/externalDocuments/1729153562585_V
aluation_Report_Pratiksha_Chandansingh_Thakur__Mr_Chandansingh_R_Thakur.pdf",
  "size": "7771904",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
  "createdAt": "Thu Oct 17 2024 13:56:02 GMT+0530 (India Standard Time)",
  "uploadedBy": "63f31d626f9c2254a9b39144"
},
{
  "path": "../CDN/cases/670902c6ba5e64b24a3391ca/
externalDocuments/1729161066246_390181.pdf",
  "filename": "1729161066246_390181.pdf",
  "documentType": {
    "organization": {
      "status": true,
      "isdelete": false,
      "_id": "5f2bdee67813470eb443deb4",
      "name": "Vastukala Consultants India Pvt. Ltd.",
      "gstNo": "18AABCT3518Q1ZZ",
      "panNo": "ABCDE1234A",
      "email": "vastukalamumbai@vastukala.com",
      "phone": "9819670183",
      "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E),
Mumbai - 400 093",
      "shortName": "VCIPL",
      "type": "ORGANIZATION",
      "city": "Mumbai",
      "ownerEmail": "umang@vastukala.org",
      "ownerName": "Umang Patel"
    }
  },
}
```

```
"_id": "60ae124daa6d152c1801b307",
"document": {
  "documentType": "Office Copy",
  "documentDate": true,
  "to": false,
  "from": false,
  "amount": false,
  "nameOfApprovingAuthority": false,
  "number": false,
  "remarks": true,
  "caseStatus": {
    "value": "DELIVERED",
    "label": "Delivered"
  }
},
"createdAt": "2021-05-26T09:18:05.809Z",
"updatedAt": "2023-06-20T10:17:50.158Z",
"__v": 0,
"label": "Office Copy",
"value": "60ae124daa6d152c1801b307",
"Name": "Office Copy",
"Value": "60ae124daa6d152c1801b307",
"caseStatus": {
  "value": "DELIVERED",
  "label": "Delivered"
}
},
"createdAt": "Thu Oct 17 2024 16:01:06 GMT+0530 (India Standard Time)",
"uploadedBy": "60b7177d2ffdf65bcd65882a"
}
],
"processingDocuments": [
{
  "originalname": "Adobe Scan Oct 14, 2024.pdf",
  "filename": "1728992523644_Adobe_Scan_Oct_14_2024.pdf",
  "path": "cases/670902c6ba5e64b24a3391ca/
processingDocuments/1728992523644_Adobe_Scan_Oct_14_2024.pdf",
  "size": "716586",
  "createdAt": "Tue Oct 15 2024 17:12:03 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f9147bf3dd69653a591e8c"
},
{
  "originalname": "document_Chandan_Singh_Thakur.pdf",
  "filename": "1728992523653_document_Chandan_Singh_Thakur.pdf",
  "path": "cases/670902c6ba5e64b24a3391ca/
processingDocuments/1728992523653_document_Chandan_Singh_Thakur.pdf",
```

```
"size": "11878721",
"createdAt": "Tue Oct 15 2024 17:12:03 GMT+0530 (India Standard Time)",
"uploadedBy": "60f9147bf3dd69653a591e8c"
},
{
"originalname": "Pratiksha Thakur (Cal).xlsx",
"filename": "1728992523772_Pratiksha_Thakur_Cal.xlsx",
"path": "cases/670902c6ba5e64b24a3391ca/
processingDocuments/1728992523772_Pratiksha_Thakur_Cal.xlsx",
"size": "4024170",
"createdAt": "Tue Oct 15 2024 17:12:03 GMT+0530 (India Standard Time)",
"uploadedBy": "60f9147bf3dd69653a591e8c"
},
{
"originalname": "1 Commencement Certificates _ NA Order for plotted
development.pdf",
"filename": "1728992591115_1_Commencement_Certificates__NA_Order_for_plot
ted_development.pdf",
"path": "cases/670902c6ba5e64b24a3391ca/processingDocuments/1728992591115
_1_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
"size": "936100",
"createdAt": "Tue Oct 15 2024 17:13:11 GMT+0530 (India Standard Time)",
"uploadedBy": "60f9147bf3dd69653a591e8c"
},
{
"originalname": "Sagar Jadhav (Ref).doc",
"filename": "1728992591128_Sagar_Jadhav_Ref.doc",
"path": "cases/670902c6ba5e64b24a3391ca/
processingDocuments/1728992591128_Sagar_Jadhav_Ref.doc",
"size": "7622656",
"createdAt": "Tue Oct 15 2024 17:13:11 GMT+0530 (India Standard Time)",
"uploadedBy": "60f9147bf3dd69653a591e8c"
},
{
"originalname": "Pratiksha Thakur (Cal) (Revised).xlsx",
"filename": "1731577561752_Pratiksha_Thakur_Cal_Revised.xlsx",
"path": "cases/670902c6ba5e64b24a3391ca/
processingDocuments/1731577561752_Pratiksha_Thakur_Cal_Revised.xlsx",
"size": "4446536",
"createdAt": "Thu Nov 14 2024 09:46:02 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f9147bf3dd69653a591e8c"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
```



```
{
  "createdBy": {
    "_id": "60f9147bf3dd69653a591e8c",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Vinita",
    "lastName": "Surve",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "670dea293b2d190c88dfa48f",
  "note": "Pending for Approved Plan",
  "taskId": "67090f826d5ad2b2230c419e",
  "createdAt": "2024-10-15T04:06:01.736Z"
},
{
  "createdBy": {
    "_id": "656aa949cebbe1714411d21b",
    "role": "FRONTDESK",
    "firstName": "Priyanka",
    "lastName": "Pawar"
  },
  "workType": "MAKER",
  "display": true,
  "status": true,
  "_id": "6710a6c49f905c0b8b75e3ec",
  "note": "Changes in Report (Task Reopen)",
  "taskId": "670f9c3397568e0b99dde94f",
  "createdAt": "2024-10-17T05:55:16.840Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdfc2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdfc2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "6735c53d77990f3be011575c",
  "note": "For Rate Change (Task Reopen)",
}
```

```
"taskId": "6710a2ed97568e0b99de65cf",
"createdAt": "2024-11-14T09:39:09.789Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "PRINT",
  "display": true,
  "status": true,
  "_id": "6735c54777990f3be01157a7",
  "note": "For Rate Change (Task Reopen)",
  "taskId": "6710b20397568e0b99de83bf",
  "createdAt": "2024-11-14T09:39:19.983Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "SIGNED_REPORT_UPLOAD",
  "display": true,
  "status": true,
  "_id": "6735c54b77990f3be01157af",
  "note": "For Rate Change (Task Reopen)",
  "taskId": "6710b44b97568e0b99de8763",
  "createdAt": "2024-11-14T09:39:23.856Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  },
```

```
"workType": "DELIVERY",
"display": true,
"status": true,
"_id": "6735c55a77990f3be01157ce",
"note": "For Rate Change (Task Reopen)",
"taskId": "6710ca4297568e0b99deaf60",
"createdAt": "2024-11-14T09:39:38.096Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "COLLECT_OC_COPY",
  "display": true,
  "status": true,
  "_id": "6735c55f77990f3be0115800",
  "note": "For Rate Change (Task Reopen)",
  "taskId": "6710e76b9f905c0b8b765293",
  "createdAt": "2024-11-14T09:39:43.569Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "6735c821d1078a4ea7f4b606",
  "note": "Page Adjustment (Task Reopen)",
  "taskId": "6710a2ed97568e0b99de65cf",
  "createdAt": "2024-11-14T09:51:29.732Z"
}
],
"createdAt": "2024-10-11T10:49:42.034Z",
"updatedAt": "2024-11-14T09:53:06.017Z",
"__v": 0,
```

```
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 205, 2nd Floor, Building No 1, Wing - A, Kendale
Emeralds Phase I, Badlapur Katai Road, Village - Belavali, Taluka - Ambernath, District
- Thane, Badlapur (East), PIN Code - 421 503, State - Maharashtra, India",
"updatedBy": "60f9147bf3dd69653a591e8c",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Chandansingh R. Thakur",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9867276268",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 593.00",
"flatRate": "7700",
"landOtherRate": "5200",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Thu Oct 17 2024 17:03:39 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-10-16",
"finalSaleablePercentage": "0",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + 2 Passage +
3 Balcony",
"carpetTotal": "530",
"otherCarpetTotal": "82.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "82.00",
```

```

"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "673.20",
"finalCarpetArea": "612.00",
"finalSalableArea": "740.52",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 442.00\nEnclosed Balcony Area in
Sq. Ft. = 62.00\nCupboard Area in Sq. Ft. = 16.00\nTerrace Area in Sq. Ft. = 73.00",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 481.00\nBalcony Area in Sq. Ft.
= 49.00\nDry Balcony Area in Sq. Ft. = 12.00\nTerrace Area in Sq. Ft. = 70.00\n\n",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	16'0"	9'0"	144.00
Bedroom	5'00"	15'00"	75.00
Bedroom	17'00"	6'00"	102.00
Kitchen	7'00"	8'00"	56.00
Toilet	5'00"	6'00"	30.00
Toilet	3'0"	9'0"	27.00
Passage	5'0"	7'0"	35.00

Passage	4'0"	3'0"	12.00
Balcony	4'00"	4'00"	16.00
Balcony	4'00"	4'00"	16.00
Balcony	17'00"	1'00"	17.00
Other Composition :			
Dry Balcony Area	3'00"	4'00"	12.00
Terrace Area	7'00"	10'00"	70.00