

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa0"
    },
    "firstName": "Rajesh",
    "type": "CREDITOFFICER",
    "_id": "653de381d6fbd83553d3f51a",
    "lastName": "KUMAR",
    "mobileNo": "",
    "workMobileNo": "7892953881",
    "email": "1coorddesk.rasmecbhy@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "12500000",
    "discussWithPerson": "Rajesh",
    "expectedFees": 6250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa0",
  "branchCode": "000286",
  "type": "BRANCH",
  "name": "RASMECCC Bhayandar",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "RASMECCC Bhayandar Branch Unit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, Opp. Maxus Mall, Bhayander
(West), Thane – 401 101, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.284031811061325",
  "longitude": "72.8867233672105"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.8867233672105,
19.284031811061325
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "16/10/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-16",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Ghodbunder",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "32",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "North Barcelona",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Vinay Nagar, R.N.A Complex, Ghodbunder Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
```



```
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "JP North",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "31/4(Part), 20/1(Part), 20/2(Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "3209",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 107",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mira Road (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Mira_Bhayander_Municipal_Corporation",
"label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Open Plot ",
"west": "Under Construction Road ",
"south": "Internal Road ",
"east": "Vinay Nagar Road"
},
"asPerDocumentAgreement": {
"north": "Survey No. 31",
"west": "Survey No. 30/6, 30/8",
"south": "18 Mtrs. Road ",
"east": "60 Mtrs. Road "
},
"unitBoundaries": {
"asPerActual": {
"north": "Building is under construction ",
"east": "Building is under construction ",
"south": "Building is under construction ",
"west": "Building is under construction "
},
"asPerDocument": {
"north": "Staircase ",
"east": "Flat No. 3208",
"south": "Marginal Space ",
"west": "Marginal Space "
},
"setDisplay": true,
"title": "Boundaries of The Flat"
```

```
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of Flat will be 2 Bedrooms + Living Room + Kitchen + Passage + 2 Toilets. (i.e. 2BHK).",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. MNP / NR / 2772 / 2022 - 23 dated 20.10.2022 issued by MBMC norms ",
"approvePlanVerified": "Yes ",
"empanelledOfApprovePlan": "Building is under construction ",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "19000.00",
  "depreciatedBuildingRate": "3000"
},
"igrRate": {
  "propertyName": " Residential Flat",
  "rate": "101400",
  "landRate": "27700",
  "igrImage": "cases/670e6112c844c39d22ee9275/igr_1729074075994_Image.png",
  "squareMeterGuideLineRate": "121680.00",
  "squareFeetGuideLineRate": "11304.00"
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "20",
  "depreciationPercentage": "0",
  "rate": "101400.00",
  "squareMeterGuideLineRate": "121680.00",
  "squareFeetGuideLineRate": "11304.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MBMC norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Along with One Shared Stack (Upper Stack) Car Parking
Space ",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2027",
  "fullDate": "1/1/2027"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C._Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
}
```

```
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
```



```
"label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "8",
"noOfAmenityFloors": "1",
"noOfFloors": "35",
"flatFloorNo": "32",
"noOfLifts": "5",
"noOfDwellingUnitsInBuilding": "9"
},
"finalPlinthArea": {
  "area": "717.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/670e6112c844c39d22ee9275/
routeMap_1729084341747_Image.png",
    "routeLat": "19.283835",
    "routeLng": "72.886439",
    "stationName": "4.2 Km.",
    "routeDistance": "Mira Road ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
```

```
"finalatlng": false
},
"locationMapImg": [
  {
    "id": "cwgpdp",
    "name": "cwgpdp",
    "image": "cases/670e6112c844c39d22ee9275/
routeMap_1729084197013_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "12388000.00",
```

```
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "12388000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Oct 16 2024 18:45:02 GMT+0530 (India Standard Time)",
  "number": "2308650",
  "dayCount": "18",
  "monthCount": "190",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "44",
    "percentage": "38.26086956521739",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "44",
    "percentage": "6.70",
    "isHideFloor": false,
    "status": true
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "44",
  "percentage": "6.70",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "61.66",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "8107229.00",
  "selectedBuildUpValue": "717.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "670f756447c6f80b8c4ea210",
      "name":
"externallmg_1729066340841_WhatsApp_Image_20241016_at_133533_2.jpeg",
      "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340841_WhatsApp_Image_20241016_at_133533_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "670f756447c6f80b8c4ea20d",
      "name":
"externallmg_1729066340777_WhatsApp_Image_20241016_at_133532_1.jpeg",
      "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340777_WhatsApp_Image_20241016_at_133532_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "670f756447c6f80b8c4ea20f",
      "name":
"externallmg_1729066340838_WhatsApp_Image_20241016_at_133533_1.jpeg",
      "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340838_WhatsApp_Image_20241016_at_133533_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "670f756447c6f80b8c4ea211",
      "name":
"externallmg_1729066340841_WhatsApp_Image_20241016_at_133533.jpeg",
      "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340841_WhatsApp_Image_20241016_at_133533.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "670f756447c6f80b8c4ea210",
  "name":
"externallmg_1729066340841_WhatsApp_Image_20241016_at_133533_2.jpeg",
  "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340841_WhatsApp_Image_20241016_at_133533_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "670f756447c6f80b8c4ea212",
  "name":
"externallmg_1729066340853_WhatsApp_Image_20241016_at_133534_1.jpeg",
  "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340853_WhatsApp_Image_20241016_at_133534_1.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16867.00",
    "max": "21429.00"
  },
  "builtUpRateRange": {
    "min": "15333.00",
    "max": "19481.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
```

```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "652.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "670e6112c844c39d22ee9275",
"ownerName": "Ganesh Pandharinath Shelar & Rahul Ganesh Shelar ",
"ownerPhoneNo": "9152031256",
"appAddress": "FLAT NO 3209 D WING 32TH FLOOR JP NORTH BARCELONA
VINAY NAGAR NEXT TO RNA COMPLEX GHODBUNDER ROAD MIRA ROAD
THANE 401107",
"remark": "visit urgent\nDhanjay JP north 9152031256\nRahul barcelona builder office
9833455254\n\nRahul verma SSL sbi rasmeccc 9984849643\n",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "13/09/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. JP Infra Residency Pvt. Ltd. ",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      }
    }
  },

```

```
"Allottee": "Ganesh Pandharinath Shelar & Rahul Ganesh Shelar ",
"number": {
  "value": "No",
  "label": "No"
},
"No": "16723 / 2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "893128",
"path": "cases/670e6112c844c39d22ee9275/
document_1728995383054_1728995381460_GANESH_SHELAR__AGREEMENT.pdf",
"fileName":
"document_1728995383054_1728995381460_GANESH_SHELAR__AGREEMENT.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "20/10/2022",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
  },
  "remark": " (As downloaded form RERA site) ",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "MNP / NR / 2772 / 2022 - 23"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1729080754192_1729074106565_Plan.pdf",
"path": "cases/670e6112c844c39d22ee9275/
document_1729080754192_1729074106565_Plan.pdf",
"id": "856846",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Wed Oct 16 2024 17:42:34 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
```

```
},
"inputs": {
  "documentDate": "20/10/2022",
  "nameOfApprovingAuthority": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "MNP / NR / 2772 / 2022 - 23 "
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1729080778064_1729074106550_CC.pdf",
"path": "cases/670e6112c844c39d22ee9275/
document_1729080778064_1729074106550_CC.pdf",
"id": "143532",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Wed Oct 16 2024 17:42:58 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700028384"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1729080910614_213227.pdf",
  "path": "cases/670e6112c844c39d22ee9275/
document_1729080910614_213227.pdf",
  "id": "326514",
  "uploadedBy": "62fe044a48a26047e6552796",
```

```
"createdAt": "Wed Oct 16 2024 17:45:10 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011807",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
{
  "id": "413663",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Tue Oct 15 2024 18:03:22 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Ganesh Pandharinath Shelar & Rahul Ganesh Shelar ",
  "phone": "9152031256",
  "ownershipShare": "",
  "email": "",
  "id": "832675"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "60.57",
  "totalAreaDocument": "652",
  "docBultupPercentage": "10",
  "docFinalBultUp": "717.20",
  "docFinalBultUpSquareMeter": "66.63",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
}
```

```
"id": "250968"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "560.00",
    "squareMeterArea": "52.03",
    "expectedRate": "21428.57",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "616.00",
    "squareMeterArea": "57.23",
    "expectedRate": "19480.52",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "670f93dc97568e0b99ddd67c",
  "property": "Residential Flat",
  "area": "560",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "12000000",
  "expectedRate": "21428.57",
  "builtUpExpectedRate": "19480.52",
  "image": "cases/670e6112c844c39d22ee9275/
indicator_1729072927806_Image.png",
  "squareMeter": "52.03",
  "id": "495238"
},
{
  "carpetArea": {
    "area": "850.00",
    "squareMeterArea": "78.97",
```

```
    "expectedRate": "20000.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "935.00",
    "squareMeterArea": "86.86",
    "expectedRate": "18181.82",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "670f93dc97568e0b99ddd67d",
  "property": "Residential Flat",
  "area": "850",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "17000000",
  "expectedRate": "20000.00",
  "builtUpExpectedRate": "18181.82",
  "image": "cases/670e6112c844c39d22ee9275/
indicator_1729073335960_Image.png",
  "squareMeter": "78.97",
  "id": "361754"
},
{
  "carpetArea": {
    "area": "694.00",
    "squareMeterArea": "64.47",
    "expectedRate": "16866.29",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "763.40",
    "squareMeterArea": "70.92",
    "expectedRate": "15332.99",
    "percentage": "10"
  },
}
```

```
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "670f93dc97568e0b99ddd67e",
"property": " Residential Flat",
"area": "694",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "11705205",
"expectedRate": "16866.29",
"builtUpExpectedRate": "15332.99",
"image": "cases/670e6112c844c39d22ee9275/
indicator_1729073697792_Image.png",
"squareMeter": "64.47",
"id": "766659"
},
{
  "carpetArea": {
    "area": "437.00",
    "squareMeterArea": "40.60",
    "expectedRate": "17830.74",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "480.70",
    "squareMeterArea": "44.66",
    "expectedRate": "16209.76",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "670f93dc97568e0b99ddd67f",
  "property": "Residential Flat",
```



```
"area": "437",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "7792033",
"expectedRate": "17830.74",
"builtUpExpectedRate": "16209.76",
"image": "cases/670e6112c844c39d22ee9275/
indicator_1729073753842_Image.png",
"squareMeter": "40.60",
"id": "942777"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "670f756447c6f80b8c4ea20c",
"name":
"externallmg_1729066340740_WhatsApp_Image_20241016_at_133531.jpeg",
"path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340740_WhatsApp_Image_20241016_at_133531.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "670f756447c6f80b8c4ea20d",
"name":
"externallmg_1729066340777_WhatsApp_Image_20241016_at_133532_1.jpeg",
"path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340777_WhatsApp_Image_20241016_at_133532_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "670f756447c6f80b8c4ea20e",
"name":
"externallmg_1729066340812_WhatsApp_Image_20241016_at_133532.jpeg",
"path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340812_WhatsApp_Image_20241016_at_133532.jpeg",
"orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670f756447c6f80b8c4ea20f",
  "name":
"externallmg_1729066340838_WhatsApp_Image_20241016_at_133533_1.jpeg",
  "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340838_WhatsApp_Image_20241016_at_133533_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670f756447c6f80b8c4ea210",
  "name":
"externallmg_1729066340841_WhatsApp_Image_20241016_at_133533_2.jpeg",
  "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340841_WhatsApp_Image_20241016_at_133533_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670f756447c6f80b8c4ea211",
  "name":
"externallmg_1729066340841_WhatsApp_Image_20241016_at_133533.jpeg",
  "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340841_WhatsApp_Image_20241016_at_133533.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670f756447c6f80b8c4ea212",
  "name":
"externallmg_1729066340853_WhatsApp_Image_20241016_at_133534_1.jpeg",
  "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340853_WhatsApp_Image_20241016_at_133534_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "670f756447c6f80b8c4ea213",
  "name":
"externallmg_1729066340853_WhatsApp_Image_20241016_at_133534.jpeg",
```

```
    "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340853_WhatsApp_Image_20241016_at_133534.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f756447c6f80b8c4ea214",
    "name":
"externallmg_1729066340854_WhatsApp_Image_20241016_at_133535_1.jpeg",
    "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340854_WhatsApp_Image_20241016_at_133535_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f756447c6f80b8c4ea215",
    "name":
"externallmg_1729066340855_WhatsApp_Image_20241016_at_133535_2.jpeg",
    "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340855_WhatsApp_Image_20241016_at_133535_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "670f756447c6f80b8c4ea216",
    "name":
"externallmg_1729066340855_WhatsApp_Image_20241016_at_133535.jpeg",
    "path": "cases/670e6112c844c39d22ee9275/
externallmg_1729066340855_WhatsApp_Image_20241016_at_133535.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1729074106498_Calculation_Sheet_NEW.xlsx",
    "path": "cases/670e6112c844c39d22ee9275/
processingDocuments/1729074106498_Calculation_Sheet_NEW.xlsx",
    "size": "3269941",
    "createdAt": "Wed Oct 16 2024 15:51:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },

```

```
{
  "originalname": "CC.pdf",
  "filename": "1729074106550_CC.pdf",
  "path": "cases/670e6112c844c39d22ee9275/
processingDocuments/1729074106550_CC.pdf",
  "size": "812284",
  "createdAt": "Wed Oct 16 2024 15:51:46 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "Plan.pdf",
  "filename": "1729074106565_Plan.pdf",
  "path": "cases/670e6112c844c39d22ee9275/
processingDocuments/1729074106565_Plan.pdf",
  "size": "2965523",
  "createdAt": "Wed Oct 16 2024 15:51:46 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "670f899597568e0b99ddc68a",
    "note": "Value given for confirmation ",
    "taskId": "670f30e3dc9f609d03cad0b9",
    "createdAt": "2024-10-16T09:38:29.557Z"
  }
],
"createdAt": "2024-10-15T12:33:22.674Z",
"updatedAt": "2024-10-16T13:16:12.487Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
}
```

```
},
"fullAddress": "Residential Flat No. 3209, 32nd Floor, Wing - D, North Barcelona, JP
North, Vinay Nagar, R.N.A Complex, Ghodbunder Road, Village - Ghodbunder, Mira
Road (East), Taluka - Thane, District - Thane , PIN - 401 107, State - Maharashtra,
Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Miss. Shweta Ambire",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Executive ",
"siteVisitContactNo": "9152031256",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 652.00",
"flatRate": "19000",
"landOtherRate": "16000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
```

```

"holdType": {
  "label": "Free Hold",
  "value": "Free_Hold"
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Wed Oct 16 2024 17:32:49 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-10-16"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			