

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "masterTypeOfPurpose": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "toAssess": {
    "value": "Capital_Gain_2001",
    "label": "Capital Gain 2001"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "670e6873dc9f609d03cac74a",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Humpareys & Glassgow Constructions Pvt Ltd",
"displayname": "Humpareys & Glassgow Constructions Pvt Ltd",
"initial": "H"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f9343b45132d6a6bdd96e8",
    "role": "SITEENGINEER",
    "firstName": "Rajesh",
    "email": "rajeshb.ghadi@gmail.com",
    "lastName": "Ghadi",
    "mobileNo": "8652092666",
    "designation": "",
    "shortName": "RHG",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": null,
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
```

```
{
  "value": "[N]C.C.I.T/I -14/52/2008-09",
  "label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
],
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.018011404719815",
  "longitude": "73.04308354586074"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "15/10/2024 06:37 pm"
    },
    {
      "dateTime": "15/10/2024 12:00 am"
    },
    {
      "dateTime": "15/10/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "C B D BElapur",
    "label": true
  },
}
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "14 & 15",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Chawla Plaza",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "11",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
```

```
"status": false,
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "501",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
```



```
"name": "Postal Code",
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "670e6873dc9f609d03cac750",
"ownerName": "Humpareys & Glassgow Constructions Pvt Ltd",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9819871976",
"contactPersonName": "Prakash",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Humpareys & Glassgow Constructions Pvt Ltd",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "296792"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Contact Person",
"fullAddress": "Residential Flat No. 501, 5th Floor, Wing - C, Chawla Plaza, Plot No. 14
```



& 15, Sector 11, Village - C B D BElapur, Navi Mumbai, State - Maharashtra, India",

"remark": "",

"documents": [

{  
 "documentType": {  
 "value": "60ae124eaa6d152c1801b30b",  
 "label": "Other"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document\_1728997763653\_C501\_Original\_Deed.pdf",

"path": "cases/670e6873dc9f609d03cac750/

document\_1728997763653\_C501\_Original\_Deed.pdf",

"id": "734824",

"uploadedBy": "6006d4ce5080a310ac1fdfc2",

"createdAt": "Tue Oct 15 2024 18:39:26 GMT+0530 (India Standard Time)"

}

],

"isUrgent": "false",

"isExternal": "false",

"proposePurchaserName": "",

"assignmentType": {

"value": "Commercial",

"label": "Commercial"

},

"scheduleSiteVisitDate": "Invalid date",

"caseNumber": "011809",

"createdBy": "6006d4ce5080a310ac1fdfc2",

"caseHistory": [

{  
 "id": "439008",  
 "title": "Create Case",  
 "description": "Create Case",  
 "datetime": "Tue Oct 15 2024 18:34:51 GMT+0530 (India Standard Time)"

}

],

"proposePurchasers": [],

"siteInspection": [],

"composition": [],

"otherComposition": [],

"externalReport": [],

"documentPerArea": [],

"images": [],

"indicatorArr": [],

"externalImages": [

{

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a82c6eb1c39d9925652",
    "name": "externallmg_r_1729313410260_1729264109444.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313410260_1729264109444.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a82c6eb1c39d9925653",
    "name": "externallmg_r_1729313410265_1729264109466.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313410265_1729264109466.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a82c6eb1c39d9925654",
    "name": "externallmg_r_1729313410267_1729264109489.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313410267_1729264109489.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a82c6eb1c39d9925655",
    "name": "externallmg_r_1729313410269_1729264109513.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313410269_1729264109513.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a82c6eb1c39d9925656",
    "name": "externallmg_r_1729313410273_1729264109536.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313410273_1729264109536.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67133a82c6eb1c39d9925657",
    "name": "externalimg_r_1729313410276_1729264109562.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externalimg_r_1729313410276_1729264109562.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a82c6eb1c39d9925658",
    "name": "externalimg_r_1729313410278_1729264109585.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externalimg_r_1729313410278_1729264109585.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a82c6eb1c39d9925659",
    "name": "externalimg_r_1729313410281_1729264109607.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externalimg_r_1729313410281_1729264109607.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a82c6eb1c39d992565a",
    "name": "externalimg_r_1729313410228_1729264109403.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externalimg_r_1729313410228_1729264109403.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a82c6eb1c39d992565b",
    "name": "externalimg_r_1729313410240_1729264109420.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externalimg_r_1729313410240_1729264109420.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "67133a8fc6eb1c39d9925670",
    "name": "externalimg_r_1729313423062_1729264109649.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externalimg_r_1729313423062_1729264109649.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d9925671",
    "name": "externalimg_r_1729313423065_1729264109701.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externalimg_r_1729313423065_1729264109701.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d9925672",
    "name": "externalimg_r_1729313423064_1729264109674.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externalimg_r_1729313423064_1729264109674.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d9925673",
    "name": "externalimg_r_1729313423060_1729264109627.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externalimg_r_1729313423060_1729264109627.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d9925674",
    "name": "externalimg_r_1729313423067_1729264109726.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externalimg_r_1729313423067_1729264109726.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d9925675",
```

```
    "name": "externallmg_r_1729313423068_1729264109758.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423068_1729264109758.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d9925676",
    "name": "externallmg_r_1729313423071_1729264109786.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423071_1729264109786.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d9925677",
    "name": "externallmg_r_1729313423074_1729264109821.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423074_1729264109821.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d9925678",
    "name": "externallmg_r_1729313423075_1729264109850.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423075_1729264109850.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d9925679",
    "name": "externallmg_r_1729313423078_1729264109901.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423078_1729264109901.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d992567a",
    "name": "externallmg_r_1729313423077_1729264109877.jpg",
```

```
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423077_1729264109877.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d992567b",
    "name": "externallmg_r_1729313423079_1729264109924.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423079_1729264109924.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d992567c",
    "name": "externallmg_r_1729313423083_1729264109974.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423083_1729264109974.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d992567d",
    "name": "externallmg_r_1729313423081_1729264109949.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423081_1729264109949.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d992567e",
    "name": "externallmg_r_1729313423105_1729264110024.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423105_1729264110024.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d992567f",
    "name": "externallmg_r_1729313423109_1729264110048.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423109_1729264110048.jpg",
```

```

    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67133a8fc6eb1c39d9925680",
    "name": "externallmg_r_1729313423085_1729264109996.jpg",
    "path": "cases/670e6873dc9f609d03cac750/
externallmg_r_1729313423085_1729264109996.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-10-15T13:04:51.360Z",
"updatedAt": "2024-10-19T04:50:23.235Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fdfc2"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			