

```
{
  "typeOfReport": {
    "value": "11_U_A",
    "label": "11 U A"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "masterTypeOfPurpose": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "toAssess": {
    "value": "Capital_Gain_2001",
    "label": "Capital Gain 2001"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "670e6cbfc844c39d22ee9e8e",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Worley Service India Pvt.Ltd",
"displayname": "Worley Service India Pvt.Ltd",
"initial": "W"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "65dee3f79a876858ab30487f",
    "role": "SITEENGINEER",
    "firstName": "Saiprasad",
    "email": "saiprasadpatil1010@gmail.com",
    "lastName": "Patil",
    "mobileNo": "8830049996",
    "designation": "Valuation Engineer",
    "shortName": "SSP",
    "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
    "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
  },
  "rateVerifier": null,
  "maker": null,
  "checker": null,
  "valuers": [
```

```
{
  "valuersRegistrationNumber": [
    {
      "value": "[N]C.C.I.T/I -14/52/2008-09",
      "label": "Wealth Tax"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
],
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.11601466266428",
  "longitude": "72.87032142453106"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
```

```
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kondivita",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
```

```
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "New Energy House",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```

```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
```



```
    "key": "suburb",
    "value": "Andheri East",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": ""
  }
}
```

```
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```

```
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
```

```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "670e6cbfc844c39d22ee9e94",
"ownerName": "Worley Service India Pvt.Ltd",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9819871976",
"contactPersonName": "Prakash",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Worley Service India Pvt.Ltd",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "605593"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Contact Person",
"fullAddress": "Commercial 11 U A No. Ground Floor, New Energy House, Village -
Kondivita, Andheri East, Mumbai, State - Maharashtra, India",
"remark": "",
"documents": [],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "011811",
```



```
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "360531",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Oct 15 2024 18:53:11 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6710b6fa9f905c0b8b75fc32",
    "name": "externalImg_1729148656308_1729148653086_image_0.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/externalImg_1729148656308_1729148653086_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6710b6fa9f905c0b8b75fc33",
    "name": "externalImg_1729148658541_1729148653086_image_1.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/externalImg_1729148658541_1729148653086_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6710b6fa9f905c0b8b75fc34",
    "name": "externalImg_1729148659817_1729148653086_image_2.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/externalImg_1729148659817_1729148653086_image_2.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6710b6fa9f905c0b8b75fc35",
    "name": "externallmg_1729148659962_1729148653086_image_3.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148659962_1729148653086_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6710b6fa9f905c0b8b75fc36",
    "name": "externallmg_1729148661487_1729148653086_image_4.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148661487_1729148653086_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6710b6fa9f905c0b8b75fc37",
    "name": "externallmg_1729148662717_1729148653086_image_5.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148662717_1729148653086_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6710b6fa9f905c0b8b75fc38",
    "name": "externallmg_1729148663621_1729148653086_image_6.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148663621_1729148653086_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6710b6fa9f905c0b8b75fc39",
    "name": "externallmg_1729148663961_1729148653086_image_7.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148663961_1729148653086_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "6710b6fa9f905c0b8b75fc3a",
  "name": "externalimg_1729148665047_1729148653086_image_8.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externalimg_1729148665047_1729148653086_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b76347c6f80b8c4f46a9",
  "name": "externalimg_1729148740791_1729148736365_image_0.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externalimg_1729148740791_1729148736365_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b76347c6f80b8c4f46aa",
  "name": "externalimg_1729148742950_1729148736365_image_1.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externalimg_1729148742950_1729148736365_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b76347c6f80b8c4f46ab",
  "name": "externalimg_1729148743506_1729148736365_image_2.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externalimg_1729148743506_1729148736365_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b76347c6f80b8c4f46ac",
  "name": "externalimg_1729148745107_1729148736365_image_3.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externalimg_1729148745107_1729148736365_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6710b76347c6f80b8c4f46ad",
    "name": "externallmg_1729148746251_1729148736365_image_4.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148746251_1729148736365_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46ae",
    "name": "externallmg_1729148747261_1729148736365_image_5.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148747261_1729148736365_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46af",
    "name": "externallmg_1729148748556_1729148736365_image_6.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148748556_1729148736365_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46b0",
    "name": "externallmg_1729148749797_1729148736365_image_7.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148749797_1729148736365_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46b1",
    "name": "externallmg_1729148753971_1729148736365_image_8.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148753971_1729148736365_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46b2",
```

```
    "name": "externallmg_1729148755241_1729148736365_image_9.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148755241_1729148736365_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46b3",
    "name": "externallmg_1729148756312_1729148736365_image_10.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148756312_1729148736365_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46b4",
    "name": "externallmg_1729148759867_1729148736365_image_11.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148759867_1729148736365_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46b5",
    "name": "externallmg_1729148761337_1729148736365_image_12.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148761337_1729148736365_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46b6",
    "name": "externallmg_1729148763462_1729148736365_image_13.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148763462_1729148736365_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46b7",
    "name": "externallmg_1729148764737_1729148736365_image_14.jpeg",
```

```
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148764737_1729148736365_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46b8",
    "name": "externallmg_1729148765417_1729148736365_image_15.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148765417_1729148736365_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46b9",
    "name": "externallmg_1729148766277_1729148736365_image_16.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148766277_1729148736365_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46ba",
    "name": "externallmg_1729148767356_1729148736365_image_17.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148767356_1729148736365_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46bb",
    "name": "externallmg_1729148768334_1729148736365_image_18.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148768334_1729148736365_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b76347c6f80b8c4f46bc",
    "name": "externallmg_1729148769476_1729148736365_image_19.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148769476_1729148736365_image_19.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b79947c6f80b8c4f477f",
  "name": "externallmg_1729148810147_1729148803367_image_0.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148810147_1729148803367_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b79947c6f80b8c4f4780",
  "name": "externallmg_1729148810437_1729148803367_image_1.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148810437_1729148803367_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b79947c6f80b8c4f4781",
  "name": "externallmg_1729148810666_1729148803367_image_2.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148810666_1729148803367_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b79947c6f80b8c4f4782",
  "name": "externallmg_1729148810876_1729148803367_image_3.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148810876_1729148803367_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b79947c6f80b8c4f4783",
  "name": "externallmg_1729148811001_1729148803367_image_4.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148811001_1729148803367_image_4.jpeg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b79947c6f80b8c4f4784",
    "name": "externallmg_1729148811487_1729148803367_image_5.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148811487_1729148803367_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b79947c6f80b8c4f4785",
    "name": "externallmg_1729148813562_1729148803367_image_6.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148813562_1729148803367_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b79947c6f80b8c4f4786",
    "name": "externallmg_1729148813872_1729148803367_image_7.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148813872_1729148803367_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b79947c6f80b8c4f4787",
    "name": "externallmg_1729148814701_1729148803367_image_8.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148814701_1729148803367_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b79947c6f80b8c4f4788",
    "name": "externallmg_1729148817682_1729148803367_image_9.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148817682_1729148803367_image_9.jpeg",
    "orientation": "landscape"
  },
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b79947c6f80b8c4f4789",
  "name": "externallmg_1729148817683_1729148803367_image_10.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148817683_1729148803367_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b79947c6f80b8c4f478a",
  "name": "externallmg_1729148817684_1729148803367_image_11.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148817684_1729148803367_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b79947c6f80b8c4f478b",
  "name": "externallmg_1729148818422_1729148803367_image_12.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148818422_1729148803367_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b79947c6f80b8c4f478c",
  "name": "externallmg_1729148818528_1729148803367_image_13.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148818528_1729148803367_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b79947c6f80b8c4f478d",
  "name": "externallmg_1729148818529_1729148803367_image_14.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148818529_1729148803367_image_14.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b79947c6f80b8c4f478e",
    "name": "externallmg_1729148818529_1729148803367_image_15.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148818529_1729148803367_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b79947c6f80b8c4f478f",
    "name": "externallmg_1729148818530_1729148803367_image_16.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148818530_1729148803367_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b79947c6f80b8c4f4790",
    "name": "externallmg_1729148821352_1729148803367_image_17.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148821352_1729148803367_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b79947c6f80b8c4f4791",
    "name": "externallmg_1729148821737_1729148803367_image_18.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148821737_1729148803367_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b79947c6f80b8c4f4792",
    "name": "externallmg_1729148824697_1729148803367_image_19.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148824697_1729148803367_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6710b7e89f905c0b8b75fed3",
  "name": "externallmg_1729148862552_1729148859715_image_0.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148862552_1729148859715_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b7e89f905c0b8b75fed4",
  "name": "externallmg_1729148864852_1729148859715_image_1.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148864852_1729148859715_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b7e89f905c0b8b75fed5",
  "name": "externallmg_1729148867477_1729148859715_image_2.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148867477_1729148859715_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b7e89f905c0b8b75fed6",
  "name": "externallmg_1729148868077_1729148859715_image_3.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148868077_1729148859715_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b7e89f905c0b8b75fed7",
  "name": "externallmg_1729148872282_1729148859715_image_4.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148872282_1729148859715_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6710b7e89f905c0b8b75fed8",
    "name": "externallmg_1729148873502_1729148859715_image_5.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148873502_1729148859715_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fed9",
    "name": "externallmg_1729148876672_1729148859715_image_6.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148876672_1729148859715_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75feda",
    "name": "externallmg_1729148878702_1729148859715_image_7.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148878702_1729148859715_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fedb",
    "name": "externallmg_1729148881422_1729148859715_image_8.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148881422_1729148859715_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fedc",
    "name": "externallmg_1729148882822_1729148859715_image_9.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148882822_1729148859715_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fedd",
```

```
    "name": "externallmg_1729148884601_1729148859715_image_10.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148884601_1729148859715_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fede",
    "name": "externallmg_1729148886787_1729148859715_image_11.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148886787_1729148859715_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fedf",
    "name": "externallmg_1729148887622_1729148859715_image_12.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148887622_1729148859715_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fee0",
    "name": "externallmg_1729148889748_1729148859715_image_13.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148889748_1729148859715_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fee1",
    "name": "externallmg_1729148892442_1729148859715_image_14.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148892442_1729148859715_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fee2",
    "name": "externallmg_1729148896302_1729148859715_image_15.jpeg",
```

```
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148896302_1729148859715_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fee3",
    "name": "externallmg_1729148899304_1729148859715_image_16.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148899304_1729148859715_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fee4",
    "name": "externallmg_1729148900631_1729148859715_image_17.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148900631_1729148859715_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fee5",
    "name": "externallmg_1729148901913_1729148859715_image_18.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148901913_1729148859715_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b7e89f905c0b8b75fee6",
    "name": "externallmg_1729148903232_1729148859715_image_19.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148903232_1729148859715_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b84397568e0b99de90d2",
    "name": "externallmg_1729148952848_1729148946745_image_0.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148952848_1729148946745_image_0.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b84397568e0b99de90d3",
  "name": "externallmg_1729148954747_1729148946745_image_1.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148954747_1729148946745_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b84397568e0b99de90d4",
  "name": "externallmg_1729148957377_1729148946745_image_2.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148957377_1729148946745_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b84397568e0b99de90d5",
  "name": "externallmg_1729148958197_1729148946745_image_3.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148958197_1729148946745_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b84397568e0b99de90d6",
  "name": "externallmg_1729148960482_1729148946745_image_4.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148960482_1729148946745_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b84397568e0b99de90d7",
  "name": "externallmg_1729148964457_1729148946745_image_5.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148964457_1729148946745_image_5.jpeg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b84397568e0b99de90d8",
    "name": "externallmg_1729148965017_1729148946745_image_6.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148965017_1729148946745_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b84397568e0b99de90d9",
    "name": "externallmg_1729148967002_1729148946745_image_7.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148967002_1729148946745_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b84397568e0b99de90da",
    "name": "externallmg_1729148969172_1729148946745_image_8.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148969172_1729148946745_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b84397568e0b99de90db",
    "name": "externallmg_1729148971072_1729148946745_image_9.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148971072_1729148946745_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b84397568e0b99de90dc",
    "name": "externallmg_1729148972527_1729148946745_image_10.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148972527_1729148946745_image_10.jpeg",
    "orientation": "landscape"
  },
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b84397568e0b99de90dd",
  "name": "externallmg_1729148975102_1729148946745_image_11.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148975102_1729148946745_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b84397568e0b99de90de",
  "name": "externallmg_1729148976982_1729148946745_image_12.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148976982_1729148946745_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b84397568e0b99de90df",
  "name": "externallmg_1729148978902_1729148946745_image_13.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148978902_1729148946745_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b84397568e0b99de90e0",
  "name": "externallmg_1729148981942_1729148946745_image_14.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148981942_1729148946745_image_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6710b84397568e0b99de90e1",
  "name": "externallmg_1729148983722_1729148946745_image_15.jpeg",
  "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148983722_1729148946745_image_15.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b84397568e0b99de90e2",
    "name": "externallmg_1729148985667_1729148946745_image_16.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148985667_1729148946745_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b84397568e0b99de90e3",
    "name": "externallmg_1729148988606_1729148946745_image_17.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148988606_1729148946745_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b84397568e0b99de90e4",
    "name": "externallmg_1729148990628_1729148946745_image_18.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148990628_1729148946745_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b84397568e0b99de90e5",
    "name": "externallmg_1729148993032_1729148946745_image_19.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729148993032_1729148946745_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91c9",
    "name": "externallmg_1729149038223_1729149035716_image_0.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729149038223_1729149035716_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6710b87497568e0b99de91ca",
    "name": "externalimg_1729149038788_1729149035716_image_1.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externalimg_1729149038788_1729149035716_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91cb",
    "name": "externalimg_1729149039599_1729149035716_image_2.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externalimg_1729149039599_1729149035716_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91cc",
    "name": "externalimg_1729149039601_1729149035716_image_3.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externalimg_1729149039601_1729149035716_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91cd",
    "name": "externalimg_1729149039775_1729149035716_image_4.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externalimg_1729149039775_1729149035716_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91ce",
    "name": "externalimg_1729149039930_1729149035716_image_5.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externalimg_1729149039930_1729149035716_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6710b87497568e0b99de91cf",
    "name": "externallmg_1729149040284_1729149035716_image_6.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729149040284_1729149035716_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91d0",
    "name": "externallmg_1729149040384_1729149035716_image_7.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729149040384_1729149035716_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91d1",
    "name": "externallmg_1729149040561_1729149035716_image_8.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729149040561_1729149035716_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91d2",
    "name": "externallmg_1729149040846_1729149035716_image_9.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729149040846_1729149035716_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91d3",
    "name": "externallmg_1729149041470_1729149035716_image_10.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externallmg_1729149041470_1729149035716_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91d4",
```

```
    "name": "externalImg_1729149041905_1729149035716_image_11.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externalImg_1729149041905_1729149035716_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91d5",
    "name": "externalImg_1729149042333_1729149035716_image_12.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externalImg_1729149042333_1729149035716_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91d6",
    "name": "externalImg_1729149042444_1729149035716_image_13.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externalImg_1729149042444_1729149035716_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91d7",
    "name": "externalImg_1729149043095_1729149035716_image_14.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externalImg_1729149043095_1729149035716_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6710b87497568e0b99de91d8",
    "name": "externalImg_1729149043570_1729149035716_image_15.jpeg",
    "path": "cases/670e6cbfc844c39d22ee9e94/
externalImg_1729149043570_1729149035716_image_15.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
```

"remarks": [],
"createdAt": "2024-10-15T13:23:11.862Z",
"updatedAt": "2024-10-17T07:10:44.456Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "65dee3f79a876858ab30487f"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			